

BANFF/2001 PIPELINE WORKSHOP

Managing Pipeline Integrity A Workshop for Sharing Technology and Experience





April 9-12, 2001

Tutorials: April 9, 2001 Banff Centre for Conferences Banff, Alberta, Canada

Proceedings







GreenPipe







ASME Pipeline

HUNTER • M®DONNELL PIPELINE SERVICES















NIVET ----

A Varco Company







TRANS MOUNTAIN







In-line Inspection

Bruce Nestleroth, Battelle and Pat Vieth, CC Technology

The in-line inspection tutorial was attended by over 50 workshop registrants and was a mix of pipeline company experts with years of experience with in-line inspection, pipeline company neophytes, inspection vendors, consultants and government regulators. The afternoon portion added about 20 additional workshop registrants from the morning corrosion assessment workshop. Bruce Nestleroth led the morning session, which covered the technical aspects of inline inspection. After a brief introduction to terms used on all types of in-line inspection tools, the workshop focused on the most commonly used technology, magnetic flux leakage (MFL). This included both the widely used technology that magnetizes in the axial direction, and the emerging technology that magnetizes in the circumferential direction, transverse to the axial direction.

The MFL tutorial started with application of the magnetic field and the inspection variables that effect the results including velocity, pipe material, wall thickness, diameter and remanent magnetization. Then characteristics of flux leakage from pipeline defects was discussed. Examples from defects recorded using the GTI Pipeline Simulation Facility MFL Test Pig were shown along with the effect of inspection variables. Sensor and data recording considerations were discussed. Finally a performance capability prognosis was given.

To compliment the theory of in-line inspection, the two applications of pigging was presented by Pat Vieth. The first was corrosion example and the use of assessment criteria such as RSTRGTH and B31G. Concepts of prioritization and dealing with the uncertainties of in-line inspection were presented. The second was a seam weld defect example using transverse (circumferential) MFL technology. Detection of hook cracks, lack of fusion and other defects were presented. Since all defects detected with this technology and removed from service passed hydrostatic testing, the pipeline was confidently returned to service.

Attendees at In-Line Inspection Tutorial – April 9, 2001

9:00 a.m. - noon Session

1.	Chris Horkoff	AEC Oil & Gas	Medicine Hat, AB
2.	Chris Grant	Alberta Energy and Utilities Board	Calgary, AB
3.	Arti Bhatia	Alliance Pipeline	Calgary, AB
4	Daryll Wendland	Alliance Pipeline Ltd.	Grande Prairie, AB
5.	Terri Johnston	Alliance Pipeline Ltd.	Calgary, AB
6.	Ben Sokol	ATCO Pipelines	Edmonton, AB
7.	Fred Baines	BC Gas Utility Ltd.	Surrey, BC
8.	Chris Billinton	BC Gas Utility Ltd.	Kelowna, BC
9.	Chris Hallam	BJ Pipeline Inspection	Calgary, AB
10.	Jenny Been	CANMET	Ottawa, ON
11.	Bill Tyson	CANMET Materials Technology Lab	Ottawa, ON
12.	Alebachew Demoz	CANMET Western Research Centre	Devon, AB
13.	Cliff Mitchell	CJ Mitchell & Associates Ltd.	Calgary, AB
14.	Dave Webster	Colt Engineering Corporation	Calgary, AB
15.	Chris Pollard	Cornerstone Pipeline Inspection Group	Houston, TX
16.	Zane Reinhart	Corrpro Canada Inc.	Calgary, AB
17.	Grant Firth	Corrpro Canada Inc.	Calgary, AB
18.	Doug Doran	Corrpro Canada Inc.	Calgary, AB
19.	Don Engen	Enbridge Pipelines Inc.	Edmonton, AB
20.	Shawn Dawe	Enbridge Pipelines Inc.	Edmonton, AB
21.	Garrett Hilkie	Enbridge Pipelines Inc.	Edmonton, AB
22.	Mo Mohitpoul	Enbridge Pipelines Inc.	Edmonton, AB
23.	Blair Carroll	Fleet Technology Ltd.	Edmonton, AB
24.	Kyle Keith	Foothills Pipe Lines Ltd.	Calgary, AB
25.	John Chase	Hunter McDonnell Pipeline Services	Edmonton, AB
26.	Debbie Siemens	Hunter McDonnell Pipeline Services	Edmonton, AB
27.	Al Forth	Imperial Oil, Pipeline Operations	Waterdown, ON
28.	Neil S. Hay	Koch Pipelines Canada L.P.	Calgary, AB
29.	Bruno Romero	Maya Database & Internet Apps. Inc.	Calgary, AB
30.	Dennis Hinnah	Minerals Management Service	Anchorage, AK
31.	Tom Morrison	Morrison Scientific Inc.	Calgary, AB
32.	Rima Raed	National Energy Board	Calgary, AB
33.	Josef Kopec	National Energy Board	Calgary, AB
34.	Paul Trudel	National Energy Board	Calgary, AB
35.	Mary Gale	Nova Chemicals	Red Deer, AB
36.	Ray Jones	Nova Chemicals	Red Deer, AB
37.	Pete Donnelly	Pembina Pipeline Corporation	Drayton Valley, AB
38.	Chris Pierce	Pierce Consulting Ltd.	Calgary, AB
39.	Lee Greanyp	Positive Projects International Ltd.	Calgary, AB
40.	Ivani De S. Bott	Puc-Rio/DCMM	Rio de Janeiro, Brazil
41.	Rick Stelmachuk	Rosen Inpsection Technologies	Houston, TX
42.	Jim Yukes	Russell NDE Systems	Edmonton, AB
43.	Dave Toporowsky	Simmons Group Inc.	Calgary, AB
44.	Brian Dennis	Suncor Energy Marketing Inc.	Sherwood Park, AB
45.	Gabriel Nahas	TransCanada (Ventures Projects)	Calgary, AB
46.	Greg Toth	TransMountain Pipeline	Vancouver, BC
47.	J.P. McNeice	TransMountain Pipeline	Kamloops, BC
48.	Tom Weber	Trenton Corporation	Houston, TX
49.	Lance Bengert	Westcoast Energy	
50.	Gord Gairdner	Westcoast Energy	Fort Nelson, BC

Risk Management / Risk Analysis Tutorial

Presented by Ian Dowsett, RWDI West Inc.

Increasing pipeline infrastructure coupled with a growing and knowledgeable public located near pipelines is resulting in increased public concern about pipelines. These concerns include public safety, health, the environment, quality-of-life and the distribution of the risks and benefits from pipeline activities.

The Risk Management / Risk Analysis tutorial addressed many of the factors underlying "Public Safety' decisions (both technical and non-technical). The tutorial presented:

- An overview of the views, roles and responsibilities of industry and the regulators.
- The views and influences that the public has in effecting energy development decisions.
- An example (through the use of a video) of public involvement and influence on a recent energy development decision.
- A summary of the technical tools used to estimate hazards and risks.

The tutorial provided an interactive setting. Attendees indicated that:

- The public's view of hazards and risks is very different than the view held by industry.
- Standardization of the methods used for calculating hazard and risks would provide more consistent estimates of hazards and risks and would minimize uncertainty resulting from differences in the opinions expressed by experts.
- There is a need to differentiate between "the hazard" (i.e., worst case scenario) and "the risk" (i.e., the probability of being affected), and to differentiate between the decisions and their priority (i.e., public safety, health, and environment).
- There is a need for risk acceptability criteria.
- There is a need to improve the communication of all of these issues to the public and industry

Attendees at Risk Assessment/Risk Management Tutorial - April 9, 2001

1.	George Prociw	Enbridge Consumers Gas	Scarborough, ON
2.	Lawrence Ator	National Energy Board	Calgary
3.	Nathan Len	National Energy Board	Calgary
4.	Nancy Dubois	National Energy Board	Calgary
5.	Rick Gulstad	Alliance Pipeline	Eden Prairie, MB
6.	Allan Bouwers	NeoCorr Engineering Ltd.	Calgary
7.	Bob Longpre	BP Canada Energy Company	Calgary
8.	Daryl Baxandali	CorrOcean Canada Inc.	Calgary
9.	David Coleman	Centra Gas Manitoba	Winnipeg, MB
10.	Leonard Lozowy	AltaGas Utilities	
11.	Aldo Diflumeri	Canadian Natural Resources Ltd.	Leduc, AB
12.	Bob Shapka	Talisman Energy	Calgary
13.	Andy Isherwood	BGC Engineering	Calgary
14.	Denene Geissler	Hunter McDonnell Pipeline Services	
15.	Siu-Yung Tsai	TransCanada Pipelines Ltd.	Edmonton
16.	Lorance Pasiechnyk		Redcliff, AB
17.	Lyle Gerlitz	Simmons Group Inc. – Pipelines	Calgary
18.	Steve Lambert	FLG Engineering Ltd. University of Waterloo	Calgary
19.	Duane Cronin		Waterloo, ON
		University of Waterloo	Waterloo, ON
20. 21.	Roy Pick Norm Trusler	University of Waterloo	Waterloo, ON
		BC Gas Utility	Surrey, BC
22.	Bruce Fowlie	Nu-Trac Management Consulting Ltd.	Calgary
23.	Paola Bonandrini	SNAM s.p.A.	Italy .
24.	Bruno Romero	Maya Database & Internet Applications Inc.	Calgary
25.	Bob Wiens	Oesa Associates	
26.	Ken Poloway	Mobiltex Data Ltd.	Calgary
27.	Rob Slevin	Mobiltex Data Ltd.	Calgary
28.	Daphne Snelgrove	Transportation Safety Board	Hull, PQ
29.	David Don	HCI Canada	Calgary
30.	Larry Dyke	Natural Resources Canada	Ottawa
31.	Cindy Smallman		
32.	Lin Zharo	ABS	
33.	Ramesh Singh	RAI Inspection Service	Edmonton
34.	Noel Billette	Natural Resources Canada	Ottawa, ON
35.	Wenyue Zheng	Natural Resources Canada	Ottawa, ON
36.	Jenny Jackman	CANMET	Ottawa, ON
37.	Dan Powell	Corrpro Canada Inc.	Calgary
38.	Reg Eadie	NRTC - University of Alberta	Edmonton
39.	John Skalski	Enbridge Pipelines Inc.	Edmonton
40.	Rick Doblanko	Enbridge Pipelines Inc.	Edmonton
41.	Jim Oswell	AMEC Earth & Environmental Ltd.	Calgary
42.	Ian Smith	Sun Canadian Pipeline	Waterdown, ON
43.	Brad Smith	Enbridge Pipelines Inc.	Edmonton
44.	Walter Kresic	Enbridge Pipelines Inc.	Edmonton
45.	Darron Mazurek	Tri Ocean Engineering Ltd.	Calgary
46.	Maury Dumba	Positive Projects International Ltd.	Calgary
4 7.	Jules Chorney	TransGas Ltd.	Saskatoon, SK
48.	Jill Hopkins	Conoco	Rock Spring, WY
49.	Catherine Pineau	TransCanada Pipelines Ltd.	Calgary
50.	Graeme King	Greenpipe Industries	Calgary
51.	Monica Santander	National Energy Board	Calgary

R-STRENG User Course

Pat Veith, CC Technologies

Pat Vieth, CC Technologies, described the historical development of the B31G and RSTRENG methods used to evaluate the pressure-carrying capability of corroded pipe and to ensure that an adequate safety margin is maintained. B31G was originally appendix G of the ANSI B31 code. RSTRENG stands for Remaining Strength. Both methods are referenced in the US Federal Regulations Part 192.485 as acceptable method to determine the remaining strength of corroded pipe, and the B31G method is embedded in CSA Z662. There are two versions of RSTRENG. The following table summarizes the key aspects of the methods.

Method	Flow Stress	Folias Factor	
B31G	1.1 SMYS		Area
RSTRENG 85% Area	***************************************	2 term for $L^2/DT = <20$	2/3 total length x depth
	SMYS + 10,000 ksi	3 term, no length limit	0.85 x total length x
	SMYS + 68.9 Mpa	8	depth
RSTRENG Effective	66	~	
Area	***************************************		Iterative calculation to
			determine lowest failure
The RSTDENIC Effort		ibes the profile of the me	

^{*}The RSTRENG Effective Area method describes the profile of the metal loss area and uses an iterative calculation to determine the lowest failure pressure for all combinations of effective length and the associated metal loss area.

The RSTRENG methods were validated by comparing actual burst pressures from 90 experimental burst tests, hydrostatic test failures and service failures of corroded pipe and burst tests of machined slots.

The RSTRENG software was developed in 1991 and is recognized to have some limitations that make it "user hostile" and can make the output results confusing. It requires input data for the diameter, actual wall thickness, pipe grade and MOP, and the metal loss geometry. For the RSTRENG effective area method data is entered to describe the profile of the corroded area. For the 85% Area method, a profile must be entered that represents a maximum depth and total length.

When the calculated failure stress is greater than SMYS, no repair is required. If the failure stress is less than SMYS additional analysis is required to determine a safe operating pressure that will provide the intended safety factor.

The output identifies a safe maximum operating pressure that is based on a safety factor corresponding to the pressure at SMYS divided by the value entered for MOP/MAOP. The calculated factor of safety is the predicted burst pressure divided by the MOP.

Kiefner and Associates have an Excel spreadsheet called KAPA, (Kiefner & Associates Inc. Pipe Assessement) available at no charge from www.kiefner.com, that includes user instructions and performs essentially the same analysis as the RSTRENG software, as well as calculations for crack-like flaws whose failure depends on material toughness.

Attendees at R-Streng User Course Tutorial - April 9, 2001

-			
1.	Bert Johnson	4J Ventures Ltd.	Calgary, AB
2.	Chris Horkoff	AEC Oil & Gas	Medicine Hat, AB
3.	Lorne Carlson	Alliance Pipeline Limited	Calgary, AB
4.	Artur Janz	ATCO Pipelines	Edmonton, AB
5.	Dave Hektner	BJ Pipeline Inspection Services	Calgary, AB
6.	Peter Chan	BJ Pipeline Inspection Services	Calgary, AB
7.	Mimoun Elboujdaini	CANMET Materials Technology Lab	Ottawa, ON
8.	David Jolivette	Canspec Group Inc.	Edmonton, AB
9.	Brian Paradis	Canspec Group Inc.	Edmonton, AB
10.	Stanley Wong	CC Technologies Canada Ltd.	Calgary, AB
11.	Don Wallace	Centra Gas BC Inc.	Nanaimo, BC
12.	Howard Wallace	Colt Engineering	Calgary, AB
13.	Bruce Moore	Conoco Canada Limited (PTC Pipeline)	Regina, SK
14.	Bob Coote	Coote Engineering	Calgary, AB
15.	Tanis Elm	Enbridge (U.S.) Inc.	Duluth, MN
16.	Scott Ironside	Enbridge Pipelines Inc.	Edmonton, AB
17.	Deb Billey	Enbridge Pipelines Inc contractor	Edmonton, AB
18.	Harvey Haines	Gas Technology Institute	Des Plaines, IL
19.	Chris Hartnell	Hunter McDonnell Pipeline Services	Billings, MT
20.	Shamus McDonnell	Hunter McDonnell Pipeline Services	Edmonton, AB
21.	Scott Arndt	Husky Oil	Lloydminster, SK
22.	Darryl Shyian	Imperial Oil Resources	Bonnyville, AB
23.	Delton Gray	Keyspan Energy Canada Inc.	Edmonton, AB
24.	Mark Johnson	Marr Associates	Calgary, AB
25.	Framci Jeglic	National Energy Board	Calgary, AB
26.	Doug Waslen	National Energy Board	Calgary, AB
27.	Minh Ho	National Energy Board	Calgary, AB
28.	Myles Artym	NeoCorr Engineering Ltd.	Calgary, AB
29.	Greg Van Boven	NOVA Research & Technology Corp.	Calgary, AB
30.	Neb Uzelac	PII (Canada) Ltd.	Concord, ON
31.	Christine Rubadeau	PII North America, Inc.	Houston, AB
32.	Bruce Hagerman	PII North America, Inc.	Houston, AB
33.	Gerry Wilkinson	Positive Projects International Ltd.	Calgary, AB
34.	Bryce Brown	Rosen Pipeline Inspection	Houston, AB
35.	Kyle Loewen	Trans Mountain Pipeline Company Ltd.	Sherwood Park, AB
36.	Mike Reed	Trans Mountain Pipeline Company Ltd.	Vancouver, BC
37.	Shawn McGregor	Trans Mountain Pipeline Company Ltd.	Kamloops, BC
38.	Mark Ottem	Trans Mountain Pipeline Company Ltd.	Burnaby, BC
39.	Blaine Ashworth	TransCanada Pipelines Ltd.	Calgary, AB
40.	Curtis Parker	TransGas	Regina, SK
41.	John Parsons	Tuboscope Pipeline Services	Houston, AB
42.	Theresa Bell	U.S. Minerals Management Service	Camarillo, CA
43.	Brian Ogden	Westcoast Energy Inc.	Hope, BC
44.	Errol Batchelor	Westcoast Energy Inc.	Prince George, BC
45.	Jennifer Wong	Westcoast Energy Inc.	Vancouver, BC

The Application of GIS Technologies to Integrity Management

Bruce Dupuis, Baseline Technologies Inc., Calgary

Food for Thought and Lessons Learned

GIS (Geographic Information System) should be thought of as functionality rather than necessarily an application. In essence GIS represents a map-based interface to a database. There are various levels of implementation of this functionality, these include:

- Image/document management
- Visualization tool to identify the spatial relationship of data and to locate data in space
- Spatial Analysis

What is particular to the application of GIS to pipelines is the consideration of chainage or the distance measure along the contour of the pipeline (how much pipe is in the ground from point A to point B). It is important to note that the GIS functionality is but one element of an effective data management solution for pipeline integrity. Unfortunately, a broad scope of other functionality has historically fallen under the umbrella of a GIS project. Aside from the general confusion this leads too, it also facilitates scope and cost creep as well as misplaced expectation. GIS functionality is not the silver bullet, but it is an effective and important piece of the puzzle.

One key functionality of a GIS is the capability to handle and derive GPS coordinates in an efficient and robust manner. However, this can lead to a misuse and over dependence of GPS data. Always be cognisant of the error band associated with GPS measurements and consider how it will impact any derived distance and positions.

The GIS functionality associated with an integrity data management solution can be implement a number of different means within a single organization depending on the use and deployment situations. The bulk of your integrity management needs may be fulfilled by a broader application of which GIS functionality is but one element, but this does not preclude the use of a separate GIS application to perform higher-level spatial analysis and modeling. In the same way you may utilize a separate risk management application. This "best of breed" approach assumes the underlying data structures are open and accessible.

Pipeline Database Models

Introduction of standard database models has only recently occurred within the pipeline industry. The Gas Research Institute developed the first pipeline model (ISAT - Integrated Spatial Analysis Techniques - circa 1994) for the purposes of introducing some commonality among transmission companies' Geographic Information Systems (GIS). The ISAT model has since been updated into PODS (Pipeline Open Data Standard - circa 1999) to better utilize a relational

Even though these database standards exist very few companies have been able to implement them in unadulterated manner because of their rigidity, non-conformance with existing in-house database structures, or for embedding spatial relationships in the database.

Benefits and detriments of existing pipeline database models will be addressed followed by a demonstration of a spatial implementation of the PODS database.

Overlay Errors in GIS

GIS is a powerful tool for analysis but most users are unaware of the errors that can easily propagate though various analyses. These errors occur, primarily, because GIS has made it too easy to combine data captured at varying scales and resolutions into one product. But is this the fault of the technology or an awareness issue with the user?

Presentation will cover a brief discussion on map scale, resolution, and data quality measures. Examples of map accounting for overlay errors will be shown along with a demonstration of how data quality can affect analysis output.

The Need for Metadata

Metadata is often defined as data about data. While this is a good high-level definition it glosses over some of the finer details and business reasons for its use. Metadata is better defined as the information or documentation that describes content, quality, condition, and other characteristics of data. With this definition in mind it, metadata is a tool that enables a company to better utilize data. Metadata enables companies to:

- Search and find data sources
- Document data for posterity
- Share data with other organizations.

Several standards exist for collecting Metadata but the one standard that has come to the forefront is the Federal Geographic Data Committee (FGDC). This is quickly becoming the North American metadata standard for government agencies and data clearinghouses.

Field Data Collection During Construction

Tracking of pipe materials during construction has become a best practice for many transmission companies. Recording and understanding metallurgy during construction can ease the task pipeline integrity during operations. There have been many efforts made to track pipe materials during construction all with varying levels of success and shortcomings.

Discussion will center on three common data collection methods used:

- Paper based,
- Barcodes and handheld computers,
- Barcodes, handheld computers, and GPS,

Issues and advantages of each method will be discussed and a demonstration of data use will be given.

Banff/2001 Pipeline Workshop Managing Pipeline Integrity: Application of GIS Technologies to Integrity Management April 9, 2001 1:30-4:30 p.m.

	pehene bjæ pehene bjæ woznie @ att Hagermadbe gregte try gregte try brad.smitheenpl jashue.th.g.ma	(403) 531-1520 (403) 931-2974 (713) 849-6333 (50) 571-4030 (604) 739-5324 (604) 691-5923	ter chan Hagerman Them. Sourch Sourch Wong	* 50
	art.janze	(780)420-7536 art. janz @ atcopipe lines. com	Janz	
Li.org Fernigh-Way v	Jywong Owe	180)420-7536	7	ATCO PIPELINES A
	ilwong @we	604) 691-5933		The state of the s
Junar-assaciates com Affle	Jashue H	103) 258-22 53	i	
capt carbidge con	brad.smithe	780) 420.8607		
The are	7		WATER TO THE REAL PROPERTY OF THE PARTY OF T	
trust, en Nost	greate	4252 - PET (408)	Wey Toff	
·····	marko	115/05/		
- Mary		650) 271-11020	The state of the s	
AND @ PII-USA, UM Sylling	Hageran	(113) 849-6332	OKINE HAGERINAN	INC. L
managina Mis	, , , , , , , , , , , , , , , , , , , ,		DIN a HAMBOMON	I NORTH MAINICH &
2) attenias	woznie (462) 931-2974	NDREW MOZNIEWSK	***************************************
by services, ed		02 (7-1((6.)		1
		(401) C2 2 C3	ŧ	ST Page 1
_ 		19, 9, 7,		
rengions nather		(403) 71121-2		-
	To the second se	(403) 711, -31,3	West S. Hay	And the second s
A STATE OF THE PROPERTY OF THE	ms ps	(463) 711-31-31-31-31-31-31-31-31-31-31-31-31-3		
	E-mail	(403) 758-86.75 (403) 711 31.3.		KINS S

Banff/2001 Pipeline Workshop Managing Pipeline Integrity: Application of GIS Technologies to Integrity Management April 9, 2001 1:30-4:30 p.m.

ىد.	ز	1		0	0	3		K	T		1
Dhun	Ballu.	or A	THE STATE OF THE S	07770	Money	BATTA		Not the	hot he	W	Jac Slanks
 Dwallace & Centralic, well, org	baden@wei.org	(403)250-4702 ikedack@novachem.com	VANBOVEZ @NOVACHEM.COM	Chrish & him psi. com	shamus@hmpsi.com	gregh @ corridor pipeline.com		403-260-8776 markwebster @grempipe.com Joh Me	Scott. Arnute husky-oil.com	Simmons Que de als sus ans	Bane, Binhart @ (OITPIC)
6158-156 (552)	phss-188 (non)	463)250-4762	1090-052 403 250-0601	3158-804 406-6 78	180-948-8884	(780) 416-2284		403-260-8776	780-871-6553	8053/45 204	403 335-6400
Dun WALLALB		by Keda-Cameron	Gizz Mr Bren	Chris Hawthrell	5 hamus M=Donnell	CRK ACT		Mark hibbster	Scott Arnut	DON HERMAN	Zone Rinhart
CENTRA UMI BC INC	WESTCOOST ENERSY	15 Nova Research & Fechalogy Katherine	//	Hunter McDonnell Pipeline Services Corp	-	CAR POR PIPELINE	Prince of the reservence	Greenpipe Industries Ltd., Mark Webster	Husky Oil	SIMMONS GRUUP	CORRPRO GAMADA INC.
2	4	5,	g/16	1 7	18	61	20	21	22	23	24

Banff/2001 Pipeline Workshop Managing Pipeline Integrity: Application of GIS Technologies to Integrity Management April 9, 2001 1:30-4:30 n m

AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE	April 9, 2001 1:30-4:30 p.m.				
25	Green P. fo Freductions	SEARCH THARDY	2608187	Sharan hardye or foon 830.	
26	TUBBSCOPE	TODD PORTER	713 799-8160	toorter@ tuboscope. com	
27	TUBOSORE	JOHN FARSONS	713 799-5180	713 799-5180 Jarsons@ Euboscope.com	CE S
28	Tubescope	Dewe Bosner	780-955-8611		
29	Imperial Oil	Korau Harrun	760-655-6177	7 BO-955-6177 lorna-haccon @8550. com	
30	Cake Engineering Llo	. Bob Coote	403 247 1480	Caste & a home 10 4	111
31	Notional Energy Everd	Nama Jeghi	htt255280h	Neghi anebycica	100 m
32	CoLT	DARIYS BOUCHEN	259-1818	boucheth.darius olouton in 2000	Donath
33					
34					
35					
36					
The state of the s			And the state of t		

Pipeline Safety: Technology and Communication Jim Dilay, Board Member Alberta Energy and Utilities Board

Thank you for inviting me to the 2001 Banff Pipeline Workshop. CANMET and especially Winston should be congratulated on putting together what I believe will be another very successful workshop. This is the sixth workshop to be held since the first in 1993 and this venue has become known as an important and unique opportunity for pipeline issues to be discussed and resolved. This workshop is a clear example of the pipeline industry, pipeline engineering firms and pipeline regulators cooperatively working together to identify and resolve issues of the day.

To briefly acquaint those of you who may be attending from other countries, Canada's pipeline industry is regulated by a number of distinct agencies. Canada's National Energy Board is responsible for the regulation of interprovincial and international pipelines, and each province has its own regulatory body that is responsible for the regulation of intra-province pipelines. In Alberta, the Energy and Utilities Board (EUB) regulates the almost 300,000 km (186,000 mi) of pipelines wholly within Alberta. These pipelines include everything from the biggest natural gas transmission pipelines to the smallest production gathering pipelines, and everything in between. EUB-regulated pipelines transport a wide variety of products, not only natural gas and oil, but also ethane, propane, butane, pentanes plus, refined products, hydrogen, sulfur, produced water and ammonia - plus all the varieties of product mixtures that come out of the approximately 100,000 producing wells we have here in the province. Our pipelines are located everywhere: in the generally unpopulated areas of Northwest Alberta; the grass lands of Southern Alberta; agricultural heartland; forestry preserves; rural, suburban, and even urban areas. This variety and quantity of pipelines gives the EUB a unique perspective on the issues facing the pipeline industry. The issues themselves are not unique, they are similar to those in British Columbia, Saskatchewan, and other parts of Canada, but in Canada the density of pipeline development is currently the highest in Alberta. This is of course to be expected as Alberta currently produces the majority of Canada's oil and gas.

In a few moments, I will briefly discuss two key issues, and challenge you to consider them in your workshop sessions, to come up with new and creative ways to resolve those issues in ways that would not only ensure public safety, and environmental protection, but which will also be sound from economic and orderly development perspectives. By way of introduction though, let's first consider some good news and.....some bad news.

The good news is that pipelines continue to be the safest way to transport the large volumes of product the long distances necessary to get them to market. Let's have a brief look at the importance and significance of pipelines in terms of products that are moved. In a year, more than 170 billion cubic metres (6 trillion cubic feet) of natural gas are produced from Canadian

wells. This is enough gas to provide heating for over 30 million homes. Each year, more than 150 million cubic metres of hydrocarbon liquids (945 million barrels) are produced. Every day, Canadian pipelines deliver hydrocarbon liquids equal to more than 10,000 double tanker truckloads. Without pipelines, how would you effectively and safely deliver those products, and at what cost to the environment and the public?

In Alberta, it is a regulatory requirement that all pipeline failures, no matter how small, are reported to the EUB. Failure is defined as any release of product, whether from a pinhole leak or anything up to a total rupture, regardless of location, volume, or product type. The requirement to report every failure, along with the abundance of pipelines regulated by the EUB and the variety of products transported - many of which are highly corrosive - results in over 800 pipeline failures being reported to the EUB annually.

In general terms, we have found:

- Over 90% of failures are on small diameter, small volume gathering system pipelines, 168.3-mm (6-inch) diameter and smaller.
- About 87% of the failures are leaks, resulting in small losses of product.
- About 74% of the failures are due to internal and external corrosion.

In its fiscal year 1999/2000, the EUB conducted Operations Inspections of 69 companies and inspected 376 different pipeline systems to check their ongoing operations and maintenance programs. The EUB currently has more than 900 pipeline operators on record. Selection of inspection candidates is done taking into account the operator history, site sensitivity, and inherent risk of the operation. The EUB classifies unsatisfactory results into one of three categories:

- Minor, which are small deficiencies;
- Major, which are deficiencies that are having adverse impact or have potential to cause adverse impact;
- and Serious, which are incidents where total disregard for regulations and requirements has occurred and from which adverse impact is occurring or has the potential to occur.

None of the Operations Inspections resulted in a "serious unsatisfactory" rating. The overwhelming majority of recorded unsatisfactory items were minor in nature.

You will note that, despite the relatively high number of reported failures, we believe that the consequences of pipeline failures have been usually remediated quickly. The EUB is currently working with the Canadian Association of Petroleum Producers to develop a method to better record and assess the consequences of pipeline failures. From the failure and operations inspection information, there seems to be a positive record of performance. But could this record be interpreted differently? What about public response to pipeline development? This is what could be considered to be the Bad News - a perception by the public that pipelines are becoming

unsafe - and this is one of the things that we are here to make improvements upon. So why is the public becoming more concerned about pipelines?

First, oil and gas development and related development of facilities is significantly increasing in Alberta and elsewhere. For example, in 1992, the EUB issued a little over 4300 drilling licenses. In 1997, it issued 13 000 drilling licenses and in the fiscal year just completed, we issued over 18 000 well licenses! The amount of pipeline activity resulting from increasing levels of drilling increases proportionally.

Second, with increased resource development in Alberta and in Canada, it is inevitable that more petroleum development is occurring near human habitation. At the same time, the human population of the province is growing. Census figures tell us that the population of Alberta has increased by one million people in the last 12 years. Pipelines are encroaching on an increasing number of people, and indeed people are encroaching on pipelines. This encroachment brings an increased real and perceived risk to people. As well, consider for a moment that about one third (46 billion cubic metres per year) of Alberta's gas production is from sour sources, meaning gas with a H₂S content of greater than 1%. This is likely to increase in the future.

Third, the public is demanding greater safety measures, less risk, and has become increasingly intolerant of environmental and safety incidents. The ability to quickly and easily access information from all over the world has enlightened people as to some of the more serious pipeline incidents such as those that occurred in Washington state and New Mexico, which included fatalities of members of the public. Some dramatic failures have also occurred in Alberta and elsewhere in Canada in recent times.

So, the net result is that the public is starting to feel uncomfortable about pipelines. They demand better pipeline performance; especially since oil and gas development is interfering with other uses of their land. Pipelines bring with them setback requirements and land development restrictions, both of which provide no compensation.

They look at the same statistics from the pipeline failures that we have previously discussed, but come to very different conclusions! Some are shocked that there are almost three pipeline failures per day in Alberta! Some suggest that as the pipelines are getting older, they must be also becoming unsafe!

As more people are living close to pipelines, some of them are choosing to participate actively in the consultation processes to ensure that their concerns are heard. Some feel they need to actively participate, as they don't trust the industry and regulators to resolve the issues. These concerns can result in a significant impact to the way that resource development is conducted in this province. Opposition, whether warranted or not, can result in significant and costly delays to development while these concerns are addressed. In some cases, where the impacts are judged to be unacceptable, denial of those applications may result.

So this leads us to the two key issues I mentioned a few moments ago, and that I hope can be discussed in later sessions to see what recommendations might be found. These are:

- 1. How do we Ensure the Safety of Pipelines?
- 2. How do we Make Pipelines Acceptable to the Community?

The sessions in the workshop intend to discuss both of these issues, not only from the technical aspects of design, operation and maintenance, but also the public perception aspect. Both are very important.

1. How do we ensure the safety of pipelines?

Ensuring pipeline safety involves many technical considerations. All of us here deal with these in some manner. The considerations necessary to get a pipeline approved, built and operating are commonly understood; issues like design, construction, operation and maintenance. For new pipelines this should be relatively straight forward, however, how extensively have you considered the long-term issues? Did you consider the corrosion mitigation and monitoring aspects during the design of the pipeline? What could you do differently during the design and construction stage to make the operation of the pipeline easier? How will you ensure that the proper techniques are used for pipeline construction? Do you have a documented operations and maintenance program BEFORE the start of operation to ensure that pipeline is operated safely and does not experience failures? Do you have a program in place to monitor pipeline integrity that will ensure that you know the condition of the pipeline and can deal with operational conditions BEFORE they could lead to a failure? Will you have proper documentation in place for materials, design, construction and operation of the pipeline? EUB Operations Inspections have shown that the majority of minor unsatisfactory items are related to record keeping.

With increasing drilling activity, consolidation of fields and the concern about well flaring, there is more demand to use existing pipelines. This may result in changes to the existing pipelines, such as using pipelines that have been discontinued from service or even abandoned, to re-certifying pipelines to higher operating pressures, or to carry different products. All of these modifications have unique safety considerations that must be thoroughly assessed before a decision is made to proceed. Would it be possible to develop specific standard requirements to ensure that the changes are done safely?

With oil and gas activity being closer to where people live, there is increased potential for third party damage to pipelines. What precautions or processes could be implemented to protect the pipelines from damage?

This is just a small sample of the questions that the public has about the safety of pipelines. The workshop sessions will hopefully touch on many of these technical questions and I challenge you to look for solutions that would increase your confidence, and public confidence, in the safety of the pipelines.

2. How do we Make Pipelines Acceptable to the Community?

This is a difficult challenge! It is not enough to do an excellent job in ensuring pipeline safety, the public must understand and believe that pipelines are safe. How do you determine if a pipeline is safe? What data do you use to determine the level of safety? If you use risk analysis, what is an acceptable level of safety? Why can it change from area to area? Why is it important that the public understand?

There are some obstacles that make clear communication of pipeline safety difficult. One is that there are many different data sources on pipeline safety, but each collects and presents the information in a different way. This makes comparison of the results difficult if not impossible and raises questions about the validity of the results.

Environmental and safety consequences of failures are not clearly documented. It is difficult to consistently assess the consequences in such a way that the public would accept the results.

Another problem is that any progress made in communicating about the safety of pipelines gets a major setback from each incident that is reported in the media and is perceived as having the potential to occur near people. How do you ensure that such incidents don't occur near people or environmentally sensitive areas and how do you share the knowledge with the public? How do you influence how incidents might be reported in the media?

These questions must be considered along with the questions about ensuring pipeline safety. The process will not be a complete success unless both aspects are addressed.

In conclusion ...

The EUB has a number of initiatives in place to address pipeline safety and provide information that can hopefully alter the perception the public has about pipeline safety:


- The EUB is developing a pipeline inspection manual and corrosion guide to ensure that inspections are conducted consistently, that compliance with requirements is correctly assessed, and that pipeline corrosion is managed.
- The EUB is expanding the field surveillance program to re-establish public confidence in the inspection program. The EUB hired new qualified inspection staff and has a program to increase inspection staff by 30 people over the next 4 years.
- The EUB has received valuable comments regarding the way it has collected and reported
 its annual pipeline statistics, and will endeavor in future to improve the ways it presents
 these statistics to achieve greater clarity.


- By April 2002, the EUB will review High Vapour Pressure pipeline safety and integrity requirements with external stakeholders, and identify and incorporate any necessary measures needed to assure public safety.
- The EUB is conducting Open Houses in communities around Alberta to directly interact
 with the public and to provide opportunity for sharing of information on issues specific to
 the area, including pipelines. If requested by the community, the EUB participates in
 public meetings to discuss and address issues about proposed and existing pipelines.
- Late last year, the EUB received the final report and recommendations of the Provincial Advisory Committee on Public Safety and Sour Gas. Some of the recommendations pertain to pipelines. A number of actions have already been taken by the EUB to address some of the recommendations. A documented plan identifying actions for each of the 87 recommendations will be made public this month.


The pipeline operators, designers and regulators must work toward a common understanding of the pipeline safety issues and then work together to resolve the issues and to make sure that the public has confidence in pipelines. Pipelines must be safe AND they must be understood by the public to be safe!


This cooperation between the pipeline operators, engineering staff, and regulators to come up with solutions to important issues is what makes this workshop unique. I challenge you to apply your creativity to devise new and productive ways to resolve the pipeline safety issues facing us today, and ensure a cooperative, productive working relationship between industry and the citizens of Alberta, as well as Canada, for future resource development.


Thank you very much for your attention and I wish you a very successful and productive workshop.
















Increasing Resource Development

- In 1992, the EUB issued 4300+ drilling licenses
- In 1997, the EUB issued 13,000 drilling licenses
- In fiscal year 2000-2001, the EUB issued over 18,000 drilling licenses
- With more drilling, we will have more pipelines!

April 9-12, 200

Band 2001 Pleating Wartship

44.7



Increasing Population

- In the last 12 years, the population of Alberta has increased by One Million people
- People are moving to rural residential areas
- Pipelines are encroaching on people
- People are encroaching on pipelines

April 8-12, 2001

Banif 3001 Pleatine Werkshop

Stine 2



Why are People Concerned?

- Rapid access to information better informed
- High profile catastrophic failures in other parts of North America
- Land Development Restrictions
- · Setback Requirements
- No Ongoing Compensation
- · Aging of the Infrastructure

April 9-12, 2001

Rentf 2001 Pipaline Workship

Side 0



What are the Two Key Issues?

- How do we Ensure the Safety of Pipelines?
- How do we Make Pipelines Acceptable to the Community?

April 9-12, 2001

lanff 2001 Physics Workshop

Sticle 16



How Do We Ensure the Safety of Pipelines?

- Proper design, with due consideration to long-term use
- · Proper construction
- Proper operation, maintenance, and monitoring
- · Proper evaluation of operational changes
- · Control of Third-Party Damage

April 5-12, 200

Sard 2001 Pipelina Warkshop

\$8**40** 71



How Do We Make Pipelines Acceptable To The Community?

- Must satisfy people that pipelines are safe
- · Ensure statistical data collected is compatible
- Document environmental and safety consequences of failures
- Ensure that media reports in an objective manner

April 6-12, 2001

Bardf 2001 Pipeline Wartshop

\$36e 12



EUB Initiatives to Address Pipeline Safety, and Public Understanding

- Pipeline Inspection Manual and Corrosion follow-up guide
- Expansion of the Field Surveillance Program
- Revision of the way statistics are collected and presented
- Review of HVP pipeline safety for 2002
- Open house meetings to address public concerns
- Adoption of recommendations of the Provincial Advisory Committee on Public Safety and Sour Gas

April 8-12, 2001

Sent 2001 Pleating Washing

Shin 13



The Key Message:

 Pipelines must be safe AND they must be understood to be safe!

April 9-12, 2001

and 2001 Pipeline Workshop

.

	Woogsto (Assisted American
	NASS William N. Command display.
	1908ahoojileeejii Aalaadqoqeejio
	to на сумента выправания вы
	Pri for this first of 33 dilates dessifyed a file
	mally vy qoʻshi Momilyoshi yuddi Ad
	steriliye ezzáládás (A pögyör, i Ádameny e
	vikosança ildə ekişti təsisiyi.

NEW TRENDS IN PIPELINE TECHNOLOGY

S. J. Wuori, President, Enbridge Pipelines Inc.
R. A. Hill, President, Canadian Energy Pipeline Association
M. A. Powell, Chief Executive, PII Group Limited
E. Glynn Jones, Bechtel Pipeline

Abstract. The technology applied to pipeline systems has evolved significantly over the past 30 years. During that time, societal attitudes and expectations toward energy development have also changed considerably.

Highly competitive market conditions and rising regulatory and public expectations, particularly in North America, have facilitated the rapid development of technological innovations for the pipeline industry. The resulting new technology is being applied to pipeline systems throughout the world, providing the answers to many complex issues associated with pipeline design, construction, operation and maintenance, and ultimately to public safety.

INTRODUCTION

The pipeline industry has experienced many changes over a short period of time, and change will be a constant well into the new millennium. One of the primary drivers of change is declining productivity in established sedimentary basins, such as the Western Canadian Sedimentary Basin. This has compelled the oil and gas industry to find innovative ways to reduce the incremental cost of production, and to look to frontier areas for new production. This in turn puts pressure on pipeline operators to lower transportation costs so shippers can remain competitive with other energy supply sources. At the same time, aging pipeline systems are incurring higher maintenance and operating costs to meet rigid safety and reliability standards. Compounding this trend, public expectations are rising to reduce the effects of pipeline construction and operation on the local community and environment.

While practices in pipeline design and operations continue to improve technologically, the public's expectation is often one of "zero tolerance" for errors that result in accidents or Despite great improvements environmental assessments, construction and restoration practices, and reductions of some 50 to 70% in pipeline spills over the last few decades, 1 an atmosphere of public opposition is increasingly apparent. This atmosphere of public resistance is becoming more common, manifested as opposition to new pipeline siting, pipe rehabilitation or expansion, route acquisition, and even opposition to the pipeline resuming operations after an accident.4

OPERATION and MAINTENANCE

1.1. Risk Management

Faced with rising expectations from the public and regulators combined with pressure to reduce costs from shippers, it's apparent that the international pipeline community must make safety performance a top priority while ensuring that spending on safety is directed to where it will have the greatest effect. Risk management programs are designed to fulfill this need.

Risk management, which includes risk analysis, helps decision-makers identify and prioritize effective risk reduction measures. It requires detailed reviews of operations and maintenance, and an estimation of the probability and consequences of various failures. Several new software tools are available that integrate data from many sources to provide the framework for a risk model. Furnished with adequate data and continually updated, the computer software can generate an analytical overview to help pinpoint sources of risk that may go unrecognized in management systems that are based only on regulatory compliance.

Pipeline operators in the United Kingdom and France have used risk analysis for several years to assess the need for pipeline diversions, proximity infringements and uprating. In the United Kingdom, the new Pipelines Safety Regulations support the development of risk analysis programs. In the USA, the Accountable Pipeline Safety and Partnership Act law provides a framework for the Office of Pipeline Safety to establish demonstration projects using risk management programs. Under these projects, companies are given some relief from government regulations if

they can demonstrate that their risk management plans provide an equivalent level of safety. Australia, Western Europe and other countries are also moving in this direction.

Clearly, risk management may be the single best method for the pipeline industry to address public safety and environmental concerns while managing expectations of greater efficiencies and cost control.

1.2. SCADA Data Analysis

Most pipeline companies now use supervisory control and data acquisition (SCADA) systems to remotely operate and monitor their pipelines. A centralized SCADA system is an economical method to control not only the operation of a pipeline within a predetermined set of parameters, but also to capture data for further analysis.

Traditionally, SCADA data has been archived only to meet regulatory requirements for pipeline operational history in case of an incident. Increasingly, data from the SCADA system and other data from field locations constitute a wealth of information useful for analyzing all aspects of the pipeline operation.

By combining historical information with powerful data analysis software tools, engineers can scrutinize the operation of the pipeline in terms of power consumption, equipment performance, maintenance scheduling, pressure cycling and product quality. For example, data mining of archived SCADA data could be used to benchmark operator performance by how efficiently they operate a pipeline based on throughput versus energy. In doing so, patterns of "best" operation may be discerned that could be used to improve the performance of all operators or to find patterns that minimize energy use.

Electrical energy is typically the single largest cost of liquids pipeline operation. The combination of (a) the amount of electricity used, (b) the uncertainty of prices due to electrical deregulation and (c) the increasing pressure to reduce costs, presents a significant challenge to pipeline companies. The capability of a SCADA system to respond to the ever-increasing demands of energy management makes it one of the most powerful tools for managing energy costs.

Since data acquisition and analysis are key to managing power costs, an effective energy management strategy begins with accurate data collection. Comprehensive data analysis gives pipeline companies the confidence to evaluate all the potential rate structures, and to negotiate a customized power supply contract that better suits their operational and cost control needs. The result of proceeding without a complete understanding of the pipeline's power usage profile is to either incur a cost premium associated with a more conservative power contract, or to be exposed to an unreasonable amount of risk when a more aggressive contract is chosen.

Technical roadblocks to this type of operation no longer exist. Knowledge based expert systems and data mining software are now usable by a wider audience, rather than confined to highly trained application experts. Expert systems, or artificial intelligence, are developed by encoding expertise into "rules", which provide guidance or act as tools for the user. In the simplest applications, a user will query the expert system and be given procedures or suggestions as to how an expert might respond in the same circumstances. In more sophisticated applications, the expert system will examine the data, e.g., real-time SCADA data, and recommend a "best" course of action without a request from the user.

The operation of a pipeline is an ideal application for expert systems, and the SCADA data source is ideal for data mining. Today, pipeline companies are recognizing that there is value in looking at SCADA information using analytical techniques.

1.3. Leak Detection

Early recognition of a pipeline leak is critical to protect the public and the environment, and to preserve the company's credibility. Computational pipeline monitoring refers to methods used for detecting pipeline anomalies (which may be caused by a leak) through software algorithms that are fed SCADA data (flows, volumes, pressures, temperatures valve status). Because these systems depend on a large number of data points, and considering the complexity of pipeline hydraulics, it is often difficult for a pipeline controller to analyze the alarms and determine the cause with certainty. While simple rules or procedures can be imparted to the pipeline controller through training, the expertise of both the software developer and the pipeline controllers is sometimes necessary to determine the reason for an alarm. Recent advances allow an expert system to (a) look at the incoming data and the system outputs, (b) consider the encoded expertise of the application developer and the best pipeline controller, then (c) offer the controller immediate guidance.5

While the expert system could be programmed to act automatically, it will more likely remain a sophisticated tool to assist the pipeline controller. To improve the expert system, data mining and analysis of archived data should be ongoing, so that the system can become "smarter" over time. In this way, the thresholds of computational pipeline monitoring system alarms can be tightened, and the "advice" offered will become increasingly reliable.

1.4. Electronic Flow Measurement and Automated Operations

Not long ago, tank gauging or meters that recorded observed volume were used for custody transfer, and corrections for temperature/pressure were manually calculated. In the early 1980's, flow computers revolutionized this process. Flow computers use meter pulses and fluid property data (temperature, pressure and density) to calculate corrected volume, providing timely and accurate measurement while eliminating the possibility of human error within the correction calculations.

Since their introduction, flow computers have been linked to a number of systems that require custody transfer information. These include leak detection systems, inventory-tracking systems, batch tracking systems, and customers who require real-time information (accumulating volume, temperature, pressure, density, etc.).

In addition, flow computers now control peripheral equipment, including valves, samplers, etc., and receive non-measurement related signals such as gas detection alarms, man-on-site alarms, etc. These additions allow the flow computer to be used for all operational and SCADA requirements of a metering site.

The present trend within the pipeline industry is to maintain accurate flow measurement while streamlining the current processes for distributing this internally and externally. This is due to the ongoing goal of increasing operational efficiencies, and the customer's requirement for quicker/easier access to custody transfer information.

In the future, a common server will poll all flow computers along the pipeline. As injections and deliveries are terminated, batch information will be electronically transferred to the server and subsequently to a local database, which will store this custody transfer information. Various departments will be able to access the database, and ad-hoc reports will be available while eliminating the possibility of re-entry errors. Customers will have the option of viewing, approving and printing their tickets online. As well,

they may print the custody transfer information to a file, then easily transfer it into their database/spreadsheet, thereby eliminating errors from manually re-entering the data.

PG&E Gas Transmission has recently made similar advancements to their electronic flow measurement system. Many of their flow computers are now polled to a central location, which allows measurement information to be more readily assessable, and shortens measurement cycles from a monthly to a daily (and soon perhaps hourly) cycle.⁶

Improved communication technology, such as wide area networks, will move the pipeline industry closer to a totally automated system. Custody transfer information will be transferred electronically, accounting and commodity tracking systems will become further automated and precise and, possibly, measurement audits will be completed "online".

1.5. Inline Inspection Tools

As the global pipeline infrastructure ages, there is increasing focus on technologies that allow pipelines to be operated safely and efficiently. These technologies, especially in the area of inline inspection (commonly known as "smart pigging") are now used by the vast majority of pipeline operators throughout the world to ensure security of supply for the world's hydrocarbons, and to extend the design life of over two million miles of high pressure pipeline—an expensive and vital asset.

When initially constructed, many pipelines had an economic design life of 20 to 40 years. In many instances, replacing these pipelines at the end of their design life is impossible. New techniques have been developed to keep pipelines in prime condition well beyond their originally planned life cycle. For example, years of research and development work have resulted in highly sophisticated inspection tools that have improved the ability to accurately determine the condition of pipelines.

Determining the condition of pipelines means not only identifying potential failure mechanisms, but also detecting such mechanisms long before they pose a threat to the integrity of the line. At the same time the tools must be accurate enough to allow pipeline engineers to discriminate among defects that may not be significant, thereby allowing optimization of maintenance and rehabilitation activity.

Inline geometry and metal loss tools have progressed significantly since the first prototypes were run well over 25 years ago. Since then, inline inspection has developed and matured into one of the most important technologies for preserving pipeline assets worldwide. In the late 1990s, the pipeline industry witnessed and benefited from the addition of new inline inspection tools that can detect narrow axial external corrosion, cracks, stress corrosion cracking and other formerly indistinguishable pipeline defects.

With today's geometry inspection tools, the location and severity of pipeline dents, buckles, wrinkles and bending strain all can be measured to a very high degree of accuracy. In addition, the same tools now provide pipeline operators with three-dimensional geographic information via inertial navigation and sonar caliper measurements. Centerline axial data and internal cross-sectional details can be obtained in a single inspection run, allowing operators to determine the presence and dynamics of slope instability, subsidence, overburden, frost heave (common in the northern regions of Canada), free spanning, and changes in river crossings, over burden, temperature and pressure.

While magnetic flux leakage (MFL) is the oldest and most established technique for corrosion detection and measurement, in recent years ultrasonic technologies have emerged as a more accurate means of locating and quantifying defects. Commitment to R&D by the tool vendors has eliminated many of the earlier problems associated with ultrasonics, and the industry now has the benefit of inspection tools that provide extremely accurate direct measurement of not only defects, but also the thickness of the remaining wall. Ultrasound technology can also detect and differentiate among such other important features as laminations, inclusions, blisters, longitudinal channeling and narrow axial external corrosion.8 With the ability to accurately classify defects, the operator can focus on the more severe defects and develop the most appropriate repair program.

Ultrasonic technique has been particularly effective in refined products pipelines, and the fundamental nature of this technology presently limits its application to lines carrying liquids. Several vendors are working on the challenges of deploying ultrasonics in a high-pressure gas medium. These projects require significant scientific research, in many cases in association with universities and technical research institutions worldwide.

Despite the success of MFL and other technology in qualitative and quantitative detection of corrosion and metal loss, the need to detect cracks at an early stage is still a serious challenge for pipeline operators. In response, inline inspection tools have been developed specifically to detect cracks. These tools, used successfully in several commercial inspection runs, allow a complete pipeline inspection with the entire circumference of the pipe scanned in a single run, with detection sensitivity for cracks and crack-like defects of 30 mm in length and of 1 mm in depth.9 Due to industry collaboration and other developmental work, new tools are being developed and tested that could soon be used to inspect and detect varying crack-like defects. Included are the PII tool employing transverse field inspection (TFI) technology and the elastic wave (EW) inline crack detection vehicle. 10 As well, the French pipeline operating company, TRAPIL, has developed and tested a transverse MFL tool with the capability to detect stress corrosion cracks.

In combination with other existing and emerging technologies for inline inspection, and ongoing improvement and further development, these tools will allow pipeline operators to address many integrity issues affecting their pipelines in the years to come. In the near future, demand from pipeline operators will likely lead to the development of multifunctional inspection tools that have the capability to detect corrosion, stress corrosion cracking (SCC), dents, cracks, etc. during a single run, which will further reduce operating costs. Another likely development will be to miniaturize today's inline tools to provide operators of small-diameter pipelines (168.3 mm, 323.9 mm, etc.) with the same capability, i.e., crack detection, that exists for larger lines.

1.6. GIS (Geographic Information Systems)

The development of increasingly sensitive and reliable inline inspection tools is, however, only one of the advances in pipeline integrity technology. Inspection vendors and pipeline companies have invested a great deal of effort into the analysis of increasingly large amounts of data. This data must be handled in a way that is cost and time effective, and must produce results that are "user friendly" if it is to be of maximum value to the pipeline operator. For example, to effectively use the information generated by inline inspection tools as a basis for a risk management system,

appropriate software is needed that handles the full amount of data and integrates it with other relevant data gathered by the pipeline company. For many pipeline companies, a geographic information system (GIS) is the solution to this need.

GIS are specialty databases for storing, retrieving, manipulating, analyzing and displaying geographically referenced data, i.e., data identified according to their locations. The software combines common database operations such as query and statistical analysis with the unique visualization and geographic analysis benefits offered by maps. Mainline pipeline companies are joining distribution companies in turning to GIS to help map, monitor, and analyze data involving transmission facilities. 11 A GIS can contain all the information needed for right of way management and taxation, adjacent landowners information, survey data, emergency response plans, and situation reports for the pipe. The situation report can include centerline location and pipe condition, planning data for future inspections, e.g., inline inspection, cathodic protection, maintenance digs, and records of repairs and modifications. Records can include text, pictures, and any other digitized information. Data from inline inspections will automatically be read into the system, keeping it up-to-date. As well, alignment sheets can be generated quickly and accurately, reflecting current database information.

During the past decade, GIS technology has progressed from a system with potential to present day applications that provide a cost-effective operational and economic tool affecting virtually every aspect of the pipeline industry, from project planning through facility operations. ¹² GIS technology is particularly advantageous for larger and more complicated pipelines systems that need to manage proportionate amounts of data.

In the future, GIS technology will provide improvements in efficiency, reliability, safety and risk management. By integrating GIS, Global Positioning Satellites (GPS), LEOs (low earth orbiting satellite), digital mapping software and portable computing power, along with new ways to communicate information visually, GIS will open up new opportunities for the pipeline industry to streamline and lower operating costs.

1.7. Satellite Technology used to Monitor Corrosion

Satellite communications provide a valuable service to the oil industry, particularly in remote regions. For the pipeline industry, the need for communication alternatives has always been an issue, since field facilities often lie outside the range of wireline communication, and pipeline corridors can extend thousands of kilometers.¹³

Recently, satellite technology has been extended to monitor internal corrosion of oil pipelines. For example, Enbridge Pipelines Inc. is now combining LEOs (low earth orbiting satellite) technology with the use of hydrogen flux foils (beta foils) to monitor internal corrosion activity in the more remote locations of its pipeline system. The company has used beta foil technology since 1995 for detecting and monitoring internal corrosion. This technology measures external hydrogen flux generated by internal corrosion activity, which generates atomic hydrogen atoms. 14 The hydrogen atoms in turn migrate through the pipe steel wall to the outside where they recombine to form molecular hydrogen gas (H2). Depending on the level of internal corrosion, the hydrogen evolution detected by the hydrogen flux foil will indicate whether internal corrosion activity is high, low or nonexistent.

Field personnel routinely take readings in accessible areas, but some of the installation locations are in remote areas or not readily accessible. In such areas, beta foil readings are recorded by an above ground instrument, usually powered by solar panels. The data is transmitted to the LEO satellite and relayed back to global operation centers, where it is decoded, organized and transmitted back to the pipeline company, allowing personnel to monitor internal pipeline conditions regularly in remote areas without further expense. ¹⁵

The pipeline industry will not have to look too far into the future before LEO and GIS technologies provide real time corrosion monitoring of pipelines and real time surveillance of existing pipelines corridors.

2. DESIGN and CONSTRUCTION

2.1. High Strength Steels

Technological advances in steel-making have resulted in the availability of new materials for pipeline construction. This began over 25 years ago with the development of thermo-mechanical rolling practices that brought high strength steel to the pipeline industry. In the early 1970's, Grade X-70 steel was used for the first time in a gas pipeline. As satisfactory experiences with X-70 led to its acceptance, during the 1990's Grade X-80 steel started to become widely used in large diameter, high pressure gas pipelines. In Canada

for example, TransCanada PipeLines used X-80 pipe for over 300 km of large-diameter pipelines. 16

More recently, X-100 grades have been achieved through further refinement of the manufacturing processes and are under assessment for future projects. Trial lengths of Grade X-100 pipe have been produced and subjected to extensive testing by some major pipe producers and operators. Since 1995, Shell, British Petroleum and British Gas have been jointly researching the implications of using Grade X-100 grade material for design, construction and operation. Truther work is being done in the area of fracture propagation control, which is a concern of pipeline designers when high operating pressures are involved.

2.2. Automated Ultrasonic Testing

Weldability has historically been a concern when high strength steels are used in pipeline construction. Mechanized gas metal arc welding (GMAW) has become widely used in large diameter pipeline construction, usually in conjunction with automated ultrasonic testing (AUT) and an alternative defect assessment standard based on engineering critical acceptance. The recently constructed Alliance Pipeline saw the first use of these technologies in the USA on a major cross-country pipeline project. ¹⁸

One of the past objections to mechanized welding has been that a defect found in welds made by the GMAW process—sidewall lack of fusion—is often hard to find and to quantify using conventional radiographic inspection. Extensive nondestructive testing with radiography and automated ultrasonics, coupled with the destructive analysis of an array of defects typically generated with mechanized welding processes, has resulted in absolute confidence that AUT can detect all relevant defects produced during mechanized welding. ¹⁹

As well as a proven non-destructive examination (NDE) technology, AUT has made the transition to a viable process control method. Often welding defects do not occur randomly, but are a result of gradual malfunction or incorrect parameter settings of the welding system. With the resolving and accurate detection capabilities of AUT, many welding problems can be prevented before they cause weld repairs.

Increasing acceptance of automated welding technology may open the door to homopolar welding, a technology that allows a weld to be made in seconds, with the resultant joint as strong in tension and as tough as the parent metal. Industry participants in the Homopolar Pipeline Welding Research Program, managed by the University of Texas at Austin, have estimated that savings of 20–30% on total project cost may be possible, which could significantly change the economics of developing a particular field.²⁰

2.3. Composite Reinforced Line Pipe

Several manufacturers are developing an interesting high strength material called composite reinforced line pipe (CRLP). This technology uses high strength fibre to reinforce a liner made of conventional steel pipe.

In manufacturing CRLP, high strength fibreglass is drawn through a proprietary resin, which ensures long term protection of the glass fibres, before it is wound in tension over the external surface of a conventional steel pipe liner. The two components work together to carry the applied load of a high pressure pipeline. This technology is an extension of the ClockSpring3composite repair sleeve technology.

This new technology also has some disadvantages. For example, longitudinal stresses must be carried solely by the steel liner, which has a reduced thickness compared to all-steel pipe.

2.4. Design Changes

Concurrent with the development of high strength steels, pipelines are being designed to operate at higher pressures using cost- and energyefficient pump and compressor stations. A typical example of this trend is the Alliance Pipeline, a 2973 km \$3 billion natural gas pipeline extending from northeastern British Columbia to Chicago, Illinois. This 914 mm and 1067 mm, Grade X-70 pipeline was designed to take advantage of high operating pressure (12 000 kpa) and a rich gas stream, which combine to allow a reduction in the power required to compress gas along the pipeline. In the United Kingdom, pipeline operators are using new risk-based analytical methods to support increased operating pressures for transmission pipelines. This new approach was made possible by changes made in 1996 to the Pipeline Safety Regulations, which now are based on a modern. goal-setting regime that requires operators to demonstrate that risks arising from the operation of a pipeline have been reduced to a level "as low as reasonably practical."

This new regulatory environment has allowed pipeline companies such as British Gas to explore higher operating pressure levels using a "limit states design" approach. By its simplest definition, limit states design is a risk-based method that incorporates the failure probability for segments of the pipeline system. In some cases, British Gas has been able to safely uprate segments of their transmission system from 7590 kpa to 8625 kpa with no increase in risk. In 1999, a group of world-leading pipeline engineering companies led by BG Technology launched a joint industry project to develop guidelines for applying the techniques now being used by BG. This will provide an accepted framework that will allow other pipeline operators to achieve benefits including capacity increases, maintenance reductions, life extension and reduced construction costs.

2.5. Slurry Pipelines

Slurry pipelines have provided safe commercial transport for many commodities since the mid-1900's. Commodities that have been successfully transported in slurry form include coal, iron sands and iron concentrate, copper concentrate, phosphate concentrate, limestone, zinc concentrate, and most recently, oil sand at the Syncrude mine in northern Alberta. Eric Newell, Syncrude CEO, says hydrotransport could be the key technology for expansion of oilsands mining.²¹

There are major deposits of shale oil and oil sands worldwide, and slurry pipeline technology can be applied to these materials as energy prices increase. As well, large coal deposits worldwide can be served by slurry pipeline technology for transport to market. The technology is current, with the 439 km Black Mesa coal slurry pipeline, which originates in Arizona, being in use since the early 1970's. 22

High density polyethylene (HDPE) liners, which limit the potential for corrosion and wear in slurry pipelines, have recently been applied in the slurry pipeline industry. These liners are typically used in high-pressure slurry service, 24 150 kpa operating pressure being common.

Corrosion resistance requires a continuous HDPE lined system to be an effective barrier between the steel and the slurry. The liner is applied by pulling the HDPE liner through a diameter reduction unit into the line in continuous lengths up to one kilometer long. After insertion, the liner expands close to its original diameter, and "press fits" to the pipe wall.

Several other liner systems have been used worldwide including rubber lining for tailings applications, and polyurethane for highly abrasive slurries.

CONCLUSION

Change is inevitable, and nowhere is this phrase more true than in the pipeline industry. During the past several years, the industry has undergone substantial change resulting from highly competitive market conditions, technological developments, and rising regulatory and public expectations.

The pipeline industry must apply its expertise technology to continue improving performance. Investment in internal inspection technology, maintenance, and inspection needs to focus on leak prevention and swift detection as well as efficient oil recovery, transportation and refining. In addition, information management capabilities must be tapped to allow each operator to analyze and control risks on a more comprehensive and cost-effective basis. Finally, constructive, proactive relationships landowners, customers, communities governments must be maintained to ensure the benefits of an efficient and safe pipeline infrastructure are fully realized.

All players in the industry must take responsibility for careful pipeline siting, environmental sensitivity, and performance improvements.

REFERENCES

- 1 1998 CONCAWE report "Western European Cross-Country Oil Pipelines 25year Performance Statistics"; The U.S. Oil Pipeline Industry's Safety Performance, July 29, 1999, Allegro Energy Group published for U.S. Association of Oil Pipe Lines
- 2 Chad-Cameroon Petroleum Development and Pipeline Project, www.worldbank.org/afr/ccproj/project.htm, Rainforest Action Network urges opposition http://www.ran.org/ran/kids_action/aa_world bank.html
- 3 Conoco's Yellowstone Pipe Line rehabilitation project in Montana faces opposition http://www.clarkfork.org/listserv.html, October 1999
- 4 Olympic Pipe Line June 1999 incident in Washington State in U.S. still not resumed operations http://OPS.DOT.GOV/bellingham/olympic.htm

- 5 Zhang, J., Designing a cost-effective and reliable leak-detection system, Pipes & Pipelines International, January-February 1997.
- 6 Grimes, J. and Slack, D., Electronic Measurement Vital To PG&E GT's Cash Register, Pipeline & Gas Journal, July 1999.
- 7 Grimes, Keith, Changing Role of Inspection. Proceedings of the 1998 International Pipeline Conference, Calgary, Part 1 (of 2).
- 8 Engen, D., Jaarah, M. Aging Canadian product line inspected internally ultrasonically. Oil & Gas Journal, July 19, 1999.
- 9 Kamp., Pipeline Inspection Latest Developments in the Field of Crack Detection Tools, Erdoel Erdgas Kohle/EKEP, Vol. 113, No. 1, January 1997.
- 10 Miller, S., Gardiner, M., Clive, R. In-line inspection detects early cracking on Canadian crude-oil line, Oil & Gas Journal, September 28, 1998.
- 11 Conference Proceedings, 8th International GIS for the Oil & Gas Industry Conference, September 20 22, 1999, Houston, TX.
- 12 Sanders, M. Doyle., Proceedings of the 1998 ASME Energy Sources Technology Conference, February 2-4, 1998, Houston TX
- 13 Creighton, J., Industry On Board In Seeing Satellite Technology To Take Control, Nickle's Daily Oil Bulletin, New Technology Magazine, Vol. 2 No. 7, March 1997.
- 14 Freeman, H. B., How to use and Properly Position Hydrogen Flux Monitoring in Corrosion Control Programs, Proceedings from the NACE Annual International Conference, Denver, Colorado, March 24-29, 1996, Paper No. 335.
- 15 Munnoch, S., Space Age Watchdog Poised To Track Pipeline Stress From Above the Earth, Nickle's Daily Oil Bulletin, New Technology Magazine, Vol. 2 No. 7, March 1997.
- 16 Glover, A., Horsley, D. and Dorling, D., High-strength steel becomes standard on Alberta gas system, Oil and Gas Journal, January 4, 1999.
- 17 Sanderson, N., Ohm, R. and Jacobs, M., Study of X-100 Line Pipe Costs Points to Potential Savings, Oil and Gas Journal, March 15, 1999.

- 18 Aucoin, M., Alliance Pipeline Breaks New Ground for Industry, Pipeline & Gas Journal, September 1999
- 19 Kopp, F. et al., Automatic welding, ultrasonic inspection used on J-Lay project. Pipe Line & Gas Industry-Offshore Pipe Line Technology Supplement, April 1998.
- 20 Carnes, Robert W., Is homopolar generator a unique power source? Pipe Line & Gas Industry, October 1998
- 21 Newell, Eric P., Canada's oilsands industry comes of age, Oil and Gas Journal, June 28, 1999
- 22 Hill, R.A., Black Mesa Pipeline, Proceedings of the 10th International Conference on Slurry Technology, Lake Tahoe, Nevada, March 26-28, 1985, pp 15-18



2001 Banff Pipeline Workshop

"New Trends in Pipeline Technology"

Presented by Robert A. Hill, President Canadian Energy Pipeline Association

New Trends in Pipeline Technology

- Presented at the World Petroleum Congress -June 2000, Calgary
- · Co-Authors:

Stephen Wuon - Enbridge Inc. Robert A. Hill - CEPA E. Glyn Jones - Bechtel Pipeline, USA M.A. Powell - Pil Group Ltd., UK

Rapid Technological Change

- · Pressure on Costs
- · Aging Pipeline Systems
- Public and Regulators have High Expectations by - 0 Spill Tolerance
- · Landowner Pressures

Operation and Maintenance

- Risk Management
- SCADA Data Analysis
- Leak Detection
- Electronic Flow Measurement and Automated Operations
- Inline Inspection Tools
- GIS (Geographic Information Systems)
- Satellite Technology Used to Monitor Corrosion

Design and Construction

- · High Strength Steels
- · Automated Ultrasonic Testing
- · Composite Reinforced Line Pipe
- Design Changes
- Slurry Pipelines

Conclusion

- · Change is inevitable
- · Technology key to improving performance

Working Group 1 - Issues for Managers in the Pipeline Industry

Tuesday, April 10, 2001, at 10:30 a.m.

Co-Chairs:

Walter Kresic - Enbridge Pipelines Inc.

Dan King - TransCanada Pipelines Limited

Objective:

To provide a forum for discussion and create an awareness of the various issues

facing today's pipeline manager.

Overview:

A presentation (attached) by the co-chairs provided the framework for discussion. A collection of viewpoints expressed by workshop participants is presented below. Key outcomes were summarized during the workshop and are presented

at the end of these notes:

A "straw poll" conducted at the beginning of the session indicated that approximately half of the participants identified themselves as managers in the pipeline industry.

State of the Industry

Recent high profile pipeline incidents (Olympic Pipe Line, El Paso Natural Gas, etc.) and regulatory changes/initiatives were reviewed:

- Increasing public hostility towards pipelines appears to be aligned with increases in drilling activity and increased public opposition to new wells. Pipeline companies get lumped in with E&P companies and pipeline failures affect all of industry - "we are all painted with the
- · Regulators are moving away from regulating the business aspects of the pipeline industry (tolls, tariffs, etc.) to more environmental and technical oversight.
- Considerable time is being spent in industry trying to understand business implications of new regulations. Regulations appear to be trending towards greater conservatism and the "regulatory pendulum" shows signs of swinging towards greater regulatory "intensity".
- Regulations in the USA are becoming more prescriptive in response to public outrage while Canadian regulations (OPR 99, etc.) are more "goal oriented" and less prescriptive. There is a general opinion that US-style pipeline regulations will eventually move north to Canada.

Pipelines and Perceptions

- Workshop participants were asked to consider if they would be willing to live next to a pipeline and what changes would have to be made in industry before they would do so.
- Negative perception stems from industry's inability to get a good message out. There was a
 general consensus that pipeline operators do a lot of good things, but only negative aspects
 are reported.
- Public perception that there is too much industry cost reduction and these cost reduction initiatives result in a reduced level of safety. There was an alternate view expressed that cost reducing initiatives do not necessarily affect safety performance. Amongst those opinions expressed, safety was help up as a core value.
- Does industry do enough to communicate "good news" i.e. volume safety moved, etc.?

CEPA indicated that it has spent considerable time and resources reviewing recent incidents and concurs with workshop comments regarding a greater need to communicate good things to the public. CEPA has established a committee and will be retaining additional support to better address public communications issues.

- In times of increased operating costs, tighter budgets, and human constraints, has risk
 modeling become a crutch to compensate? Industry must manage this perception.
- In order to reduce the negative industry perceptions, industry must foster a fundamental "grassroots" belief in pipeline safety within individual companies and amongst stakeholders.
- Are pipeline integrity management challenges perception problems or real safety issues?

Administrative Challenges

In addition to administrative challenges of increased demands on staff, external resources and budgets as identified by the workshop co-chair, additional immediate challenges identified by the group included:

- In spite of ongoing industry changes, there wasn't a strong reaction from the group regarding understaffing or budget constraints.
- Struggle to attract new people to the pipeline industry in general and specifically to pipeline
 integrity. Attributed to the relatively stoic image of the industry as compared to sexier "hitech" and to the historic volatility of the oil patch. (drives off lots of potential candidates
 seeking greater stability).
- Lack of balanced hiring practices and limited succession planning highlighted.
- Training; USA-style Operator Qualification requirements may come to Canada. Requirements to demonstrate proficiency (in an auditable manner) at the field level will be very expensive. (figures of several million dollars were quoted)
- The issue of specific technical expertise moving outside of companies and the general employment trend towards consulting and outsourcing was discussed. Pipelines and other industries (automobile etc.) previously embraced large staffs with various competencies. This has largely changed to outsourcing using specialization firms. Managers must adapt to a system where internal and external resources are employed efficiently

- The recent price of gas and corresponding desire to bring more gas on stream quickly has forced additional loading on older infrastructures as additional compression is added to old systems etc.
- Changing the mindset from "a small sweet gas release in the back forty" isn't that big a deal to "concern for all releases" is required to reduce overall leak statistics.
- General belief exists that additional funding could be obtained for key pipeline integrity issues if required.
- Lack of mentorship was identified as an industry issue. "Downsizing" of senior level staff (largely as a cost control measure) was suggested as a problem area affecting training of new employees. A suggestion was tabled that industry consider sponsoring a program at UofC or UofA to train people and increase industry profile.

Manager's Environment

Management Systems

- · A common understanding regarding "what a management systems is and what it should it do" was not reached.
- Management Systems were generally defined as a "formalized decision making process" used to demonstrate transparency. Strong regulatory (OPR99) endorsement of "systems approach"
- The general consensus within the workshop is that most participants have a series of programs to manage integrity, but it remains a challenge to assemble the "total package" and develop comprehensive documentation that brings together elements in an auditable fashion.
- Recommendations from those currently developing an Integrity Management System (IMS) are that systems should be developed as a iterative process with initial "rough cuts" being refined through time.
- Additional recommendations suggested that workshop participants not develop an IMS "in a vacuum" but rather leverage from other existing management systems such as Environmental Management System (EMS).
- Grouping together the integrity and EH&S audit components of management systems was cited as an example of a way to minimize impact to field operations.
- · Any management system must start with a higher level strategy and become part of the corporate culture. The "buy in" for the underlying philosophy must exist from Senior Management through to line staff.
- Based on investigations of recent failures in the USA, a key post incident query involves review of the "system" in place at the time of the accident. As such, proponents must have (and be prepared to defend) a management system.
- ISO14000-type system may be too rigid or formalized to fit needs of all companies.
- Questions regarding overall value and appropriate degree of formality for a management system were largely unresolved.


Zero Failures


Are zero ruptures an attainable realistic goal?

- Opinions varied within the group as to whether this was an attainable target. Opinions were expressed that application of new technologies can make zero failures attainable while other suggested that the number of uncontrollable variables (third party strikes, etc.) make this target unreachable.
- If zero failures are unreachable, why is it being proposed as a goal.
- Although greater than 90% of leaks in AB occur on lines <6 inches in diameter operators of large diameter transmission lines are lumped in with small E&P operators as part of the broader leak statistics.
- As such, "the industry" is only as good as it's weakest link. What can industry do to move smaller companies away from "reactive" programs of leak repair towards prevention programs?
- Can a corporate culture be developed that embraces the ideal that integrity performance is an
 important aspect in the success of the company? Can tangible value be added through
 integrity programs?

SUMMARY & KEY MESSAGES

- 1. Public perception remains an industry problem. Only the "bad news" stories get heard in the public domain. Although it falls outside the traditional "core" pipeline manager role, managing public perception has become an important job aspect.
- 2. Prescriptive USA regulations and training requirements are expected to influence Canadian regulations and management programs.
- 3. No (admitted) concerns re: lack of staff or budget constraints; however, significant concerns regarding lack of mentorship, inability to attract talent to the field in light of competition from "sexier" hi-tech companies.
- 4. Varying views of management systems exist. There is little commonality regarding what a management system is or does. Some indications that individual parts (integrity programs) are enough, with a minority view that an overall management system is important. Most companies are at the stage of having several integrity management programs but not a "system". Significant challenges acknowledged regarding assembling program elements into an auditable package or system. Agreement that integrity management plans systems must have senior management support and become part of the corporate culture.
- 5. Diverse views regarding "zero failures". No resolution as to whether this is a viable goal.







Issues For Managers in the Pipeline Industry

- First time this session has been held
- Our intent is to create awareness of issues among Pipeline Managers, create a common understanding and discuss possible approaches / solutions
- At the end of the session, we are required to summarize the key outcomes from our session

Banif 200 : Pipeline Work



Recent High Profile Incidents

- Olympic Pipe Line (Bellingham, Washington June, 1999) Refined petroleum leak and fire causes three deaths
- El Paso Natural Gas (Carlsbad, New Mexico August, 2000)
- Natural gas explosion results in 12 deaths
- Pembina Pipeline (Chetwynd, B.C. August, 2000)
 - One million litres of oil spilled into the Pine River contaminating drinking water.
- Westcoast Energy (Coquihalla Highway August, 2000)
- Natural gas pipeline rupture (no ignition) rained debris and blew windows out of nearby vehicles.
- Exxon Mobil (Abilene, Texas September, 2000)
- Bulldozer damages pipeline. One death and other injuries.



Regulatory Initiatives - United States


- United States Federal Legislation Pipeline Safety Act
- - Liquid Pipeline (>500 miles) HCA
 - Proposed Liquid Pipelines (<500 miles) HCA
 - Proposed Natural Gas Operater Integrity
 - National Pipeline Mapping System





Regulatory Initiatives - Canada


- NEB Publishes new OPR's in late 1999
 - audits underway
- AEUB report published in Spring 2000 indicates high failure rate and regulatory infractions on Alberta pipelines


April 4-12, 2001














Banff/2001 Pipeline Workshop

Managing Pipeline Integrity: Issues for Managers in the Pipeline Industry April 10, 2001 10:30 a.m.-12:00 p.m.

The second secon					Olicylott Sumst.
WATER THE THE PARTY OF THE THE THE PARTY OF THE THE PARTY OF THE THE PARTY OF THE THE PARTY OF THE THE THE PARTY OF THE	Company	Name	Phone		
The state of the s	EN BRIDGE	BRAD SWITH	200 100 60.7	E-mail	Signature
7	WEB	7	100. 450. 860+	Drak. Smithe Cnpl. androdge. com	BLA
3	t,		(405/211: 2690	JRopec @ neb.gc. ca	Habby and Market
	7 <i>A</i> 71	GABRIEL NAHAS	(403) 920-6578	Gabriel natuse @ T.	
†	UNAM S.P.A.	PROLA BONANDRIN	03) 590 18686	Color of the standards	am Lebus Ki
2	BS Reline Instalion Einices	THOUSE THE	3000 mm ()	- F	(Remomented
9	SIMMONS GROUP INC	Don Hear	2056-1660)	somerhunde bysonies, ca	The state of the s
I	Trensage of D. D.	V T	3085145 504	Elmmons (a) cadvision, com	The ferries
8	Alana all	Ken laylor	403-920-7257	-7	X
6	NOVA CHEMICALS	KAY LENES	403-351-8319	Jones. R. A. NOWALYPH, COM	2 - L
The second of th	Curpos Como de Trai	Dennis Zadosy	783 - 400 1100		1
01	Cokata Caraca Tou			almis, Toldery & Corpos. Ca	Com
		Round Devis			Sample of the
12	-	HUND FUNCKO	403-363-4848	marphoode Boodistol, con	Bluckanon
		rett	43-258-233	justimenth @ marr-associales. com	THE
		No-Trac	403.21/10387	to Tolland	
		Don WALLACE		3	7 20
+	BUSSELL NDE SYSTEM	JIM CKES.	†		O. K. wee
- 1	CANSPEC GROUP INC	Lis		Jyckes Orusse/Kech.com	
	THERE DI			obanadis Danger. com	Defende,
	Transpillary Agents	The second secon			and the second

Managing Pipeline Integrity: Issues for Managers in the Pipeline Industry April 10, 2001 10:30 a.m.-12:00 p.m.

7 Bell	9	É				Pann of					0000	W TOU	4-19-2	To h		A. S.
Thereson Bell @ MHS.gol	hau @ Petro-Cambrille	den @ how. com	d few s @ leveling. com	domination of the state of the	CENDIAL COM	Paul . Marking mus	(780) 420 -8434 Parks. But @ Cad and Lister	(x4) 592 786 The mish of house	possil mobilice	thebyle		Mp31.com	ol.com	POSTAVE CASA, CONDO. C.M.	250-863-4586 cbilling boass con	403 260 6714 graemekingagreen plac. com
The Germe B.			dhows Q1		Steve Jemes & often Diffe : Com	Paul Mank	Corte But @ C.		rayla Bud	Tobat Sutulay &	S	Charles of virgosiscom	Chief Phance Com		cbillings	gaeneking
(205) 589. 9554	403) 2964750	2795-02 (49)	8054-182 (20%)	185-629 08 <u>6</u>	42 560 6727	1591 -1690	780) 420 - 843d	C4) 592 RE	(403) 2607389	1809-024 CON	167 940 BOOL	100 COV < 210	120 - C85 (4(Z)	13.70c/KK	So -863-4586	+119 097 EON
Bel	A	786	KwAS 6		N	Poul ENMAIN 17						_		who.		
1 heresa	Henry	David	Dans	DARRAL SHIMA	STEVE LEMON	-		Then BANO	David Feier	BOS	Shame	CHKIS HAPTURELL		Naur	CHRIS BIL	Graeme King
Service U.S. Minetals Management	Petro Canada	rmon.	J. (5. ~	RESOURCES	GreenPpe Industries Ltd.	US. Minerala Met Surve	Enbridge Pipelines Jac	7.18	20 The	Translande Poline Bob Su Harby	HUNTER MYDONNELL HORINE SERY STRONGE WEIL SAMO	Hunder McDonnell Applian	146	Pojects	RC GAS UTILITY CAP. CHRIS BILLINTON	ije
U.S. Hinem	Petro.	11CI Canuda	Lembing Pipe (1.	IMPERIOL OIL RESOURCES	GreenPipe,	US. MINERA	Enbridge	BCCM	Ranbow Pipe Line	Trans Care	HUNTER MEDON	Hunter McDa Services	Coras Inc	Positive Projects	RC GAS UT	Greenlike
18	6.1		21	22	23	24	25	26	27	28	29	30	31	32	33	34

Managing Pipeline Integrity: Issues for Managers in the Pipeline Industry April 10, 2001 10:30 a.m.-12:00 p.m.

Banff/2001 Pipeline Workshop

	- May	V	1	The same	C.Cappi	Con Con	m Stee 1th	nota .com	ŧ	60	(X)	Halson	Courthur				16 cu Clear	A Company		SAME OF THE
,	(604) 576-7004 ptruster abagas. com,	PIPELINK (952) 983-1608 guistar @allinner-Disclar	Juan @ marr- 0550codes, com	416)482-342 1 uzelacna mi . C. n. J.	(403) 920-6086 Kg. J. Cado, Comes tro	sicer	Jaris-norted to Transcanady. Com	780/464-9133 delton-gray Okeyspanca	c parker @ transgus .sk.ca	ace but a cat i	Telus planet	017 161-1214 Speuvers@cc+14 bs. 10m	+lawrence@ipsco.com	403.444-4550 Cyc.1. Karvarena 11	403-686-8412 in 1011	Conspinal Net	403) 247-713,	Lgerlitze telusomes. net	Sy056@ Wei 019	ALDODO CNR. COM
	1001-925 (Agg)	E(952)983-1008	(403) 258-2233	(416)482-3421	(403) 920 - 6086	408-930-6508		780/464-9133	(306) -4 203		<u> </u>	4151-191 110	306-924-7385	403.444-4550	403-686-8412	J.612-175.080	(462) C47-712,			(43)517-7276 /
By Cooltanno	111111111111111111111111111111111111111	ALLIANCE PIPELINI	MARR ASSOCIATES	PIL	TOPL	TCPL	KEYSPAN ENERGY	TANAOA	SWASOUL	CC TECHNOLOGES (403) 250. 904,	CC. Technology	7000))	NERCY	4T VENTRES LAS		JZG ENG. LTD			
Nopera Transias	RICK Gill STAN	VI LICENT SIGNA	NIA MARR	Net Uzelac	BRAD SADOW ALL	Gurry Norton	DELTON GRAY	CURTIS PARKER	8	.9	bhn Beavers	Tom Lawrence	YEU PROMILE	O TITOPEN CHIAMS &	DERT JOHNSON	Vernie hrost	KYLE GERUTZ	Hepha Gossa	1	and the same
35	36	37	38	Į	1	9	41	42	43	44		45	94	47 +	48		The same of the sa	50 -	51	defel skama vej kažnadaš venšši vej dešendaš je goverdentaja.


Managing Pipeline Integrity: Issues for Managers in the Pipeline Industry April 10, 2001 10:30 a.m.-12:00 p.m.


(Administration of the state of			
22	Ale 7.P	NEB	403)299-3195	Kyip @ nebige. ca	M
23	SHU C. LEE	EUB	(405) 197, 2367	73	11/6
22		<u> </u>	196-11-20	गामायहरू पुरा १८०. एव	2002
THE STATE OF THE S	_	Corresion Englasting LAL (405) 202-2050	(403) 202-20160	pteeverse telusplanes, net	3
55	DAKE MUNCO	GUSTON'S ENSURES SHOW (403)560-7264		DAVE_ MUNICHO MBAST. BUTTONSU. O	S.
99	Bob Longpre'	BP Canada Exergy Company (403) 255-1230	0521-552(104)	longport 10 bp. com	B
57	LEWARD LOZOWY	ALMGAS UTIWARS	(78) 980-7313	11020Wy@agutl.cm	
28	Artur Jane	ATCO Pipe lines	(780)420-75 36	avt. Jaux Catodipolius, Com	17- R
26	Z. 5860/	Atco Pyolines	(763) 420.7581	Den, 30Kol @ etcopy ne low, con	S S
99	Martin Winspear		2608 Cop (887)	7.77.7.77.07.07.08.07.08	?
19	Bob Simmons		78 468 3619	bs.mons @ ETDOMAN.	
62	AJORE FLIATERING	RTD GUALITY SERVICES	0099-044(28)	abliakau Ho ctdonolity com	M. Floor
		7	1009 -39/ (021)	(180) 168-3601 Anrosicuric Allandi h. com	7 3
64	Bro VILYUS		0059-648-816	VILYUSK @ PIT-USK. Dan	Mille
65	Alan Millan	Tanlanadian A exerces	(403)-290-3340	alan_miller@pcp.ca	G
99	IAIN COLOURIOUN	PII	713-822-5288	1 ;	X
67	67 Dave Toporo 15ky	oup Inc	403 541 5319	Simmons ad (1310 . com	
89	Duame CROWIN	UNIVERSITY OF WATERIAD	514-888-4567 ×2682	dscronin @ engmail. umaterlos ca	

Banff/2001 Pipeline Worksho

Managing Pipeline Integrity: Issues for Managers in the Pipeline Industry April 10, 2001 10:30 a.m.-12:00 p.m.

		RI						ŧ	1	1	Not N		**	W		CC	D. WA		***************************************	Buse Graylo.	1	22			
	Later latin (a) Leaving	בייט בייטרפר ומספוואפרופרה בסיה	darylo corroceun. com			-021 FWOINERING 1193 059-1873 / 1500 301 10 1842	7 7 7	Schoney@ transgas. sk.ch	goy Erretismscient of Licent		ज्यात्मा क राज्या	Com D. Machine	-		Car. Perest S	Colfor mass rate to an		TOO. PESTA S. COV. A. C.A.	\Box	dant gizyble gov ab in	don-King@ fronsconcode Con				
	(463) 266-3860		(403) 286-0606	; ;	703260 6773	103059-1873		306) 475 28550	2018-EPE (504)	400 869-5344		403-262-8160	4020111	10 1 31 7 7 7 8 7	ARELIA 43 517 7 23			tos its pres	6670 CBC CV		402 820-6015	MANAGEMENT AND ASSESSMENT OF THE PARTY OF TH			
	BASELINE TECH NOCOGES	(5.50 (5.50)	(מטרקל	Succession	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-OLI FOUNTERING	[RAWS GAS (X)	ż				To seem to	Howard Rolling		THE PROPERTY	Tri Ocean Granding		FUS	M W) s poores to (
	SKUCE DUPUE	DART BAXANDALL		JRENT -TWART	ART HARAIL		Jules Choaney		and Armenia Commission of State of Stat	The second leaves to the secon	an Morrisa		1 (5.1 D##/1.4	であるのが		Dutten Mazurek	Messa Mer		Jawe (21/324/)	DAN KING	**************************************		į		
07	6	2	7	A	72	7.3		74	7.5	_	76	77	***************************************	78	70	And the state of t	08	× 18	_	82	83	The second secon	84	85	And the second s





Working Group 2 - Regulatory Developments Tuesday, April 10, 2001 at 1:30 p.m. - 5:00 p.m.

Co-chair:

Tom Pesta Alberta Energy and Utilities Board

Co-chair:

Ken Yip and Joe Paviglianiti, National Energy Board

Rapporteur:

Lawrence Ator, National Energy Board

Objectives:

Is aging of pipelines a valid public concern?

2. The role of regulators in addressing public pipeline integrity concerns.

Presentation 1 - Aging Pipeline Systems

Mike Hallihan Skystone Engineering Inc.

Although there are failure mechanisms that are time dependent, statistics do not support the proposition that failures are more likely on older pipelines.

Statistics are not sufficiently clear to deal with the age issue and the statistics that are available might be leading the public to perceive that older pipelines are dangerous.

Presentation 2 - Aging Pipelines - A Landowner Viewpoint

Roy Baguley Metal Engineers International Inc

There have been a number of serious incidents involving pipelines. This justifies the concern that the public has regarding the safety of pipelines.

Pipeline companies will lie or mislead landowners with statistics.

The pipeline industry and pipeline regulators are seen in a negative light in public perception.

Discussion

There were four main issues that came up in the first session and were dealt with in the second session. These were: regulation, communication, financial concerns, and standards. The following is a list of the comments that were said about each on during the first session.

Regulation

The public perceives that regulators: do not operate independently, are in bed with industry, act more as mediators than regulators, and need to be hassled by the public to look at issues.

Regulators do not report incident information and statistics in a clear and consistent manner. Every regulatory body has a different definition for incident.

The consequences of incidents are not communicated by regulators.

When looking at statistics the public sees numbers of incidents but not the magnitude of each one.

There is a perception that the number of incidents is rising but fines and penalties associated with this are not.

Communication

Public perception is very real.

Age is a way for the media to focus issues when there is an incident. This might produce a public perception that age is a factor that produces dangerous pipelines.

The public relates corrosion to car rust, which is an age issue.

It is only human to assume that age will cause breakdowns.

Other industries have similar public perception problems. One industry that was compared with was the airline industry.

The airline industry has big media-covered disasters and yet are perceived favourably. Some of the reasons why this might be include the perception that airlines are high-tech, shiny machines while the oil industry is perceived as low-tech and dirty, airline crashes are seen as being out of the norm, and people volunteer to take the risks associated with air travel.

The incidents that get covered by the media are large scale disasters. The majority of incidents that occur are small.

Industry use the term 'age' as shorthand for a multitude of time related issues; this perpetuates the perception that age makes pipelines dangerous.

Financial Concerns

Facilities are used for longer than intended.

Old pipelines are not as easily inspected and newer pipelines.

The news reports pipeline sales.

The buyer of a pipeline is forced to rely on information about its condition from the seller. There are increasing trends towards pre-sale inspection by the buyer.

If these inspections were made mandatory by regulators it would be easier for companies to justify the cost.

Is it acceptable for pipe that can't be inspected to have unlimited operational life?

Standards

Industry can develop good standards if they put the resources towards it. Regulators can comply them to do so

External corrosion protection is required by standards. Why are there no requirements for internal corrosion protection?

What follows now is a list of the comments on each topic at the second session.

Regulation

There are two issues, public perception and pipeline performance.

There is concern that this discussion is calling for a less cooperative approach from regulators, contrary to the current trend of working together with industry.

There is a panel in Sundry that includes all stakeholders; it works well in a cooperative manner.

Regulators at the federal government level are perceived to be more independent. The example given is the TSB.

We should distinguish if a problem exists and if there is a bad public perception. The NEB has perception as a goal.

Airline regulators are seen out there on the news after major accidents.

The NEB is out there with the TSB investigating major incidents. The NEB looks at every reported incident for causes.

There needs to be consistency with between regulatory bodies in the defining of incidents.

There is a danger that prescriptive regulation with force companies to spend their safety dollars inefficiently. We should establish performance measures and management systems to attain them

There should be prequalification of companies who will operate pipelines.

Management system frameworks should be established by regulators.

Zero tolerance goal is too simplistic.

Application process should consider operating practices.

Maybe we don't need more regulation. As the public becomes more aware they prevent industry from pushing things through.

Offshore US companies are ranked. These rankings are public. This justifies more safety expenses to shareholders.

The cost of being responsible might take years to get paid back in the form of better performance, but it will get paid back.

Communication

Recall a W5 report where the reporter was able to use a rupture to make a mockery of an NEB official saying things were safe.

The best advocates of a good public perception are the people in this room.

The public perception in Saskatchewan is different while safety performance is largely the same. What the public sees in different places is largely what industry is reporting to them.

The media has to be better managed to form a good public perception.

Media operates by selling sensationalism.

The media affects the public at large, but landowners and those individually affected get there information in the form of packages from industry, followed by stonewalling.

Industry must impress upon the public how valuable industry is by using advertising to promote the industry.

Regulations should use a risk based approach to deal with both frequency and consequences.

It would be difficult to communicate a risk base approach to the public.

Communication to the public must be designed by people who have communication expertise.

Statistics won't convince people.

All stakeholders should be involved with communication strategy.

The public sees big money in industry and doesn't buy the financial limits arguments.

There should be pro active community awareness at the local level.

CAPP and CEPA could have working groups to develop a plan to communicate with the public. CEPA does have a communication initiative.

There are no CEOs here they are the ones who need to get the message.

The public perception impact by media coverage of big incidents is transitory. The landowner contact with industry is on-going and should be dealt with differently.

Associations can deal with general public concerns.

Individual companies can deal with site specific landowner concerns.

Financial Concerns

Industry functions by making money, and decisions are affected by this. There is a balancing act to try and satisfy all concerns.

The sale of the product is the only source of money in the industry. Regulation, production, transportation, refining, and landowners all get money from this 'pie'.

There is a strong correlation between the money spent on corrosion control and the number of incidents.

It is amazing how money becomes available when there is a catastrophe. Regulators and industry need to take the lead.

Industry should implement an integrity management program.

In the production industry the cost is not passed on to the consumer, it is market driven.

We could have CEO pay linked to safety performance.

We could link regulatory fees to safety performance like WCB does.

If standards are set up and required they become financial requirements.

Standards

We have been talking about risk of pipelines. Almost everyone has gas heating and that carries similar risks. We don't concern ourselves because we know there are standards. Standards create a feeling of comfort.

Are those standards not in place?

We should determine what is the base acceptable performance.

It is difficult to involve the public with standard development.

There is a lot mandated but it is not clear how it should all come together.

Common ground might be found with a ISO like quality standard. Auditable processes should reassure that problems won't be repeated.

Current standards are too broad they should separate different areas of industry.

The people who are not at the conference might be the problem.

We should enforce the current regulations, not make new ones.

There is too much interpretation involved with current standards. They need to be more specific to level the playing field.

There is an enforcement ladder that was put in place recently (AEUB). We should wait to see if it works.

Would like to see some kind of performance ranking for company. It gets attention with shareholders and makes it easier to justify safety expenses.


After the discussion the two presenters made closing comments.

Roy Baguley's Closing Comments (paraphrased)

What it would take is meaningful regulations enforced meaningfully. Public had to make effort to enlighten regulators this is not right. Level the playing field.

Mike Hallihan's Closing Comments (paraphrased)

Take the time to talk to people who you affect who don't work in oil industry. It is a bad idea to have engineers tell landowners 'what is what' in their lives. We need to have better statistics and information. It's about trust.





How Have the Regulators Affected **Public Perception?**

- There is a perception the regulators may not be working fully in the public interest
- Is it reasonable to allow an unlimited life for a pipeline?
- Regulators are lax in inspection during construction
- Regulators could specify more integrity management
- Failure statistics should be fully available and presented without any spin
- The regulators should set performance standards, measure against them, and report on performance
- Regulator should impose more fines and prosecution

April 9-12, 2001

Banf 2001 Pipeline Wartshop



Why is Pipeline Aging a Concern?

- Is the issue of aging just a convenient target?
- Despite industry efforts, public perception will remain for extended time
- What are other industries doing? Industries like air transport and rail transport also have safety issues, but do not seem to have the same problems with public perception. Why?
 - They are highly regulated
 - Personnel are highly trained, credentials are
 - we accept the risk of air travel willingly, it is not forced



Technical issues that may be contributing to the problem

- Old designs may make today's maintenance difficult
- Major differences between upstream and downstream
- Age is irrelevant! The issue is lack of inspection and maintenance
- Production declines in aging systems will create cost pressures for maintenance of marginal systems
- Technical records are sketchy for old facilities
- Are companies properly conducting due diligence?
- Construction done as cheaply as possible in cases
- Industry must perform a balancing act between funds available and technical needs

April 9-12, 2001

Sent 2001 Pleating



Why is Pipeline Aging a Concern? Continued

- Aircraft may be more easily inspected
- pipelines are not as high-tech as aircraft
- Corrosion is not fully understood by the general public
- is there an automatic assumption that everything has a finite life-span?
- Should we automatically assume that all pipeline leaks are

April 1-12, 2001

Bert 2001 Pipeline Works



Communication Problems

- Catastrophic transmission line failures cause a false perception of the consequence of a pipeline failure
- Frequent failures on upstream lines cause a faise perception of the frequency of failures on all pipelines
- Even technical publications may be reinforcing the "aging"
- Risk is driven by the numbers of failures occurring
- Terminology use the term "maturing" pipelines instead
- The media does not report objectively on pipeline
- Statistics are easily manipulated or easily misunderstood



Standards

- Industry could come up with better standards and the regulators could adopt them. Industry would buy in to their own standards more readily
- Modern standards are usually the result of public pressure on regulatory authorities
- Existing Standards not clear on the expectations for pipeline integrity management

April 9-12, 2001

Sout 2001 Pipeline Workshop

tribe ?



Financial Constraints, Possible Solutions

- · Evaluate how the wealth is distributed
- Regulators help finance technology development that might assist industry performance
- Examine or audit financial expenditures towards integrity and ensure it reflects volume of actual production
- Mandating integrity management programs might eliminate the issue of financial constraints
- Find way to pass increased costs on in a commodity market

April 9-12, 2001

anif 2001 Pipulina Warsanup

Siide 10



A Summary of the Key Issues Developed During Session 1

- Regulatory issues
 - require independence and transparency
- Must ensure compliance through enforcement
- Financial constraints
 - on industry, on regulators, on public
- · Communication problems
 - performance statistics, regulator communication, industry communication
- Standards
 - development, requirements, involvement

April 9-12, 2001

Sant 2001 Pipeline Workehop

Şiiya A



Financial Constraints, Possible Solutions Continued

- Prioritize according to consequence use risk based approach
- · Tie corporate bonuses to pipeline performance
- Reduce risk to a level at which increased financial expenditure would not result in further reduced risk
- Consider WCB model more leaks equates to more costs (higher levy or fines)

April 9-12, 2001

Sanif 2001 Pleatine Workshop

Sticks 11



Regulatory Issues, Possible Solutions

- panels of stakeholders working together (SPOG)
- · regulator should be an independent body
- need strong presence, with immediate action & investigation
- Each regulator has a purpose which may influence the way they report their information
- Industry and regulators set a benchmark as to acceptable level of performance
- · include commitments for operation and maintenance

April 9-12, 20

Recel 2001 Pipeline Wartsho

Sinte 8



Communication Problems, Possible Solutions

- Pre-qualification (have regulator evaluate and verify quality of operator)
- · Zero-tolerance comments are a distraction to real issues
- · Must define the problem, and then design a solution
- · Technical people may not be the best to talk to the public
- · Public sees high corporate profits
- · Risk based approaches require careful communication
- · Include requirements for maintenance in regulations
- Use proactive regional communication programs (SPOG)

April 1-12, 2001

Sand 2001 Physics Workshop

Sinte 12



Communication Problems, Possible Solutions Continued

- Have CAPP and CEPA develop public communication
- · Get the small producers on board
- · Get support at the CEO and Director level
- Communication needs to be different for different levels of involvement, i.e. directly affected public vs. indirectly
- Associations are most appropriate to communicate generally on global issues
- · Companies should do the communication on local issues
- More careful reporting of failure statistics
- · Make failure statistics fully available

April 5-12, 2001

Hard 1994 Disable Wallet

-




Standards / Regulations Possible Solutions


- Standards make it easier to mandate work
- industry and regulators should establish key performance indicators to verify that Standards are working
- implement a quality standard e.g. ISO9000
- Standards are very broad (minimums), leave too much room for interpretation. Make more specific to the application.
- · Don't need more Standards, need more enforcement
- · Prescriptive Standards not suitable for variable situations


April 1-12, 2001


Senff 2001 Pipeline Worksho


Silde 14



























The Job of the Regulator By way of example the NEB says that it is responsible for ensuring the safe operations of pipelines, and it has published the following corporate goals: Ensure that NEB regulated facilities are safe and perceived to be safe. Ensure that NEB regulated facilities are built and operated in a manner that protects the environment and respects individual's rights. I would propose that other regulators have similar goals and objectives, although they may be stated differently.





Primary Result of Landowner Perceptions: A Call for More Regulation

- Need for clear and effective regulations that will force companies to pay attention to pipeline integrity and safety.
- Enforcement of such regulations by impartial autonomous regulatory agencies.
- Severe and meaningful penalties and compensation orders for companies that do not adhere to regulations.
- Revocation of licenses for operators with serious or chronic non-conformances.

April 9-12, 200

Band 2001 Pipuline Worksho

\$566 13



Secondary Results of Landowner Perceptions

- Simple mechanisms for public input to decision-making processes, and compensation for those directly affected.
- Consideration of risk, exposure, and loss of enjoyment in the assessment of land values.
- Disclosure of all facts with applications to construct, and throughout the approval process.
- Impartial audits of Regulator performance respecting the administration & enforcement of Acts & Regulations.
- A system that requires pipeline companies to be prequalified by the Regulator before being given permission to build and operate pipelines with hazardous products.

April 9-12, 2001

Sant 2001 Pipeline Workshop




Secondary Results of Landowner Perceptions (Continued)


- Periodic publication of the results of Regulator activities including facility names, operator names, and locations.
- Improved data collection by regulators & communication of results without spin & other "fun with numbers".
- Industry funded research into pipeline safety, integrity, and risk, that is administered by Regulators and carried out in an environment independent of industry influence.


April 8-12, 2001


Banat 2000 Br. 6


Strin 18





































Aging Pipeline Systems


Improvements

- Continue to reduce failures due to design, materials, and operations thru improved standards and compliance.
- Reduce failures due to inadequate maintenance by establishing clear standards and competency for planning maintenance.

April 9-12, 2001

Hand 2005 Blooks Market

Slide 13



·	
	(
	was in the manufacture of the second of the
	and and the state of the state
	Stationach
	deli intervendo dispessioni
	a.
	rabbiogialisty voltania, sept.
	Moneyanasa

Managing Pipeline Integrity: Regulatory Developments April 10, 2001 1:30 p.m. - 5:00 p.m.

	Signature /	The state of the s	0		com offer.	Pérshaudini	Quil		Ch Ch	A A			12	N. N.	200	J. V.	Less I	7	THE REPORT OF THE PARTY OF THE	The same
K-mail		tow Le Decal Vision, Can	don- King @ Hons count	40. 363.35	10 3-40-65/8 gabriel - nahase transianadas com	02-52048686 paga bananda'niasmam.eni.it	BOUCHER, DARIUS O COLTENC, Com	Cherca O Pelus cion +	gerge Main Beac. entiriles com	The state of the state of	المراد ال	403 920 6035 brian rothwell etangemedica	Jamie. Cex Ocan. duport. com	ia has 6 cons	in f & in the	che Learn com	allow miller	van de mondam 1/10 cm. 10. 1.0	-hames @ course on	780 955 6/59 day adamson @ esso. com
Phone E.	1 _	40167504	403 820-6015- d	4,2 No. 1120	103-40-65/8 g	07-25048686 par	403-259-1888 Bo	405-281-8627 Cp	416-495-6332 que	217-527-52 53 cold	300000000000000000000000000000000000000	403 920 6035 has	403-254-6145 Ja	403.221.8779	P	403 237-1953 he	403 240-3340 (2)	30	7	80 955 6159 day
Name	Chiles Trilling	المراد المسارلة	Jon King	GABRIEL NAME	9	יייייייייייייייייייייייייייייייייייייי	DARINS BOUGHER	Chris Pierze	GERGE PROLIN	AIN COLOCATIONS ARE 522-CODES COLOCATIONS		SKIAN KOTHWELL	Jamie Cox	AKE ABES	Flaser King	Ka		Reg MacDonald	ענ	+ Doug Adamso 1
X	No. Tran		1ens Concola		SNAT S. P.A.	The state of the s		1	OMNINE COSUMED CAS 6	PIL	766		Canadia Form	occaring.			the Canadian Accurred	Oil Resuras	A CALLED TO SERVICE AND A CALL	Imparial Oil 4
And the state of t		7	The second statement of the se	en et alaganian e reconscipi de le recompositivo manaque.	4	2	9	STATES OF THE PROPERTY OF THE	And the second of the second o	8	٥	91								dakyo enakikha malikha dasuu halimpikka esana

Managing Pipeline Integrity: Regulatory Developments April 10, 2001 1:30 p.m. - 5:00 p.m.

Hart		H	18	Branch	J&Z	SMR.			A A	The	2	& Control of the Cont		K	Sant - like	theat
al, forth@esso ,com	780 539-3007 cellan, habitis @ Chellan	hwallare () caduision (am)	tobert suttenty &	100+ 739-5367 MINERE @TOWN.CA	NORM TRUSIER 604-576-7004 MMISIER@ Dayor.com	64 592 7688 Fhanesa Scars com	bt yson Onrcan. Ge. ca	······································		frencie home, com	j.mitchell@ campipe.ab.ca	Stayara @ comprise. Com	i 4 0 kes@rosselfeck, Com	780-490-2445 - bparadis Aunspa: com	garrett. wilkie @ cnpl. enbridge.com	LZHAO@EAGCE. ORG
1617-189-506	780 539-3007	(405) 259-1811	403.820.603	eat 739-5367	604-576-7004	3696 545 pm	613 972 9573	80 85/18 894	432-266-4575	250-752-1467	403-213-8855	706723116	760 Y68 6800	780-490-3445	\$2h8-07h(08L)	281-877-6116
AL FORTH	A Fillery Hobbins	Howard Waller	Bob Cutura	MIKE REED	NORM TRUSIER	FRED BAINES	BILLTYSON	C Don HERMAN	Ken Taylon	FRANK (HRISTENSEN 250-752-1467	JIM MITCHELL	HEK STABBENIS	Sim Yokes	Brian Paradis		Lin zhao
Imperial Oil	Parcedien Huter Exploden	Cost Engineering	Trans Canada PIC	TRANSMONIAM FIL	15C GAS UTILITY	BC GAB	CANMET / NRCL	SIMMONS GROUPING	Traves Converse Pipe	-HCM([CAMROSE PIPE	Mylose 1/2	Russell NOE Systems	CANSFEE AROUP INC	ENBRIDGE PIPELINES INC	700
18			- 5	•	2.23	24	25	26	`	28	29	9			25	t C

Managing Pipeline Integrity: Regulatory Developments April 10, 2001 1:30 p.m. - 5:00 p.m.

	nadura 20		con May Minis	7	4	em Alle tal	WIN S	10x 15/1/16/1	San Reference	thubush,		I THE	180 M	1/	Se	September 1
	han Petro -canadade		(87) 131.7508 11 11 0 1	Winte Contraction	113 562 3702 PRICHA Cattolate Linet	glenna densona com	steve lemon egreenpiperam	thul. MANINGWUS. GUV	Rome. Sulgione & tho. gc.ca	ptrudel @ neb.gc.ca	codeb a home, com	dand-a-Past Oleman mebil, com	(805)389-7554 Thereson, Bell BHH5, COV	(408) 520-724 - 10cl - 11 Den e MSTX GUERRE	DAVE_MINDED MEAST, EMERORY ON	demis. 24day 0 Ostporace
	(403)296 4750	700 / 20	2082-180 (64)	780 907 8CAT	\$ 113 \$62 3702 P		403 260-6717	127/-1/20	25.2 E	(403) 299 2768		403 360 7359 As	(2005) 389-7554 TI	# hos 200-028 (34)		
	Henry A	DARRIC SHILM		Martin Disspace	Estendes Long	UC CLOW MACING	The Paris	NAW YOU	The Table	and the second	Dob Cale	(Javid Peser	-	CUMPRIS MAG	7-90-4	Dennis Zeder 1803-355-Color
	Jetro Canada	MPERLAL OL RESOURCES	Pombine Pretine	Nutech Inspersion	PARCHE ASSESSIONALS	Creen for INDICTIVE CIENT MACINISH 780,910,1217	Us. Minerals not Su	Transporte his Schell By and	NATIONAL ENERGY BOARD	Cost Line	Culbray P.	modules and sold modern	LEEL ACTION OF SENTINCIPLE ISELL	C. C	Mana	
32	36		38		4	42	43 4	44	45	46	47	48	49	50	51	**************************************

Banff/2001 Pipeline Workshop

Managing Pipeline Integrity: Regulatory Developments April 10, 2001 1:30 p.m. - 5:00 p.m.

Banff/2001 Pipeline Workshop

Banff/2001 Pipeline Workshop	216-3486 ibaruestast	5 ~		- 7604 HAYNOKAHINDIG	Thort weldermonkahing	with delicity of the commence		2			YOUTH R &	Eventstund Eye complete in	6701 Graene Ling	Of to de 16 Comments	403-297-3520 str. 1220	49 7244 720 839 Ustone mart	
Phone For		9/hE-912 Sd	0506 (403665-9750	76-70 (403) 716.	ho92-94(20H) 785	(180) 420-8270 (780) 420-523 4	888 612 BEX	2794 (403)293-5875		S.	6188	6.6723	403 260 6714 403 260 6701	756/ 750-7411			103-054 -123
	e Eng. 216-3485	286-3485	(and (403) 286-0606	KOCH PIPE IN ES (D) (403) 7/6- 7670 (403) 7/6- 7604	1857-41-7586		Test Charage U wATERLE SI9888778 519888 6137	National Energy Board (405)299-2794	700 955-8611	· ·	16ALS 463 357-8319	1 hourse 63.26.6783		180 420-256/	403-297-3367	MARR ASSOCIATES +44 796 8952755	ASSOCIATES 45% 5 1 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1
p.m.	on Skystone	SKYSONE ENG.	Corr Ocean	KOCH PIPEIN	KOCH APPELINES (A) PODA		740 U WAT	National En	Tuboscope		Nova CHEMIERES	ET GREENPIDE	Greenpipe	Atto Prietues	EUB		MARR ASSO
April 10, 2001 1:30 p.m 5:00 p.m.	John Baron	KELLY MABBOTT	DARYL BAXANDALL	Mac S. Hay	Macy Wasen	WAGER KRESIC	Steve Come	Nathan Len	WAVE BOOLEST		RAY JONES	SRENT STUART	Groeme King	Ben Sokal	SHU C. LEE	DEKEK STOREY	こめととに
April 10	52	53	54	55	26	57	58	59	99	91	62	63	64	65	99	<i>L</i> 9	89

Managing Pipeline Integrity: Regulatory Developments April 10, 2001 1:30 p.m. - 5:00 p.m.

(403) 199-2700 (403) 199-2700 27 Chti bhatala collicare good line, con delton grande conda Sesse lovi ofg 1 gray & leta.con 1 gray & leta.con 1 gray & leta.con 1 gray & leta.con 2 Sesse lovi ofg 2 Sesse lovi ofg 2 Sesse lovi ofg 3 of 3 - nortuno transcon 2 Selowy & the san	The state of the s		61010 95h west	MSantouder@ melo.a		malle tungho	N. T.	D		B	NO.	1 1 1 1 1 1 1 1 1 1	K	X	•	1888	4 707 A		PS		" Hall	7	2.10x 18	7	W	W. C.	K Spall	J.
299-2622 299-2622 3)512746 517-776 64-9133 517-776 71-527 440-539, 720-636 720-636	The state of the s		2021	7	Manager of the company of the state of the s		1.4: hustile		CD, Rive G	alliane-postine un			3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	V	1			1	W. C. C. W. C.	MODITARY COM	gary-norton@transconedace	Sool Saloury @ Howen		>1 mmons (a) carlysion. Co	11020wy@agut/.com	da. m. 160	1 - 100 Compres . Cle	longer (a bo con
((403) 1 (403)		4920-6032	1	(403) nan 21 Co	7,090 - Ha / COL	911-53(81203)	こくせてい ン(ないれ)	transfer from	COUNTY AND ELLINA	2011/201	780 464-9133		506/11/102	2 (2) (137 (P))	1701-110/00	780-480-939			403-517-727E	(11)	1059-062- Gz	403 920-6086	We 546219	()501000	780 980-7313	(403) 235-6400	403 728-122	しつここの
Trans Canade Prochines Un Weten Squit (algusts HILLIANCE P. DELINE CANADA TRANSLITS TRANSLITS TRANSLITS TRANSLITS TRANSLITS TOPL TOP		ranslanade lipolm				2/10/01/2	Allance Postinal		PLIPS TO THE	KEYSPAN ENERGY	CANADA	TRANSLIAS		Energy									Simmons Group ly	AlfaCAS 11-	1212-039 (280) 980-7313	Covepue Canada		
69 Staine Ashworth 70 Monica Santander 71 June Santander 72 July 1 Chiptild 73 Res Fewers 74 DELTON GRAY 75 CURTS PARKER 76 Steph Casse 77 Lind Downert 78 In Downert 79 ALDO DIFLUMER! 80 Garry Norton 81 Jeth Stowny 81 Jeth Stowny 82 DaveToporowsky 83 Lemmen Lexing	-	1. 1. 2. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.		" Ionica Cantarder		-	1,						·	-			LAN DOWETT	ALDO N.C. Inc.	14 JUN 19 00 1	Garry Norton	6.5	12/ Mar 1 11/12	LAVET Operowsky	LEWIND LIZAN	1,0,7	Jen Jour (1	506 Longmi	The state of the s

Managing Pipeline Integrity: Regulatory Developments April 10, 2001 1:30 p.m. - 5:00 p.m.

Ex TREVENS	Bradework Gr. 63	403-202-2060	403-247-8825	ptaenns etalspur
SORT DHINEN	45 VENTURES LAD 403 68 8412	1 1	ina; le telusplanet. net	
Herr	BRUER Ans	\sim		
Bran Coven	WESTLOOST ENERGY	htss 893.457	progenence	The second secon
	GERPE CAMADA	78-447-4565	doing doin a compro. Cu	Graffeth
	ENGULE CONSUMABION	411-495-6332	george. Mocint le ege, entribles. com	D.K.
Coney Gowlet	Trans Consda Pipeling 403-920-6025	3 403-920-60 25	403-420-2343	comy-goulet
Jenny Jackman	CANMET - MR	- MT2 613.995.8248	613.992.8735	Jackman@ NRCan ac. ca
	National Frangy Exard (403) 299-2762	(fes) 299 - 2762	(403) 292-5503	mhowingbyc.ca
THE PARTY OF THE P	TIC	416 482-3421	446148222 Canada Co	1/1/1/
	EXXONHOBIC CAMADA	(403) 260,779	Poter_M_manucoco o order	
BURKE DELANTY	SE TECHNOLOGIES	(40) 250 - 7041	176-357 (304)	1, 0,10
Catherine Aneau			***************************************	Catherine - pineaul
ROBERT LAZOR	Flet Tahnalogy Ltd. 780-465-0077 780-465-0035	180-465-0077		Mazora Fleetech.com
Brant most	AEUS	280-542-5183	780-542-5182 Servie Prot DEUB. ab. ch.	


Managing Pipeline Integrity: Regulatory Developments

April 10, 2001 1:30 p.m. - 5:00 p.m.

(463) 235-1650 maury dumba Opsitive projects com m.L. has 900 654 (reno-subraye hous condia "ican Minerals Management Servic 907-346-1633 Dennis. Hinnah Cymms gov My 780 468 3019 BSIMMONS @ RTDDUALITY.COM MO COMMITY SEVICES (280)440-6600 Offichault@rtdquality.com 780 420-7581 bon, 50 Kol @ otco 1.40 1.40. com (403)2020548 CSMALLMAN @HOWLON (403) 350-1770 Tim. hetu Obakerathus com 403 260 6714 gravemeking agreenple con (403) 547-7186 Agastite @ telusplant.net 250-960-2022 ebatchelor (2) were ory baden awei ang Fleet Tahuelogy Ltd. 613 542-2830 | beavuil of fleetal. com Neo (of the Engineering 403-531-1926 allangue ocorr. Com 405-297-3367 shuler@gor. ab. ca shamus@hmpsi.com (bod) 691-527 | Squise Ever, 0.9 604-869.55744 HUNTER MYDAINEL PIRELING SOR. 940. 888-1 WESTCOOKST ENVERBUY. BAKER ATLAS Postive Projects RTD QUALITY SEEN. TG ENG. Aten Prolines Greenbipe 797 60B る研 IND & SMALLMAN KNORE MATRAUNT AME GERUTZ Kena Sahirey ERAGL BATCHELLOR Hope Gosse SHU C. LEE Allan Bowners Maury Dunba BRION CROSEN Shamus MEDONNEY Graeme King Dennis Hinnah 30B SIMMONIS Bon Sokat Blair Carrell Tim HEZZ

Managing Pipeline Integrity: Regulatory Developments April 10, 2001 1:30 p.m. - 5:00 p.m.

Jabes @ cepa		TO THE THE PARTY OF THE PARTY O			The demonstration of the desired property of the desir					THE CONTRACTOR OF THE CONTRACTOR AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION ADMINISTRATION AND ADMINISTRATION ADMINISTRATIO					
403 2218779 403 221 8760									1						
pr 1 22 1 24	2433.602.6048	250-940-302	P\$ (48 m m m m m m m m m m m m m m m m m m	e projektivina menemen je projektiva projektiva menemen kalaman je projektiva je projektiva projektiva projekti	The second secon	No. Control and the second			er e			The state of the s	NVO	And the control of th	The second secon
Canadian Energy PIDELLING ASSE.															The state of the s
JALE ABES	Circling Smallman	Errol Batchelor						1910 - 19							
10 A			A consequence of the consequence				***************************************	A CAN-Lamings Lip (1941), J A Cambridge and Applicate Lip (1942) on	***************************************	11 YAM AN ANIMAL TANAN ANAMA ANIMA	AAAA III II I			e company and the statement is assumed a statement of the	





A Summary of the Key Issues Developed During Session 1

- Regulatory issues
- require independence and transparency
- Must ensure compliance through enforcement
- Financial constraints
 - on industry, on regulators, on public
- Communication problems
 - performance statistics, regulator communication, industry communication
- Standards
 - development, requirements, involvement

April 9-12, 2001

Sand 2001 Proping Workship



Working Group 2 - Regulatory Developments

- Theme: Aging Pipelines are Unsafe
- Two Presentations:
 - Roy Baguley Aging Pipelines A Landowner Viewpoint
 - Mike Hallihan Aging Pipeline Systems
- Viewpoints:
 - Pipeline Reliability Declines with Age
 - Pipelines Are Safe Indefinitely if Maintained

April 4-12, 2001

Banif 2001 Pipeline Workshop



Possible Solutions

- Regulatory Solutions:
 - need strong independent presence, with immediate action & investigation of major incidents
 - Industry and regulators set benchmarks for acceptable level of performance and develop a ranking system
- Financial Solutions:
 - Consider WCB model more leaks equates to more costs (higher levy or fines)
 - Reduce risk to a level at which increased maintenance expenditure would not result in further reduced risk

April 9-12, 2001



Sample of Comments Received During the Session

- Regulators do not operate independently, are too friendly to industry, act more as mediators than regulators, and don't act on issues until pressured by the public
- There was much discussion on how the pipeline industry is perceived against other transportation, such as airline or rail travel, where regulation is perceived to be very strict
- Media has strongly influenced the public perception
- A variety of financial concerns have influence
- Standards are perceived as being inadequate or inadequately enforced
- Regulators should establish performance measures and hold the companies accountable through penalties



Possible Solutions

- Communication Solutions:
 - Have CAPP and CEPA promote the industry
 - More careful reporting of failure statistics
 - Use Risk assessment to evaluate, not to communicate
- Proactive regional communication programs (SPOG)
- Standards / Regulations Solutions:
- improve inspection and enforcement rather than build more regulation (meaningful regulations, meaningfully enforced)
- CSA develop appropriate standards, regulators enforce them, industry must develop appropriate practices

Sanf 2001 Pipulna Warkshop

Working Group 3: Upstream Pipelines Inspection, Corrosion and Integrity Management

Wednesday, April 11, 2001, at 8:30 a.m.

Chairmen:

- Reg MacDonald
- Dave Kwas
- Alan Miller

Rapporteur's Report

Reg MacDonald welcomed the attendees and presented the highlights from previous Pipeline workshops.

The key outcomes from previous workshops are summarized as follows:

- Banff 99: Advance techniques for corrosion monitoring
- Banff 97: An industry consortium to predict internal pitting corrosion of multi phase pipeline (due to finish in 6-8 months time)
- Banff 95: Risk assessment (More companies are performing it now)
- Banff 93: Laboratory methodologies for corrosion inhibitor evaluation (The outcome of a joint industry consortium formed that the basis of an ASTM Standard, that is expected soon)
- The industry is changing as a result of the Banff Pipeline Workshop.

Reg also noted that in the Banff '99 workshop, upstream pipeline had one session, but in Banff 2001, we have one full day to discuss the upstream pipeline issues.

He concluded that the success is due to the fact that the people attending the workshop will be able to take home some values that will help to perform the work better.

Bernie Frost presented the Regulator's perspective - "An Action Plan for 2000 - 2004"

To a question as to how many companies do not have corrosion mitigation program, Bernie answered that about 50-60% have mitigation program, but not necessarily monitoring.

He noted that in the past there were no penalties for non-compliance, but penalties may come in the future.

Bernie further informed that the EUB direction on consequence is expected in fall, 2000. He categorized three levels and presented the details on actions items and consequence in each category:

- Minor Levels (1, 2, 3, and 4)
- Major Levels (1, 2, 3, and 4)
- Serious Level
- The category will be "minor" if mitigation is in place, but not properly operated.
- The EUB is producing a "Frontline Stakeholder Awareness Corrosion Guide" and enforcement action.

The issue of training the inspectors was discussed at length. The Department of Transport, U.S.A., is taking training seriously.

In Canada, the personnel dealing with sour gas are trained, but not necessarily those involved in crude or water lines.

Keith Cartmell presented data on the pipeline failures in Alberta.

He advised that the majority of the 852 failures are on natural gas (30%), oil emulsion (22%) and salt water (9%).

The major cause is INTERNAL CORROSION.

One graph describing the total number of failures over the years showed an increasing trend, while another graph showed that the number of failures remained flat. It was observed that a detailed analysis should be performed on the data before any meaningful conclusions can be drawn.

The majority of the failures are occurring on 6" pipelines.

The EUB regularly produces a report on pipeline failures. The most recent report was released in December 1998. Detailed data on the pipeline failures in Alberta are available in the EUB Report 98-G, December 1998.

<u>Ian Scott presented "Upstream Pipelines: Inspection, Corrosion and Integrity Management" (Consequences of Pipeline Failures)</u>

He advised that a CAPP Task Group is working on this issue. He advised that this effort is coordinated with CEPA, EUB, NEB and non-government organizations).

The consequence of pipeline failures can be classified into low, medium high.

There is a memorandum of understanding between CAPP and Alberta Environment. CAPP is also soliciting comments from the APESC Committee. The plan is to have a "1-Year Pilot Project"

To a question, Ian advised that, based on the previous year's data, most of the consequences are classified between low to medium. Very few consequences are high.

The Public does not care about the volume of spills but rather they are concerned about the number of spills.

The issue of training of operators was discussed.

With Regard to the Need For An Internal Corrosion Management Program

- There should be a good Internal Corrosion Management Program in place.
- The Producers should meet to set practices and/or guidelines for field operators.
- Industry should move to a pro-active state from the reactive state.
- In many cases the program is in place, but not applied properly.
- The industry should obtain self-auditing status.
- The issue of larger vs. smaller companies was discussed.
- There should be a minimum set practice.
- There is a CAPP Pipeline Technical Committee for CAPP members.
- There should be a sponsoring organization, e.g., CAPP to develop and maintain the document on corrosion management.
- Such a document can be first developed by CAPP, and could be moved to CSA.
- Relatively few upstream personnel are on CSA committees.
- The CSA Production Subcommittee is searching for members. Without improved interest, the Subcommittee may be disbanded.
- Similar documents from others (e.g., DAOAC) can be used as a guide.
- At present producers are in charge and they develop corrosion control practices. The EUB may review them.
- The issue of accepting a standard was discussed. It is observed that the standard should be considered as minimum guideline.
- To a question on the current level of inspection of failures the EUB advised that the about 90% have been inspected. The reports of these inspections are being prepared. The intention is to complete the inspection and report in all cases.

James Ferguson presented "A Framework for Integrity Management for Internal Pipeline Corrosion"

How many companies are going beyond the EUB requirements on integrity management? A show of hands indicated that about 10 companies that were represented at the session go beyond the EUB requirements.

The guidelines do not go far enough; therefore it is necessary to go further on integrity management.

What are the different standards available on integrity management?

U.S. regulatory requirements (API) are being produced.

CSA Z662.99 has a non-mandatory clause on risk assessment.

Can regulatory standards be used for integrity management?

Risk control is presently out of the scope of the CSA Z 662.99 appendix on risk assessment.

Industry, the regulator, and the public have different perspectives on risk.

Can predictive models play a role in integrity management? Models are a less concrete rule, but can be used as a factor that contribute to corrosion mitigation and to rank the system appropriately.

The issue of Risk Management vs. Frequency Management was discussed.

In any management, the public perception should be taken into consideration. The Public should be involved in risk

There is a Federal initiative on green gas emission

There is no hard science to back up the low, medium, and high classification of risk.

Does the board ask for risk assessment? Should risk assessment be there as a part of integrity planning? The companies will choose the plan.

The CSA standard is only a tool, not necessarily the integrity management program.

The issue of corrosion monitoring should be dealt within the CSA document.

Colin McGovern presented the "Integrity Management of Acquired Pipeline System"

He noted that there should be a focus on integrity management.

It is necessary to transfer the knowledge to an operations team.

Typically a 4 hours course/discussion on a regular basis helps in the company.

Pitting corrosion is the cause of major failures.

To a question, Colin answered that there is no set budget for corrosion management.

The cost of inspection should be compared with the cost of replacement.

There are instances that the failures can be associated with the management change.

In some instances, the static state (when the pipeline is not operating) corrosion rate is high.

In some cases, we do not react quickly.

Real time corrosion monitoring will be beneficial.

Risk assessment is only a part of Integrity management.

We can learn from other programs, e.g., the management of pressure vessels and related equipment (in Alberta – the ABSA programs).

If a company chooses to excavate pipeline locations, and show that the pipeline is in good shape, is it enough for the board?

Is digging a good method to show pipeline integrity?

An internal corrosion control program is based on science, mathematics, physics, and chemistry. Therefore it should undergo engineering scrutiny. It should be involve a professional engineer.

A detailed technical assessment is carried out before a digging operation is carried out. The technical assessment may include modeling and/or in-line inspection etc. But in many cases digging is the only way to obtain information on pipeline integrity.

How many digs do you need? It is a far-reaching question.

Alan Miller presented "PanCanadian Pipeline Risk Assessment Challenges for the Industry"

He noted that CSA standard is only a direction, not a plan.

The difficulties include:

- Probability of failure the most difficult to quantify
- Location of next failure
- Modeling vs. Inspection

Asset inventory management resources are allocated on a consequence basis - not necessarily devoted to the numbers of incidents.

He noted that the probability of pit initiation might be associated to the probability of the presence of inclusions.

There are instances where the locations were predicted by flow models to be potential locations for corrosion - the pipeline was clear and vice versa.

Flow models are not reliable.

Corrosion was observed on the downhill section of pipelines.

Owner/user system is acceptable. But in order to be useful, a recognized organization such as CAPP should lead the initiative.

How should we decide to run the next risk assessment program?

Will there be an operating envelope?

There should be a red flag, (i.e., if the operating conditions change, a risk assessment should automatically be carried out).

There is generally a procedure that is followed for line suspension.

It will be appropriate to run the flow models to predict "what if" questions.

There should be a set range in which the pipeline should be operated.

Flow modeling is good for gas condensate but needs improvement to include oil properties.

How can one delegate responsibility within a company?

Where is the priority? High-risk areas or high-consequence areas?

Risk Assessment programs are run frequently, but it is difficult to catch the production changes in between the

There are techniques available for automation.

Flow models can be accurate.

If somebody constructs a house near the pipeline, does the risk assessment change?

Not all upstream owners are present in this workshop. More participation is required in the future.

Dave Kwas presented an overview on, "Challenges by Small Diameter Pipelines to Inline Inspection

In crude laterals, microbiologically influenced corrosion is a problem.

There are some unexplained internal corrosion problems.

In some cases, the monitoring methods have failed.

In one instance, the cost due to a failure is as high as \$ 28 million. This cost does not include long term as well as indirect costs.

Public perception adds to the cost. Credibility is an issue.

MIC is an issue. Pit growth modeling is useful.

Karol Szklarz presented, "Inspection of Wet Sour Gas Pipelines"

In general, only the deepest pit per joint is analyzed from the ILI result. It is possible to obtain information on all

If there are a large number of pits, the ILI may miss individual pits. Which pits are missed - the deepest or the

Sometimes the ILI indicates pits, but actual digging indicates no pits.

Weld beads can cause dead zones.

It is necessary that the ILI run does not disturb the scale that protects the pipeline. There were some instances where active corrosion was observed after the ILI run.

Inclusions can cause false information.

There is a need to increase the resolution of the ILI tool.

ILI is relatively easy to run in a liquid pipe, due to the velocity effect.

There is no experimental flow loop in Canada to test ILI tools.

Alan Miller presented, "Shallow Gas Pipeline Corrosion and Corrosion Control Strategy"

Condensed water does not lead to localized corrosion, but produced water leads to corrosion.

A 2-inch inspection tool not available.

Smaller pinhole leaks is the cause of many pipeline failures.

Failures generally occur at the first uphill rise.

Sands and clays are the main cause

How much of the gas is lost? Sometimes the leak goes undetected for about 6 months.

Can't use continuous inhibitor due to the location of the pipes.


Greenhouse gas is an issue.

Main Issues and Ideas

- The session was well attended, there was a good mix of people (producers, transmission, regulators, consultants, and others) ~ 100 attendees
- Ranking of spills
- Public perception that the pipelines are not safe
- Internal corrosion
 - o sweet
 - o sour
 - o oil-emulsion
- No standard method for corrosion monitoring
- Role of flow modeling in the pipeline integrity program.
- Training and accreditation program for field operators/inspectors (is required?)
- Internal corrosion monitoring program
 - o Guidelines needed (many companies will be interested)
 - o Program should not only be developed, but should be used
- How to set a minimum pipeline integrity program
- Many times the integrity program is cost driven, not necessarily safety driven
- Sponsoring organization to look into the internal corrosion monitoring program
- CSA committees not much representation from producers
- ILI program
 - o tool/sensor failure
 - o speed problem
 - o still conservative
 - better length determination
 - o use in liquid vs. gas pipeline.
- Industry should lead the way in establishing the internal corrosion control program
- Automation of corrosion monitoring/risk assessment
- Digging frequency
- Inspection tool for 2" pipelines

Main Outcomes

- A group was established to work on an Integrity Management program.
- Champions were identified.
- The Goal is to share the best practices.
- There will be a Task Force within CAPP.



Working Group 3: UPSTREAM PIPELINES Co-Chairs: Dave Kwas (Pembina),Reg MacDonald

p-Chairs: Dave Kwas (Pembina),Reg MacDonal (ExxonMobil), Alan Miller(PanCanadian)

April 3-12, 200

Berell 2001 Pipeline Warkshop



2001 Upstream Pipelines Today's Guide

- "What's the Problem?" 8.30-10.00
 - Current issues facing upstream PL's and downstream crude laterals
- "How do we manage this?" 10,30-12,00
 - What is the right approach to integrity management?
- "How do we find it?" 1.30-3.00
- Inspection in small diameter pipe containing various substances and suffering various forms of damage is a challenge
- Other I time required 3.30-5.00
- "What can we do here today which will help me tomorrow?"

April 5-12, 200

Bard 2001 Peptina Washphay

Slide



2001 Upstream Pipelines Desirable Outcomes - #1

- Identify specific problem areas so as to bring interested parties together to devise ways to minimize the problem(s).
- CSA Z662's Appendix on RA Does Industry use it? How to apply it? Should it be modified? How to encourage a standard?
- "Pipeline Quality Management Programs" Owner/User system acceptable? Should there be a group, CAPP or other, promoting this? Can an upstream producer earn a self-auditing status?

April 8-12, 2001

Berd 2001 Pipeline Warkshop

Slige :



2001 Upstream Pipelines Desirable Outcomes - #2

- Develop tools and practices to improve accuracy in small diameter inspection tools. Form a group to pursue improvements to accuracy in these tools.
- Define what Industry and Regulators find as acceptable inspection technologies for various forms of pipeline damage.
- What is an acceptable alternative to assessing integrity when Upstream Industry cannot justify an ILI or installation of corrosion resistant lining?
- Develop a decision tree for inspection Technologies for Upstream Pipelines.

April 8-12, 2001

Banf 2001 Pleating Workshop

St. .



1999 Working Group 4B: "Risk Management/Internal Corrosion Producers"

- Single session for Producers discussed risk management, relationships with regulators, predictive models, and field monitoring.
- New technologies are required for monitoring internal corrosion andeffectiveness of inhilitors with a focus on cost-effectively increasing theares of coverage of corrosion monitoring tools.
- Performance metrics need to include a measure of the consequence.
- The consequence side of tak should be more actively considered and included in the measure of performance.

April 9-12, 2001

Banif 2001 Pipaline Workshop

Sice 6



Progress from Earlier Pipeline Workshops

- '99 WS: CAPP/EUB task force working on a system for reporting of safety and environmental of consequences into the spill report forms. - progress report in this program
- '99 WS: New corrosion monitoring techniques are being used by a few, le; electrochemical noise, FSM's, flushmounted coupons, etc.
- '95 WS: Risk Assessment became more common
- 93 WS; CANMET Laboratory Test Method for CI selection in Sour Service
- Conclusion: Industry is changing as a result of the Banff Pipeline Workshop

April 6-12, 2001

Sant 2001 Pipeline Workshop

Single :



How we got started

- The Banff Pipeline conferences have provided an opportunity for people to meet and share ideas and common goals
- · Upstream pipeline risk assessment (RA) was a topic for discussion in 1995
- Few upstream companies did structured RA at that time.

April 9-12, 200

Sant 2001 Pipeline Works!

Side)



What have we accomplished

- · By 2000
 - Many companies have a RA process
 - There are numerous consulting and chemical supplier companies that can do RA for you
 - RA is non-mandatory appendix in CSA Z-662
 - There has been seminars, conferences and courses of risk assessment
- Risk Assessment is a common well understood practice in the upstream industry

April 9-12, 2001

Sanii 2001 Piyaana Warkshap

... a




Why were we successful

- This change happened because the people involved in integrity management made it happen
 - It was not driven by upper management
 - It was not driven by regulators
- During this conference we will talk about the current issues and opportunities and where we want be in the future

April 8-12, 20


Band 2001 Pipalina Worksho

Side 9





New Corrosion Monitoring Technologies Chevron Fort Liard FSM-IT Installation Used on 8" piping - Can be usedon small (2") to large



- 10 mary - 10 m

. State 11 2001 Upstream Pipelines "What's the Problem?"

- Regulator Focus and Plans Bernie Frost, EUB (10min)
- Detailed Review of Alberta's Pipeline Failures -Reg MacDonald, EMC, Keith Cartmell, BP (10min)
- Current CAPP/EUB Initiative to Add Safety and Environmental Consequences to Spill Report Forms -, Ian Scott, CAPP (10min)
- · Discussion workshop session (60min)

Am 9-12, 2001 What are the challings in 1055 22 PC operation loday?

56de 12



2001 Upstream Pipelines "What's the Problem?"


- Third Party hits 1st CALL, penalties for non compliance
- EC Regulatory requirement for CP, only rare disbonded coatings remain a problem, but small compared to IC
- IC no "direct" regulatory requirement, how to enforce proper CI selection and application, inspection, then eventual replacement?


"is the technology to combat IC adequate but not being used, or is the technology inadequate to do the job?"


April 6-12, 2001

Banf 2001 Pepalina Workshop

Since 13









Operations inspections

- Each Field Center to conduct pipeline operations inspections on multi-licensed systems, on 8 companies, that meet the following criteria:
 - Operators with high failure frequency.
 - Operators with questionable performance;
 - Operators of main trunk line systems.
 - Conduct two provincial pipeline operations inspections based on criteria mentioned above.

April 9-12, 200

Benil 2001 Pipalina Warisha

State 10



Third Party Damage Investigations

- Investigate 100% of 3rd party damage incidents.
- Investigate causes/trends of 3rd party damage incidents and recommend strategies to reduce the number.

April 6-12, 2001

Barell 2001 Handay Manager



Improve Industry and Public Awareness of Hazards Excavating near Pipelines

- Conduct 3rd party damage presentations to operators, contractors and public for education and awareness purpose
- Encourage operators/contractors to obtain ground disturbance certification.

April 9-12, 2001

Sand 2001 Pipeline Westelle

Sindo 18




FAILURE INCIDENTS


- Track increase/decrease in failures
- Track overall failure incidents compared to total pipeline lengths
- Analysis of historical data for failure frequency per 1000 kilometer indicates a 35% reduction over the past 11 years


April 8-12, 2001


Sanff 2001 Pipulina Workshop

3444 E











FAILURES BY CAUSE

- Internal corrosion failures increased 5% in the past year.
- Sensitive leak detection equipment has enabled industry to locate minor leaks that previously went undetected for longer periods of time.
- External corrosion failures are lower than historical.
- Third party damage (hits) are higher than historical.
- Construction damage failures are slightly higher
 Than historical.




FAILURES BY CAUSE

- Joint failures are higher than historical, however this infrastructure is increasing as non-metallic and coated pipe is being used more frequently to prevent internal corrosion
- · Weld failures are lower than historical
- Over pressure failures are lower, due to more sensitive shut-in equipment being developed.
- Pipe failures are down as manufacturing improves.
- Valves and fitting failures are down as manufacturing improves
- Other failures are up due to failures not being dug up to determine failure cause.

AME & 12, 2001

Bank 2001 Pipalma Wartston

\$1460 ZŠ






DAMAGE BY OTHERS GRAPH

- This graph indicates a historic view of the number of pipelines hit each year
- The Oil and Gas industry is the leader in contact damage to pipelines at 80%, landowners and other construction activities account for the other 20%

Aws & 12, 2001

Seed 2004 Name to the contract of the contract

Stiele 27





FRONTLINE STAKEHOLDER AWARENESS CORROSION GUIDE

- EUB staff have developed a Corrosion Gide for use by Field Surveillance inspectors to effectivelyand consistently address corrosion faiures.
- Enforcement action has been developed teleal with industry when a corrosion failure occurs. "U" minor "M" major "S" serious.

April 9-12, 2001

bank 2001 Pipalina Wartshap

4244-20



CORROSION INSPECTION SUMMARY

- Our action plan dictates all corrosion failures be addressed. The companies mitigationplans documentinghow they will prevent further corrosion failures must be reviewed and evaluated. These follow-up reviews/evaluations may take placewithin 12 months of the occurrence.
- When a failure occurs the companywill be instructed to look at the mitigation program of the faled pipeline and the rest of thepipeline system.
- All systems operating underEU8 jurisdiction not monitoeng for corrosion potential shall be subject to the EUB's escalating consequences of enforcement action as outlineds IL.99-4.

April 9-12, 3001

Band 2001 Pipatine Wasterne

S**** 30




Closing

- The direction Field Surveillance Branch is taking as you can see by our operating plan for 2001-2004, pipeline corrosion failures and pipeline integrity is our number one goal.
- We appreciate the opportunity to attend the Banff/2001 Pipeline Workshop and the opportunity to give industry an idea of where we're heading as a regulatory board.
- Thank you and enjoy the rest of the workshop.

April 8-12, 2001

benf 2001 Pipulina Werteburg

Sheka 31



Presentation to 2001 Banff Pipeline Integrity Workshop Group3

"Upstream Pipelines: Inspection, Corrosion and Integrity Management"


April 11, 2001

Ian Scott

Manager


Northern Canada and Pipelines


CAPP




Historical Perspective - Workshops • First June 1993 Pipeline Lifeline Second June 1994 Pipeline Lifecycle Third October 1995 Managing P/L Integrity Fourth April 1997 Managing P/L Integrity, Planning for the Future • Fifth Managing P/L Integrity, April 1999 Technologies for the New Millenium Sixth April 2001 Managing P/L Integrity, A Workshop for Sharing Technology and CAPP Experience

Consequence of P/L Failures - Objectives • Develop EUB IL which defines - Minor, moderate & severe p/l failures - environmental damage/impact - public safety • Revise EUB Incident report form - environment - safety • address w's p/ls initially








Consequence of P/L Failures - Next Steps

- Task Force soliciting comments
 - EUB & NEB
 - CEPA
 - APESC
- EUB/Industry to pilot "system" for one year
- Review with NGOs
- Amend as necessary
- EUB issue Interim Directive apply all releases
 - Pipeline Act
 - Oil And Gas Conservation Act.

CAPP

Consequences of Pipeline Failures Definitions - Environmental

- - requires short-term remed
 - untikely to decrease wildlife populations or habitat
 - surface water & designated/locally important areas not affected by the release
- - may have affected wildlife habitat but are unlikely to decrease populations



Banff Pipeline Workshop April 11, 2001

Framework for Integrity Management of Internal Pipeline Corrosion

James Ferguson
CorrosionWATCH Inc.

Agenda

- Integrity Management Background
- Integrity Management Today
- Application of CSA Z662-99 Risk Management to Integrity Management
 - Definition of Terms
 - The Process of Risk Management
 - Frequency Analysis
- Summary

Integrity Management Background

"Federal regulations and industry safety codes and recommended practices provide guidelines for the safe design, operation and maintenance of pipelines, but pipeline operators still have to continually monitor and assess the condition of their pipelines to prevent them from being seriously degraded by things like corrosion, damage from outside forces, which includes excavating equipment, and operational wear and tear."

-- Dr. John F Kletner, NTSB Pipeline Safety Hearing, Washington, DC on Nov 15, 2000

Integrity Management Today

- Upcoming US regulatory requirement
 - API Standard 1160 'Managing Pipeline System Integrity' (in progress)
 - New OPS rule requiring integrity management programs expected in Oct 2001 (OPS is the DOT Office of Pipeline Safety)
- Non-mandatory guideline in EUB ID 99-7
 - CSA Z662-99 includes 'Guideline for Risk Assessment of Pipelines'
- NEB Onshore Pipeline Regulations, 1999
 - Section 40. 'A company shall develop a pipeline integrity management program'
 - Non-compulsory guidelines

Application of CSA Z662-99 Risk Management Process to Integrity Management

Definition of Terms

- From CSA 2662-69, B3.1

Risk management - the integrated process of risk assessment and risk control.

Risk assessment - the process of risk analysis and risk evaluation.

Risk analysis - the use of available information to estimate the risk, arising from hazards, to individuals or populations, property, or the environment.


Risk estimation - the process of combining the results of frequency and consequence analysis to produce a measure of the level of risk being analyzed

Risk evaluation - the process of judging the significance of the absolute or relative values of the estimated risk, including the identification and evaluation of options for managing risk.

Risk control - the process of decision-making for managing risk, and the related implementation, communication, and monitoring activities required to ensure the continuing effectiveness of the risk management process.

The Process of Risk Management

- From CSA 2662-09, Appendix B





Frequency Analysis for Internal Corrosion Integrity Management


- Use qualitative measurement for frequency analysis
 - Apply "Judgement of experienced and qualified engineering and operating personnel, based on known conditions."
 From CSA 266249, E5.2.4.2(d)
- Rational:
 - Conditions that lead to internal corrosion of pipelines can be identified and ranked using scientific models based on available data of material properties, product composition, and process conditions


Summary


- Regulation of Integrity Management is approaching
- CSA Z662-99 Risk Management process framework can be used to manage internal pipeline corrosion


















































		tellommentellimintalisissi (1945) epitellisissi.
		e e
		- POST CONTRACTOR CONT
		3000 Symmetry states
		endaliseivoise
		ēdosejā, viņa ir
		indologija dang
		North Control
		riviilihani eöiketa
		парабую в дамон.
		destangentish
		Mini-fraktyn (Under
		võid de en
		resolutional despendant
		NAN 4 0-0-7 ZA ALIGAN
		1. Constitution of the con
		Military





PanCanadian Pipeline Risk Assessment Challenges for the Industry


- Probability of failure the most difficult to quantify
- · Location of the next failure
- Modeling versus inspection
- Asset Inventory Management
- Resources allocated on consequence basis not necessarily devoted to numbers of incidents


April 8-12, 2001 Banff 2001 Pipeline World


Sindle 51






































OWNER/USER AUDIT

- "Pipeline Quality Management Programs"
- Owner/User system acceptable?
 Should there be a group, CAPP or other industry group, promoting this? Can an upstream producer earn a self – auditing status?

April 9-12, 2001

Senf 2001 Pipeline Worksho

Slide 8






PanCanadian Pipeline Risk Assessment Issues for Discussion

- Resources should be allocated on consequence basis not necessarily devoted to numbers of incidents..or both?
- How often should we be repeating RA's?
- Suggestions for managing large asset inventories?
- Define A,B,C, and D (Probability in Risk Matrix)
- Industry managed Pipeline Quality Management Programs

April 9-12, 2001

Sanff 2001 Pinatina Woman

Sinte 87





Presenters

- Dave Kwas Pembina Crude Laterals
- Karol Szklarz Shell Sour Gas Pipelines
- Alan Miller PanCanadian Oilwell Effluent Pipelines
 Shallow Gas Pipelines

April 8-12, 2001

Banif 2001 Pipeline Werkshop



Getting Started

- Probability of failure x impact of failure
- As pipeline service increases, probability of failures due to corrosion increases
- Are there any corrosion defects present?
- After inspection, what causes risk to be reduced?
- When to re-inspect?

April 6-12, 200

Sanff 2001 Pipeline Workshop

Skde 70



Crude Laterals - Pembina Pipeline Corporation

- 4400 km. (52%) are less than 10" in diameter
- Various operating / corrosion challenges
- Pipeline Operators' priorities
- Bottom line

April 8-12, 2001

Burd 2001 Pipeline Wartshap

State 7 ;



History

- Aerial / ground patrols, geotechnical, leak surveys third party damage ground movement leakage
- Smart tool logging, CP/coating surveys, product quality materials / construction defects coatings fatigue / cracking
 - internal / external corrosion
- Corrosion monitoring methods for the most part failed

April 9-17, 2001

Band 3001 Pipelina Workshop



Integrity Maintenance

- No leak objective
- Periodic internal inspections
- Defect assessment using fitness for purpose criteria
- Selective repairs
- Data management

April #-12, 200

Benf 2001 Pipeline Workshop



Conclusion

- · Smart tool accuracy
- · Risk of leaving defect in the pipeline
- · Rate of defect growth
- All must be considered when making pipeline repairs

April 1-12, 2001

Sout 2001 Pipeline Workshop



What's Next

- Other cost effective ways of determining integrity of a short, small diameter pipeline
- When are digs absolutely necessary
- Is corrosion growth / life prediction models next?
- · Where is internal logging headed?

April 4-12, 3001

and 2001 Planting Workshop



INSPECTION OF WET SOUR GAS PIPELINES

Karol E. Szklarz Shell Canada Limited

Prepared for Banff 2001 Pipeline Workshop

CURRENT SITUATION

- · Almost exclusively mag flux leakage (MFL)
- Low to medium resolution tools for internal/external corrosion pit depths
- · Conducted as frequency- or condition-based
- Cornerstone of pipeline integrity programs (proactive & reactive)

CURRENT SITUATION (cont'd)

- · Run reliability (with no problems) is 70%+
- Medium resolution ~ +/- 10% of wall thickness for "normal" aspect ratio
- Otherwise resolution is +/- 20% of wall
- Data is electronic and hardcopy; hardcopy still used a lot
- Reasonable local supply of contractors

ISSUES

- Tool/sensor failures and speed problems are still significant
- Where pits are more numerous can miss individual pits
- · Ghost pits
- Weld beads can cause small "dead zone"

ISSUES (cont'd)

- Length and width measurements are still very conservative leading to conservative strength assessments
- Can cause initiation of corrosion by removing protective scales (need batch inhibitor)
- Still need dig RT/UT data to "calibrate" run
- · No crack detection capability

FUTURE


- · increased reliability in data collection
- Better software to analyze all pits above a threshold deep (underway)
- · Higher resolution tools
- Better length determination so that realistic pit interaction assessments can be done (underway)
- Calibration by pull through on all pipe OD/ thickness combinations (underway)
- New tools for finding and sizing cracks


4


Î




Internal Corrosion Initiated at Wheel Tracks Made by In-Line Inspection Tool













Location Test	Contenzaci Potime	Sellyfliver Foremost	Sest? me	Madeini	Mak Runts	Belly River	Medicine Kat	Second Whatspeck
120	2.1	15200	5220	5410	1810	8115	8810	1:000
PC02, %	ā. i. cisti	0,35	3.2	<u> </u>	\$,1	2.25	0,1	0,08
oczisot Comosion (0-1)	2	0.64	5.55	0.701	5.11	1.28	\$. †	0.51
General Corresion mov	نسند ڈۂ		2.2	2.6	3.9	ź.,		4,5


























Pipeline Corrosion Control Options Case Description Repair and Replace over time Mechanical Pig Equipment Chemical Pig 2"/mechanical pig group flowlines Chemical Clean 2", Install Wellsite flowdrips at siphon string wells HDPE Liners or FibreSpar (FRP reinforced, HDPE Liners)









Banff 2001 Workshop Working Group 3


06-26-013-08W4 Flowline Leak Site




06-32-013-08W4 Flowline Leak Site



06-07-013-08W4 Flowline Leak Repair



13-29-013-08W4 Flowline Leak Repair Site



Banff/2001 Pipeline Worksh. Managiny ripeline Integrity: Upstream Pipelines: Inspection, Corrosion & Integrity Management April 11, 2001 8:30 a.m. - 5:00 p.m.

æ	ſ		T	(Ja		9	19	 :		X		T	- T	······································		. .T					· · ·	-		
ALCALO A CINCAL		Signature	I Like	to lan	11011	6, ca / Un brain	Len Januar	Ψ.,	X)	SA CORPUTE	VEM (al)		The Contract	Day D	C R			1.				The Ma	が、地	Herry
	E-mail	(403) 233-2601 tdare Democraci	THE THE PRINCE OF THE CO.	poonellepembing con	340 5419 (ON) 11 = 1	THE KIESTIONIA (a) gov, a	Barti leonarde en govalica	CENT VAN CGALLY 405-476-5873 Treat-120-641066 transmile un	1-703-787 1580 Cahast 6 111 a	THE THE MINE YOU	1107-1666 1901. MANAIN COMMS, COV	dhwas @ Pambina con		bshapke (c) + Elismen - energy . Con	maury dunba Opositive griate	Lightsian	be grany & Bathreporch Con	geny Wilkinson Elbsitions into 10		oternor 60 to Link	the state of the s	Too) TIG- TOTO HAYN @ FMDUISION.COM	grant fiethe comporce	Kuralbott @ SKYS rove, ca
, a	Fhone	(403) 233-2601	76. 64.	1/35 - 234/	403 340 5429	780.460.3806		+ CL35-44-5013 4	2 08 81 787 507-1	, col aso (60b)	1 291.101.1.	8054-122 (cm)			(403)231-1650 ma			(403) 235-1650 pm		(401)202-2061.	} -	(tes) +16-+6-+0 HA	(78c) 447-4565 gr	403 216-3485 K
Name		IRBUR PIAGE	Por Samery		ROW CHMALKSWOATH	FARL LEONARD	13 1000			PAUL 8 MALL	ł	Vave. BWHI	1. 21. H. D	2000	Mainy Dunda	LE GRAMA			Jean of Long	15.21				REKELLY MINESOII
Company		CORROSION JENVICE	1 Tolling Prance Corp	3 /// 4		508		6 5.5.	7 11 5.	MinorAls Mgt. Source	8 Tentra France		1 elisman Energy		Strafall	butwe legich zw.	·····	The state of the s	14 6	Wordsing Corosi, Ca.	KOCH PIPQINIS CON	<u> </u>	17 HELLY HANGLETT	28.

Banff/2001 Pipeline Workshop Managing Pipeline Integrity: Upstream Pipelines: Inspection, Corrosion & Integrity Management April 11, 2001 8:30 a.m. - 5:00 p.m.

THE PROPERTY OF THE PROPERTY O					
18	Dering Boughen	DAAIUS BOUCHED	403.	***	The state of the s
10	AEUB	- (1)	403 297 5432	dave arzah aov. ab.co	All Metanh
20	MAY JAMBAK THU	BLUND FOMERS	Appl Circon	Jest Salada Salada Circ Call	John St.
21	ALLIANCE PIPELINE	DARYEL (SENDIANI)	780-5,8-7612	780-5/8-7612 Wondlad B. allines Con.	D. We alone
22	Cambien Honke Frankin Allen Hons	La Allen legals	780 534-8007	780 534-307 A. M. A.	2 Com
23	Minh Ho		(603) 2999-2762	Mho@neb.ac. ac	
24	LEOWARD LOZOWY		(78) 980-7313	11020Wy@agutl.com	
25	JOHN ChASE	Į.	780 436 4460	1010-0 Dunger	
26	Imperial Oil	AL FORTH	177-639-506	1 fath @ 200	Dell
27	11CI CANADA	BARRY NICHOLS	403 391-1335	Professor Com	rora.
28	+ 5		463 1510387	403 2510 387 84 Nober 115 Confliction	
58	Russell NDE Syspans	Jim WKRS	780 468 6500	Jank P. P. Wassell Feel and	
30	BAKER ATLAS	Tim HETY	49-350-1710	tim. het. @ho. he c. st.	
3.1	1/5 VENTURES LTD	DERT JOHNSON	463 688 8413	403 686 8413 (m. 1/2 tol. c. t. + + + 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2	*
32.	ALL TEST INSPECTED	Res Prette	463 362 5757	403 362 5757 royette @ telusplanet net	
33	Tuboscope	3	180.955.8611	780 955 8681 Fring & tubuscope pls abun	711
34	Kamest J RAE INSPECTON SERVICE	RECTON SERVICE	ĺ	780-699-2461 ramesh@raeinsperhan. com	18

Banff/2001 Pipeline Workshop Managins. ·ipeline Integrity: Upstream Pipelines: Inspection, ປັດເວລາດ & Integrity Management April 11, 2001 8:30 a.m. - 5:00 p.m.

1. (on	com Alutho	78/6			Car langer Bare	12/A		(8)	3	100 M	12/3/	John Mary	77.47.6			2	200		Y
403-218-8207 mark. William Oshawind. (Om	glenne densona con	780-440-939 19 my 10 kto.	day 6 her w. r. C.	damy. shuipa aid sout a		Dugper (@ bp. com	Kittelvwebp.com	Philosophy H.		12 - 20 - 8/83 Mo Hore gom ke Egreenpire con	Ken Co base line tech som 12	John Coll	Lite : 15 Tay Sules (1 Ca Pass Ma	work mails inc. foc .no. br	192. DOWSETTE RUSTUEST. COM	yean. yound dynamicrosk, net	garner meglikatte.co.n	Fc hicke Galgally your	dan. Powell@ Corrpro. ck
403-812-80h	H 280.510.1112	780-440-939 1	403 720 546 C	780-639-5813 Obr	402-255-1254			120 -383-7109 Phi	403-06-02	127 x 20 - 8 / 8 2 M C	4032663800 14	423 5722200 6				403 S47 8638 dem.	403 244 6163 garn	1 -	403-235-6400 dar
Mark William	CLENN MACINIES	LINDA GRAY	David Jan		Sob Longers	VINCE KITTELLES	ייייי אין ואביייי	Phil Guathien			15en 10x16	JAMES FEROUSON	IVAUL BOTT	TAN DOWNSET				ridge	Dan Powell
Canusa-CPS			HLI COMECCE	IMPERING OIL KESOURCES	SP Canada Emen Can Solo Longere	BI CAMAGO ENERGY (O VINCE KITTING INS 223 122			Greenpipe Widustries 1				CAMBILL UNIVERSITY CPRIO	RWDI WEST INC. I			Slope / Themsoluting (-	NAG	Lorrpro Canda Inc D
35	37	30	1	9		4	42	7.2		4	45	_	9		\$4	64			

Managing Pipeline Integrity: Upstream Pipelines: Inspection, Corrosion & Integrity Management Banff/2001 Pipeline Workshop April 11, 2001 8:30 a.m. - 5:00 p.m.

		The state of the s		4		ANCON S	126.	PST _M		1/10. P.	0 100		9,7	OFFIC	Monthe	Che The
(403) 847-71% Rgs, litz Ctobsolant	pricare & by.com	Alex Petrusev Comosin Service Gun 403) 733 -2601 anothusev & Comosingenia	Scot. Aratte has Kan of con	Mcgoue CO AxL.CC		0	barow@skystone, ca	1403/284-6550 Karol. 52Klarzastollica	alan-miller @ 20.cg	780-287-860 ale an can secon	11 Cal. J. Cal. J. Cal. Con	613-992-4252 (Deen @wcan.gr.ca	(6/3)995-3971 mallo: 10	scotte capo. co	403233 6324 CARTNIEW R. K. P. CURS	(403)503-338) chrisharhythanence
763) SH7-118	403)233.6851	1 (403) 233 - 26	(180) 871-6553	ENPOSITION (265) 732 7013	(403) 932 -83/6	(403) 2%-0606	(403) 216 3485	7557-182(101)	45)26-334	780-887-860	11 Call 2/100	2524-595-519	6137995-3971	(403)267-1132	4032336324	(882-605(80h)
JLG ENG.	BP CANADA	COMOSin Service Gu	Husky Oil	ANDORSON SVRODEN	NA0.4		13	Shell langda	1) Re	CANMET/WTL	MTL				AEC ON & GRS
LYLE GERLITZ	KAT PRICE	Alex Petruser	Scott Aradt	C. W. M. Sovern	KEN KOVACS	DAGNE BAXANDALL	John Baron		Alan Diller	4. Demoz	S. Papaving sam	Jenny Been	Mimeon ELBOUTDAIN CANMET/MTL	ian scoit	KETTH CARTMENS KI CANSOA	Chris Ho-Lotte
\$2	53	54	55	99	57	58	59	9	19	62	63	49	65	99	29	89

Banff/2001 Pipeline Workshop Managins، /ˈipeline Integrity: Upstream Pipelines: Inspection, كريتوها ه Integrity Management April 11, 2001 8:30 a.m. - 5:00 p.m.

	town		1004	A San	8		TO ACC	Zul		Maie	as de		SBANK	4	61.7	Ser	100
	4) Neorahi 10 2	apience Ofelia, Jan 1	shu. lee @ gor. ub. ca	ching agreenil,	gphipps@dniongas. co.	Zane. rembattorempro.ca	Local Entres. Mil	. or t & colfery com	utr @telusplanet.m	Coouchem.cem	stagama Campipe Con	Amalave Corempipe Com	nestler @ battalle. org	b paradis locunspecien	demis, Zaday & Carpo. Ca	jhopec @ neb. gc. ca	Mypick @ Owaterloo Ca
	48-531-1926 allan 6 Neorally 182	603-281-8627 apres	403.297.3367 Shu.	W3 260 6714 girlemelling agreenbil.	519-683-4468 aphi	(403) 255-6400 Zan	403-285 8005 JAHLINGE ZUEB. WITT	403 254-1873 horms. art @coltery com	Kours Freemuth (603) 253-0729 edelmute etelusplanet.nd	163-314-7491 galemenovachemicem	10/2010 appear	(403)260-6703 nmalla.		1) 494-3690 j	1984 888
**************************************	\$7	- Lerre					4	TAN HARMS 4	MED FREEMUTHGO	Churce Par 10	1/1/2	Į.	7	Dema Taradis 18			Koy #1616 519
		Chi. P. Consulting Ltd. Ch.	Annual transport			INVICTO GRADAM. AN				1	NEGET HUMBER TO		3.70	+			
09	1	17	72	73 //	74	3 57	76 CA,	77 15	78	79 /	Z/V 08	1 <u>8</u>	82 CA	83 50	84 Nation	85 UNI	The state of the s

Banff/2001 Pipeline Workshop Managing Pipeline Integrity: Upstream Pipelines: Inspection, Corrosion & Integrity Management April 11, 2001 8:30 a.m. - 5:00 p.m.

Postlide	00		No.			Cereme Chevolu		1	Mulker	* XY.				
780-447-4565 dory doran @ Corrprov. Ca	gape morrisonscientific con	403-362-5757 rejette@telusplanet.net	thamre & conson con	dscrowing a	Chi Mailey W. aftholog Con	beavers & cotlabs 10m		rubedauce PII _ USA Com	Tall reposition of	raw-macdonald Cenail. nobycom KM				
780-447-4565	(403) 2#F. 8160	403-362-5757	780 490 2432	6936 808 815		180-436-4400	403-76.9.116.1	713-12012	0.79	403 237 2548				
Dara Degn	Guy Despardins	200 RETTE	TES HAMRE	DUANC CROWING	John 1300 112 12	Denene Geissher	VINC STELMARCEUR	Orantino Rilades 1849- 62412	Ratio To A	I'KG Factonaya				
GREPRE CANADA INIC	Morrison Scientific	ALL TEST INSPECTION	CANSPEC	WATER OF	College Man College	HUNTER MEDONNELL PIPELINE SERVICES	ROSEN CHIACA	ne.	W.T.	TAXALL AND THE PROPERTY OF THE				
98	87		68	06	16	92 +	93	94	95	96	97	86	66	001

Working Group 3: Upstream Pipelines Inspection, Corrosion and Integrity Management

Co-Chairs: Dave Kwas (Pembina), Reg MacDonald (IOR), Alan Miller (PCP)

Highlights

- 95+ Attendees
- Internal Corrosion
- EUB Enforcement Ladder
- CAPP/EUB Spill Report Form
- · Corrosion Monitoring
- · Integrity Management Program

Main Outcome

- Group Established to Work on Integrity Management Program
- · Champions Identified
- -Col in McGovern
- -Ra y Price
- · Goal: Share the Best Practices
- Task Force within CAPP

Working Group 4 - Construction, Repair, and Maintenance

Tuesday, April 10, 2001, at 10:30 a.m.

Co-Chairs: Reynold Hinger, Corridor Pipeline Ltd., Sherwood Park, Alberta

Mark Yeomans, TransCanada Pipelines Ltd., Calgary, Alberta

Rapporteur: Greg Hill, Corridor Pipeline Ltd., Sherwood Park, Alberta

Speakers: Bob Smyth, Petro-Line, Nisku, Alberta

Kyle Keith, Foothills Pipe Lines Ltd., Calgary, Alberta

Topic: Petro-Sleeves - Steel Compression-Type Pipeline Repair Sleeves

Notes (Bob Smyth Presentation):

- Bob Smyth passed around samples: a full-size cross-section of pipe and sleeve and a small-
- The Petro-Sleeve is a steel repair sleeve designed for installation on an operating pipeline.
- The Petro-Sleeve works by changing the hoop-stress regime in the pipe wall from tension to
- Compression is achieved by pre-heating (expanding) the sleeve just prior to installation, so that after installation, when it cools to operating temperature, its shrinkage is enough to drive
- The stress regime change effectively makes defects "disappear".
- How are Petro-Sleeves installed?
 - exterior wall of pipe in the area of defect is sand blasted
 - epoxy gel is applied to pipe
 - sleeve is heated to appropriate (calculated) temperature
 - sleeve halves are installed first top then bottom
 - special jacks are used on large diameter sleeves
 - joining bars or "zippers" are welded to connect sleeve halves
 - sleeve is allowed to cool and shrink
- Additional points regarding installation:
 - for pipelines up to 24", heating is done by hand torches; a specially designed heater is
 - better results are achieved on flowing lines, as heat is transferred away more quickly
 - longitudinal weld caps can either be ground flush or a groove can be ground into the
 - "zipper" fillet welds are very strong in tension (design factor is 0.92)
- Test results:
 - numerous tests have been done using strain gauges
 - notable were tests done on two samples (with 5 ft-lb Charpy values) at Canmet

- Petro-sleeve was applied to milled slot defect on test sample
- multiple strain gauges were applied to pipe
- internal pressure was applied to pipe 36,500 times at intervals of 40 seconds (equivalent to 1 shut-down per day for 100 years)
- results revealed pipe wall hoop stress was never tensile, only compressive
- strain disappeared 75mm from end of sleeve
- edge stress was under 6000kPa, less than 15% of SMYS
- the test was repeated with a crack defect in the ERW seam:
 - · sleeve was removed and pipe was sectioned
 - metallurgical tests revealed no growth in the crack defect
 - epoxy bond remained intact

Questions, Answers, and Discussion:

Question (Trevor MacFarlane, Dynamic Risk Assessment):

- What weld procedure is used?
- Is semi-automatic welding used?

Answer (Bob Smyth):

- 7018 rod with pre-heat.
- No, semi-automatic welding has not been used or found necessary.

Question (Trevor MacFarlane):

• Does the amount of compression achieved depend on the pressure in the pipeline when the sleeve is installed?

Answer (Bob Smyth):

• The sleeve thickness and temperature are selected based on the pressure and diameter to achieve the required compression.

Question (Shaun Dawe, Enbridge Pipelines):

• Have there been problems with ovality?

Answer (Bob Smyth):

• No.

Question (Shaun Dawe):

• Do the installation jacks force the pipe to round?

Answer (Bob Smyth):

• The internal pressure forces the pipe to round.

Question (Glenn Cameron, Greenpipe Industries):

• Can Petro-sleeves be used to repair buckles?

Answer (Bob Smyth):

• Petro-sleeves have been used for temporary repair of buckles prior to cut out and replacement.

Comment (Ron Charlesworth, EUB):

• A permanent repair of a severe buckle using a sleeve would likely affect the ability to carry out in-line inspection programs.

Comment (Bob Smyth):

Petro-sleeves have been tested on dents. A test sample with a dent was pressurized –
 1.5mm deflection of the dent was noted during pressurization. A sleeve was installed and pipe was re-pressurized – deflection was reduced to 0.05mm. Conclusion was that Petro-sleeves "freeze" dents in their configuration.

Question (?):

Was a load-transferring agent required?

Answer (Bob Smyth):

• No, the epoxy acts as a load-transferring agent.

Question (David Katz, Williams Gas Pipelines West):

• Can Petro-sleeves be used on sag bends and over bends?

Answer (Bob Smyth):

• Yes. A recent example was on a 10in pipeline, where 3ft sleeves were cut to 1ft and fitted on a sag bend. 2ft and 3ft sleeves were used at the transition to straight pipe.

Question (Wayne Duncan, CSI Coatings):

• What pre-heat is used?

Answer (Bob Smyth):

• It depends on the variables, but typically 250°F for 16in-20in diameter and 550°F for 42in diameter.

Question (Ron Charlesworth):

• Does the pre-heat burn the epoxy?

Answer (Bob Smyth):

• No, the heat transfer to the flowing line creates a temperature gradient that prevents damage to the epoxy.

Notes (Kyle Keith Presentation):

- · Background:
 - Foothills Pipeline is 1000km long, was constructed in 1980-1982
 - coating is polyken tape, so there are some areas of external corrosion
 - 13 excavations were done in 2000 as follow-up to an in-line inspection run
 - in 2000, 10 clock-springs and 10 Petro-sleeves were installed
 - the Petro-sleeves were fabricated from inventory pipe
- Oualification:
 - Petro-sleeves were approved by parent company (TCPL)
 - Foothill approved weld procedure
 - interpretation is that the sleeves can be used as permanent repairs for corrosion per CSA-Z662
 - awaiting CSA approval for dents / cracks
- Advantages:
 - better for longer defects than clock-springs
 - less risk of contact loss between sleeve and pipe
 - better resistance to SCC crack growth if SCC present
 - can be seen by in-line inspection tools
 - no welding to pipe required
- Disadvantages:
 - high initial cost
 - not good for significant bends
 - logistical (installation space) issues
 - can't see defect under sleeve using MFL tools
- Installation:
 - sleeves are installed with pipe at 80% of highest pressure seen in last several months
 - excavation is 600mm under pipe, 1500mm each side
 - long seam is ground flush rather than sleeve grooved

- pipe / sleeve are blasted to NACE-2 finish
- back-hoe is used to lift sleeve and jacks
- welding inspector is used
- MPI is done on fillet welds
- epoxy is used to taper pipe to sleeve prior to re-coating
- **Economics:**
 - in BC, \$/ft are approximately equal to clock-spring
 - for 36in pipeline, costs average \$3000/ft
 - longer defects favor Petro-sleeves, since less sleeves need to be used 3 Petrosleeves are equivalent to 8 clock-springs
- Conclusions:
 - Petro-sleeves are approved for permanent corrosion repair
 - Petro-sleeves may be considered for linear defects and dents
 - economics are used to decide between Petro-sleeve and clock-spring for specific

Questions, Answers, and Comments:

Question (Reynold Hinger, Co-Chair):

- How do you determine that the annulus is completely filled with epoxy? Answer (Bob Smyth):
 - Epoxy is over-applied and squeezes out ends of sleeve.

Question (Patrick Porter, Clock Spring):

• CSA-Z662 allows the use of standard (non-compression) sleeves for permanent corrosion repair. Why use a Petro-sleeve?

Answer (Kyle Keith):

• Several reasons - we wanted to try it out, we can use our inventory pipe, and it gives us a better feeling about the integrity of the repair.

Question (Trevor MacFarlane):

What wall thickness do you use?

Answer (Bob Smyth):

• We typically use about 1.5 times the pipe wall – I believe for Foothills we used 13.7mm on 8.2mm pipe.

Question (Glenn Cameron):

Do ditch widths depend on diameter?

Answer (Bob Smyth):

• Yes, to an extent - the 36in and 42in sleeves require special lifting jigs and, therefore,

Question (Wayne Duncan):

Have you looked at the compatibility of the topcoat and the epoxy used at the edge

Answer (Kyle Keith):

• We haven't done any specific tests but the adhesion appears acceptable.

Question (Chris Pierce, Pierce Consulting):

- Have you had any weather related issue with the annulus epoxy? Answer (Bob Smyth):
 - We have done installation in -40°C and very hot weather as well. We make sure the epoxy is pre-warmed to ensure it doesn't freeze during mixing. Once it is applied it is kept warm by the pipeline and it will cure at 0°C and above.

Comment (David Katz):

• Regarding the previous ILI issue with clock-springs, we install steel banding with clock-springs so the ILI tool can identify them

Question (Scott Arndt, Husky Oil):

• Have you any experience on hot oil lines?

Answer (Bob Smyth):

• We worry about the epoxy we are using at temperatures higher than 65°C – it loses its strength. We are working on a solution now for well casings up to 300°C.

Comment (Barry Martins, Rainbow Pipe Line):

We have been using steel epoxy-filled sleeves since the early 1990's. We were concerned about corrosion continuing under the epoxy but have pulled some sleeves off and have not found any problems with continuing corrosion.

Comment (Bob Smyth):

Our standard QC procedure after installation is to check for electrical conductivity between the sleeve and pipe. We have always found that a bond exists and have not

Question (Frank Christenson, FM Christenson Mettalurgical Consulting):

• What is the status of CSA-Z662 approval?

Answer (Bob Smyth):

 Wording was presented at the March CSA-Z662 meeting. Changes are required in terminology - "bars" not "zippers", "steel compression sleeve" not "Petro-sleeve", etc. Petro-sleeves are OK for corrosion but not yet approved for dents, cracks, and arc burns. Letter ballot approval for these defects is hoped for by the end of the year.

Question (?):

Can engineering assessments be used per CSA-Z662 to allow use on dents, cracks,

Answer:

Maybe, but many companies won't go away from strict interpretation of the basic requirements of CSA-Z662.

Question (Frank Christenson):

Have you sought approval for leak repair?

Answer (Bob Smyth):

• No, not yet, but we have done some initial testing on high-pressure leaks and the Petro-sleeves have performed well.

End of Session 1

Session 2:

Tuesday April 10th, 1:30 P.M., Max Bell Building, Room 251

Speaker:

John Hair, JD Hair & Associates, Tulsa, Oklahoma

Topic:

Horizontal Directionally Drilled (HDD) River Crossings

Notes:

- Summary of current capabilities of HDD
 - drills of more than 6000ft have been achieved
 - largest diameter pipeline ever installed using HDD is 48in
 - drills have been done in rock, but are usually done in fine-grain alluvial material
 - an 3000 ft HDD crossing for 42in pipe is not unreasonable
 - we usually look at the history to determine if a proposed crossing is reasonable
 - some say a 10,000ft crossing will be done in the future
 - the only thing that prevents a successful HDD crossing is coarse-grain material (having boulders / cobbles) crossings where these materials are present are better done a different way
- General design considerations
 - 1st step is to define the obstacle there are a number of ways HDD crossings can be done, i.e. bank to bank, channel only, etc. what exactly are you trying to achieve with the HDD crossing and what are you trying to avoid?
 - 2nd step is to carry-out an accurate, but not necessarily detailed surface survey, with control point a complete profile of the river bottom is not required, but determination of the deepest point is
 - 3rd step to do a sub-surface survey, primarily using bore holes, occasionally supplemented by ground-penetrating RADAR.
- Cross sectional profile (Overhead #1 typical drill path profile):
 - typically, HDD contractors should not design the crossing profile
 - for bidding consistency, potential contractors should be given a profile at bid stage, with profile tolerance and maximum / minimum radii of curvature
 - key points on radii of curvature:
 - the longer the better
 - circular curves are laid out
 - rule of thumb for minimum radii 100 times (in feet) the nominal diameter (in inches), i.e. 3000ft for 30in diameter pipe
 - when HDD is done, the actual radii might be tighter
 - JD Hair & Assoc. looks at worst case for stress analysis
- Pulling loads (Overheads #2 & #3 pulling load calculations)
 - JD Hair & Assoc. received research contract from PRCI to determine pulling load calculation methodology
 - divided drill path into straight and curved sections to determine soil friction loads
 - use 0.3 as coefficient of sliding friction
 - incorporated fluidic (mud) drag
 - use 0.025psi of surface area for fluidic drag

- Drill path design example (Overhead #4 target and worst case drill profiles)
 - Target and worst case drill profiles are developed and stress analysis is done on the
- Drill path design example (Overheads #5 & #6 typical stress analysis results summary)
 - Part of PRCI research contract was to determine stress calculation and acceptance criteria methodology
 - API specification for combined loading on offshore platform jacket structures turned out to be most applicable to the HDD case
 - pipe is divided into segments
 - combined tensile, bending, and buckling stresses in each segment are used to determine acceptability of drill path
- Coating damage assessment (Overheads #7 & #8 bearing load on coating)
 - JD Hair & Assoc. received another research contract from PRCI to determine bearing loads on coatings and assess potential coating damage
 - again straight and curved cases were assessed to determine typical bearing loads
- Coating damage assessment (Overhead #9 test apparatus)
 - 8in coated pipe was placed in a tank of mud and rotated while the ends of three rock cores were forced against it
 - forces on rock cores were determined to achieve bearing loads calculated in the first part of the research
 - coating thickness was recorded at intervals along the pipe under the rock cores at Ohrs, 6hrs, and 12hrs
 - point load test (sharpened core) was also carried out
- Coating damage assessment (Overheads #10 & #11 test results)
 - coating losses were only up to 15mils (worst sample) after 12 hours
 - point load test showed rapid initial coating loss but rock point seemed to dull quickly and continued loss did not occur
 - conclusion was that previous practice of putting 80-100mils of wear coating on HDD pipe was over-kill - 30-40mils was determined to be completely adequate
- Environmental issues (Overhead #12 HDD drilling fluid flow schematic)
 - drilling mud return flow will follow path of least resistance, which is usually along the outside of the pipe but may be into weak or fractured areas of the soil
 - common term is "frac-out", but better term is "inadvertent mud return"

Slide Show:

- Photo #1: 30in diameter pipe for high volume, low pressure pipeline, buckled during HDD pull under the Houston Ship channel - d/t ratio of 100 was not adequate to prevent collapse
- Photo #2: 16in diameter pipe, buckled during HDD pull
- Photo #3: pulling head on pipe in Photo #2 head hit rock and buckle propagated to pipe
- Photo #4: 16in pipe being pulled under Mississippi River lots of mud at hole entrance
- Photo #5: close-up of hole in Photo #4, now dry mud disappeared through subsurface
- Photo #6: close-up of road surface with mud oozing from HDD drill path 60ft below

- Photo #7: road in Photo #6 flooded with mud
- Photo #8: mud seeping from roadside (Niagara Peninsula)
- Photo #9: mud oozing up in grassy area
- Photo #10: photo of grassy mud-seep area, several weeks later no damage to grass
- Photo #11: wash-out of road caused by mud-seep into sub-grade

Questions and Answers:

Question (John Craig, Pacific Northern Gas):

• How many bore hole locations are required?

Answer (John Hair):

• Usually one per 1000ft; 500ft spacing is considered close. The biggest mistake made is usually depth not spacing – bores should extend a minimum of 30ft below the proposed drill path.

Question (Ron Charlesworth, EUB):

Does polyethelyne make a good protective coating?

Answer (John Hair):

Polyethelyne may be good, but the weak point is probably the girth-weld coating.
 Some good results have been achieved with armored sleeves.

Question (John Craig):

• Do you have a rating system for coatings?

Answer (John Hair):

• 11 coatings were tested and each given a wear index, however, a better wearing coating may not be better if it costs more – a cheaper coating can be put on thicker to achieve the same result.

Question (?):

- Are liners (casings) ever used to mitigate problems with inadvertent mud return? Answer (John Hair):
 - Not usually the casing has to be installed using the same method as the pipe, with the same inherent problems, so there is no benefit. In general, as well, the industry tends to avoid casings where possible.

Question (John Craig):

Can casings be used in localized areas?

Answer (John Hair)

• Yes, like near the drill rig, but they tend to cause other problem, causing the reaming / pulling tools to get hung up, for example.

Question (Daryll Wendland, Alliance Pipeline):

• Are there any techniques to prevent inadvertent mud return?

Answer (John Hair):

• The best technique is to size the hole properly so that the path of least resistance is along the drill path, as intended. In our experience, other techniques attempted to

prevent inadvertent return have not worked well. The best option is to proceed quickly with the drill, ream, or pull – as the work proceeds the problem usually disappears. It is important to note that the mud itself is not an environmental hazard – if the public is protected from washouts or unstable areas, then an inadvertent return is not usually a big problem.

Question (Jeff Sutherland, BJ Pipeline Inspection Services):

• How is the drill path verified?

Answer (John Hair):

• The best way is to monitor the pilot hole, with the driller, and look at the exit point. Some have pulled a "geo"-pig through (both ways, distributing the error), for independent verification, but this is rare.

Question (Mark Ottem, Trans Mountain Pipe Line):

• What is the accuracy of navigation?

Answer (John Hair)

• We can usually give an "as-built opinion" within +/- 1m in any direction.

Question (Dave Hektner, BJ Pipeline Inspection Services):

- How do you ensure radii are not to sharp? Is re-reaming an option?
 Answer (John Hair):
 - Best method is to use heavier drill / reaming pipe to start. Re-reaming has little benefit; the second ream is deflected by the same discontinuities as the first.

End of Session 2

Session 3:

Tuesday April 10th, 3:30 P.M., Max Bell Building, Room 251

Speaker:

Barry Nichols, HCI Canada Inc., Red Deer, Alberta

Topic:

Enhancement of Pipeline Pigging Programs

Notes:

- Why enhance a pigging program?
 - · improve flow efficiency by removing deposits from walls
 - improve inspection results deposits in pits can cause problems
 - improve film application on inhibitor runs
 - remove more solids per run
 - reduce differential pressure on pigging runs
 - reduce chances of pigs becoming stuck
- Typical cleaning pig characteristics:
 - mechanical force at pipe wall
 - · push material through pipeline
 - bypass holes to create turbulence
- Cleaning pig features:
 - brushes
 - not good for pits
 - effectiveness is determined by stiffness, size, shape, and orientation
 - cups / discs
 - effectiveness determined by thickness, hardness, shape, and velocity
- Cleaning pigs are not designed for:
 - suspending solids in a long fluid column
 - penetrating solids
 - getting deep into pits
 - coating solids to keep them from sticking together
 - bringing solids out in a slurry
- Chemicals are necessary and used to assist cleaning pigs with these tasks.
- Case History #1:
 - pipeline:
 - 218km of 20in diameter pipeline (Toronto to Sarnia)
 - originally in crude service
 - · cleaned and put into products service
 - problem:
 - line was being cleaned on-stream
 - refined products were being contaminated with fine solids (iron-based)
 - · time had to be allowed in tanks to allow solids to settle
 - 17 pig runs were made with 4 to 7 aggressive cleaning pigs per run, at turbulent velocities
 - at the 1/4 point along the line, refined products were still going off-spec

- solution:
 - chemicals were run with cleaning pigs, one chemical to penetrate solids, and one to suspend solids
 - two runs were carried out with 4 pigs in each run and chemicals selectively placed between pigs
- results:
 - after 1st cleaning run, the products were clean up to the 1/4 point along the line and the quality at the end point was significantly improved
 - after the 2nd cleaning run, the exiting products were essentially as clean as the entering products
- Case History #2
 - black powder was packed into pits in pipe wall by previous cleaning runs
 - after chemicals were added to cleaning runs and dry powder was removed, some pits thought to be 20% deep were actually 60% deep
 - demonstrates importance of chemical cleaning before ILI runs
- Case History #3
 - offshore pipeline almost completely plugged with wax
 - chemical was added to dissolve wax and forced through with pressure until line was

Photos:

Photo #1: Case History #1 - pigs used.

Photo #2: Case History #1 – solids in pipeline.

Photo #3: Case History #1 - samples taken as pig train passed (front to back). Last sample is

Photo #4: Picture of typical pipe wall coupon with deposits.

Photo #5: Case History #2 - dry powder in another pipeline.

Photo #6: Case History #3 - offshore pipeline almost completely plugged with wax.

Questions, Answers, and Discussions:

Question (Reynold Hinger, Co-Chair):

Do you ever use gel pigs in these situations?

Answer (Barry Nichols):

• No - gel pigs are designed for lines in which regular pigs can't be run. They are a second choice for piggable lines because they leave too many residues.

Question (Ron Charlesworth, EUB):

• How do you adjust for speed?

Answer (Barry Nichols):

We adjust the slug lengths for the speed and the type of chemical so that deposits are exposed to the chemical for the appropriate time. Sometimes you don't want to clean everything on the 1st past if you can't handle all of the sludge at one time.

Question (Ron Charlesworth):

• What is a typical slug length?

Answer (Barry Nichols):

• It is highly variable, depending on speed, deposits, and chemical types, but typically several hundred feet for a flow rate of 500m3/hr.

Question (Ron Charlesworth):

• Can you comment on freezing? We had an experience with this.

Answer (Barry Nichols):

• We have to be very careful to mix the chemicals properly so that the slugs don't freeze.

Question (?):

• Is there a guideline for exposure time for effective cleaning (i.e. duration per mil of deposit)?

Answer (Barry Nichols):

• Again, this depends on the type of deposit and the chemical being used.

Question (Anton Walker / Jerry Wilkinson):

• How do you know before hand what deposits are in the line?

Answer (Barry Nichols):

• You try to get a sample if you can or you design for a wide range of factors. You don't want to risk improper cleaning before an ILI run, for example, and have to do the run again or unknowingly get bad results.

Question (?):

• Are the chemicals hazardous?

Answer (Barry Nichols):

• No - we use environmentally friendly, non-hazardous chemicals.

Question (Dan Powell, Corrpro Canada):

• Can you recycle the cleaning chemicals?

Answer (Barry Nichols):

• No, like all surfactants (dish detergent, etc.) they have a finite life.

Question (Trent Van Egmond, TransCanada Pipelines):

- Have you heard of, or used, pin wheel pigs, and are they effective for cleaning pits?
 Answer (Barry Nichols):
 - Yes, but they have limited effectiveness for cleaning pits since they are travelling forward and the pin wheels bend back. Again, chemicals are a necessity for cleaning pits.

Question (?):

What about compressor oil residue?

Answer (Barry Nichols):

• Again, a pig alone will smear the residue along the pipe – proper chemicals are required for effective cleaning.

Question (?):

• Are internal coatings affected by the chemicals?

Answer (Barry Nichols):

 No – the internal coatings are very strongly bonded to the pipe wall and cannot be removed by cleaning chemicals.

Question (Dan Powell):

• What do you do about multi-diameter lines?


Answer (Barry Nichols):


You have to design the pigs for one diameter or the other, usually the smallest, or use
multiple diameter cups. The problem is that in the small line the large cups may wear
quickly and then be ineffective in the big line, depending on the pigging order.
Again, chemicals are key to get the most effective cleaning.


Question (Jill Hopkins, Conoco):


- Have you heard of, or used, magnetic cleaning pigs, and are they effective?
 Answer (Barry Nichols):
 - They can be effective for iron-based deposits but they have limited capacity. They are very effective for larger magnetic items like welding rods, etc. They can also be effective in combination with other cleaning pigs and chemicals.


End of Session 3














COMPLETION OF WELDING



MULTIPLE SLEEVE INSTALLATIONS



STRAIN GAUGE TESTING






DENT TESTING



· Dent Created by Backhoe

LARGE DIAMETER TESTING





STUDY OF SLEEVE EDGE EFFECTS AND ABILITY TO PREVENT FAILURE OF SERIOUS PIPE DEFECTS

- Study Edge Stress Effect's Created When a PetroSieeve is installed.
- Determine the Sieeve's Ability to Prevent Failure of Serious Pipe Defects
- Severe Cydic Test Performed to Measure Effect of Sleeve on Pipe with Low Charpy impact Values
- · Tests Augmented with Strain Gauge Application
- · 36,500 pressure cycles
- 0.09 R value for each cycle (689 kPs to 8048 kPs)

DEFECT MANUFACTURE



- Slot 300 mm (12") Long
- · Parabolic Depth Profile
- 70% Maximum Depth in Centre of Defect
- Electrically Discharged
 Machined (EDM) into ERW
 Longseam
- Finite Element Analysis (FEA)
 Predicted Rupture Pressure of
 1400 kPa


CANMET PRESSURE CYCLING



- 16 Strain Gauge Channels
 Readings Recorded 26 times
- per Pressure Cycle


 24 Hold Test at 8048 kPa
- Cycled from 689 kPa to 8048 kPa
- One Cycle Every 40 seconds
- · Total of 36,500 Cycles
- All 16 Channels Recorded During Sleeve Removal

PRESSURE CYCLING RESULTS cont....



- Strains Inside Pipe Under Sleeve at 6:00 Position

PREVIOUS TEST RESULTS



Previous Test Results – Edge Effect Strains


PRESSURE CYCLING RESULTS


- · No Failure Observed for the 36,500 cycles
- · No Failure in:
- Pipe Adjacent to Sleeve
- Sieeve Material
- Sleeve Fillet Weld
- EDM Defect
- · Final State of Vessel Same as initial
- · MPI of Sleeve and Adjacent Pipe Revealed NO Cracking


TEST CONCLUSIONS



- Sewere Pressure Cycling Equivalent of Complete Operational Shutzown Every Day for 100 Years
- Sieeve & Pipe Assembly Performed in Elastic Range
- Strains Developed Adjacent to Sleeve Edge were insignificant
 Epoxy Bond Remained Intact for Entire Test
- Sieeve Effective in Preventing Senous Defect from Advancing to Failure
- Sieeve Effective in Restoring Serviceschility of Pipe to Original Level







INSTALLATION OVER LONG SEAMS







 Machined Groove in Sieeve for Protruding Long Seam

PETROSLEEVE **INSTALLATION 2000**

FOOTHILLS PIPE LINES LTD

Kyle Keith

INTRODUCTION


- Background
- Qualifications
- Operational Issues
- •Installati on
- Costs

BACKGROUND

- FOOTHILLS PIPE LINES LTD Prebuilt
 - 1980-1982 Construction

 - Double Wrap Polykin Tape 1000 km of NPS 36&42 in AB,BC,SK
- In-line Inspection (ILI) Program
- 2000 PII & BJ Inspected 180+km
- 13 Excavations
- History of repairs
 - Pre 2000, 1 clockspring
 - 2000: 10 Clocksprings and 10 PETRÓSLEEVES
- PETROSI EFVES fabricated from invento pipe





QUALIFICATION

- Approved by TCPL
- Foothills approved Petro-Line weld procedures
- Class A repair sleeve as defined in CSA Z662 sec 10.8.

COMPAIRISON TO FIBREGLASS SLEEVES

- ADVANTAGES
 - Covers longer defects
 - Less risk of loosing contact with pipe
 - Resistance to SCC and fatigue defects
 - Can be detected on future ILI [MFL] runs

COMPAIRÍSON TO FIBREGLASS SLEEVES

- DISADVANTAGES
 - Relatively high mobilization and unit costs
 - Can not be installed on significant bends
 - Logistical issues with equipment and personnel
 - Requires wider/deeper ditch
 - Defect can not be sized on future ILI [MFL] runs

OPERATIONAL ISSUES


- Pressure reduction to 80% recent MOP (Footbills' Policy)
- Inspection Weld inspector, familiar with sleeve installation
- NDE MPT performed on fillet welds and pipeliongseam
- · Must grind LS weld or out groove in sleeve
- Ditch must have direct access for picker (backhoe) and two welding rigs

INSTALLATION

- Grit blasted to a NACE 2 finish (green diamond).
- Require 600 mm clearance under the pipe and 1500 mm og each side
- Recoating
 - Blast and coated over the sleeve as with rest of piping.
 - Epoxy was used to taper transition between sleeve ends and the line pipe
 - Modified coating spec from split sleeve coating specification
- The backhoe was used as a lifting device.
- Handover documents Petro-Line

ECONOMICS

- Costs to install a Fiberglass sleeve approximately equal (\$/ft) for longer defects
 - The longer the defect(s) and the more defects to be repaired the more favorable the economics are for the Petrosleeves
 - The shorter and more isolated the defect, the economics favor the fiberglass seemes
- Approximately \$3000/ft total sleeve repair costs for NPS 36 repair in SC




CONCLUSIONS


- PetroSieeves are an approved method for the permanent repair of corrosion defects on Foothills' system.
- Foothills will consider using petrosleeves on other types of defects (i.e. dents, cracks gouges) on a case by case basis.
- Type of repair method used is based on an engineering decision that considers defect specifics and total costs of repair vs. other acceptable repair methods.


	 en en e	-
	i i	
	i	
	:	

	Action (Action Control of Control	
	obilizabaniceoby attitude (1/2)	
	bindnegeby eddisty, i fi	
	000 A Separate process	
	A Andrewsky Administration of the state of t	
	rédendén ja ji birok dalang Kirir	
	nääkkeisovanitpäägee, jäs	
	dere execution	



Straight Section Model





J.D.Hair&Ast Consulting Engineer.

tes,Inc.

2121 South Columbia Avenue Suite 101 Tuise, Okiehoma 74114 Date: 9/18/00

Prepared: MST

Checked: JDH

Date: 9/20/00

PULLING LOAD CALCULATION AND INSTALLATION PIPE STRESS ANALYSIS

Project:

Directory:

Description: Option 1

24.000 inches General Data Pipe Diameter = Wall Thickness =

36.91 inches² 0.500 inches 2548.20 inches* 65,000 psi 2.9E+07 psi SMYS = Young's Modulus = Moment of Inertia =

12.0 ppg Pipe Face Surface Area = Diameter/wall thickness ratio = Poisson's ratio = Mud Density =

62.4 pounds/foot³ 89.8 pounds/foof 0.025 psi Ballast Density =

Coefficient of Soil Friction = Fluid Drag Coefficient =

Pipe Weight in Air= Pipe Interior Volume=

125.49 pounds/fool

2.89 feet 7/toot

3.14 feet3/foot

Ballast Weight = Pipe Exterior Volume=

281.99 pounds/foot 80.04 pounds/fool Results Summary Displaced Mud Weight =

Segment 5 328,460 Passed Passed Passed 4,205 yes 90 ¥ ž Segment 4 307,298 Passed Passed Passed Passed Passed yes 3,697 2 Segment 3 262,266 Passed Passed 3,278 Passed 2 MA ¥ Segment 1 | Segment 2 109,186 Passed Passed Passed 1,078 Passed Passed yes 90 Passed Passed 63,301 Passed yes 9 699 ¥ ž Is this segment submerged in mud? Is this segment ballasted? Beginning = Tensile Stress Check: Bending Stress Check: Cumulative Pulling Load at End Poin Hoop Stress Check True Length to End Point from Combined Tensile and Bending Stress Unity Check: Combined Tensile, Bending and External Hoop Stress Unity Check:

John Han, John Hair & Associates

oge; €

STEEL PIPE STRESS CHECKS USING AGA DES Allowable Tensile Stress Calcula	SIGN GUIDE	CRITERIA	
Tensile Stress Limit, 90% of SMYS, Ft=	58,500 ps	Company of	
Allowable Bending Stress Calcula	ation, F _b		
For D/t <= 1,500,000/SMYS, $F_b =$	48,750 ps	i Not Applicable	
For D/t > 1,500,000/SMYS and \leq 3,000,000/SMYS, $F_b =$	42,432 ps		
For D/t > 3,000,000/SMYS and \leq 300, F _b =	42,744 ps		
Allowable Bending Stress, F _b =	42,744 ps		
Critical Hoop Buckling Stress Calcu			
Elastic Hoop Buckling Stress, Fhe =	11,076 psi		
For F _{he} <= 0.55*SMYS, Critical Hoop Buckling Stress, F _{he} =	11,076 psi	**Applicable**	
For $F_{he} > 0.55$ *SMYS and <= 1.6*SMYS, $F_{hc} =$	31,244 psi	Not Applicable	
For $F_{he} > 1.6$ *SMYS and ≤ 6.2 *SMYS, $F_{hc} =$	12,133 psi	Not Applicable	
For $F_{he} > 6.2$ *SMYS, $F_{hc} =$	65,000 psi	Not Applicable	
Critical Hoop Buckling Stress, Fhc =	11,076 psi		
Allowable Hoop Buckling Stress, Fhd/1.5 =	7,384 psi		
Segment 1, Straight Segmen			
Tensile Stress, f _t =	1,715 psi	Passed	
External Hoop Stress, f _h =	1,712 psi	Passed	
Combined Tensile and External Hoop Stress Unity Check =	0.06	Passed	
Segment 2, Deflected Segmen			
Tensile Stress, f _t =	2,958 psi	Passed	
Bending Stress, f _b = 1	. 12,083 psi	Passed	
External Hoop Stress, f _h = Combined Tensile and Bending Stress Unity Check =	2,258 psi	Passed 4	
Combined Tensile, Bending and External Hoop Stress Unity Check =	0.33	Passed	
Segment 3, Straight Segment		Passed :	
Tensile Stress, f, =	~7,105 psi:	Passed	
External Hoop Stress, f _h =	2,258 psi	Passed	
Combined Tensile and External Hoop Stress Unity Check =	0.13	Passed	
Segment 4, Deflected Segment	CONTROL MICROSCO CARROLLES AND		
Tensile Stress, $f_i =$	8,325 psi	Passed	
Bending Stress, f _b =	12,083 psi	Passed	
External Hoop Stress, f _h =	1,712 psi	Passed	
Combined Tensile and Bending Stress Unity Check = Combined Tensile, Bending and External Hoop Stress Unity Check =	0.42	Passed	
Segment 5, Straight Segment	0.25	Passed	
Tensile Stress, f _t =	8,898 psi	Passed	
External Hoop Stress, f _h =	393 psi	Passed	
Combined Tensile and External Hoop Stress Unity Check =	0.04	Passed	
		Country and the second	ASSESSED OF THE PARTY OF THE PA






FIGURE 1. DEARING FORCE RESULTING FROM WEIGHT









J.D.Hair&Associates,Inc.

Consulting Engineers


Banff 2001 Pipeline Workshop



Banff 2001 Pipeline Workshop



J. air&Associates,Inc. Consulting Engineers



Enhancement of a Pigging Program

Banff/2001Pipeline Workshop Banff, Alberta, Canada April 9-12, 2001 Barry Nichols HCI Canada Inc

Why Enhance a pigging program?

- · Improve Flow Efficiency
- Improve Inspection Results
- · Improved film application on inhibitor runs
- · Remove more solids per run
- Reduce differential pressures on runs
- Reduce the chances of becoming stuck on runs with heavy debris

Typical Cleaning Pig Characteristics

- Clean with mechanical force between pig and pipewall
- · Push material through the pipeline
- · Bypass holes to create turbulence

Typical Cleaning Pig Characteristics

- · Brushes good for cleaning pipewalls
 - by design not overly effective at cleaning pits
 - effectiveness determined by
 - * shape of brush
 - · how brushes are mounted
 - · size of brush
 - stiffness of material in brush verses material to be cleaned

Typical Cleaning Pig Characteristics

- Some cup/disc designs better for cleaning
 - effectiveness determined by
 - · hardness of material
 - · thickness of material
 - · shape of contact edge
 - velocity of pig

Typical Cleaning Pig Characteristics

- Not designed to:
 - suspend solids in long fluid columns
 - penetrate solids
 - get deep into the pits in the pipewall
 - coat solids to keep the from sticking to each other
 - bring solids out in a slurry

Case History

- · Pipeline History
 - 218 km of 20" pípeline (Toronto to Sarnia)
 - originally in crude service for a number of years
 - line cleaned, tested and switched to refined product
 - gasonne
 - · furnace oils

Case History

- · Problem
 - line was to be cleaned on stream
 - refined product were being contaminated with fine solids
 - product would have to be put to a storage tank to allow solids to settle
 - product would have to be filtered prior to delivery

Case History

- At least 17 pigging runs were made with aggressive pigs
- 4 to 7 cleaning pigs per run
- velocities were such that line was in turbulent flow
- Line fluids after all this was at marginal spec
 1/4 of the way up the pipeline

Case History

- Solution
 - chemical solutions where run
 - · one to penetrate material
 - · one to suspend solids
 - cleaning pigs were run in conjunction with chemicals
 - job was done on stream

Case History

- · Solution
 - chemical batch solutions where run
 - · one to penetrate material deposit
 - · one to suspend solids
 - cleaning pigs were run in conjunction with chemicals
 - job was done on stream

Case History

- · Results
 - after run #1
 - Line fluids past test 3/4 along the line
 - · improved results at the end of the pipeline
 - after run #2
 - Line fluids were about the same condition leaving the pipeline as going in




Cleaning pig

Cleaning pig







Case History



Case History



Case History



Case History

- Conclusion
 - Solids in the pipeline were not tightly adhered to the wall
 - Fine solids were not being supported by the fluid in the line
 - The chemical solutions were able to suspend these solids

Managing Pipeline Integrity: Construction, Repair and Maintenance April 10, 2001 10:30 a.m. - 5:00 p.m.

Banff/2001 Pipeline Worksho

To the intervention		Signature	1 Jan	Willingua.	30	in thirt	Desemble inter	77	8	The second second		to Martin	1,938	7				211	o favor	101	4-house-
		- 1	The Chest of the Control of the Chest of the	a Nome, Con	mauri dawe a Cripi. enbridge. co.	Part - 3 - martens wennig mobile a	@ hmpsi.com	glenn-your e dynamic viste. net	bruc-gray Chasan	CPIENCE CHELLEGIAMA	I Wond & Work and	5 10 13 10	1gray @ Kta. Com	CATT & WELLANDS	Krishna muthurapii oca	Com	Photone sulgione + tob , go . 10.	locas harras (2000)	TAIPL. 18	upl.ca	At or Car
	E-mail	 	1	1		200 - C - L	is Tab THOO General @ hmpsi.com	8638 glenn-yue		J		+-		691 DADIE, C. K412	1			į	250371-4011 Shuchan CTAIPL. 1	5913 Kylal @ Theplica	
Dhon	+	MIS 780 449 2108	······································		700 - 405-ECO	Sakr 190			1809.02b.2ab	403-281-8627	(604) 691-5933	, , ,,,	180-440 939,	701-584-691	Kari Arishnamusty 713-849-6339	0	(815) 953-5728	780-955-6177		780 -449-5913	nce 403-258-2233
Name		RIGHT DER	ne FRANK CHRISTENSEN	Shaun Dawe	Borry Martens	Deneme (re ;	Glenn Yes	0	i		Jennife Wars	hinda GRAY		DAUD (472	Kari Krishno	Orbins Dalami		borna Harron	Now Ille track.	Kyla Loewen	Lavid Partelar
Company	· · · · · · · · · · · · · · · · · · ·	FINCKISTER SPENSON	Same !	Endridge Pipelines	Tainbery Fire Line Homes!	Pipeline Services	Systems Misk Hiskisment	TOPL	Plene Comute Just		YTA-T . 0	FN 1965 GRAS	WILLIAM SAC & PELLIKE	1		Transpertickin solary Secon	Imagin 1 0.1 P. 1	rans Ill.	11 (C) 1.	2,2	Tas contras
	√	7 2			and providence of the second				8 Pie	A VIVI		-	3	12 077		+	14 —	15 +	16 7000	17 Mes.	The state of the s

Maintenance April 10, 2001 10:30 a.m. - 5:00 p.m.

mit fortym	Von Corr Eng. Lid	9261 185	my 1000000 600 m	2) The
TATRICK	HATRICK PORTER.	2815908491	pporter & clockspring.com	MA
Trevor Mac	lac Farlane	403 S47 8638	trever macter langedynamic is Knut	1-12-0
Fleet Technology Ltd.	why Ltd.	613 592-2830	blawell (a) thetech. com	1.00 00
Compass	Congrowth Corp	780 3337/09		Harden S
BCCAS		(250) 848-4572	bwanderson @ broos com	Delle Comment
BC GAS	. ^	1254 - 898 (act)	Toology of the second	
BCGAS		250 868-4568	borlizer house	1
WESTED	ACT ENERSY	250-760-2000	WESTCOAST ENERGY 250. 760-2000 / brassat & wat one	
Positive	Positive Projects	(403) 235-1650	(408) 235-1650 gerry. Wilkinson apositive projects, com	Ser
Husk, Oil		£559-1L8 (08L)	Scott. Andt@husky-oil.com	1
ENB, 2106.	ENBRIDGE ROSEINES	780-420-5267	Scatt. 1 conside @ copl , Entridue. com	Sapa
שטרשושן	ALLIANCE PIPELINE	780 518 7622	inenialical (alliance - significant	Ne West a
2 m. 3. 109 /	Maine Com	145-547 5341	Porsus Para Car 780-542 5341 Polanelle pembing. con	El Van Sli
4CI CAN	HCI CANADA INC	403 391-1335	403 391-1335 Brichols @hoiww.com	The state of the s
SI CONTO	JG SYSTEMS THE	780-955-2856	CSI CONTING SYSTEMS THE 780-955.2856 wduncane esicoating. com	Wayn J.
A16.08		780 460 -386k		2 19

Managing Pipeline Integrity: Construction, Repair and Maintenance April 10, 2001 10:30 a.m. - 5:00 p.m.

Banff/2001 Pipeline Workshop

Canning Cool I ripeline Workshop	 	1 Julianos	Can May	Jehn Re	Hanscanade	To II	Mangana	Soll my	1X/An	MAL		150 CK	Com 12	K		Okuse	3	S. S.	Sold Sold Sold Sold Sold Sold Sold Sold	The state of the s	4 Morra
	11.20x 12 6 90 4. 26	dule 1 1.	wisiter & Alint-energy com	j Craige Waliorg	403-470-5893 Frent - van _ Sanonde	dan. powella compro. ca		TO TAMPA.OA	doug adamson @ esso. com	al forth@asso.com	nestlero & hattelle uti	With transfer Administration and the state of the state o	-sales oca Whempelo com	16 enger TOWET OF		Justince Centrube . wel. org	Wirakin @ pil - cump	sorche Caci no		Worder for La	10 10 10 10 10 10 10 10 10 10 10 10 10 1
	CON CHARLES ONT 14			57 j CVA	93 trent	dan. pou									\	AWallsce P		, 3	1. VOGS/6)		
	340 5429	Flint Field Sauce, 1 11 4.	105-542-806	1001	403-978 B	403-235-640	250-371-4014	780 925-112	5/9 (27) 6/8	105-689-621	198.727 719	HEMPEL CORTINGS (GILL) 22	25 - 5 - 35 - 35 - 35 - 35 - 35 - 35 - 3	250 960-2000	250-751-8219		203 - 298 - 233	905-751-0978	449-7244-7415-110 1. VONS167 111	4CI CANDON IL (403) 232CH 56	
	8	14 Service, 1 L	ノナラ	WO TEN SE		Corpro Camba, Inc.						CORTING OF	3	1 ENGERA 2	Sec. 2			wice Cons 90		H	
	448	Flint Fie	サジャム	<u> </u>	-	Corrpro (a	TORNS MOUNTAIN	Doug Adamson	すりは		SATTELLE			Wes 100A	Don WALLACE	P.T. 7		Integrity Service Cons	MIN Engueering	HCICA	
AMPARAMAN TO CHARLES AND	Kod (HAKKES OKTH	Usite.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	TRENT VAN EGMOND		A TO THE	chelco		60.1	Jane North		JACANES EBERLE	LAWCE BONOIL			Mahammed Jawah				Value of the latest of the lat	The state of the s
The state of the s	35 Kod (214	On Usite	37 John Chain	38 TRENTV	39 Den Pull	40	T. Menelle	Imperial Oil	Imperial Oil	····	+				JAN CAR	Malabanage	Trumpy -	Rows 1/8		DER WHINER	
The state of the s		MOTION AND SOURCE PARAMETERS	THE PROPERTY AND ADDRESS OF	3	~	4	4	and Alexandra Underly Under	42	43	44	Additional Addition or the Land of the Lan	45	4	To the second se	Annual Conference of the Confe	48		95	The second of th	A comparation of the second of

Managing Pipeline Integrity: Construction, Repair and Maintenance April 10, 2001 10:30 a.m. - 5:00 p.m.

Green gigs Live some 403 360 7338 Joud-a-Feor Cenal mobilican Like Huber Hisomed 406-686-3318 Joud-a-Feor Cenal mobilican Confert Competition Confert Conference consistences	100	BI PIPCEING INSPECTION 403) 531-5300 CHALLAN OBJSCRVEES.CA Chi-Malli										
Les desme 403 360 7338 1000 1000 1000 1000 1000 1000 1000 1	(613) 992-373	SPKT. Dr (403) 531-5303										
	Consu In N.R. Can.	BI PIPCEING INS										
Jaid Fesser Onis Harhell	Noël Billette	CHRIS MARLAN										
52 53 54 54	\$ 29	88	65	09	01	62	63	64	99	99	19	89

Working Group 4 Construction, Repair and Maintenance

Co-Chairs:

Reynold Hinger, Comdor Pipeline Ltd Mark Yeomans, TransCanada Pipelines Ltd.

Rapporteur:

Greg Hill, Corridor Pipeline Ltd.

Best77661 Pipelise Workshop

Use of Petrosleeves

Kyle Keith, Foothills Pipe Lines Bob Smyth, Petro-Line

- · PetroSleeve steel repair sleeve
- Foothills carried out a corrosion repair program in 2000
 - +10 Petro sleeves installed
 - •10 Clo cksprings installed
- Cost per foot of sleeve repair was approximately the same
- Advantages/Disadvantages

BenfF2061 Pipeline Workshop

Use of Petrosleeves Continued...

Discussion/Questions

- CSA Z662 status?
- · Why use Petrosleeves versus Clocksprings?
- Petrosleeves and side and sag bends?
- · Installation on hot oil pipelines?
- Ditch widths for installation

Sanft 2001 Pepulian Workshop

Directionally **Drilled River Crossings**

John Hair, JD Hair & Associates

- Drills of more than 1800 metres are currently achievable
- Important Design Considerations
 - •De fine Obstacle
 - ·Surface and Su bsurface Surveys
 - •De sign Profile
- Protective Coating Research
- "Inadvertent Mud Returns"

Ban 19200; Pipeline Workshop

Directionally Drilled River Crossings Continued...

Questions/Discussion

- Bore hole spacing?
- Is casing an option to prevent inadvertent mud returns?
- Polyethylene as a protective coating?
- Pipe Radius?

Bant 7001 Pipeline Workshop

Enhancement of Pipeline Pigging Programs

Barry Nichols, HCI Canada Inc.

- Advantages of Chemical Cleaning
 - flow efficiency
 - in-line inspection results
 - removal of solids
- Three Case Studies
 - Change in product service
 - Iron Sulphide
 - Wax removal

Heaff2001 Pipeline Workshop

Enhancement of Pipeline Pigging Programs continued...

Questions/Discussion

- · Internal coatings?
- · Can chemical be recycled?
- · Slug length?
- Environmental hazard?

Banf02001 Papeline Workshop

Working Group 5 - Stress Corrosion Cracking Hearings + Five Years

Co-chair: Robert Sutherby Co-chair: Fraser King

Rapporteurs: Katherine Ikeda-Cameron and Greg Van Boven

Facilitator: Doug MacDonald

First Session - NEB 5 Years On

65 attendees, 3 Presentations:

Bob Sutherby, TransCanada Pipelines, Introduction Doug Waslen for Joe Paviglianiti, NEB presentation Walter Kresic, Enbridge Pipelines, CEPA presentation

General Discussion

Fraser King [NRTC] Is SCC a dead issue?

Bob Coote [TransCanada] SCC can't be considered a dead issue. Among all those SCC colonies is there any indication of what may lead to failure? Has the effort to date prevented any failures?

Bob Sutherby [TransCanada] # of significant or near critical defects from excavations in the CEPA database is zero. No features have been found to date on excavations that were imminent going to fail. Failures have occurred on hydrotest. Less than 10% deep and not significant is what has been found. Corrosion has a scale that differentiates severity due to rusting or pitting but in SCC when you find chicken scratches all you can do is try to learn from that and extrapolate. Models are being used. We also now find circumferential SCC from inquiry that is being managed, we now have high pH SCC in Saskatchewan and SCC that forms in corrosion.

Tom Pesta [AEUB] noted that there are no CAPP attendees?. Is this an indication that from an Alberta perspective that CAPP doesn't see SCC as important. AEUB issued letter 98-6 to increase awareness by asking companies to submit investigations into what they are doing to CAPP and CEPA. Interim directive is being drafted. SCC on CAPP member companies is associated with tape coatings and asphalt coatings but no correlations with pressure and soil data. Directive says if you have disbonded coating you have to include this in your integrity plan and look at risk associated with this. SCC is an integrity issue that will have to be dealt with just like other integrity issues. CAPP has been good about collecting data.

Jim Marr [JE Marr & Associates] seeing SCC as described (under different conditions and just as variable if not more) and is looking for soil correlations. Changing view point on how we look for SCC and are to open everything, which is an evolution. Continue to develop modeling, enhancing data mining. Consistent data collection is important. Most SCC is chicken scratches.

Steve Lambert [U of Waterloo] What is your success rate during excavations? How often do you find SCC?

Jim Marr [JE Marr & Associates] With tape coatings if conditions are there can find it but then question of severity.

Using CP, dCVG now. Starting to see it in wax coatingwhere we did not before. Improvement from six years ago is like going from Grade 1 to Grade 9. We still expect to find it but are now looking for significant cracks and in different conditions versus how many have been prevented by hydrotest?.

Steve Lambert [U of Waterloo] Are you 50, 80, 90 100% successful in finding SCC?

Jim Marr [JE Marr & Associates] Ranges from 60 to 90 %

Burke Delanty [CC Technologies] NEB CEPA showed.....since inquiry how many failures have been found in service or even hydrostatically tested?

Doug Waslen [NEB] In 1996 there was a failure where SCC was at least a contributing factor but none since on NEB facilities.

Ravi Krishnamurty [PII] There were quite a few advanced SCC found since the inquiry.

Unknown; Larger pipeline population in the United States. How many failures down there?

Jim Marr [JE Marr & Associates] 2 in-service SCC failures in the past six months.

Ted Hamre [Canspec Group] Transverse cracking recently led to leak on a small diameter line not regulated by NEB.

John Craig [PNG] We have had 5 in-service and hydrotest failures in 1996 on a small diameter pipeline. (non-NEB, non AEUB)

John Beavers [CC Technologies] Failure analysis in the United States and Canada are continuing to reflect the industry concern to eliminate critical flaws. Stats show that industry has committed to spending resources on mitigating SCC and not that SCC is dead. Near critical flaws aren't normally found in excavations programs, digs are meant to be investigative and lead to assessing the condition of the pipe.

Corey Goulet [TCP] SCC is not a dead issue. TCPL is applying mitigation processes (in line inspection, hydrotesting) and have found advanced defects — we're dealing with the issue. One SCC hydrotest failure in 2000 on an AEUB regulated pipe. It behooves us all to not ignore this problem. TCPL has prevented a handful of in-service failures in the last 6 or 7 years with hydrotesting.

Steve Lambert [U of Waterloo] public only hears of failures not hydrotest failures or inline inspection data. What does CEPA do with hydrotest failure data and critical feature data?

Walter Kresic [Enbridge Pipelines] 99.9% of CEPA SCC data entered is chicken scratch which therefore forms the majority of the correlations. Data forms part of knowledge base (data base) but not enough has been collected to say anything about critical cracking.

Steve Lambert [U of Waterloo] Should the public know this more positive knowledge?.

Walter Kresic [Enbridge Pipelines] Yes, we need to draw out the more positive statements and communicate them.

Bob Sutherby [TCP] We should say what we haven't found as well.

Fraser King [NRTC] Liquid versus gas susceptibility. Any difference in susceptibility?

Greg Toth [Trans Mtn Pipeline] SCC not dead. Programs much more mature. Just one more hazard to assess. Residual stress – SCC related to corrosion. We find SCC related to residual stress.

John Beavers [CC Technologies] Metallurgical evaluation with near neutral pH (CEPA program) the single factor with strongest correlation on gas lines was residual stress. SCC colonies were found in areas of high residual stress. In liquid lines SCC occurs where significant corrosion, wall loss or locations where residual stress are increased.

Fraser King [NRTC] Is there an affect of different modes between liquid and gas lines (eg. batch or continuous)?

John Beavers [CC Technologies] Lower R ratio sees more crack growth. Is this SCC or corrosion fatigue? Observation that more cracking on liquid lines, I don't understand it.

Steve Lambert [U of Waterloo] As a researcher I don't understand why liquid lines are less susceptible. Some statistics are biased because of more digs. Liquids lines should be considered.

Jim Marr [JE Marr and Associates]. We're beginning to see just as much SCC on liquid lines as gas and as severe. Primarily non-classical. Doing more work on liquid lines. Looking more often. Using CEPA guidelines.

Ravi Krishnamurty [PII] I see a systematic trend, higher pressure deeper cracks and in last 6 months have seen at least 2 or 3 liquid lines in warmer southern states with substantial cracking. Dependent on cyclic loading and coatings.

John Beavers [CC Technologies] Any high pH SCC on a liquid line?

Jim Marr [JE Marr] Only near neutral pH SCC.

John Beavers [CC Technologies] defines the difference between high and neutral SCC. High pH SCC is primarily intergranular, high pH solution associated with little or no corrosion, concentrated bicarbonate solution. Near neutral pH SCC is transgranular, found under tape coatings, shielding of CP or inadequate CP, frequently associated with corrosion and near neutral dilute solutions.

Ray Fessler [BIZTEK] One difference is high pH SCC is sensitive to temperature where near neutral pH SCC is not temperature dependent. In gas lines higher temperature at compressor stations have distinct non random distribution of SCC. Liquid lines are less susceptible to high pH SCC. The probability is much lower of finding high pH SCC on liquid lines.

Fraser King [NRTC] Are there any individuals who have seen changes since NEB hearing?

Bob Sutherby [TC] Who was involved in SCC issues at the time of the NEB hearings? ½ of room

Is everyone comfortable with language, cracking morphology?

Did inquiry change the focus? Has it changed the way we do things? Is SCC a bigger issue now?

Tom Pesta [AEUB] Knowledge of SCC has increased as a result of inquiry. Before that limited to transmission lines, now SCC can be found upstream and in other areas.

Bob Sutherby [TC] Contractors are still seeing work with SCC. Comments from contractors as to what the inquiry has done for them?

Ravi Krishnamurty [PII] after inquiry 2 things came out. Upstream started to look at SCC. And other ways were looked at – more aggressive tool vendors were going after inspection technology. More work in US as well. This will position us better in dealing with SCC in the future.

Bob Sutherby [TC] What about in another 5 years?

Ravi Krishnamurty [PII] Fewer failures, better position

Doug MacDonald [SNC Lavalin] Perceived lack of understanding of SCC is what started this workshop in 1993. We've come a long way.

Bob Sutherby [TC] What about concerns with contact damage, internal and external corrosion? Is SCC a small component of big picture?

Walter Kresic [Enbridge Pipelines] The fear of the unknown is gone. We don't know all the hows and whys but we have more tools to keep industry safe. We are managing the child (since the birth)

Steve Lambert [U of Waterloo] Yes SCC was a concern because we didn't know that much. Industry and NEB have done a good job in putting in procedures. SCC is ahead in how we handle the problem and getting industry to act effectively. Still bigger hazards out there.

Bob Sutherby [TC] Perception between first and second inquiry was that SCC was getting worse, just tip of the iceberg. The potential hasn't grown a whole lot over the years.

Tom Pesta [AEUB] SCC work is more defined. Understanding is that SCC is on many different pipelines and now we are evaluating the risk. Chicken scratches will not result in ruptures. Perception was that ruptures were the only outcome but now it is perceived that there is less risk.

Bob Coote [TC] SCC is still of great interest. The methods available for detection, to give the operator confidence, are not yet available. Maybe hydrotesting. Great hopes for inspection technologies to help us manage SCC.

Corey Goulet [TC] Hydrotesting only one method. Liquid crack tools are advanced technology and will eventually be available for gas. EMAT scan tool is progressing. This is why continuing research is necessary - develop more cost effective mitigation methods.

Fraser King [NRTC]—Is the public safer?

Bob Sutherby [TCP] Is SCC perceived to be only a big company issue relating to big inch pipelines?. Is there not a problem with smaller diameter pipelines?

Tom Pesta [AEUB] Quote from CAPP letter - downstream pipeline demonstrates sufficient risk for SCC (acknowledges issue). Upstream does not possess significant risk. Will maintain data base.

Fraser King [NRTC] Risk as opposed the susceptibility to SCC.

Bob Sutherby [TC] 600 to 800 failures a year, how many SCC?.

Tom Pesta [AEUB] We do not know because the AEUB data does not identify this.

Stan Wong [CC Technologies]. SCC hasn't gone away. Have a better handle of SCC as a threat relative to other threats. Corrosion bigger and higher frequency threat on smaller diameter pipelines

Bob Sutherby [TC] Vigilance but not actively looking on small inch diameter lines. Transportation Board had wanted to reduce pressure. This would have cost billions of dollars but research has shown that this would be a short term solution at best.

Yes public feels safer.

Fraser King [NRTC] Any last comments before break?

Second Session - SCC Site Selection Models

57 attendees

Bob Sutherby [TC] Introduction

Issues from 1999 session What are people using models for, role of models Refocus

Discussion

Steve Lambert [U of Waterloo] Point of clarification. Deterministic should have been empirical, based on correlations/observations or based on some understanding of the mechanism? What do experts base their models on?

Jim Marr [JE Marr] Our models are based on observations from excavation programs. Apply terrain data to pipeline conditions. Extrapolate this to other similar conditions on pipeline. Empirical.

Steve Lambert [U of Waterloo] Any mechanistic models?

Bob Sutherby [TC] What about pressure?

Jim Marr [JE Marr] Other aspects of operating pipeline are being included in models, temp, R ratio, metallurgy. Focussed on correlations of terrain conditions; it worked but are now refining it to get better conclusions. Bringing in ILI, CP data to help locate areas of disbondment. Refinement. Used to use soil models before now use more data.

Glen Cameron [GreenPipe] We use GIS and Jim's soil model, elevation maps, pressure, aerial photos. Going down road with everything and will see if get empirical model.

Barry Martens [Rainbow Pipeline]. ILI will miss as much as soil model. First program with Jim Marr there were 16 areas that detected minor SCC. Started using CD Ultrascan tool and found deep SCC. Still used soils model because it finds the start of SCC but will the model take you to the more severe? Used field observations of tape disbondment etc. but didn't find SCC necessarily on similar areas. Now considered wrinkles and trapped water against pipe. Found free flowing water didn't propagate SCC so now use trapped water criteria. Well drained soils found severe SCC. Water table fluctuations would trap water. Can't predict this but look for the same scenario – SCC in corrosion.

Bob Sutherby [TC] Are you learning from your own experiences?

Barry Martens [Rainbow Pipeline] Metal loss corrosion with severe SCC – can't find with tool.

Bob Sutherby [TC] Sometimes we find all corrosion on one side of pipe.

Barry Martens [Rainbow Pipeline] TRAPIL presentation of asphalt coated line, SCC at 10 and 2 o'clock position; Rainbow finds it at 5 and 7. Disbondment catch the water when it fluctuates. On Rainbow tape on the top half is tight with TRAPIL they find their SCC on top opposite. Makes sense.

Jim Marr [JE Marr] Where would operators be without models before other things were available? At time of hearings they were quite valuable. Models can be useful for decision making, optimize cost benefit and maintain pipeline integrity. Rainbow's model works—have compiled data and used info for making better decisions.

Stan Wong [CC Tech] Experience from 1930's vintage, combination of deterministic and mechanistic. Quality issues around construction practices.

Steve Lambert [U of Waterloo] What is the focus on where models are going? Models are useful and have done good. How does the severity of SCC work into the model? We know there is a lot of SCC. Fine tune models to pick out worst SCC. Will in-line inspection make models obsolete?

John Beavers [CC Tech] Severity vs occurrence. Can't use soils model to predict severity. Good news is that there is not a lot of severe SCC with near neutral SCC. Use all types of input data (manufacturer etc.)

Bob Sutherby [TC] What else can we look at?

Stan Wong [CC Technologies]. Early construction practices highlighted problems. Circumferential SCC caused by construction practices of the day.

Reg Eadie [NRTC] You are looking for intersection of two sets. Topography of water/wrinkles and change from chicken scratches to severe. Several techniques, models, ILI, hydrotests. Need both or all techniques. Missing factor is extra stress, bends, residual plus susceptible conditions. Intersection of conditions for severe cracking is rare.

Barry Martens [Rainbow Pipeline]. Not much success on 20 inch line when dug on soils model or when dug on corrosion loss. CP was found to be going through outer wrap. Picoflex coating. Soils model were not responsible just condition of pipe.

Presenter

Keith Leewis- GRI "Direct Assessment"

Bob Sutherby [TC] What do you need to put into the model?

Keith Leewis [GRI] History, land forms, soil types, chemistry to relate data. Bottom of hills, coating, these are all indirect measurements then you need to dig and find the truths.

Barry Martens [Rainbow Pipeline] If disbonded coating doesn't have a chance for water being trapped ie the disbondment doesn't reach the edge of the tape, is that wrinkle put in to the assessment?

Keith Leewis [GRI]. May find that you need to dig in places where you don't think you have SCC and determine that – need to validate the predictions with the truth (digging the pipe)

Bob Sutherby [TC] What are direct assessment expectations?

Keith Leewis [GRI] Expectations to help NACE committee out in integrity management plan.

Walter Kresic [Enbridge Pipeline] Why the word direct assessment?

Keith Leewis [GRI] That word was chosen by regulator. Need to touch the pipe to take measurements and to validate.

Wenyue Zheng [Canmet] What kinds of things do you look for in chemistry of soils?

Keith Leewis [GRI] General clay and moisture content. Each company has found own experiences and should look to CEPA for the definitive answer.

Presentor - Scott Ironside [Enbridge Pipelines] "SCC Monitoring Program"

John Craig [PNG] Is 34 inch most susceptible?

Walter Kresic [Enbridge Pipelines] 50% of line is tape therefore susceptible. Less susceptible on asphalt.

Barry Martens [Rainbow Pipelines] Is there something that could constitute a change? Bigger companies need to guide smaller companies with their knowledge. We rely on these companies for direction.

Walter Kresic [Enbridge Pipelines] Based on all the work we've done, SCC is everywhere but not severe. We feel confident to say our pipeline is safe whereas we couldn't have said that in 1995.

Barry Martens [Rainbow Pipelines] What is different about models today that will guide me to the more severe SCC? Any changes that can direct me?

Walter Kresic [Enbridge Pipelines] No panacea. Need models and this would be important to companies just starting. We use all technologies – know that SCC risk is low.

Barry Martens [Rainbow Pipelines] What can a 12 inch pipeline company learn from you?

Keith Leewis [GRI] No silver bullets. Need to do it for your own system. If another company finds a strong correlation it may or may not work for other companies.

Barry Martens [Rainbow Pipeline] Industry follows a few companies and relies on them for new information. Need to disseminate info to help small operator that doesn't have money, tools, etc who could still have a rupture that could hurt someone.

Bob Sutherby [TC] CEPA database is a source of information. Nine company members. Need to continue to gather information and trend it.

Stan Wong [CC Technologies] Bigger companies making available mechanistic info. In-house deterministic model mixed with mechanistic model in lieu of pigging for smaller diameter companies.

Steve Lambert [U of Waterloo] Bigger companies can take models to next level. Did ILI make changes to your model? How does this filter down to smaller companies?

Walter Kresic [Enbridge Pipelines] No changes yet have been made to the landscape models from ILI data. Doesn't matter where you are you can find SCC. FBE and properly applied coatings are far less susceptible – good info for decision making. All additional data will incrementally improve your individual companies decision making process.

Steve Lambert [U of Waterloo] As a small operator – you can't tell me where severe SCC is? With more ILI you should be able to correlate soils model better.

Walter Kresic [Enbridge Pipelines] Maybe that will happen.

Glen Cameron [GreenPipe] Populated area – consequence of failures should be incorporated. That's what we are going to use in the GIS world.

Keith Leewis [GRI] Models should not be thrown away. Need all the tools in your toolbox. Models and direct assessment need to feed each other.

Stan Wong [CC Tech] On small diameter – have their been any significant SCC on 16 inch or less?

John Craig [PNG] has had 5 hydro failures and 2 in-service failures on ERW pipe.

Glen Cameron [GreenPipe] Yes we found SCC on a 10 inch liquid line (from excavation)

Curtis Parker [Trans Gas] Limited amount of SCC on 12 inch and 16 inch pipe.

Bob Sutherby [TC] Rimby failure? SCC or mechanical damage? I want to be clear on what we call these things.

Barry Martens [Rainbow Pipeline] Mechanical damage can mean wrinkles. Can this mechanical damage lead to SCC.

Fraser King [NRTC] Closing comments.



- Validation -

Direct Assessment External Corrosion

Keith Leewis, GTI March 2001



Direct Assessment


- Alternative to Pigging & Hydro in HCAs
- Provide NACE with justification & draft language for a new standard
- Operator Gathers & Integrates Data
- Operator Provides the DA Output
- · Validation Report Battelie



An Integrity Process

(not a tool)

- DA requires the integration of all three
 - alignment sheet information (GIS)
 - · facilities
 - historical records, DOT incident etc
 - · repairs, leaks, coating reports, etc.
 - · digs at concerns & were OK
 - above ground inspections
 - voltage (CIS, Annuals)
 - · current (DCVG, C-Scan, ACVG, PCM)
 - · historical records changes in CP system






Use the Right Tools


- No Blindly Applying Vice Grips to Nuts
- Use the Direct Assessment Process Matching Tool(s) to the Threat
- DA Works
 - CP Prevents Corrosion
 - Regs Require Annual and CP inspections
 - Annual Leaks Continue to Dropped 60% since 1985



Direct Assessment Validation Report

- Field Inspection Work
 - Conduct Continuous Inspection(s)
 - Use the DA Process to Determine Locations
 - · Yes, Moderate, No
 - Digs provide the Truth
- Document DA Process Decisions
 - When DA Appropriate & Not
 - Integration (Paper & Electronic)
 - Facilities, CP Inspections, & History (All three)







Correspondence with MFL ILI Assessment (Wall Loss)

- · Bad, Medium, Small, & Missed
- · Check vs Bell Hole (Truth)
- Can't find active corrosion only total wall loss from day one
 - One to One Correspondence with DA impossible
 - DA Estimates Active Corrosion Proactive & Regs, Looks Now
 - Pigging Estimates Deep Wall Loss Reactive, Looks Back

April 9-12, 20

of Mr. Padin Visitin



Direct Assessment Timeline

- Direct Assessment Standard in NACE
- · Validation & Reporting
 - May 1st for 20 data participants
 - June 30 for submission of all data
 - June 30 to complete funding
 - Sept 30 for draft report of the validation
 - Dec 15 final report due



Direct Assessment Confidentiality

- Ed Ondak & Greg Hindman the OPS Witnesses
- · Baseline Tech Info Gathering and Organizing
- · Battelle Statistical Proof, Documentation
- · Aggregate in Report has No ID Location
- · Company Data Returned

April 5-12, 3801

Direct Assessment

Funding

• FERC (GRI & PRCI)

\$180K approved

· OPS

\$180K solicited

Other Participants


\$600K soliciting


- Management by INGAA Pipeline Safety
 - GTI Prime, subcontracting to
 - . Baseline data gather/migrate to electronic files
 - Battelle Statistics and Report
 - Paragon, CCTechnologies, GTI confirmation


April 6-12, 2001


Sent 2001 Penter Western


1000 12
















		od opida de ministra de des de la companie de la c
		derekerizelik kiris et erman handa et erman kiris kiris et erman kiris produktura et erman et erman et erman e






















Outline

- · Inquiry Report
- · Post-Inquiry
- · SCC Liaison Group
- · Ongoing Activities
- CEPA Trending
- · What's New
- · Plans and Priorities

April 9-12, 2001

Bunil 2001 Pipeline Workshop



Inquiry Report Recommendations in 6 Key Areas

- SCC management program for all pip elines
- · Changes to the design of pipe lines
- · Continued research
- · Establishment of SCC databas e
- · Improved emergency response practices
- · Continued information sharing

April 9-12, 2001

Banif 2001 Pipeline Warkshop

Silde 10



Post-SCC Inquiry

- SCC Inquiry Report
- · NEB SCC Liaison Group
- · Community visits
- SCC Management Plans submitted by All NEB regulated companies & reviewed
 - Meetings with 4 companies

April 8-12, 20

Banif 2001 Pipeline Workship



NEB SCC Liaison Group

- CEPA/CAPP/CSA/EUB/BC O&GC and NEB
- Monitor progress of implementation of recommendations
- · SCC research funding
- CEPA/CAPP SCC database & trending

April 9-12, 2001

Seef 2001 Plyains Workshop

Slide 12



NEB Ongoing Activities

- Qualitative Risk Ranking of Companies SCC Susceptibility
- SCC Management Plan Updates (1999)
- Company Meetings
- NEB SCC Liaison Group

April 9-12, 2001

Read 2000 Minutes Minutes

Nute 13



CEPA 2000 SCC Database T rending Report Results

AW	Larginirapacisci(m)	No SCCOlores
Gas	125,855	17,925
Liquid	20,532	388
Total	146 387	18.291

Approx. 300 cases of significant SCC reported to the NEB

72.2001 Banf 2001 i

654. es



What's new?

- · Residual stress
- · Concrete weights and asphalt coating
- Circumferential SCC
- High pH SCC in Saskatchewan

April 9-12, 2001

Benil 2001 Pipeline Worksho

Sinder 15



What's needed?

- More SCC research?
- Is ILI technology improving quickly enough?
- Need clarification regarding termino logy associated with EAC mechanisms?
- Are predictive models reliable?

April 9-12, 2001

enfl 2001 Pipeline Workshop

State 18




Plans and Priorities - NEB Operations Compliance Team

- Continue to meet with companies
- Continue to monitor in cidents
- Integrate SCC Management with Integrity Management Program audits
- Continue to monitor SCC sc ene

April 9-12, 200

Band 2001 Securior Michael

Sincia 17






Somebody recently told me that SCC is a dead issue.

- At the NEB we still feel that it is an issue that requires continued monitoring as part of an overall integrity management plan.
- Do you and your company think SCC is not a problem?
- · Are you managing it effectively?

April 9-12, 2001

Sanif 2001 Papaloss Wartship

Sim 18





Industry Accomplishments

- Defined State of Industry
 - 1995 SCC Inquiry
- · Industry Guidance
 - CEPA Recommended Practices
- · Enhanced Collaboration
 - National / International Agencies

April 9-12, 2001

Sent 2001 Pipeline Worksho

Sinda 21



Industry Accomplishments (con't)

- · Formalized Processes
 - CEPA Data Collection
- · Continued Improvements
 - Research Projects
- · Disseminate Kn owledge
 - Trend Reports
 - Public Presentations

April 9-12, 2001

Benff 2001 Pipeline Worksho




Five Years On ...

- · Are we 5 Years better?
 - better at preventing SCC?
 - Is the public safer today than 5 Years ago?
- · Pipeline systems are 5 Years older
 - 5 Years more issues
 - what is the significance of 5 Years more age?

April 9-12, 2001

Bant 2001 Plenine Wertero

Fac. 71



1999 SCC Summary

Evaluation of SCC Defects

- · SCC in Corrosion
- · Bacteria associated with SCC
- SCC is proportional to tape application
- · How to document dig observations
- Role of hydrogen and microstructure
- · SCC at/near weld seams
- · Liquid and Gas lines
- · CEPA data base

SCC Site Selection Models

- · background & objectives
- roles & components
- expectations of performance
- · future of models

Evolving SCC Scope ...

- Near-neutral pH (Non-Classical) SCC
- High-pH (Classical) SCC
- · Toe Cracks
- · Circumferential SCC
- · Cracks in Corrosion
- · Other environmentally-assisted cracking

Objectives

- · Create a refocus of issues
- · What are models to you?
- · What goes into models?
- · What do we use them for?
- Do / Can models meet our expectations?
- What is the future of models?

Background

- CANMET Workshop 1989
 - based on TCPL ruptures and digs by TCPL and NOVA
- Correlations
 - Tape
 - Soil Texture: Heavy Clay
 - Drainage: Imperfect to Poor
 - Topography: Depressional or Slope Toe

Background

- Reference to an "SCC Soil Model" in the 1996 SCC Hearing
 - deterministic based on excavations
 - "to identify areas of potential susceptibility"
- Recommendation 4-2: " ... develop a predictive model to identify and prioritize sites ..."

Background

- CEPA SCC Recommended Practices (1997)
 - "SCC Predictive Model"
 - Terrain, Pipe Design, Coating Condition, etc.
 - Condition Monitoring

Background

- Alberta Energy & Utilities Board
 - = notyrthx/sne_tener aspkalt or coal tar
 - -hoop stress > 45% SMYS
 - installed 1968 1973

Background

- · "Direct Assessment"
 - to comply with U.S. Federal Law
 - INGAA developing
 - remote inspection information to provide an "equal measure of pipeline integrity with pigging and hydrotesting"
 - Keith Leewis of the Gas Technology Institute

SCC Site Selection Models

- Why are we <u>discussing</u> models? Why are we <u>not teaching</u> models?
- Models embody <u>your</u> knowledge of <u>your</u> system based on <u>your</u> experience
 - age, region, fluid, operation, coatings, etc.
- Correlations and Mechanisms may be portable
- Entire Models may not be ...

Model Considerations

- · Deterministic or Mechanistic
- · Portable
- · Different Coatings and Conditions
- · Correlation to failure?
- · Applicability to different forms SCC?
- · Who develops models?

Roles of Models

- · Regulatory 'Compliance'
- Integrity Management
- Due Diligence
- · Risk Assessment
- · Research Tool
- Other?

Objectives

- Create a refocus of issues
- What are models to you?
- · What goes into models?
- What do we use them for?
- Do / Can models meet our expectations?
- What is the future of models?

			ndisperre o malalita je pisipe je ne ve opaz je jeka in
			turbili mere i de escor por esterminamilos este escor
			A Salada de Caracido de Caraci

Managin ⊌ipeline Integrity: Stress Corrosion Cracking April 11, 2001 8:30 a.m. - 12:00 p.m.

Managing Pipeline Integrity: Stress Corrosion Cracking April 11, 2001 8:30 a.m. - 12:00 p.m.

SIGNATURE	MONTON	Do State	Maj.	KA	6.5.	Beensteins	RP 1#1	May Hate	A THE STATE OF THE	in And in	you an	A STATE OF THE STA			Say Cont	n Em	Maria Jackud
e-mail	ALDODGCNAL.COM	ebatehelor@wer.ang	begden e wei. org	dous adamson @ asso. com	deb & Ampai.com	denene Chmpsi.com	COD, PRIVER O	jashwerth Eman rassociatesca	- of the region of states	403 260 0714 graemeking Syeenppe.cm	glenner or or erwo againgto, com	afflaten He daguelthy.com	Bsminens @ 1 Hquality.com	Krishnamuzthyred Pii-Usa.com	Stere @ awater ba.ca.	biztekrrfwaol.com	msontander & neb.gc.ca
PHONE	403-517-7276	250-760-2022	604.866.5544	780 955-6159	78~ 913 - 5677	780-436-4400	43.517-7760	403-258-2233	144-791 8352755	403 260 6714	4032606748	0099 -0h), (08c)	(35) 468 SO19	(413)849 6339	12 5 888 Piz	847-733-7410	(403) 299-3652
NAME	ALDO DIFLUMERI	ERROL BATCHELOR	PRION OCOEN	Doug Adamson	DEBBIE SIEMENS	Deneve Geissler	203 PEWFR	JOEL ASHUONTH	DER BOREY	Graeme King	Cleur Candon	KNORE FLATRAULT	FOE Simmons	Ravi Krishnamm #4 (713)849 6339	Sew Lambert	,	Monica Sandander
COMPANY	CANADIAN NATURAL RESCURCES LTD.	VESTCOAST ENERGY INC	WESTCOST ENERGY	Imperial Oil	8	4) prime Services	ALLIA FLACE	MAKA ASSOCIATES	MAKR AGOZIATES	Greenpipe	CARREN PIPE	Aro Quality SERVICES	RES QUALITY SECTIONS	1.0	d Waterloo	BIZTER CONSUlling, Inc. Ray	National Brungy Board
	18	61	20	21	2	23	7.	25	26	27	28	29	30	3	32	33	34

Managin, 'ipeline Integrity: Stress Corrosion Cracking April 11, 2001 8:30 a.m. - 12:00 p.m.

35					
	Mimoun ELBOUTDAIN, CANMET/MTL		1468-34619	malbooid ONKan.ac.ca	0
	July Beavers	CC Tor huslosia	4121 192 419	stravers (8 Cct/abs.com	
37 6	Burke DelANTY		(403) 250- 9c41	4 c. bunks a telusofor st	
	TON PESTA	EVB	8412 CB2 SA4	701. PESTA 3 601. A 6. CA	
8	Suwn McGragor.	Trans Mountain.	150 ST UP!	Sherson & TMP1. 14	(), 7, C
40	108 HADOEN	TML	604 268 3011	Worth Truel. Ca	1111
41 /	Kyla Loewen	Trans Mountain Pipe Line	780-449-5913	Kylal @ tmpl.ca	The land
42	340 C. LEE	EUB	403 297.3367	403 297. 3367 Shu loop any ab co	10 0
	Tom Lawrence	IPSCO INC	306-924-7385	+ law Pence @ 10500 Co.	~ I \
William Contraction		The second second second		Water Control of the	Var. Mar
(-1	2AUD COLEMAN	CENTRA 445	204-480-5570	hydra. mb. cq	W
7	Dennis Zadary	Compro Cornelle, Inc	760 - 447-4565	demis Tuture O Course on	, , , , , , , , , , , , , , , , , , ,
<u>Z</u>	Nancy Jubois	National Eneral Spand (403) 299-3101	(403)299-3101	ndubois@neb.ac.ca.	W. W.
4	REG Emois	NRTC /USA.	403 350 4526	reg. codica wallsch. ce	Sold of the second
40	Mary Gale		403-314-749)	3	
\$	very Garlet		405-420-6025	1-7	S.
N	Scott Kensile	6N6,2106 E	780-42 5267	Softwarily to and saled.	SAS
					ーーーーー

Managing Pipeline Integrity: Stress Corrosion Cracking April 11, 2001 8:30 a.m. - 12:00 p.m.

	June	The Minne	W. Kursis	allosh		O fantamil	R	at Ti	Motioner	Reful	W. C. L. D. C. W.	Jat J	Jan		On	Dricken
ben Divicange.ca	BELLING COM	simmons Q cad Usion, com	walter tresse @ capi can	dwasten Eneb.gc.ca	batt Princil, order pur not br	Parlas, Pardo @ Cnpl-enbridge. Com	Shaun.dowe @ Cnpl. enbridge con	catherial-pinan (c) transcanada com	a petruseup corresionseine com	Mjohnene Marr-assermte, com	jmare structure with a	simmons advision. com	ntruster @ bogas. com	ALL TEST INSPECTION 403-262-5757 rojette Orklusplanet.net	morbieher a egreonpiph. con	doctelance @marr-associates.com
613-992-4282	780- 449-2108	403 541 5308	180 420 -8278	403 299 3680	55(21) 5400763	780 - 054 - 08434	780 420 -8684	403-920-6575	403-335 3601	403-758-2233	403-258-2253	P15-54) 5319	4001-972-40d	403-362-5757	9462-202 (804)	403-288-2233
CANMET/MTL	Sundrak Enlergy MARKETLIK INK	SIMMONS GROUP INC	ENZX 10GE	NATIONAL ENERGY BOARD	CATHOLIC UCIVERATY OF RICOR TAMERICO		Enbridge	Trans Gnada	Corresion Service Comp.	MARK ASSOCIATES	MARR ASSOCIATES	SIMMOJS GROUP INC	Bl Grs Whiling	ALL TEST INSPECTION	GREENPINE INDUSTRIES	Marr Associates
Jenny Been	SR.Ad DENNIS	DON HERMAN	WALTER KRESIC	Doug MASLEN	WANI BOTT	CARLOS PAROS	Shaun Dawe	Catherine Pineau	Alex Petrusev	MARK JOHNSON	JIM MARR	Dave Toporowsky	Norm, Trustur	RON PRETTE	PHUA MURBACHER	Dave Porteance
52	53	45	55 (99	57	58	65	9	61	62	63	49	65	99	10	89

Banff/2001 Pipeline Workshop

Managing ripeline Integrity: Stress Corrosion Cracking April 11, 2001 8:30 a.m. - 12:00 p.m.

AKGL	517	ere transmission de la companya del companya de la companya de la companya del companya de la co					тива предперава от поставления в поставления от п	A CONTRACTOR CONTRACTO			териной и нападууна на на предууна од стој стој стој стој стој стој стој стој				Annual proprieto managemente com approprieto de la manca de la companya de la com			
ramesha) raeinspection. Con		bamy , nattens es email mbis con											And the second s					**************************************
780 · 469 · 240		9<8<																
Ramesh Singh	N. T.	.i																
RAE MSPECTION SERVICE	Signal Signal	1					The second section of the section of th		i				e de la companya del la companya de	The second secon				
69	92		72	73	47	75	92	The state of the s	278	7.9	Name of the contract of the co	¥ Q	T S	82	83	84	85	The state of the s



SCC Working Group Summary

- NEB Hearings 5 Years On
- 5 years wiser? Or 5 years older pipelines?
 - Bob Sutherby (TCP) NEB hearings background
 - Doug Wasien (NEB) summary and recommendations from hearings
 - Walter Kresic (CEPA) gave the industry response to the recommendations
 - In 1993, SCC was one of the major issues that prompted this workshop, and now we are in a position to ask......

April 9-12, 2001

Soul 2001 Pipeline Warkshoe



SCC Working Group Summary

- is SCC a dead issue? Consensus says No!
- But the "fear of the unknown" is gone
 - at least from perspective of liquid lines with in-line inspection tools
 - dry gas lines still waiting for improved technology
 - In-Service failures have been largely prevented by proactive actions

April 8-12, 2005

Land 2001 Pinning Workshop



SCC Working Group Summary

- Liquids versus Gas led to a difference in opinion on perception of risk
- Some say equal susceptibility
- Some say liquid lines are less susceptible
- · Good topic for next workshop
- SCC on upstream lines
 - upstream under-represented (scheduling conflict)
 - do upstream companies see SCC as an integrity issue?

April 9-12, 200

Sanf 2001 Positive Workshop



SCC Working Group Summary

- Should the Canadian Public feel safer now than they did 5 years ago?
- Yes, but require continuing vigitance and education

April 9-12, 2001

ienii 2001 Pipeline Wartshou



SCC Working Group Summary

- · SCC Site-Selection Models
 - What are they? What are they used for? What are our expectations? What is the future?
 - Bob Sutherby (TC) Background to models
 - Keith Leewis (GTI) Direct Assessment
 - Scott Ironside (Enbridge) Landscape models with ILI
 - current models do not predict severity, just occurrence

April #-12, 2001

Burll 2001 Papeline Wartsho



SCC Working Group Summary

- · Evolution in Models
- More focus on predicting deeper cracks
- More types of info being incorporated
- Models must be company/line specific
- But companies should share experiences!
- Direct Assessment
 - Formalized U.S. initiative (int/ext corrosion, SCC)

April 9-12, 2001

Banif 2001 Pleating Workshop



SCC Working Group Summary

- Direct Assessment
 - Models by another name
- · Models will still be required even with good crack ILI tools
- Models will be developed more quickly with the help of ILI
- · "NEED TO USE ALL THE TOOLS IN YOUR TOOLBOX"

April 9-12, 2001

Working Group 6 - Coatings Wednesday, April 11, 2001 at 10:30 a.m. - 5:00 p.m.

Co-Chair:

John Baron, Skystone Engineering

Co-Chair:

Doug Waslen, National Energy Board

Rapporteur:

Kelly Mabbott, Skystone Engineering

Introduction and Objectives of the Session

- Approximately 90 people attended the workshop.
- The objectives of this session include:
 - O Update issues identified in 1999 coatings workshop
 - O Discuss proposed changes to the CSA Z662 code for coatings
 - o Define Cathodic protection compatibility with coatings
 - o Address field assessments of in-service coatings
 - Qualification of coatings for high temperature applications
 - Quality of field applied coatings
 - O Discuss selection and application of repair and rehabilitation coatings

Presentations

Paper #1: Doug Waslen (NEB)

- **Proposed Changes to CSA Codes**
- Changes should be published in 2002
- NEB SCC inquiry report stated to develop standard tests and incorporate these tests
- Work started in 1998
- Do tests determine performance over the life?
- Reduce variables
- Five areas of the team
 - Assess coating suitability
 - Pipeline Design, Construction, operation, Coating application, Service changes, interaction with different coatings, coating storage
 - Test the coating
 - Isolate from the environment, adhesion, ductile, strength and adhesion, resist degradation, compatible with CP
 - Application and OA
 - Documented procedures for shop and field applied coatings. (QA test, personnel standards and application)
 - o Re-assess coatings in formulation or manufacturer or location of manufacturer
 - O Re-assess coatings for change of Service for the pipeline
 - Change in service, change in temperature
 - O Coating Selection, Assessment, Application and Inspection

Discussion and Question

- Tom Weber (Trenton) Is this document going to have minimum criteria?
 - No. Liability of CSA. Must update the criteria. Some controversy and arbitrary.
 - John Baron (Skystone). The changes to CSA represent a new approach that involves up front engineering to avoid last minute selections.
- Mike Reed (TMPL) What about replacements. Do we need to assess the coating for every minor repair?
 - Assessments are specific to coating products under certain applications
- Jim Banach (SPC) How do you audit a system with no criteria?
 - That is difficult. It comes down to professional judgment.
 - The assessment of the coating could be audited
 - Can you tie short-term tests into long time performance? Is there anything published with a minimum time required?
 - No. It is up to the design of the pipeline. No minimum amount of time is stated.
- Linda Gray (KTA Tator) How do you handle new products? How do you set criteria now for future possibilities?
- Glen Macintosh When does this take affect?
 - Once it is approved by the CSA technical committee, it is basically waiting to be published.
- Jacques Eberle (Hempel Coatings Canada) Why do you have to re-assess if you change the manufacture location. One plant to another.
 - It is a QA issue between plants.
- BC Gas Application of this new practices, I'm I responsible for a good coating throughout the pipelines entire life. That is tough to do.
 - Assess the factors listed in CSA. The requirement to assess these factors in conjunction with service life is not required.
 - The possibility of service changes should be looked at.
- How do I certify that the coating meets the end use? I will not go out and test 100 coatings for one pipeline. I will leave it up to the coating manufactures.
 - Regardless of who selects the coating, the accountability in meeting CSA is still on the owner. This is consistent with current requirements.
- Becky Morse (Charter Coatings) Almost impossible to compare coating to coating due to testing differences. The new CSA requirements will help.
- Neil Hay (Koch) New requirements for application procedures are included in the new CSA revisions.

Paper #2: Tom Jack (Nova Research and Technology Center)

- Coatings and CP Compatibility
- CP and Coatings. Must work together.
- A checklist was presented to aid in the definition of CP compatibility. Is it damaged by CP, allow CP to get to the pipe even when the coating fails, does not generate a damaging environment, will coating save the day without CP, and minimize the CP costs
- Examples: Use the checklist to answer the questions on that sheet.

- o PVC tape wrapped coatings. Contains plasticizers and therefore fails over time as the plasticizer comes out. NOT CP Compatible.
- O PE Tape. Shields the pipe from CP. NOT CP Compatible when failed.
- O Asphalt Coating: Become permeable. Water and CP do get in. Promotes SCC environment. NOT CP Compatible.
- o FBE: Under ideal conditions it is good. But with a defect you get cathodic disbondment. Is pretty good CP Compatible.
- O New Coatings: Are these compatible, do we need CP?
 - FBE used in combination with tape wrap 2 meters away. FBE was good, tape had SCC and corrosion.

Discussion and Questions

- John Baron: How far under a disbondment can CP protect?
 - Not far, 10 to 15 cm but based on salinity of electrolyte. There are some exceptions due to geometry
- Jim Banic (SPC) With respect to multi-layered coatings, if the substrate was coated no shielded was seen.
- Peter Singh (Shaw Pipe) Do you need massive disbondment. Where does soil conductivity come into play?
 - A pipeline buried in rock had water soaking into the asphalt but due to the rock no CP could get to the pipe and corrosion occurred.
- Becky Morse What is your experience with extruded PE?
 - It is pretty good. Not a lot of problems.
- Linda Gray CP disbondment with FBE. Has there been active corrosion found under FBE with good CP?
 - Aida Lopez Some, but very little.
 - Becky. You get breaks in the blisters and the low PH water gets out.
- Jamie (Dupont) yes there is some in the states.
 - Tom Webber If the blisters are intact, there is no problem. This implies that if the blisters break your CP may not be good enough.
- John Baron Over protection may have been a problem.
- Jim Banach (SPC) It is still possible to get corrosion due to low current densities often used for cathodic protection of FBE coating pipelines.
- Jim Banach Are there going to be changes to the testing with regards to coating disbondment? (i.e. longer CDs).
 - Merely extending current test duration is not seen as appropriate. New test methods are
- West Coast Energy. Pipe handling with respect to coatings (i.e. trucking). Is there anything within the new CSA with respect to this?
 - No specific changes.

Lunch Break

Paper #3: Becky Morse (Charter Coatings)

- How We Perform Field Assessment of Coatings
- Objective: Discuss the elements of field assessment of pipeline coatings.
- Two elements of Inpsection. Visual Inspection and Non-Destructive testing.

Visual Non-Destructive Assessment

- · Girth Weld Coatings
 - Sleeves, Tape, and Other
- Types of Defects
 - Application problems, Environmental issues, blisters in Epoxy, clockspring compatibility

Destructive Testing

- Coating Integrity and Condition of the metal
- Field adhesion tests (X, triangle, peel)
- Holiday Testing (ASTM Test Method or Voltage0)
- Cathodic Protection Compatibility
- Decision Path (Large or Small)
 - O Short term moisture barrier
 - o Long term mitigate corrosion
- Criteria for Repair
 - o Compatible with existing coating
 - Compatible with operating temperature
 - o Work for intended service

Discussion and Questions

- Tom Weber Do you feel that field coatings require third party inspection?
 - Yes, coating in the field must be applied in the same way as in the plant.
- Phillip Nidd (Agra) Do you have a data base with special problem relating to coatings
 - No but would consider being involved.
- Jim Banach (SPC) What are the main causes of coating failure for shop and field?
 - Shop applied failures -1) Coating used in the wrong application.
 - 2) Operating conditions change.
 - Field applied failures 1) Application!
- John Baron (Skystone Eng) Holiday Testing, what is your recommendation for field holiday testing. Voltage?
 - Bob Bauer (TCPL) Low voltage (67.5V) wet sponge works well. Must educate the field personnel
- Mat Cetiner (Anteris Corrosion) Should you include soil condition.
 - Yes
- Stan Wong (CC Tech) Some of this information may already exist in the CEPA database.
- Glen Macintosh (Denso) Absence of service history complicates coating assessments.
- Tom Weber Look at current leakage testing procedure ASTM G18. It tests coating current leakage using a 6-volt cell tied to a specimen and measures the leakage.
- Phill Ned One other factor is economics associated with coating application and cure time extending pipeline outage.

Barry Martins (RPL) - Want to ensure coatings fail safe. We don't put rock shield on in rocky areas so that when it fails, CP gets in.

Paper #4: Peter Singh (Shaw Pipe Protection)

- How We Select Coatings for High-Temperature Pipelines
- Most applications are in heavy oil and conventional Oil and Gas
- Temperatures between 85 and 135 degrees C.
- Coatings used include tapes, FBE, multi-layers and liquid epoxies.
- Failure modes include embrittlement, cracking, disbondment, and mechanical damage from shear stresses.
- These coatings must do all normal coating requirements in addition to high temperature.
- Temperature effects include, lowered adhesion, reduced mechanical properties, increased permeation, increased corrosion rates and increased thermal stresses.
- Evaluation tools? There are currently no industry standards for assessment of high temperature coatings.
- Techniques used include cathodic disbondment, hot water adhesion, mechanical properties, glass temp, oxygen induction time
- Water adhesion at 95 degrees may not apply to service at higher temperatures.
- Cathodic disbondment increases with temperature and peaks around 80, less disbondment may occur at higher temperatures, 90-100C.
- Mechanical property tests do not indicate change in value with time dependence.
- Glass temperature (Tg) can be measured by DSC or DMA and is a reversible step change in properties, which limit the useful temperature.
- Higher Tg for multi-layered systems gives higher adhesion and peel strength.
- Oxygen induction time determines the antioxidants level in coating
- Accelerated heat aging. You age it at a higher temperature to accelerate the temperature effects and then extrapolate to determine coating life at lower temperatures.

Discussion and Questions

- Linda Gray (KTA Tator) Temperature 85 to 135 degrees C, is there liquid water in conduct with the line at those temperatures?
 - Often not since the heat tends to dry out the soil surrounding the pipe.
- Tom Weber (Trenton) Do you know if any tests can be made to predict high temperature
 - There needs to be a number of tests to do this.
- Bob Smyth (Petroline) do you have experience around 300 degrees C
- Anteris Corrosion In the CP disbondment graph presented, how many different types of coatings were used?
 - The idea wasn't to focus on the materials and the numbers, but rather on the trends; data is not specific, but more general in nature.
- Linda Gray Indication tests are used how about Shore D Hardness. Is that a good method?
 - Yes, it is a good value. Indication is more time dependant.

- John Baron (Skystone) the Tg slide with multi-layered coatings. The "Primer" appears to have a large effect.
 - Yes
- Becky Morse (Charter Coatings) The choice of primer is very important. Effects of long term CD and long term water adhesion testing.
 - CD has been run up to a year. 30-60 days is more typical. Solution has to be changed and therefore you require more in depth procedures.
- Jamie Cox (Dupont) is seeing pipelines around the world and was designed for around 110 degrees C using 3 layer polypropylene coatings.
 - Most qualified with CD tests around 100 C.
- John Baron (Skystone) Can you update us on CSA Z245.20/21 activity.
 - Discussion on 3 layered polypropylene standard, but has been on hold.
- Stan Wong (CC Tech) Are there tests for high temperature coatings for areas around reciprocating equipment
 - Some
- Doug Waslen (NEB) Peter has looked at many tests; can you combine tests to gain more information?
 - Some of the testing is heading in that direction.
 - Jamie Cox (Dupont) This is being done in some projects
 - John Baron (Skystone) There needs to be more testing and standardization in this area. We have a lot of learning to do.

Paper #5: John Baron (Skystone Engineering)

- How We Achieve Field-Applied Girth Weld Coating Quality
- More emphasis on Field-applied coatings.
- Number of failures due to external corrosion has started to come down based on AEUB statistics.
- Coating performance testing will be included in the next CSA Z662
- Field applied coatings used on risers, repairs, welds etc.
- There are many different types of coatings to be used in these cases
- Problem usually due to bad design and application
- Shop + Field = Coating System. The system must be accurately designed
- For application most people use "Manufacturers recommendations"
- Application OA will be in CSA including procedures and personnel
- Industry needs increased standards to address field coatings until they reach a level close to shop applied quality.
- Shop applied coatings have good quality programs in place resulting in generally acceptable quality coatings.
- Field coatings also have to address insulated pipelines
- Coatings also have to deal with soil shear stresses not just peel and pull off adhesion.

Discussion and Questions

- Jamie Cox (Dupont) Do you have shear stress numbers that are normal
 - 0.12 mPa is a normal resistance stress quoted in some European standards. This may be a little high. The trick is getting these values at the operating temperature required.
- Becky Morse (Charter Coatings) Can you comment on specialty joint coatings for long bores
 - People are currently using a Fusion bond spec (CSA Z245.20) to apply liquid coatings.
 There needs to be a separate standard.
- Wayne Duncan (CSI Coatings) How do you qualify people?
 - Usually a training seminar is put on by the manufacturer
 - Bob Bauer (TCPL) Anyone touching the coatings is trained and will be tested.
- Mark William (Canusa) It is the manufacturer who is doing the training. There is a large problem in many companies not asking for the training.
- John Morse (Charter Coatings) Quality of sleeve application goes up with trained people and using the same trained people all of the time. Destructive testing could be used to keep the crew honest. Cut off a few sleeves with criteria of good and bad.
- Wayne Duncan (CSI) You need more than a one day seminar. What is needed is quality
 procedures usually produce by the manufacturer. Possibly legislate that the people are
 trained and that the shop applied standards are met.
- John Baron (Skystone) maybe you have to require more accountability by individual installers. For example, requiring putting the installers name on the joint. Gives some accountability.
- Mark William (Canusa) Some companies have procedures that have destructive testing to prove quality. (i.e. cut off every 100th sleeve and test it)
- John Baron (Skystone) Is this happening for liquid systems as well?
 - Wayne Duncan (CSI) The do destructively test a percentage of the joints as required.
- Phillip Nidd (Agra) His people go through a 3-day seminar. They also explain the results of bad coatings.
- Jim Banach (SPC) Is it in CSA now to qualify personnel
 - Yes, personnel training is part of the new requirements.
- Bob Smyth (Petroline) The inspectors should go through the same training. Often
 misinformed inspectors can create application problems by lack of knowledge of application
 procedures.

Paper #6: Aida Lopez (TransCanada Pipelines)

- How We Select and Apply Repair and Rehabilitation Coatings
- Two main repairs are large scale Rehab and then the small rehab during excavations.
- Large Scale Rehabilitation started in 1996. Currently use line travel equipment on areas over 5 km.
- Smaller sections, there are patch repairs, entire joint repairs.
- Depending on the coating uncovered and the length of damaged coating, different repair coatings are used.

- Depending on the pipeline operating temperature at that location, again different coatings are used.
- For cold temperature applications, the best coating are the Vinyl Esters and the Polyethylene
- Surface preparation is critical. Usually near white blast.
- For yellow jacket girth welds, they use liquid epoxy with the ends wrapped with a sealant.

Discussion and Questions

- Jim Banach (SPC) Liquid epoxies with yellow jacket. The PE needs more treatment, has TCPL looked into this.
 - Bob Bauer Treating the PE with Fluorine gas does help a small amount. Although, due to safety this is not practical solution.
- Are there any safety problems with asphalt coatings?
 - Yes, asbestos in the coating is a problem. People wear the appropriate safety clothing, wet blasting techniques used to eliminate dusting.
- Peter Singh (Shaw Pipe) The flame oxidation of the PE can be completed to help the bond although the spec is very specific.
- Jim Banach (SPC) Flame treatment helps but there are others such as chemical treatment that may be more effective.
- Phillip Nidd (Agra) The 2 layered epoxy continuous to cure after burial. Have you seen problems due to backfilling before coating is cured?
 - Backfilling should not occur if the coating isn't properly cured in accordance with TCPL specification for hardness.

Conclusions and Recommendations - Working Group 6

Proposed Changes to CSA Codes

- The new changes will help define the coating selection, application and quality processes.
- The challenge will be to implement the new requirements.
- The CSA Z662 Commentary document currently being prepared should include information on these new requirements such as the flow chart from the presentation and background information.

Coatings and CP Compatibility

- The definition of CP compatibility is not clearly understood.
- The proposed definition will provide a basis to assess coatings.
- It appears that not all coatings will meet the definition discussed.
- The CSA Z662 Commentary document currently being prepared should include information on the definition of CP compatibility.

How We Perform Field Assessment of Coatings

- You need to perform visual and destructive testing to assess coating condition.
- Operators should take the opportunity during excavations to assess and document the coating condition.
- A database to capture this information would be a benefit to industry.
- A simple checklist was presented which could facilitate the gathering of coating assessment information.

How We Select Coatings for High-Temperature Pipelines

- No industry testing standards exist specific to high temperature coating qualification (>85C).
- High temperature coatings have been used based on individual company specifications.
- CSA coating standards should address high temperature coating requirements.
- High temperature assessments will likely require accelerated heat aging methods.

How We Achieve Field-Applied Girth Weld Coating Quality

- The new CSA revisions, which include selection and application requirements for field, applied coatings, will require more up-front design.
- The industry requires a frame work for applicator qualification (including training, documentation and quality assurance)
- The compatibility of the field applied coating with the shop applied coating must be assessed.


How We Select and Apply Repair and Rehabilitation Coatings


- Coating selection for repairs and rehabilitation are dependant on the various factors such as pipe temperature and existing coating specific to a location.
- Often a combination of coatings is often required to achieve compatible system.
- Each repair method has documented procedures for application and training.


General Conclusion and Recommendations


- A coatings discussion group should be established to enable regular and ongoing improvements.
- It appears that coating selection, application and quality controls are improving.
- Coating technologies are continuously improving to meet the needs of industry.



























































































The Basic Problem

Iron is an abundant, inexpensive metal used in the fabrication of much of our infrastructure including pipelines.

Unfortunately it is also

- Thermodynamically unstable in most operating environments ⇒ Corrosion.
- Subject to a degradation of its mechanical properties in some environments ⇒ Cracking.

April 8-12, 2001

Sand 2021 Pipalina Warishne

Stide 5



The Protection of Iron (0)

In pipeline applications, iron is maintained in its original form by a combination of

- Cathodic protection (CP)
- Protective Coatings

These systems must work together for the life of the facility in all foreseeable circumstances

- CP must not damage the coating in a way that exposes unprotected metal to a damaging environment
- The coating must not allow a damaging environment to contact the metal surface

April 9-12, 2001

Soul 2001 Physics Wartshap

Sies 3



A Mission Statement for Coatings!

A coating must prevent a damaging environment from contacting the pipe surface under all foreseeable circumstances over the life of a facility in a given operating environment.

Any deviation from this expectation is a coating failure.

April 9-12, 2001

Sanf 2001 Pipeline Workshop

FIG. 4 - -



CP Compatability - A Check List

A CP Compatible coating is one that


- is not damaged by CP in a way that leads to coating failure
- allows CP to protect the pipe from corrosion even when damaged, defective or degraded in service
- does not generate a damaging environment at the pipe surface as a result of interactions with CP
- provides value by
 - · minimizing the cost of CP installations and operations
 - providing stand alone protection when necessary under all circumstances


April 9-12, 200


Sant 2001 Pipalina Workshop


Säder S


() c	P Compatat	ility Ch	eck Li:	st	
	PVC tap	e PE tape	Asphalt	FBE	New
CP promotes coating failure?		······································			
CP protects pipe despite costs defects, degradation, dama					
Harmful environment forms at			***************************************		
surface through action of				minore.	
Loss of CP never matters - the	coating				
will always save the day?	***************************************		***************************************		
Coating always keeps cost of C	P low?	**********			
April 9-12, 2001	Sant 2001 Pipeline Works	hop		San	• •


















































































Coating BACKGROUND -Pipeline

- Increased awareness of external corrosion owners, regulators
- 1/3 of Pipeline failures due to external corrosion
- CSA Z662, will include of coating testing to ensure performance criteria met. (Clause 9.2.8.1)

April 9-12, 2001

Bard MO: Pinning Warrishn

Stide 2



BACKGROUND

- · Field-applied, primarily to girth welds, repairs, risers, etc.
- covers the shop-applied coatings cut-back length plus weld.
- usually applied by construction contractor or subcontractor
- coating materials normally specified by the end-user, based on experience,etc

April 9-12, 2001

Banif 3001 Pipeline Workshop

Stide 3



OBSERVATIONS

- External corrosion at girth welds is a significant concern
- Problem often caused by poor design and/or fieldapplication quality

April 9-12, 200

Sanff 2001 Pipeline Workshop

State



DESIGN

- CSA will require an assessment of shop and field applied coatings!!
- Shop-ctg + FJC = Ctg System
- · FJC's often evaluated independently

April 9-12, 200

Soul 2001 Pipeline Wartshop

Skda S



APPLICATION

- Application standards generally based on "manufacturer's recommendations"
- most pipeline companies have in-house standards for application
- personnel training & material qualification normally specified!!
- code requirements for application quality are coming in CSA Z662!!

Awii 9-12, 2001

Benff 2001 Pleasne Workshop

Slide 6



Installation Specification

- Steel preparation cleaning, drying, pre-heat, weld splatter grinding, weld bead condition
- Materials and application equipment
- Application procedure
- Qualification of materials and personnel
- Quality verification

Apre 9-12, 200

and 2005 Persons Williams

3 mars 3



What's Needed??

- Industry Design standards to address FJC's
- Specifically:
 - alignment with shop-applied coatings design performance criteria
 - shop-applied coatings/interface performance
 - CP compatibility
 - application quality personnel, QA tests

April 9-12, 2001

Carrier 2001 President Workshop

North E



FJC's- "The future?"

- Increased specialist vendors to supply and apply #I/C's
- FJC quality will match or be very close to shopapplied coating quality.
- Codes will require materials qualification and applied quality performance.
- FJC materials will further evolve to match shopapplied coatings evolution

April 9-12, 2001

Carel (SSO) Promise Warning

3244 P




Challenge for the Next Millennium


"To select and apply pipeline coatings, in a manner, which significantly lowers probability of external corrosion occurring over the life of the pipeline"

April 9-12, 2001


ant 2001 Papaino Watahana


101-au 10
















specificant and the state of th
blosickelijessiskos samele
Sphilosophilabanskistosistes
nost siedensked
en sojaat (tä leeks ehe
ştik (cicas) eveni görü elektrili elektrili elektrili elektrili elektrili elektrili elektrili elektrili elektri
aabsookeelineevoisisselle
uidet et en de la company de l
and the state of t
hand many very over your warmen.
,
















Repair and Rehabilitation **Procedures**

- · Large Scale Rehab (> 5km)
- · Smaller Scale Rehab:
 - -PMP Digs
 - -SCC Digs
 - Construction Exposure
 - -Investigative Digs



Large Scale Rehabilitation

- Since 1996 over 80 Km (50 miles) of Transmission Pipe has been Recoated using:
 - -Line Travel Equipment
 - -Liquid Epoxies
 - -Length >5km



April 5-12, 2001



Smaller Scale Program

- Existing Coating in Good Shape but Requires a Patch Repair
- Existing Coating Badly Deteriorated
- Repairs when Pipe Surface Temperature is > 10°C
- Repairs when Pipe Surface is <10°C

Rand 2001 Pleasing Workship



Existing Coating in Good Shape but Requires a Patch Repair

- FBE and Liquid Epoxies:
 - Liquid Epoxies
 - Sweep-Blast **Existing Coating** (4-10cm)
- Asphalt-Coal Tar-Tapes-Extruded Poly:
 - Moldable Sealant with Bonded Polyethylene Outerwrap
 - Sweep-Blast **Existing Coating** (4-10cm)

Auril 8-12, 2001



Existing Coating Badly Deteriorated

- FBE and Liquid Epoxies:
 - Liquid Epoxies
 - Sweep-Blast existing Coating (4-10cm)
- · Asphalt-Coal Tar-Tapes-Extruded
 - Polyethylene:
 - ... Liquid Enoxies - Extruded Polyethylene
 - Shrink Sleeves

Outerwrap

- Petrolatum &
- Fiberglass Outerwrap Moldable Sealant with **Bonded Polyethylene**

Amii 9-17, 2001



Repairs When Pipe Surface Temperature is > 10°C

- · Liquid Epoxies (Mainline & Alberta)
- Extruded Polyethylene (Alberta)
- · Tie-ins:
 - Liquid Epoxies (for FBE, Epoxies, Urethanes Coated Lines)
 - Shrink Sleeves (for Extruded Polyethylene Coated Lines)
 - Petrolatum & Fiberglass Outerwrap or Moldable Sealant with Bonded Polyethylene Outerwrap (for Tape, Extruded Polyethylene, Asphalt and Coat Tar)

Mide 17



Repairs When Pipe Surface is <10°C

- Epoxy is the Priority Coating but it has Limited Applications when Pipe Surface Temperature is Below 5 °C
- Acceptable Mixing and Application at Ambient Temperatures as low as -20 °C
- Vinyl Ester (Surface Temp -2 to 0 °C)
- Urethanes (Surface Temp. 0-5 °C only for Cases where Abrasion is an issue)

April 3-12, 2001

and 700% Summan Montagen




RESULTS


- All these Coatings Have Been Successfully Qualified for Their Applications (Tested in the Lab and Field)
- Cure Complete Usually Under 4 Hours
- SSPC SP-10 Surface Preparation (2mils anchor)


April 16-12, 2001


ant 2001 Provinci Workings

20 to 14











Coatings and TCPL

- Evaluation and Testing of New Coating Technologies
- Long Term Field Evaluation of Coatings
- Joint Effort with Coating Manufacturers
- Exchange Experiences with Other End Users

April 9-12, 2001

Barel 2001 Pipeline Werkshop

Bee 18

Managiny ripeline Integrity: Coatings (including Repair and Requirements of Z662/Z245.20/21) April 11, 2001 10:30 a.m. - 12:00 p.m.

THE PROJECT OF THE PR	Company	Name	B. c. c.	hendersteden eine er e	and the second s
-			гиопе	E-mail	Signature
ALIEV Black for my may by John John John John John John John John	HEMPEL COATINES	BERNIE JACOBSON	1114-254-082	iacobano jemestru	
7	HEMIEL CUATIONS	グラクルない ひかいせいせい	-c .rr(-1 2 0 8	Complete Name of the Party of t	
r	WEST COAST FURROY	ļ	CCH & 10 1.00	Sales - Ca When belocom	G05
Managery (Wildelfor) (Vylver (Allbonson) op		BENOH HAYNARD BERGH	250-233-6341.		an
4	ALLIANCE PIPELLY			ì	. X
Š	7.1		45-517-1746	alliance-pipeline and	8P
2 Company of the Comp	COST Engineering	Howsay SWallell	403-259-1811	hwallka O calusun com	Hu
WARRANTON TO THE REAL PROPERTY OF THE PARTY	Clearen Inches	Layten Beatly	401-260-6430	notes be 1. G. S. S.	
WHO I AN IV WARRAN OF REPORTED A CAMERON AND AND AND AND AND AND AND AND AND AN	NEB		403)299319	There of the part of the state	# (#
8	GLUBAL THERMESLECTRIC	Clerk	403 204-6134	White was the contraction	
6	N EB		(403) A8V 2£ 200	Charlette Cyclobal Ter com	
9	Transfer and the second		+000 T(100 (101)	1 and 6 nes कि वि	
	HVS KY O'L	Scot Arout	(780) 871-6553	Scott Aroute hosky-oil con	LATEL
And the state of t	KTA Tator (landa) KINDA	GRAY	780-440-9391		1 219
7	36A3	لا	· •	The comments of the comments o	7/2/2
<u>~</u>	00000		10 4 Can 76 00	PORTICZEK (W DCJOS COM-	125×
4	RC C		0/0/2/0/20	Colorates (Decision Can	40.
5	0000		250-868-4571	250-868-4571 Cyungen @ begas com	() () () () () () () () () ()
7 .	Martaloning	Amal M. Borro	(403) 250-327	(403) 250-3027 craf borno Ochar heloatia, con	San Share
Avenue.	Y	LIMES	MACIMITY (43)202 0548	CSMALLMAN CHOME, COM	de de
	KOTH PIPELINES CON.	When S. Hay			Mallotte.
		The state of the s			

Banff/2001 Pipeline Workshop

Banff/2001 Pipeline Workshop Managing Pipeline Integrity: Coatings (including Repair and Requirements of Z662/Z245.20/21) April 11, 2001 10:30 a.m. - 12:00 p.m.

Attorner remembly	14 40 C	NAME	0703	A. F.	SIGNATURG
	EXXOUNDSIC CALMON	PETER MARRECK	(400) 260.3345	LETECL HE HARBERCH & COLOR.	I THE
	Flint Field Services Ltd.	Don Ulufer	(403) 342-8066	dulsifere fliat-energy.com	an ellas
: 1	DENSO NORTH AMERICA INC	GLENN MACINIOSH	030.310.1910	glenna densona. com	They litely
1	Canusa - CPS	Mark William	t028-812-50h	403-218-8207 Mark William @Strewind Com	2
1	CSI COATING SYSTEMS INC WAYNE DUNCAN.	WAYNE DUNCAN.	780-955-2856	wdvncan eesicoating.com	Mayore Du.
	NRTC	TOM SACK	(403) # 5-04-75-1	Jackturn novachem. com	Thank
24	HUMTER MCBOWNER	JEHN CHASE	780 436 4400	CHASS (C) HAY PSICOM	
25	National Energy Band Nancy Dubois		403) 299-3101	nduboise neb. qc. ca	- Parhaix
26	BOND CONTING Suculcus	7	872 (34) 7118	cinitch@teluspladefinet	Seller Seller
27	J. G	Jamie Cox	403-254-6145	Jamie. Gx@ can. dupoit. unh	J.
28	Shaw for Protection Ltd	Peter Singh	218 8229 45 Megrada	peter singh @ bredove . com	N. B.
59	CHARTER COGING SERVICE	E BEORY MORSE	403-250-3027	bmorse@conterecating.com	con Com
30	Treuton Corp.	Tom W	181-556-(00)	Trenton Hou @ ACL. COM	ھے ا
31	COLLIPEO CANANA THE	Gen	(730) 447-45ES		À,
32	Imperial Oil Pipelines		4201-955-6177	420)-955-6177 lorna. harron @ esso, com	Land
33	SAECIALITY ALYMER	JIM BANACH	(403) 870-6233	jim @ spc-mæt.com	Bouca h.
34		IAN SMITH	1499 189 504	905 689 6691 ismithosun-conadian, com	187
İ	American Personal (**) 1. Francisco Company	4.8.8.4.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	audhomasang =	https://doi.org/10.000/10.00	Andrew Commence and the commence of the commen

Managins dipeline Integrity: Coatings (including Repair and Koyuirements of Z662/Z245.20/21) April 11, 2001 10:30 a.m. - 12:00 p.m.

and MSERDIANDE DIT-USA. COM DIM WAYER Mexic T Syl Karr 780 410-7581 Dan, 50 holo a tropialina, com KEWIN CRIHNER 403-948-8154 KEWIN DETUNES OF KANSAMADA CAM 403-580-8316 Lie-tswi Otawanih, Com 463-948-8146 Robert-Bauer @ Translanda com warg stacaduision 1CMARSOTTO SKYSWILL . CC 50 an Morse 403 250 2027 Smune 3 haster design in 403-233-260/ THACECOINERISENKEICOM Johnstfoolliance-popular.com 104-691-5857 ; craix e wei. om 780 - 490-2550 Asolinethe & Consper, com 64 739-5367 MINERER THIL. CA transland art Wreveonrean. K. ca 43 920-6033 robert working have Ilwang Dwei.org 0809-162-50h Mediath American Preuse Hageroune 113-849-6332 403 216-3485 613-992-1703 664-691-5973 403 517 7201 BobWorkhunghan Stan Wong Kelly WASSOTT CANSARC GROUPING, DAVID JELINETTE MIKE REED PENOR TLACE Terri Johnston Zon Sotil Solaw Crasa Sin 1541 Windy Revie Jennifer Wan Bob Bauer TRANS MOUNTAIN 7/L Paci-fre Northants, irains Caun de Malinie accesion Zavice CC Technologios Charler (got way **EWastcoast** Energy Alliana Frogina Ateo Prolines LANADA 1 range troubs. CANMET MTL LSKYSTOWE BUG Transcenada 36 35 40 4 43 37 38 39 44 49 42 45 46 48 20 51 47

Banff/2001 Pipeline Workshop

Banff/2001 Pipeline Workshop Managing Pipeline Integrity: Coatings (including Repair and Requirements of Z662/Z245.20/21) April 11, 2001 10:30 a.m. - 12:00 p.m.


403-	13282	Helan	Anterior Anterior	11	Na.	F.	A	20		8	1	/////ww/	Jan orth	- 1/C/	33	
Contrave Dionio	ž		7604134545 THYMES OR ON THE COM	RSMXDA @ NETROLLINGS.Co.	worbs her egreenpipe win	Tat. Isolotta Chastano	NIPP 713 562 3702 DOWN AND THACK IN	See hard See		(380)468.8619 K	1) Summers of ordered 1/2, com	1.1 A backage	The state of the control of the cont	Sharon @TMPL. (A	marke the lice	1
403 232 82)	403-258-2233	418-753-7601	7K04134545	403 271-8383	742-012-804	7005 rop Over	713 562 3762	SIGNENS 780 913-187	(mg) - 0HD (mg)	9178-89/1085/	306-924-7395	4,2) 382-4514	201-1-29			403) 299-319K
Matt Cetin	MARK JOHNEN	Alex Petrusa			Aung Maskiver	HARA HINSPAL	A Hick	BIE 516	ANDRE FLIATRAUIT	***************************************	Tom Lawrence	111 Hokins	7			La 1, 5
Andem Corrocio	MARR ASSOCIATES	Marion Service Comp	Soloman Communes Lip	PETROLIME	THENFINE MUSSIKIES	MINTERH INSPETION	MORA RIPELINE PROFESURIALS	PIPELINE SELIKES	RTD QUALITY SERVICES		TO TOUR DX	Coloxio Ani	No my in in	Pans Mewhere Peeline		1873
52	8	54	55	96	57	85	65	09	19	62 K	63	64	\$9	99	29	89

Managin⊾ .∕ipeline Integrity: Coatings (including Repair and ƙ⊾⊣uirements of Z662/Z245.20/21) April 11, 2001–10:30 a.m. - 12:00 p.m.

Banff/2001 Pipeline Workshop

Managing Pipeline Integrity: Coatings (including Repair and Requirements of Z662/Z245.20/21) April 11, 2001 10:30 a.m. - 12:00 p.m.

hytoene		(C.C.C.	2.	Silv S	M. Saw				The state of the s				The state of the s	
3 Kylal@tmpl.ca	C.P.R.	403.314-7491 golden P.novachem (0.17)	80 M. V	103-233 3680 Swaslan Queb go ca	Eng Inc 403 216 3/85 _ havougskystore - ca	D								
780-449-5913	403-281-8627	403-314-7491	L (43) 241-16.	403-233 3680	403 x163/805						To the state of th		Table 1 and	
ne Ayla Loewen	سلر	Mary Cale	Rolling lows of		Skystone Eng Inc	Į.								
Trans Hountain Pipe Line	Perce Consulting Ltd	Nova Chemicals	Pay Sonith	Doug WASIEN	John Buren									
98	<u> </u>	88	68	96	91	25	8	94	95	96	5	86	8	100



Group #6 : Coatings Workshop Summary

Co-Chairs: John Baron (Skystone Engineering)

Doug Waslen (National Energy Board) Rapporteur: Kelly Mabbott (Skystone Engineering)

April 9-12, 2001



Coatings Workshop Summary

- Paper #1: Proposed Changes to CSA Codes
 - Next edition to CSA Z662 is expected in 2002
 - Concerns were raised with the process of coatings design
- Recommendation to include workshop information in the **CSA Commentary**
- Paper #2: Coatings and CP Compatibility
 - Definition and common understanding of CP Compatibility is required
 - A definition and checklist to assess coatings was presented
 - Recommendation to include workshop information in the **CSA Commentary**

April 9-12, 2001

Senii 2001 Pipalina Work



Coatings Workshop Summary

- Paper #3: How We Perform Field Assessment of Coatings
 - Field assessment of coatings should be performed during routine excavations
 - Test methods and procedure were presented
 - Some interest in industry database
 - A one page checklist was presented

April 9-12, 2001



Coatings Workshop Summary

- Paper #4: How We Select Coatings for High Temp. Pipelines
 - Increased need forhigh temperature pipeline coatings (>85C)
 - No industry standards currently exist for testing or application of high temperature coatings
- Paper #5: Achieving Field-Applied Girth Weld Coating Quality
 - Industry requires a framework for applicator training and
 - Field applied coating requirements to be included in CSA revisions

April 9-12, 2001



Coatings Workshop Summary

- Paper #6: Select and Apply Repair and Rehabilitation Coatings Coating selection is dependant on pheline conditions
- including temperature, coating type, and ambient temperatures
- Each repair method requires documented procedures, applicator training and quality assurance
- General Condusion
 - A coatings discussion group should be established to enable ongoing improvement
 - Overall it appears that selection, application and quality control are improving due to increased awareness.

Seell 201 Pageing Workshop

Working Group 7 - Pipeline Risk Assessment / Risk Management

Wednesday, April 11, 2001, at 1:30 p.m.

Co-chairs: Iain Colquhoun - Pipeline Integrity International

Leo Jansen - National Energy Board (absent)

Facilitator: Anton Walker - Suncor Energy - Oil Sands Group

Rapporteur: Nathan Len - National Energy Board

Session Objectives:

- To provide an interactive forum where the management of the integrity, safety, and risk of the pipeline infrastructure can be discussed.
- To facilitate and promote the sharing and exchange of information and the development of pipeline industry communication networks.
- To recognize areas where coordinated efforts can be implemented to enhance risk management as it relates to pipeline integrity management.

Speakers:

Robert Sutherby - TransCanada PipeLines Speaker 1:

Title: PRASC Database

Summary: There is an initiative to develop a common set of risk definitions that will be

included in the next release of CSA Z662. In parallel to this, an industry database is being developed to provide industry with meaningful statistics on Canadian

pipeline incidents.

Speaker 2: Brian Rothwell - TransCanada PipeLines

Title: Failure Frequency

Risk analysis, a primary component of risk management, requires the Summary:

identification of hazards and the assessment of the frequency and consequences of

specific hazard scenarios. The overall estimation of risk requires partial frequencies, by failure severity and mechanism, to be combined with the corresponding consequences (with their contingent probabilities). Estimates of frequency, for each severity level and mechanism of failure, can in principle be developed on the basis of historical data, mechanistic models, expert opinion or a

Speaker 3: Graeme King - Greenpipe Industries Ltd. Title:

Consequence Estimation and Modeling

Summary: The consequences of a leak or rupture of a pipeline can be classified under the following headings:

- Life Safety
- Customer Impact
- Public Perception
- Environmental Impact

Financial Impact

Speaker 4:

Iain Colquhoun - Pipeline Integrity International

Title:

Decision Model and Implementation

Summary:

To develop an integrity program that balances safety, reliability, and profitability, we may start by applying constraints:

- Individual and societal safety risk thresholds
- · Environmentally responsible programs
- Compliance with all applicable codes

Does the net present value of the risk reduced (expressed in equivalent dollars) over the anticipated benefit horizon exceed the cost of the lowest cost program to address the risk? When the proposed program is put together, what is the estimated residual risk? Is this acceptable? Once these questions are addressed a finalized integrity management program can be put together for the general pipeline maintenance program and field implementation in the most efficient manner possible.

Speaker 5: Title: Iain Colquhoun - Pipeline Integrity International Life Cycle Considerations of Integrity Management

Summary:

Managing the integrity of pipeline systems is a challenge, considering the limited and reduced resources and the pressure of striving for maximum return to shareholders, combined with aging infrastructure. Some questions to be discussed include: How can risk management assist in managing pipeline integrity? Is risk management simply an analytical approach to justify allocation of resources and selection of equipment and duties, or is it an effective tool or mechanism that is used (or can be used) by the pipeline industry to address the many challenges faced by them. An open forum will be held to discuss how risk management can be used in the management of pipeline systems. Discussion should consider how companies address pipeline integrity from "cradle to grave", i.e. from conceptualization and design of a pipeline system, operations through to decommissioning of the system. Is risk management an effective tool to help manage pipeline integrity?

Note:

Refer to presentation slides for the specific contents of the presentations

Open Discussion Summary:

General Statements on Risk Assessment/Management in Industry

- Before we try to determine how safe is safe enough, we need to look towards continuous improvement and use risk analysis to move towards system improvement.
- To determine the acceptability of risk, the industry needs to look at both frequency and consequence. Regulators are already looking at the consequence side. There was a consensus given that industry needs to improve on the frequency side of things.
- If you keep track of historical consequences of incidents, what is to say that they will be applicable to most areas where future failures may take place?
- One method of managing risk is to develop a risk profile for the system in its current state. Determine what the risk profile would be if the pipeline was brand new. Then work to bring the current profile closer to the profile of the new state.
- Define what is an acceptable risk. If you are trying to totally eliminate risk, there comes a point when the amount of money spent on maintenance is disproportional to the benefits that you receive. Even if an infinite amount of money is spent, there is a limit where safety is no longer improved.
- EUB data is available but at a considerable cost. This data then has to be combined with a company's own data to perform a meaningful analysis. Data should be more readily available with a decreased cost so that it can be used universally.
- EUB is looking at environmental database to make it more accessible. Will be looking at pipeline database to make user friendly. They will try to link their efforts with the PRASC database initiative.
- You have to look at risk on two methodologies quantitative and qualitative. The most effective systems use a combination of both.
- There is a definite learning curve associated with risk management in industry. We are starting to see a better acceptance and use of risk management techniques by industry.

Specific Issues or Questions

Pipeline Risk Assessment Steering Committee (PRASC) Initiative

- At this point, the PRASC database is just a concept. Input is needed in order to ensure that the entire industry is covered.
- Working with sensitive data is a private issue, not a public issue. There is a need to keep most information public but keep sensitive information anonymous.
- A lot of effort is needed to manage a database of this type.
- In order for companies to see an added value of participating in databases, the data has to be broken down into meaningful data
- The data that you are keeping has to be aligned with what you are trying to achieve. We need to plan the database correctly so that everybody can use the same data.

What would you like the PRASC database to be able to answer? (What would you like to use it for?)

- Looking for trends in the information on factors that might influence failures (e.g. corrosion, pipe diameter, wall thickness etc.). This could be used to see what areas should receive increased attention. This information could also be used in the design stage as one may be able to determine how certain factors might affect the future reliability of the pipeline.
- Should be used to normalize data within the industry. This could then be used to perform a reality check on industry beliefs.
- Should be used to provide a benchmark to what companies could compare themselves to determine how they rate against other companies in the industry.
- Could be used to fine-tune regulatory programs and standards. This may lead to increased attention to certain issues and decreased emphasis in other areas.
- If the database is well thought out and developed properly, it could be used to develop best practices within industry.

How do we handle the risk of fatalities?

- Traditionally, it has been considered a faux pas to speak to the public about life loss and the dollar value associated with it.
- When quantitative analysis is done, the value that is assigned to people is actually the cost avoidance issue rather than the cost of the fatality itself. This area needs clarification so that people are talking about the same thing.
- Industry considers assigning a value or probability to people is acceptable (risk). The perception of the public is that living by pipelines is an imposed risk. The public is not willing to accept any probability of risk when it comes to people. Companies need to try to come up with rational before taking the risk plan into the public forum. The goal is for the industry to be transparent to the public but it must be realized that crossing over the threshold can be problematic. This addresses another issue other than risk management: risk communication. A possible solution is to have a communications expert portray the information to the public rather than the engineer or technical person.
- A concern is that the information that is viewed by the technical people may fall into the hands of a person without the appropriate background knowledge. As a starting point, there is a need to inform people within company as to what the information is and how to interpret it.
- Within the industry there appears to be a tendency to withhold information between one another (between colleagues, regulatory officials etc.) Companies need to become transparent (open to each other) within industry before they can achieve the goal of being transparent with the public.
- Possibly shippers and regulators should have a role in assigning the cost associated with people. This could then be adopted in company risk models.
- Other industries may have the same problems. Someone should look towards other industries with respect to how they quantify risk with respect to fatalities. Some other industry may have already done something similar (e.g. Chemical Process Industry, Airline, Rail Transportation, Health Care).
- If we don't assign a value to people we may not be able to come up with an indicator to determine when safe is safe enough.

- With regards to absolute or quantitative risk, it is very difficult to assign a risk value to capture your gut feeling of how the people living along the pipeline feel.
- Costs associated with incidents are business decisions. This is different than when you are
 talking about fatalities. This is where the risk value gets very shaky. Most people want to
 avoid assigning value to human life. The problem is in trying to determine what is
 acceptable. This may prevent proper risk assessment when dealing with people.

How do you proceed to get more resources allocated to an integrity program?

- You usually have a better chance at convincing your company to an increase in funds towards integrity if there is a real example to be seen. Other justifications seem to go unnoticed. (Some participants said their experience was that the best way to avoid such "knee jerk" reactions was through the use of an impartial risk management approach).
- The occurrence of major incidents (ruptures etc.) has an effect on how much a company is willing to spend on integrity management. The reason for this is the increased awareness into the problems themselves as well as the severe consequences associated with a similar incident.
- One good justification for additional resources is to try to reduce the frequency of occurrences
- Any resources have to be justified on a cost/benefit analysis. This is needed to justify reasons to company officials.
- Quantitative models make it easier to demonstrate to company officials the benefit of allocating resources to a certain area.
- To get more funding, the risk assessment would have to indicate a greater level of risk exposure than was previously understood. The quantitative analysis needs to seem reasonable (it must stand up to reality)
- On the upstream side, expenditures are being justified using risk models. Routinely, decisions are made using pure risk management. This has been happening since the early 1990s.

Can risk management be used to lower insurance premiums for facilities?

- With regards to service facilities, insurers have been asked that question. There seemed to be some indication that there was potential for the underwriters to start looking at the issue.
- The first reaction from the insurance companies is usually no. With some pushing, it was found that there may be some opportunity for movement in insurance premium.
- It must be taken into account that the reduction in insurance premiums would probably not be very significant. However, the greater benefit lies within optimization of integrity program expenditures.
- Generally, insurance companies do not conduct studies such as risk assessment on the
 pipeline facilities that they are insuring. The questions that are asked when insuring a
 pipeline do not usually reflect the condition of the pipeline.

What now?

- PRASC still continue to gather comments on how to approach the issues so that the entire industry is represented.
- Need to clearly understand PRASC initiative and communicate it
- Discussion is improving towards the issue of risk assessment/management. Learning needs to continue.
- There is significant improvements being made in the level and consistency of discussions on risk. The path ahead must include continuation of industry wide dialogue.

What next?

In an ideal world:


- Regulators would understand methodology and mitigative methods used by companies
- Public would have some form of understanding and accept methods used for risk management
- People within own companies need to understand methodology and mitigative methods

Summary, Conclusions and Recommendations from the Session

- Pipeline Risk Assessment Steering Committee (PRASC) Initiative
 - Possible uses of database were suggested
- How do we handle the risk of fatalities?
 - Value of life/ALARP
- How do you proceed to get more resources allocated to an integrity program?
 - Effect of major incidents
 - Use of impartial Risk Management approach
- Can risk management be used to lower insurance premiums for facilities?
 - Yes (qualified)
 - Eclipsed by benefit in optimized integrity program
- What now?
 - Move ahead on databases
 - Continued dialogue on risk
- What next?

In an ideal world:

- Regulators would understand methodology and mitigative methods used by companies
- Public would have some form of understanding and accept methods used for risk
- People within own companies need to understand methodology and mitigative methods





Pipeline Risk Management

- Risk Management is an effective tool to assess, evaluate, prioritize and mitigate risks
- Two bodies involved in implementing risk-based integrity management practices: CSA & PRASC
- Goal of improving and demonstrating the safety of pipeline systems through implementation of risk-based practices

April 6-12, 2001

Sent 2001 Pipatine Workshop

. . . .



RM Implementation

- CSA Z662 Appendix B on Risk Assessment
- · CSA Z662 2003 ed. Risk Data Dictionary
- PRASC Risk Data Base 2003

April 8-12, 2001

Bard 2001 Plyalina Workshop

Shele 3



Risk Data Base

- An industry-wide data base tool to support pipeline risk management
- Standardized and consistent risk terminology
- To improve, demonstrate and communicate the safety of pipeline systems
- By capturing and developing incident statistics in terms of frequencies and consequences

April 9-12, 200

Senff 2001 Pipeline Workshop

Milan d



Design Criteria

- To ensure a successful design and implementation
- To identify objectives, needs, advice and design criteria from potential future stake-holders
- Scope?
- · "Incident" definition ?
- · Consequence types ?
- · Opportunities and Concerns?

April 5-12, 2001

itenii 2051 Pippine Wartshap

Stice S



Contacts

David Blackadar, Pembina Pipeline Corp. (403) 231-7414, doblackadar@pembina.com

Bob Sutherby, TransCanada PipeLines (403) 920-6031, robert_sutherby@transcanada.com


Jake Abes, Pipeline Safety Consulting Inc. (403) 861-4959, jakeabes@nome.com

Tom Pesta, Alberta Energy & Utilities Board (403) 297-8148, tompesta@eub.gov.ab.ca

April 8-12, 2001

Sent 2001 Pipeline Watshop

Shor 6





Meaning of frequency

- For the purposes of risk analysis of pipelines:
 - Quantitative
 - "number of times that a given scenario is expected to occur, per unit of time and pipeline length"
 - Semi-quantitative
 - "comparative likelihood that a given scenario will occur, per system and unit of time"
 - "system" has a special meaning, defining the scope of the analysis
 - "frequent-occasional-unlikely-remote-improbable-hypothetical" is an example of a comparative scale of frequency

April S-1 2, 2001

Bank 2001 Himshan Mineral



Frequency estimation

- · Frequency of what?
 - Hazard scenario e.g. leak (size), rupture
 - By hazard cause e.g. corrosion, mechanical damage, ground movement
- Approaches
 - mechanistic models
 - · reality check with historical data
 - historical data
 - appropriate database
 - combination of both
- * attribute-related modifiers for gross statistical data




Frequency estimation-challenges

- Relate frequency of scenario to attributes of pipe and its surroundings
- resolution appropriate for purpose
- Recognize uncertainty and its influence
- Data management
- Lack of appropriate and widely available data
 - temptation to use data that's inappropriate
 - efforts to develop a Canadian database
- Lack of appropriate and widely available models

April 9-12, 2001

Bard 2001 Pipeline Workshop





Example of semi-quantitative frequency definitions

Frequency category Description

April 6 12, 2081

and 2001 Pipeline Worksho




Example of semi-quantitative consequence definitions

Consequence Description category

April 3-12, 2001

and 2001 Planter Workshop





Factors Affecting Impact

- Settlement of claims for damages
 - Community (loss of life, injury, property damage)
- Employees (loss of life, injury)
- Environmental impact
 - Cost of cleanup
 - Irreparable damage to wildlife and physical environment
- Regulatory penalties (fines, shutdowns, inquiries, etc)
- Service interruption (costs to shippers & customers)
- Loss of corporate image/public perception
- Cost of repairs

April 9-12, 2001

Benf 2001 Pipeline Wartshop



Trends in Quantifying Impact

- · Three broad approaches:
 - Qualitative or "zero-tolerance" (leading to prescriptive plans)
 - Semi-quantitative or factored (leading to risk matrix)
 - Absolute quantitative (dollar value and direct comparison)
 - Eclectic strategies (any combination of the above three)

April 9-12, 2001

Benf 2001 Pipeline Westalion




Trends in Quantifying Impact

- Good record keeping
 - Location of pipeline assets wit rivers, roads, populated places, environmentally sensitive areas, etc. (GIS & GPS)
 - Record anomalies & defects as part of inspection tasks
 - Record remediation of anomalies and defects
 - Easy to use and auditable

April \$-12, 200

Benff 2001 Pleating Workshop







Risk Assessment / Management

- Learning curve in industry starting to see a better response from industry towards risk
- Need consistent, meaningful data in order to reach what you are trying to achieve
- Availability of Data?
 - PRASC, EUB, NEB etc.
- What is the purpose of the PRASC Database?
- · How do we handle the risk of fatalities?
 - Do we need to put a value on human life?
 - Can we address the risk by specifying a low probability of fatalities (constraint)

April 9-12, 2001

Sant 2001 Pleating Wastern







Life Cycle Considerations of Integrity Management

- How can Risk Management assist in Managing P/L integrity?
- Consider each phase in the Life Cycle of Pipelines:
- Conceptual design
- Detailed design
- Operations and Maintenance
- Emergency Preparedness and Response
- Decommissioning
- Final Cleanup

April S-12, 2001



Life Cycle Considerations of Integrity Management


- In practice, how has Risk Management been used to
 - funding
 - people resources
 - purchasing specialty equipment
 - activities, programs or processes


Benlf 2001 Pipeline Worksho





Life Cycle Considerations of Integrity Management


- Considering the Lifecycle of Pipelines, how can Risk Management be effectively used in Managing Pipeline
 - include risk identification and prioritization used regularly in each phase of the pipeline lifecycle
 - make decisions based on risk (real and perceived)
- consider short and long term impacts/effects (focus on lifecycle)
- proactively manage integrity based on risk - other???

















Managins ∵ipeline Integrity: Pipeline Risk Assessment/Risk M⊾..agement April 11, 2001 1:30 p.m. - 5:00 p.m.

The state of the s	Company	Name	Phone	F.mail	
	COLT ENG'G	DARIUS BOUCHER	403 259-1880	E-man	Signature
2	CORRPRO CANDOA INC	7.00	M/-X1 (501)	SUCCHER, DARIUS & COLTENG, COM	Emsoure.
6	FNCMCI	FRANK HOISTENSEN	. V	Bone contract playara	
7	RIDOR WESS 1 MI.	Second Annual Control	200	Inches Con	
C C	Mark Total Total	1 4 C C C C C C C C C C C C C C C C C C	1)10 121 60+	IAN. DOWNETT (PRINT, COM	7
The state of the s	TATAINE TRUE INC	BRUCE DUPUIS	403 266-3800	bruce de baselinetech. com	A. S.
9	Trans Condia	Comey Gowlet	403-920-6085	403-420-6065 Com- 4011 Jet 10 tons	2
	Imperial Oil	Dow Adams on	780 955-6159 dougadamson	dougadamson a sso. Com	1000
8	NRTC 10.FA	Rel Emoria	403 250 4516	reg. earlied undberta. ca.	
6	(raw Canada.	Bb Stuby	403.920.603	Robert softeely@	y care
10	/VEB	Nathan Len	403.248-2784	Mon & neb. gc. cg	IN
	NEB	Minh Ho	(403) 2099 - 2762	whowneb.gc.ca	
12	TEANS MOUNTAIN THE	MIKER REED	£955-654 109	MIKERUCTIPLICA	
13	THING MOULEN	28 Ma.000	750 717 176 058	· I .	
14	TRANS NEUNTAIN	Re HADDEN	604 268 3011	Charles of	11/18
15	Trans Mountain Pipe Line	Kyla Loewer	1 .	Kule la trol, ca	The same
16	Contribute Contributed Con		22.2	good proud & cac. enbidge.cm	AND LOCAL
	Notural Resources and Woel Bill	· Døed Billette	(63) 992-3738/	lette (613) 992-3738 NBILIETTENREAMORGE CA BELLA	CE CHUKE

Managing Pipeline Integrity: Pipeline Risk Assessment/Risk Management April 11, 2001 1:30 p.m. - 5:00 p.m.

Signeture A record Sahnry@hor sconodo. Con glerr comerons green pipe, com (403) 260-6708 donrobert son Ogreenpipe, com 4032818627 | CPVECCE C + LLysymersh trevolunactodicus echyamicroskiat Pil-Usa.com DAVID ColEMAN 204-980-5570 dacienare hydro, mb. 403-920-725/ Ken-tyloneton Land I carlein & alliance - popular con 40 3 3 2 65 4 7 2006 6 46 Och 1261 60 0 - 7 6 20 10 6 10 6 6 780-420 - 8434 aclos. Pardo Banpl. enbridge . com 701. PESTA 3 604. AG. CA Hozowyo agut I.com INDY OMNEWAY (403) 202 OS48 CSMALLMAN@HOME. COM simmans @ cadurain. com 403 289 2774 | fleque Ones. pc. ca Kavi Knishnamud 713849 6339 Krishnamurthyre 403 247-1480 (coteb@home.com 0-50% 403.260-6748 (Trey 976-7313 403 517 6303 103 920-650A 403 Sq1 5319 8×18 COZ 8148 403 547.8638 Phone DON AOBERTSON LEUNARD LUZUWY Glewy CAMPROS Dave Toporousky Pierre Consulting With Chris Merce Trevor MacFarlane Bob Coole KRILAND Carlos Pardo Reeve Salmey Netromod Energy Broad French Scylic アルプ ton PESTA Lorne Carkon GREENPIPE INDUSTAB Creenpipe InassTRies ALTAGAS UTILITIES Alliance Pyeline Dynamic Risk Assessment Systems iste Ing LEd. Centra Geo MB Simmons Grop. Inc. Wunstanada Transcanada Cion pinny Enbridge FUB 34 33 28 25 20 S 24 6 30 8 22 23 26 27 3 32 21

Managiny ripeline Integrity: Pipeline Risk Assessment/Risk Management April 11, 2001 1:30 p.m. - 5:00 p.m.

Banff/2001 Pipeline Workshop Sighterno Trans Cather Strong Marines 780-417-4302 rexk & basclingtech ion trex follows B Hourse Ocqueram 907-271-6514 Dunis Hinnahamagand (403) 250-9041 acc bucke @ telusplanet ukt 200 BEB 4586 CENTINAMEDEGAS. COM ntrustere pajos. wm 403 920-6033 robert-worthinghan@transcon (205) 389-7554 therese, bell @ MHS. GOV Define subject to the cle. Co. alliane-pipeline and isnIt \@ sun-canadibu, con 613. 772 7904 Wenyue@ MRcnn. 9c.ca | Glenn-Tuend dynamic risk met Sparker @ transgas, skica gamys & buse linetech, com shamus@hmpsi.com lator@ neb.gc.ca Reb. powerce 6 ragi [200 DANG CON 392-7698 604-576-7004 (403)292-4911 463)517-77E (306) 777-9303 403 SH7-8638 (780) 417-4312 780.940.8884 (619)955.5528 1499 189506 Phox NORM TRUSLER Theresa Dell Burke DELANTY Lunis Hinnah CHR13 BILLINTON Be West highm REX KALEMITH Shamus MEDonned Red Rivery Wenyue Zhang CUPTIS PAPKER National Energy Board Law Race Attor ENSFLINF TRANSMEIRS GARBY SOMMER Name Depline Southwell HJIWS NEN Dynumic Risk Assessment Glenn Yven BASELIDE TECHNOLOGIES 単一世の から上方 SUNCANADIAN PIDE LIVE Minerals Myt. Sen. Then xxtering that the air Be CAS UTILITY BC BAS UTILITY CANMET- NRCAN HUNTER MEJONNELL PIRELINE SCRUICES CL TECHNOLOGIES BCGATS Trans Canada. TRANSGAS Courpenn 35 36 33 38 39 40 4 43 4 44 47 49 45 46 50 48 2

Banff/2001 Pipeline Workshop

Managing Pipeline Integrity: Pipeline Risk Assessment/Risk Management April 11, 2001 1:30 p.m. - 5:00 p.m.

AND	Con para	- Single	Arox	S. S. S.	Standard
52	1 Mas 5 cope	TODO PRIER	713 799 8160	tubes cone com	
53	MARR KECHES	-10 17618		Just the constant of the second	Yes (A)
54	Greg Teth	Trans Mountain	604-739-5324	greente tomplico	my Let
55	Hadan Gosta	hother & Enery	604 6945027	(4055e 0 40,017 /	W.
98	Grue Gray	The '	403.920.6098	bruce-gray@ transanada com	12
57	-	Cypic FARIONEN	403.444, 4550	Cyr.1. Karanan	M
28	Komek IDTEANATIONA	3L FRED CLARIDGE	403-247-0200	Komex IDTEANATIONAL FRED CLARIDGE 403-247-02021 FClaridada Colanivo Kannusian	70.
- 50	Translanady	Garry Norton	403-640-6504		the lot
99	Trans Gnada	Catherine Pineau	403-920-6575	Catherin - procant transcanasa.	Can. /
61	ENBRIDGE	DER BILLEY	750-420.5383	deb. billey@ Capl. entrige. um Debile	Siley
62	ATCO Popelinez	Autur Janz	\.	ant, janz @ ateckine lings, con	The state of the s
63	(RAMSGAS Ltd.	Tales Chamen	306-975-8550	chorocog transins. sk. 64	Carlot Ca
#9	RTO Guchty Sves	Richard Kania	780-468-364	780-468-364 rkania O vtdanalitu.com	
\$9	ENSKIBLUE PHOLINES	Scott IRENSIDE	780-420-5267	Sett. Torside & Cont. enterda.com	400
99	Trans lanada	Petr hormidi	8452-026-894	peter - corridi a harsanda con	Mer
29	(Jaams Janvala	CHELACK O) WEIN	403-920-2572	403-920-2572 she lack-ofwarentweescanade. Com	Mili
89	REET TECHNOLUGY	HOBERT GAZOR	780-465-0077	780-465-0077 rlazora Fleetech. com	chal for


Banff/2001 Pipeling Workshop

Managin, .'ipeline Integrity: Pipeline Risk Assessment/Risk M....agement

02-520 48686 | pada barandrimi psram.en. it | H3 mouduin Signature 多 (480) 420-5383 debisilley@ cmplenbridge.com Oberen 780-464-9133 delton-gray Okeyyon copedocom 人 holyed Comadiversa gabriel_nahas@Twanichado com guy enomonscionthic con 403-262-8160 Land Mirrison Scentific. con 403 531-5407 1 4 K. Losch @ Wy sermore CA darcon mazuak@tri-ceran.com epuller @ fransgas-sk.ca dscromin acagmini isuther lowe @ by xovices, ca (403)299-3634 | read @ nd. 8c.ca Movice Santander (403) 299-3652 mesantander@nes.gc. a rypick@ Unaterloo, ca ptrudele neb. gc.ca assiterio ca jjwong Dwei. org D- Men 403 262 7885 かいな・かかか・なたの 3067779303 219-488-4567 403 920 6578 403 531-5300 Stbs-149-209 405.362-3160 1403) 218-4676 2837 X 403 499 2768 からな MOLA BONANDRINI CURTIS PAPRETE I ASSEK PRICE کم (بلاغیم) GABRIEL NAHAS Dule Katoschke Darron MazuraK DELTON GRAY Sizers Cereson であるから出い RIMA RAAD Tom Morrison BILLEY Jenniter Way Namo Raul Trudel Roy Pick Durma 200 April 11, 2001 1:30 p.m. - 5:00 p.m. Kenter 1/2 18 1653 Can Sc. 2 20 1856 Morrison Scientific dri Ocean Engineering KEYSYAN EKEKBY 35 Labre Somices National Energy Bd Westcoast Energy Company うそんかっこう BSPipelia C. 4 M. A. D. A ENBRIDGE TEATUSCIOUS けっことう TCPL 2 B SNAIL N EB 69 2 71 72 73 29 7 80 75 9/ 11 78 82 $\frac{1}{\infty}$ 85 83 **2**

Managing Pipeline Integrity: Pipeline Risk Assessment/Risk Management April 11, 2001 1:30 p.m. - 5:00 p.m.

98	Pipeline Sources	CHRIS HARMELL	5188359904	Chrish Thmpsi.com	Cl. Ath
87	INTEGRITY Sementology Local Parcel		403-294-2399	403-206-2399 (622-1)	No.
88	No. Corr ENg. 1+6		100 100 2017	Jan Control of Indicator Com	
68	1845 Technology Institute	7	847 768-0871	847 768-0891 haven haines Dass Pechnology 654 7	2/ 1/2
8	MARA ASSOCIATES	_	403-258-2233	Michason @ Marr-associatos.com	Million States
16	KONEX WERNFINE	FRED CLARIDOR	403-247-0202	403-247-0200 FC60:1.0 (26.11)	Mayar
92	110m Cencola	DAN KING	403 820-6015	40 520-6015 don-kington of of	TO THE TOTAL PROPERTY OF THE TOTAL PROPERTY
93	CENTRA GAS	Don WALLACE	250-751-8319		
97			Į.	חשוויני ב רבעושם. הבן פלא	Z. Z. Z. Z.
96					
96					
97					
86					
66					
80					
101					
102	* */				
Verification and the state of t	- Annual designation of the contraction of the cont		- 74		





Pipeline Risk Assessment / Risk Management Workshop Discussion Summary

- Pipeline Risk Assessment Steering Committee (PRASC) Initiative
- Possible uses of database were suggested
- How do we handle the risk of fatalities?
 - Value of life/ALARP
- How do you proceed to get more resources allocated to an integrity program?
 - · Effect of major incidents
 - Use of impartial Risk Management approach

AW# 9-12, 2001

Benff 2001 Pipeline Workshop



Pipeline Risk Assessment / Risk Management Workshop Discussion Summary

- Can risk management be used to lower insurance premiums for facilities?
 - · Yes (qualified)
- Eclipsed by benefit in optimized integrity program
- What now?
 - · Move ahead on databases
 - Continued dialogue on risk

April 9-12, 2001

Banf 2001 Pipeline Workshop



Pipeline Risk Assessment / Risk Management Workshop Discussion Summary

- What next?
 - In an ideal world:
 - Regulators would understand methodology and mitigative methods used by companies
 - Public would have some form of understanding and accept methods used for risk management
 - People within own companies need to understand methodology and mitigative methods

April 9-12, 2001

Booff 2001 Pipeirre Workshop

Workshop Session 8 - In-line Inspection of Transmission Pipelines Wednesday, April 11, 2001 at 8:30 a.m. - noon

Co-Chair: Co-Chair:

Steve Gosse, Westcoast Energy Arti Bhatia, Alliance Pipeline

Rappporteur: Don Engen, Enbridge

Outline:

1. State of the Industry Today - Harvey Haines (GTI)

- 2. Consideration and verification when inspecting for mechanical damage, dents and hard spots - Bruce Nestleroth (GTI) and Blair Carroll (Fleet Technology)
- 3. Treatment of Vendor Tool Performance Specifications for corrosion and crack detection -Tom Morrison (Morrison Scientific)
- 4. Tool Development and Research Blaine Ashworth (TransCanada Pipelines)

1. State of the Industry Today

Harvey Haines (GTI) presented a breakdown of research endeavors and tool development as it appears today. The presentation included in these proceedings.

David Katz from Williams Gas Pipeline - West asked for clarification as to whether the dents and/or mechanical damage was from the DOT Reportable Incident summary and the Kiefner report were determined to be construction defects or defects that formed during operation.

Harvey did not believe that any of the 31 incidents were due to rock dents.

Barry Martens from Rainbow Pipeline inquired about the nature of the failures with respect to multi mode defects i.e. corrosion within dents.

Harvey emphasized that most failures are not due solely because of a dent but associated cold working and cracking can contribute.

Barry Martens inquired about the shape of the corrosion defects used in the research of multi mode defects i.e. corrosion in dents.

Bruce Nestleroth responded that their all had smooth front edges.

Barry Martens commented that he had experience where the tool has missed certain defects and a failure has occurred.

Arti Bhatia polled the group as to how many operators have asked for POF (Pipeline Operator Forum) formats from the vendors as to their tool's capability and how many vendors have received requests from operators.

Chris Billington from BC Gas indicated that they were moving towards acquiring the specifications in this format however they did not have enough data points to reference back to as of yet.

Harvey Haines asked if operators were requested the POF format.

Daryl Ronsky from PII responded by saying that clients are asking for the format and in particular are raising questions about accuracy of sizing.

Dave Hektner from BJ Pipeline Inspection Services pointed out that Mapping/IMU has been around since 1988 and RTD Laser Technology is now available in the US. He pointed that the circumferential technology has been available since 1998. He also commented that inertial technology on MFL tools is working well.

Harvey inquired as to whether the tool referenced by Dave had an axial magnetizer with circumferential sensor technology.

Dave responded that they use the circumferential technology to better identify corrosion defects but it is not used to identify crack defects.

2. Inspecting for Mechanical Damage

The group was asked if any of the operators would lime to comment on the use of circumferential MFL tools.

Blaine Ashworth (TCPL) replied that TCPL used the TFI (Transverse Field Inspection) tool for R & D purposes and it was difficult to detect and size low levels cracks.

Chris Hallam from BJ Pipeline Inspection Services asked if there was a different MFL signal for gouges on mechanical damage tools.

Bruce responded that the signal is different.

Harvey Haines pointed out the terminology for gouges need to be better defined.

Phil Nidd from Agra Monenco commented that 2400 excavations were conducted based on TFI data on the Platte system. A paper was presented at IPC 2000. He mentioned that they had some success manually differentiating dents with gouges and mechanical damage

Dave Katz commented that a tool would be useful if it was cost effective for identifying dents better such as top half defects instead of bottom since the DOT will be inquiring about prioritization of defects.

Steve Gosse asked about the Canadian experience with respect to mechanical damage instances.

A representative from Greenpipe Industries commented that Canadian pipelines were in less high-risk areas.

Deb Billey a contractor to Enbridge inquired about the multi level capabilities of MFL for detecting dents within welds.

Bruce Nestleroth that he had not done any work in that area.

Blair Carroll presented a few slides on planning rock dent excavations based on high-resolution caliper data, which is included in this package.

The group was asked if any of the operators were using various modes of tools and overlaying the data to prioritize their dent and other digs.

Shamus McDonnell from Hunter McDonnell replied that they had worked on different ILI tool data to find deformation type defects and the correlation to date was working good.

Blair responded that a three-dimensional FEA model would fine-tune the process of assessment that Shamus commented on.

Bruce Haggar from PII commented that one could differentiate on MFL data between greater and less severe defects but they could not see cracking within the dent and they generally gave customers the most severe dent information.

Blair commented that you can run a tool to determine the severity and get accurate information but dent prioritization is a staged process and operating conditions such as large pressure fluctuations could cause problems.

Brian Rothwell asked Blair to clarify in the dents Fleet had modeled were all greater that 6 percent.

Blair confirmed that the initial indentor was the number referenced on the chart but many of the dents rebounded to 6 or less percent so less that 6 percent dents had been modelled.

Bruce Nestleroth commented that there was a difference between Blair's and his work. Blair's was more representative of fatigue on dents with rocks and Bruce's was more focused on mechanical damage.

Frank Christensen from FM Christensen Metallurgical Consulting stated that he did not believe that the weld alone referenced in Z662 was considered a stress concentrator.

Blair commented that the research that Fleet had done did include the influence of the weld and such that the number of cycles to failure decreased with its influence.

3. Treatment of Vendor Tool Performance Specifications

Tom Morrison (Morrison Scientific) presented a few slides on why operators should validate their ILI tool runs. The slides are included in this package.

Phil Nidd commented the group as to whether we were moving towards a period of validating more stringently. How would the ILI vendor, the operator and an NDE company work to resolve measurement errors?

Tom replied that communication is the key and all parties have to work together to develop and stick to a project plan. He also said that field conditions play an important role in influencing accuracy. Modern technologies like the laser tool make it easier to get answers. Feedback to the vendor is key.

Bruce Nestleroth commented that the through the POF format there are eight categories of defect sizes. The operator should have a sense which tools will capture the defects in a more accurate fashion.

Phil Nidd asked if validation is recommended for each wall thickness.

Tom Morrison said yes to get confidence in your results more digs may be required.

There were no commented from the ILI vendors.

Harvey Haines felt that this is a big issue in the US and he asked Tom on his philosophy.

Tom emphasized that there are many configurations of corrosion and rather than conduct big laboratory research projects, the operator should be responsible for validating the tool on their own line.

Harvey Haines asked that if operator's used dig data, would there be enough data points to statistically validate.

Tom commented that the digs can be expensive and that mapping the corrosion accurately and gathering the most data was the first and foremost responsibility.

Bruce Haggar from PII commented that accuracy levels of data i.e. data interpretation may be improved if operators were cleaning and preparing the line more effectively.

Trevor MacFarlane from Dynamic Risk Assessment commented that caution should be taken when addressing multiple tool run data from different years and eras of tools to ensure accurate representation of growth.

Tom replied that both similar and different tools had been matched. Guy Desjardins commented that probability distributions re employed in their analysis.

4. Tool Development and Research

Blain Ashworth (TCPL) presented on TCPL's continued with the UltraScan CD tool and EMAT technology for crack detection. The slides are included in this package.

Bob Coote from Coote Engineering inquired about the differences on past EMAT development initiatives through PRCI and this tool.

Blaine commented that picking high wave mode frequencies that they overcame some of the earlier problems.

Bruce commented that wave mode selection is better today that in the past.

Harvey commented that the previous tool had a wave mode that was sensitive to coatings. The wave mode did not fulfill size and discrimination at that time.


Kyle Keith from Foothills Pipeline inquired if this EMAT tool would be as good as the UltraScan CD tool.

Blaine responded that the goal is to be equivalent. The resolution circumferential could be less due to wave mode.

5. Conclusion

The group recognized that there had been some advancements over the last two years since the 1999 Workshop in many areas related to ILI tool technology development, detection capabilities and size availability.

	; ;
	· · · · · · · · · · · · · · · · · · ·
	<u> </u>
	N) And dispersion of the control of
	encethabamila, spiligipi
	constant frage of the second to
	sangkyvelle and a
	ive eddd Amalyed noo
	rdiinaanida daaqoo in
	describing typocopy and
	handy it is not seen at laboration
	vydelevi i palilik (Avode,
	rid Addina ka bergerika na ng



GRI/PRCI ILI Projects

- Mechanical Dam age
- Corrosion
- * Stress Corrosion Cracking
- Coating Disbondm ent
- Weld Defects
- . Stress and Strain
- Unpiggable Lines

Why Build a Mechanical Damage "Smart Pig"?

≢Initiall y the need to build a pig was based on:


- incidents like Edison, NJ and Reston, VA, and
- advice from pipelines that smart pigs were not discriminating all mechanical damage anomalies.
 - . Not all Mechanical Damage is found
 - Mechanical Damage often yields very small signal on MFL "smart pigs"


Why Build a Mechanical Damage "Smart Pig"?

- In 1997 GRI advisors started asking how this tool would be best run?
 - Does it makes little sense to run an LI tool solely for Mechanical Damage?
 - The tool is designed to be an improved MFL tool to detect corrosion and mechanical damage
 - Pipelines currently run MFL tods for corrosion
 - An improved tool may reliably detect 3rd party damage.
- How effective is an improved tool going to be at reducing incidents?
 - A study was commissioned with Kiefner & Assoc. to determine potential tool impact.

Kiefner Report

- GRI-99/0050
 Effectiveness of Various Means of Preventing Pipeline Failures from Mechanical Damage
- Study examined DOT incidents from 1985-1997
- Number of incidents studied is 3719
 - Combining the DOT databases from both the Natural Gas Transmission & Gathering and Liquid Petroleum Pipeline databases.





Mechanical Damage In-Line Inspection Impact

- Improved ILI may reduce the number of reportable incidents by <2-3% out of the 4-5% of delayed incidents
- Improved ILI may help reduce some of the more prominent failures
 - Edison NJ & Beilingham WA were inspected with ILI
 Small mechanical damage signal were not apparent until after the fact
 - Improved ILI might have helped prevent one or more of these incidents
 - These incidents are some of the most expensive incidents to pinelines
 - These incidents are have caused the significant exposure to the surrounding area

Future GTI-DOT work

- Battelle will study Circumferential MFL fields
 - Hope for better characterization of gouge region
 - . Will also examine corrosion sizing & crack detection capability
- SwRi will integrate defect assessment with MFL and nonlinear harmonics
 - Non-linear harmonics is a stress measurement using 3rd harmonics non-linearities to measure stress
- GRI continues to support Tuboscope in their Axial MFL development and commercialization


GRI/PRCI NDE Projects


- Mechanical Dam age
- m Corrosion
- **Stress Corrosion Cracking**
- Coating Disbondm ent
- Weld Defects
- Stress and Strain
- Unpiggable Lines

Corrosion


 Better Algorithms for Inverting MFL Signals to Corrosion Geometry (Depth, Length, Width)


- GRI has transfered the results of its investigations to vendors (reports available)
- A Circumferential MFL Tool is Now Available from Pli
 - . Can inspect for seam weld corrosion and cracking
 - Will be investigating improvements from using both axial and circumferential fields
- **■** Working on Gas Coupled Ultrasonics
 - Long term effort to make Ultrasonic pigging work in gas pipelines








■ Mechanical Damage ■ Corrosion ■ Stress Corrosion Cracking ■ Coating Disbondment ■ Weld Defects ■ Stress and Strain ■ Unpiggable Lines




































Mechanical Damage ■ Corrosion ■ Stress Corrosion Cracking ■ Coating Disbondm ent ■ Weld Defects

■ Stress and Strain■ Unpiggable Lines









Inspection Techniques

- Mechanical Damage
- Corrosion
- * Stress Corrosion Cracking
- . Coating Disbondment
- Weld Defects
- Stress and Strain
- Unpiggable Lines

Girth Weld Inspection

- ■No ILI tool exist for inspecting girth weld in pipelines
- ■One Robotics tools w as developed by PG&E for inspecting girth welds on out of service lines
 - Technique used EMATs generating S_H waves

GRI/PRCI NDE Projects

- Mechanical Damage
- Corrosion
- Stress Corrosion Cracking
- Coating Disbondm ent
- Weld Defects
- Stress and Strain
- Unpiggable Lines


Stress & Strain

■Indirect T echniques

- Inertial navigation pigging (not a research issue)
 - Snam has performed studies
 - Vendors testing tools at the PSF

■Direct T echniques

- . MIVC (Magnetically Induced Velocity Changes)
 - Developing equipment that is portable enough to work "in-the-ditch"
 - Will probably be testing on pipelines in 2001 or 2002
- Uitrasonic Shear Wave Birefringence
 - Currently working on laboratory techniques with NIST to measure stress differentials in pipes
- Non-Linear Harmonics
 - Currently working on laboratory techniques as part of mechanical damage program



GRI/PRCI NDE Projects

- Mechanical Damage
- **■** Corrosion
- Stress Corrosion Cracking
- # Coating Disbondment
- Weld Defects
- Stress and Strain
- Unpiggable Lines

Unpiggable Lines

- Significant Problems that Male Lines Unpiggable are:
 - High Speed Single Lines
 - Speed control
 - Laterala
 - No current solution
 - Need some sort of self powered robot
 - Undersized Valves
 - Collapsible Pigs
 - Plug Valves
 - · No current solution
 - Remote Field Eddy Currents have been suggested. but no current research is active in this area

Conclusions

- Newer Technologies are Becom ing Available for In-Line Inspection of P ipelines
 - * Corresion
 - Better resolution with Magnetic Flux Leakage

- Circumferential MFL for axial corrosion
- Axial Cracking
 - Ultrasonics both imaging and guided wave techniques
 - Circumferential MFL is only good for large cracks
- Mechanical Danage
 - Reduced Field MFL additions to MFL corresion tools


Conclusion


- ***T** here are many promising technologies for improving inspections
- ■I ha ve purposefully not listed them in a concluding table because w e don't know which ones will be technically adequate or commercially successful


	47


	200
	akida-petyyy
	strate. Summate pick ye good
	edidasay, pysjá
	Statistics with the state of th
	A A designa de de delegiones
	Arthurstandia


	Militarywood
	eddingly of postuli
	ulaliquissanni



















When Does Cracking Occur?

- When the microstructure under the gouge is damaged and subjected to significant tensile stresses due to pressure or rerounding
 - Depending on the indentor, we've seen cracking in many defects with a maximum depth (before rerounding) of 2 to 3 percent. We've seen some cracking in defects with maximum depths (before rerounding) of 1 to 1.5 percent and less.

Aura 9-12, 200

Bazil 2001 Pi paling Workshop




Inspection Approaches


- · Caliper and dent-detection tools
 - Great for large rock dents
 - Requires a significantly different philosophy for third-party damage that may have cracks: examine all dents
 - Recognize that some gouges with cracking may have rerounded to a residual depth dent approaching zero; these defects will be missed
- Standard Magnetic flux leakage tools
 - Have found some mechanical damage, but not reliably

Can MFL be made more reliable and used to differentiate hazardous defects from benign defects?

April 9-17, 2001

Bard 2001 Pipalina Workshop











Sanii 2001 Pi paline Workshop





Causes of MFL Signals at Mechanical Damage Defects


- · Removed metal causing the signal to increase
- Damage to the steel generally causes the signal to decrease if the magnetization level is low;
- Stresses and strains change the signals around the defect, and denting changes the orientation of the pipe wall relative to sensors – all of which further complicates the signals
- · Cracks cause little or no signals


April 9-12, 200


Band 2001 Pi palma Wattahii




























Inspection Goals (Significant Mechanical Damage)

- Detect
 - Mechanical damage with damage to the steel under the indentor
 - High stresses and strains in wake of indentor
 - Rerounding
 - Cracks
- Characterize
 - Degree and amount of damage to the steel and rerounding
 - Dent and gouge lengths

April 9-12, 2001

Sand 2501 Physiana Wartshop





Detection Analysis


- Decoupling the MFL signal reveals the presence of damage to the steel. A defect with damage to the steel yields a distinct signature in the decoupled signal.
 - The gouge signal shows regions of deformed, moved and removed metal
 - A reround "halo" shows regions that were deformed but no permanent deformation
- Decoupling increases the probability of obtaining a measurable signal from significant mechanical damage and properly differentiates these signals from other "anomalous" signals


Apre 9-12, 2001

Bard 2001 Province Warran














	elista (ili) ili) ili yandanigan
	ı
	No exhibition of Equippe (consistent
	essigien izazat en estitui
	जेनसंस्कृताहरू
	eeskinnestangengissaadis
	v bertament verifier a franciscopy v
	correnn schools diamates (es
	venidhedissössadikssö ö
	rechilding Vessealth, dibe.
	volinykli
















Repair Considerations

- Removal of the constraint applied by the indentor can actually lower the fatigue life of a dent
 - Implication: Dents that re-round to less than 6% of the OD may still require a repair (sleeve or cut-out)
- Will a reinforcement sleeve be effective in eliminating the potential for crack initiation and growth?
 - A pressure containment sleeve may be necessary

April 9-1 Z, 2001

Sund 2001 Province Workshop

Side ?




Excavation Program Planning


- Methodologies required to rank dents on a priority list (similar to applying ASME B31G or RSTRENG to corrosion tool data)
- Numerical models developed to predict the severity of dents
- Caliper tool data should be correlated with corrosion and crack tool data
- Work underway to develop rapid characterization criteria


April 5-12, 200


Banf 2001 Pissins Workshop


. . . .













Why Should ILI Tool Corrosion Sizing be Validated?

- By validating an inspection run any ILI tool reporting problems should become quickly evident.
- To verify the tool vendors claim of sizing accuracy for penetration, length and width. Failure/rupture pressure bounds are not typically included in a contract.
- Besides repeatability, there is a need to check overall bias and variable bias (systematic misreporting as a function of penetration, such as overestimating shallow features, and underestimating deeper features).

April 9-12, 200

Barel 2001 Pipeline Workshop

Siede 5



Why Should ILI Tool Corrosion Sizing be Validated?

- To determine whether ILi tool measurement error depends upon
 - feature geometry (complicated geometry being more troublesome for some tools to interpret),
 - density of the corrosion areas,
 - penetration of the feature.
- To determine whether there is a difference in ILi tool reporting between controlled (laboratory testing) vs. inspection conditions.

April 9-12, 2001

Sunf 2001 Pipeline Warkshop

Sinte I



Why Should ILI Tool Corrosion Sizing be Validated?

- Knowledge of sizing accuracy is necessary for ANY prediction based on ILI data (such as growth modelling---see Working Group 10, Bob Worthingham and Trevor Place).
- •To c heck whether the ILI tool is "blind" to a certain type of feature, such as Narrow Axial External Corrosion (NAEC).
- Automatic vs. manual interpretation of ILI tool reporting—how good is automatic vs. manual.
- Ne cessary as part of the process of developing new ILI tools.

April 9-12, 2001

B -- E 2001 Drawling Windship

Skd. ?



Why Should ILI Tool Corrosion Sizing be Validated?

 Engineers and researchers require an assessment of the possible measurement error in penetration and length for failure/rupture pressure calculations based on ILI and field tool reporting.

April 8-12, 2001

Banff 2001 Pleatine Workshop



Disadvantages of NOT Validating ILI Tools

- If the ILI tool is not validated, the ILI tool vendor and pipeline operator can have unnecessary disagreements as to the ILI tool performance.
- The pipeline regulatory agency has to understand that the pipeline operator and ILI tool vendor agree on the performance characteristics of the ILI tool.
- A non-validated or non-understood tool can lead to unnecessary excavations, or the omission of a repair that could have stopped a leak or rupture.

April 9-12, 2001

Berit 2001 Pipuline Worksho

Sia+ 0



Disadvantages of NOT Validating ILI Tools

- It is not possible to improve ILI tool performance if the ILI tool vendor does not receive feedback from the pipeline operator as to the tool's performance.
- After every inspection, some digs are done. Making digs enables a quick check of the IL1 tool performance to be obtained, rather than having something wrong be discovered a long time later.

April 9-12, 2001

Baraf 2001 Pipalina Workshop

Since 10



Other Aspects of ILI Tool Validation

- Check False Positive and False Negative calls for cracks and corrosion.
- Incorrect orientation and/or odometer slippage sometimes the feature someone is attempting to excavate can be on the other side of the pipe, and can be several metres away.
- Measurement errors are important as part of studying the relationship between it.I and field tool reporting. A regression line between an It.I tool and a field tool is not a valid relationship unless the slope is corrected by accounting for the measurement error of both tools.

April 8-12, 200

Benf 2001 Fipsans Wertsho

Side ti



Other Aspects of ILI Tool Validation

- By having estimates of measurement error of ILI and field tools, if a comparison shows too large an error, reasons for the difference can be looked for. If things are workly, a reason should be determined for the worklyness.
- LI tool should be validated with respect to field tool data, any available multiple inspection ILi data, and using both types of data if possible.

April 9-12, 2001

unit 2001 Pipaline Wertshop

2Mde 12



Why Should Field Tools be Validated?

- Field tools are typically taken to be "perfect." The reason is that "the corrosion was right in front of my eyes." Beware, field tools can have large errors particularly if the conditions are bad, the corrosion is very complicated, and there are time constraints.
- ·Help s to compare different field tools.
- Validation of field tools will help assess the capabilities of field tool operating personnel.

April 9-12, 200

Sant 2001 Pasters Worksho

304e 13



Why Should Field Tools be Validated?

- If a field tool is not validated,
 - the measurement error of the field tool will be wrongly associated with the in-line inspection tool, which can lead to unnecessary excavations, ruptures or leaks,
 - it can lead to unnecessary refuting of the vendors contracted specifications, and
 - the regulator can call the inspection and maintenance programs into question.

April 9-12, 2001

Banf 2001 Plpstine Workshop

Pluta 64









Figure 1.1: Measured vs. Contracted 80% Confidence Interval for Penetration for the Brand New Super-Duper High Resolution Morrison Scientific Inc. In-Line Inspection Tool







































- These two UltraScan CD tool runs using the previous procedure were very smooth.
- The Average inspection speeds were:
 - 0.28 m/s for the water pumped directions, and
 - 0.245 m/s for the air compressor driven dewatering runs in the opposite directions.

April 8-12, 200

idell' 2001 Planting Waterbury

Sii 443






REPRODUCIBILITY OF INSPECTION


- Not a single defects (cracks, crack fields) with an estimated depth > 12.5 % W.T. (i.e., 1 mm) was missed in the corresponding reversed (second) run
- Lengths and depth classification from both runs were good:
 - with a mean deviation in length: ±8% and ±7% for the two inspected sections
 - with depths in the same depth categories as measured in 82% of the defects measured in one section, and 92% of the defects measured in the other section


April 9-12, 200

Banif 2001 Pipeline Westship

Side 15










CONCLUSIONS OF RECENT ULTRASCAN CD R&D

- It is possible to inspect a gas pipeline using the UltraScan_CD tool in a liquid slug
- proper preparations are important
- UltraScan CD tool has sufficient sensitivity and discrimination for finding and accurately sizing SCC for integrity management purposes
- a "base-line standard" has been established for measuring the performance of new crack detection tool against
- Assessment of CD tool data would be enhanced if Effective Area Assessment methods for calculating remaining strength were possible.

April 12, 200

Sand 2001 Pipeline Wastaling

Săde 19





EMATSCAN CD TOOL DEVELOPMENT - TIMELINE

1997 Pipetronix proposed new EmatScan CD Tool

concept for Gas Pipelines

1998 TransCanada, IzIP and Pipetronix complete Technical Feasibility Study of EmatScan CD

Tool Concept

1999 Pil and Pipetronix merge & Agreement for

Developing a EmatScan CD Tool negotiated


2000 Tool Design Finalized


2002 Acceptance Testing of Tool planned


April 9-12, 2001


Saul 2001 Pipeline Worksho


55de 21














CHARACTERISTICS OF EMATSCAN CD

- The goal of the new EmatScan CD tool are to:
- be able to operate in gas lines without a liquid couplant
- be a robust and reliable design
- provide full circumference wall coverage
- provide redundant detection of sub critical SCC features
- discriminate between internal and external features
- determine the length and depth of axial crack features
- predict effective areas, if possible

April 9-12, 2001

Banff 2001 Pleatine Workshop

State 27



	deligisä äivennessä erästä saanseetä jääätä särjä, tännennessä saatalasta järjen eta jäääläjä järjennessa, ken

Workshop Session 8 - In-line Inspection of Transmission Pipelines Wednesday, April 11, 2001 at 8:30 a.m. - noon

Co-Chair: Steve Gosse, Westcoast Energy Co-Chair: Arti Bhatia, Alliance Pipeline

Poll Compilation - Blaine Ashworth, TransCanada PipeLines

Results of workshop poll on what the next Key Research and Technological Advancements the pipeline industry will need in next 5 years.

Pipeline Operators

- Crack Detection (SCC) & sizing (Gas Line)
- Increased tool reliability (hardware)
- Improvements on CD Tools for Distinguishing different defects and terminology clarification
 - Mechanical Damage incl. orientation on caliper
 - Higher Accuracy -small diameter internal pits
 - Crack Detection
 - Increased Focus on ILI Repeatability Reporting
- Smaller diameter (i.e.,) down to 6" and 8" reliable crack detection tool
- Crack detection & discrimination tool
 - More accurate defect measurement for general corrosion
 - Automated external corrosion validation tool
- Competition for UT tools (get prices in-line
 - A tool that will grade severity of weld defects
- Better Reporting Accuracy
 - "Multi-Purpose" tools all-in one
 - Pressure Failure Predictions for all types of defects
- Tool Measurement standardization sounds logical, probably normal in other industries
 - Maybe there needs to be several "test" or "validation "pipe sections around continent that serve as baseline references to normalize between variables (tool type, operator, etc.) Vendor would certify recent validation before use.
- Multi defect identification with a single tool/ single run. (I.e., crack, corrosion, geometry & corrosion (or ideally all).
 - Algorithm development (continued) for faster, more accurate data reporting.

- Possibly a more defined set of standards or guidelines for vendors to follow in building and operating ILI tools.
- Develop a "compact" low powered tool (i.e., digital or laser) that will have redundant measurement in the same train to validate data.
 - Tools that will draw the pipeline profile and provide an image of every feature, dent, transition, etc. (i.e., like an internal camera). This tool should have the same accuracy for different speeds.

Others

- Reliable Detection of Seam Weld defects no ERW pipe in small sizes down to 6"
- UT corrosion detection & sizing for gas pipelines able to run in gas or oil.
- Better 1st run reliability
 - Detection & sizing of longitudinal cracks in gas lines
 - Inspection at higher gas flows
 - Repeatable results
 - Better accuracy of sizing
- Improvements are needed for geometry survey & feature definitions & definition & investigations. Prime focus should be verification for safety evaluations, maintenance time prediction for reliabilities. Integrate Materials & ultrasonic CD approaches good reasons, may become the best approach.
 - Pipe Movement monitoring is more viable than Stress monitoring. I believe this enhancement will be made.
- Standardization of terminology of terminology and reporting for ILI runs. We can talk about Probability of Detection until the Cows come home but is everyone (operator s, inspection companies/ regulators) an example, measuring a defect differently, and then we will never achieve the ultimate capability of using these tools!
 - Better MFL for very thick walled pipe Arctic applications
 - Real time Risk assessment /Risk Management from ILI data
- Standardization including terms, accuracy & sizing, analysis, etc.
 - Pipe in Pipe inspection
 - Better define dents & damage (stress concentration, etc.
 - Improve repeatability of inspections
 - Improve accuracy of sizing defects
 - Work towards inspecting low pressure gas pipelines
- Be able to identify mechanical damage better.
 - Be able to size cracks more consistently

- Multiple Technologies on one ILI Tool, to enhance detection and accuracy, also providing greater value to the operators
- To see the increasing development and use of EMAT technology.
- Stress corrosion cracking tool.
 - Caliper & MFL tool combination.
- 10/12" Ultrasonic crack detection tools
 - Mechanical damage characteristics too
 - New ultrasonic crack detection tools for gas lines
- Combination of technologies to consolidate crack, wall loss and deformation in one survey.
 - This is needed now to address the rising concern in 3rd party damage, which requires all three technologies to fully identify and quantify.
- Inspect the interior pipe of a steel pipe in steel pipe system. It is a liquid pipeline. The interior pipe is not concentric or in a consistent location within the outer pipe. Inner pipe is 10" x 0.688 WT, the outer pipe is 12" x 0.75" WT. Annular space in filled with inert gas. Operating temperature is 150F operating pressure 1600 psia.
- Real Time Readings from free swimming tools
 - On board comparison of inspections logs while tool is running
 - Bi-directional capabilities for large diameter transmission pipelines
 - The ability to determine if a run is good within a few hours.

		an myönen kantion kalaidijöilistää kaystasia kastainata ennitäätää, kantiintäyvenittää, kevittää järennadisenkia
		ne andre melle enter de la constante de la con

Managin, الماني المانية المانية المالية المانية المانية المانية المانية المانية المانية المانية المانية المانية April 11, 2001 8:30 a.m. - 12:00 p.m.

Banff/2001 Pipeline Workshop

Company	Name	Phone	E-mail	The many control of the control of t
Morrison Scient, Ric	Tom Morrisan	403-262-8160	403-262-8160 / Lan	Signature
-NBRIDGE PREMISE ME	1	780 420-8715	180 420-8715 doin engenecapti enbudae. com	Kern X
Stains Ashwerth TEPL	TKPL	405-196- 930		9
Jonny Jackman	CANMET-M72	613.995.8248	613.995.82.48 Mackman @ NRCan. ge,	in di
Days Hour	KOSEN	14.915.0280	CA. 925.020 brown & co.	A O
Kick Stellmaconic English as as	Rosen GERGE PROCIN	1611-692-804	rosenten & Cadustan tom	
BASELIME /EC.	1	416-415-6332	gerge, procime ogc. entri sq., com	Sing
TECH NOUGGIES		SOMMER 780-417-4303 SOMMER 780-417-4303	garrys Phaselinetech. com	on they taken
PIT Main AM			Watmer (a) + m W. Co	The state of the s
E1264	ELAC	46 482-3421 u	416 482-3421 weckendopi - wuado. com	11/11/11
Ates Parlines	DELTON GRAY 6	80/464-9133/	(80) 464-9133 delton-gray Elkeyrponconta, com	to come of
ebowell	Jill Hokins (2	(307) 420-7581 4	illmhoping auga and	. BS
y	CHKIS (FORTHELL 406 698-3318 Chursha bamps).com	106 698-3318 C	hust D forps).com	STACE OF THE STACE
		80.540.8884 5		Jane De 200

April 11, 2001 8:30 a.m. - 12:00 p.m.

Managing Pipeline Integrity: In-Line Inspection of Transmission Pipelines April 11, 2001 8:30 a.m. - 12:00 p.m.

Banff/2001 Pipeline Workshop

	A	La tate							THE PROPERTY OF THE PROPERTY O	reon .		*	Car Car		20 10 10 10 10 10 10 10 10 10 10 10 10 10	" Labouration	C. Julie	
	rues emenge, ca	150 Merland @ byservices. car	16enger @WET. Og.	ĺ	Wintech actty lokel. mt	holdening Kachinal Lan	Sales. Ca O herite L.	The state of the s		102 210 2228 1	davd-a-tesorpermil mobil.com		Masse mb. gc. ca	Jubril-Mahas @ James 1.	bade honandraini (18 singing ping); it		Drikoxh (287, CA	المادر المدر
403 299 276.8		(40x) > 15 < (50A)	260 960-2000	(HIL NIDD 713 5673702	6	483F-41F(59H)			750-4405-0CL	02 24C 2016 501			403. 287. 362CI	403- 920-6578 A	01-62048686 pc	L9h3-1 25		
PAUL TRUDEL	1 Late of the T	Jett Sumerland	12		MAKTIN MINSPEAC	MARTY WEDEN	JACQUES ESERTE	BERNIE JACOBSON	Bury Mattens	and Feren	Moramaco Tom.	0 0	Kima Kaca	GABRIEL KAHAL	TACLA BOLYNORINI	Dele Fukosahke		
NATIONAL ENERGY BOARD	BS Appline Services.	·	Dass Tree - 3	Nation 120	Can Doc 12 fe 12 fe	HELD WARD WEDEN	カート こうかっているのう ゴルにないこう ころだんし	No. of the Control of	Kandan in Kline	Kainbow Pipe Line Company David Fesch	D.T.	Jahonal Gam Rad				Lit III C	NELS T	
35	36	37	38	39	40		42	43		22 + +	45 D	46	47	48	49	+-		51

Managing Pipeline Integrity: In-Line Inspection of Transmission Pipelines April 11, 2001 8:30 a.m. - 12:00 p.m.

C 3			**************************************		Cata (AAA)
7	1 RANS GAS LTd	Jules Chorney	306 975-8550	306 975-8550 Chorney @ transgas. sk. ca	S
53	Transcanada Apelinu	Garry Nortor	P059-082-80h	gary - norten Otranscanada. com	Hea lot
54	TCAL	READ SADOWING	403-920-6086	403-920-6086 bood_sadoway@tons canada.com	
55	TCPL	Mark Yeomans	403-026-504	403-920-690 mont-yeomins etranscanda. com	my
95	TiM	Gruce Gray	403.520.6088	MILLE-Gray@ Horsconodo an	The same of the sa
27	PERBLINE	766 SmyTH	43 27-8383	DSMKTH @ KEXBOLME-CON	
58	Footbills Pipe Lives		9444 466 EOH	kyle. Keith@ Foothillspipe	THE
59	NOVA CHEMICALS	RAY JONES	403-3518319	JONES R & NOMEWEN. COM	A A
09	CORRERO CAMADIA INC	Dow DRAN	2854-144-08L	dowg. doran le corrpro.ca	Sangles
61	ENDRINGE PIPELIJES IND DEB BILLEY	DEB BILLEY	780-420 5383	det. in 1 ley @ cnpl. entridge. em Od, ieu	Odijen
62	BJ Piper into Inspector	CARIS HALLAN	403-531-5300	CLANTACKOR RESCRAFICES . (F)	10 - Yallan
63	65 Pipulice Augustra		403/531-7530	Chekter ob sommon cax	1 mm
49	SUN-CANASMAN PRECINE	IAN SMITH	1499 1489 506	15mith@Sun-conadion.com	3 4
89	Mineral & Mark comant Samile (3ch Smith	Bob Smith	17097671850	17.03.747 15.60 represed we smith Garage	1000
99	7		805) 389-7544	(805) 389-757-4 Trans. Pells LN 65.1	A. 80 00
<i>L</i> 9	Mineral Managent Enice Dennis Hinnah		D127-1218-(Ob	Ponnie House by mine and	Jan B.
89	PII	DOUL ROWSEY	1	CONSKIND & PIL. CAMOREM	of h
			A STATE OF THE PARTY OF THE PAR	The state of the s	


Managing Pipeline Integrity: In-Line Inspection of Transmission Pipelines April 11, 2001 8:30 a.m. - 12:00 p.m.

Banff/2001 Pipeline Worksho

Ollewin	And the second of the second o	10 mg		17.		how i Juhne	A MIN	10 10 C	1/2	100	C. Wedler	near Harry		Hant Like	Carent John		, X	X	M.	# 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Romofin	9.6.7.	A STATE OF THE STA		<u>_</u>
		markow+mplica		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	prian connectife languada com	fleglic Grueb, pe.ca	ete (613) 992-3738 NBILLETTE, 10, 011	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	go Jevery (entrange es	713-849-6346 rubadonica 211	I NEW MINISTE HAGE EMAN 713-X19,1227 12	AGGERMANDE PYI-USA, COM L	garrette wilking and a	mo state com	razor@fleetoch com	Police @ bome		Ken ay we transcoale.	rhania orthans	jwong Dwei.org	4	DWallace centra becwel org	Ş	250-868-4586 chillintone baggs.com	
		150 571 -4030	1/2/2 SIZ 7/2 7/2/2			11/21/20	ette (613) 992-3738	0 N (43 492.4577		113-849-6346 1	RNW 712-849,122	ACC3 12 /:	Kie (78) 420 - 8478 90	180-41 C-0072	100 501 500	403 247-1480	102-900-27-7					250-751-8319 De	403-920-6504	250-868-4586	
	B CHE		Vision WAYA Comment of the control o	BRIAN ROTHWELL	National France Jeghic Tranci Jeghic	Nation Of the Contract of the	10 mada 100 15:11	1811C + 5		Chi Sillie Kudraga	much bane Have		Jarrell VIIKie	ALTO KOBERT LAZOK		300 (0000	rige Len Taylor	J. J. J. Consi	277	y Jenniter Warz	Don WALL	Sons Show	James D. II.	11 10 p : 1)	
E. C. Cardon	7 d W 1 60	07	71 7001	7 7 - 4 8	12 Nathand Bren	73 Nation 0	74 100		PII NOTH AMPLICA	76 OTILAL	_	Enteridae Pipelines To	78 FLSET TC.	-	19 (00 ting 12)	80 (((()))	+	$\frac{81}{4}$ KIDQUO	82 Westcourt E	83	CENTRA GAS	84 TCPL	85 BC Ga.		meterbrodishdeperalyminetetelmingsepträdiddyspelminebroschangddesstädisfraktivistisksförraknafeterdiaddissorandrapserdiaddissor

Managing Pipeline Integrity: In-Line Inspection of Transmission Pipelines April 11, 2001 8:30 a.m. - 12:00 p.m.

	A Marian	- Company		M	MA	Ma		MR		Color Sulpra	X	Ri	1 1		Called "	100	000		er treat in supplier and experience of the second project comments and the second comments are second comments are second comments are second comments and the second comments are sec		designation of the second seco	emine de de la companya de la compa	
	bwanderson @ bagas.com		ajolivette 6 Garster, a.n.	6 parados (3 canspec. com	Cerry Wil Hinson Bositive prairets com	candrer to pri-118 con		cetinere home. com		Constant of the Constant of th	Icarlson allance - pirlan, con	452 - 483 - 1008 quistarte Alliance - Pipeline Con	Bruce I. Michiel Petan Chilling		DESCRIBES CALIFORNICE CAN	Sar Camp Orland	(N) (10) (N) (N) (N) (N) (N) (N) (N) (N) (N) (N						
	(250)868-4572	780 - 180 - 18 C	CE 7 17 5350	(445-044-08/	(403) 235 - 1650	2627 11/3 214		403 232 8212	32.35. 8.25 (519)	101 00 811	70 517 6303	452-483-1608	3-6)536-7520	(403) 720-4827		1921-025 (504)							Print to do comment
	BARRY ANDERSON	Davio Jourette	Boin B. A.		Gerry Wilkinson	Tow Sarrier	W-11-611	matt cenne	يعد الجلد لا مداله دا	Lorne Calen	- Andrews	٦	Bauce Moore	Bu Kanso,		SAVE MUNEO							
	5CGAS	ANSPÉC GROUP INC			Ositive Projects	FII	Anterio Course	CO 1 7 1 7 1 7 1 7 1 7 1 7 1 7 1 7 1 7 1	Throportabin State Degel	Alliance Pipeline				A ECLIPSE SCIENTER		KURSWS/IIDM:		A PARTICIPATION OF THE PARTICI			The state of the s	To prince the state of the stat	The second secon
86	3	87	88	68	T	_` <u>`</u>	5	92	-	93 /	94	50	Ī	96	97	P)	86	66	100	THE RESERVE AND THE PROPERTY OF THE PROPERTY O		102	Although the property of the p





Introduction

- Working Group 8: In-line Inspection of Transmission Pipelines
- Topics State of the Industry, Mechanical Damage, Dent Assessment, Tool Validation and
- · ILI Vendor, Operator, Regulators and Consultants

April 9-12, 2001



Today's Discussion

- State of the Industry Today Harvey Haines (GTI)
- Inspecting for mechanical damage, dents, hard spots -Bruce Nestleroth (Batelle), Blair Carroll (Fleet Technology)
- Vendor Tool Performance Specifications Tom Morrison (Morrison Scientific)
- R&D Blaine Ashworth (TransCanada Pipelines)
- Industry Standards Reena Sahney (TransCanada Pipelines)

April 9-12, 2001

Benit 2001 Pi peáne Wurkshop



1999 Discussion

- Tool development
- False Calls
- Feedback to vendors/vendor involvement
- Levels of analysis
- Circ MFL
- · User's Groups
- Industry Standards for tools specs, accuracy, confidence levels and terminology

April 9-1 2, 2001



2001 Objectives

- ILI Tool Technology Advancements
- Continue the dialogue with all stakeholders
- Defect Models, Tool Validation
- R&D

April # 12, 2001



What was discussed

- Recognition of new advances in technology for mechanical damage, high resolution and crack detection
- Recognition that standard formats need to be used in areas such as defect sizing capabilities (POF Format), defect terminology (NACE Standards, CSA - sharp dents, gouges, "cracks", multi-mode defects)
- Data gathering protocols and information feedback to vendor is the key to most successful ILI runs
- Three wishes survey

April 9-12, 2001



What still needs to be done

- Groups and consensus to come together on standardization of terminology
- Groups and consensus for validation of various configurations of defects
- CEPA, NACE, API, OPS initiatives, CSA, ad-hoc committees need to have continued communication across their levels to ensure the standards and consistency
- Vendors need to be part of these groups and consensus so that different levels do not exist.

Aars 3-12, 2001

Roud 2001 Franks Wartsho

i

Working Group 9: Risk Assessment: Communication, Public Consultation and Planning

Tuesday, April 10, 2001, at 3:30 p.m.

Chairman: Ray Smith

Presentation Summary

This working group started with a National Film Board video entitled, "Worst Case Scenario". This video presented the diversified viewpoints of industry, the regulator, and the public - on the drilling of a sour gas well. The video narrated the story on how a project of drilling a sour gas well did not move forward, in spite of the fact that the company had both surface and sub-surface permission, but not the community support. The video also highlighted the need for more communication between the industry and the public; how to consult the public; and tips to plan new projects.

The discussions that followed the video are as follows:

Ian Dowsett pointed out that the issue of public perception keeps coming up in this Workshop and it is necessary to advance this issue.

Industry should move from the "reactive" mode to the "advance planning" mode with respect to public consultation.

Bill Tyson inquired, "what is the risk of this particular well when it is compared to other wells"? Ian Dowsett informed the attendees that this particular well was classified as Level 4 and the risk can be considered as acceptable.

With respect to the particular case presented in the video, one of the principal issues was that the company wanted to reduce the emergency response zone to 4 km, as opposed to the normal 12 km.

The difference in the perception between the industry and the public was explained. For example, the industry generally performs a risk analysis and arrives at a number. This risk number is then compared with a published standard, e.g., MIACC. On the other hand, the public does not care for the numeric risk values. This makes the communication between the industry and public more important.

The time lag between the leak and risk is about 1 - 6 hours if the leak occurs in a well, but there is no time lag if the leak occurs on an operating pipeline.

Ian Scott presented some tips on how a company should move forward with a project.

• Conduct good homework. Consult with the public at a very early stage. Give options to the public. Provide room and prepare to modify the project.

Art Meyer also shared the view, and further indicated, that the public should be fully engaged; the project should be communicated properly; alternatives identified; and appropriate changes should be accommodated in the project.

Important points to be noted in communication:

- The Public should not get the impression they are dealing with PhD's and experts are being brought in to force them to change.
- Prepare to accommodate public view and needs.
- Provide options and alternatives.
- Build credibility and trust.
- Negotiation requires values.
- Identify the person to communicate.

Various forms of communications methods were discussed, as follows:

- Informal is better, stay out of adversarial issues.
- An inquiry is not necessarily the best option.
- Field operators provide the first contact with the public and should be better prepared to communicate with the public. They should be trained to communicate appropriately.
- Too much communication should be avoided. For example, if 4-5 companies are drilling in a community, and if they all communicating with the public on same issue, the public will be lost in the information overload.
- One contact rather than multiple contacts.


It was highlighted that more than 50% of the companies are not part of any association, (e.g., CAPP) and are not part of any industry discussions.


Ian Scott informed the attendees about the public consultation process that CAPP is undertaking.

With respect to the public communication:

- The issues are important, not numbers.
- Values are more important than facts.
- The regulator, (e.g., AEUB), moves in the direction in which the companies become more responsible (self audit).
- There is a process in place in which the corporations are ranked and the non-performers are punished rather than the whole industry.
- There should be an industry bench mark.

Recommendation: A coordinated effort to develop a "Risk Communication Tool"







Roles and Responsibilities: Industry

Industry is responsible for the risks and for managing these risks.

- Individual companies (due diligence)
- Industry organizations and associations e.g. CAPP, CCPA

April 9-12, 2001

Sant 2001 Pipeline Workshop



Roles and Responsibilities: The Regulator

The regulator holds the responsibility for facilitating decision-making, the decision itself, and for ensuring that agreed-upon provisions (designed to address the risks) are met. (e.g. NEB, AEUB, US EPA)

- · Incentives and disincentives
- Acts and regulations
- Standards and guidelines

April 9-12, 2005

Bent 2001 Pipaline Workshop




The Role of the Public

The public does not have a direct responsibility; they have a role in understanding the issues and being involved in the process.

- · Individual involvement
- Organizations and activities

April 9-12, 2001

Senii 2001 Pi pakee Workshop




Banff/2001 Pipelin Workshop

Managins. ipeline Integrity: Risk Assessment/Risk Manageme...: Communications, Public Consultation, Planning April 10, 2001–3:30 p.m. - 5:00 p.m.

American American Company on a department	Company	N. T.			
Validation VIV of Article of Property of Article of Art		Name	Phone	E-mail	Affirm and the second of the s
And the second s	Las Caraboog,	KAK (Ph.)!	0 " Z		Signature
2	CAN MET/NACE	21	0680-297/120	Lan. Lewis Lank Mourol, orch	X
,		2081 - 2010	613 992 9573	btyson@ncan.gc.ca	
A	CAPP	Los Scott	43 267-1132	Scotte ccoo.ca	
4	TMPL	Ros HADDEN	770 1007		Anne
S	WET TI		1198-3011	roberth @ tmpl. ca	CH
9		THYMARD BIRH	250-233-4341	M DEACH CON	J.
And the second s	HEMPEL LOATINGS	BERNIE JAWBON	780-457.4111		
The second secon	KOMEX INTERNATIONAL	FRED		Jacobson @ Icrossrands com	
∞	The second secon	•		TOS -241 0200 to lidge adjan. Konex. Com	・アンソー
The second secon	MIMORA ELBOUSDAINI	CANMET IMTL	1468-366(819)		
*	Entride	ArtMeses	1	melocula DINRIAN. 90.00	The state of the s
10	Prince 12 2	1. 8 J		all made (Lery France)	The state of the s
The second section of the sect	- Andrew Control of the Control of t	remail vow	403-282-5637	M2-morray a home. Com	Oles Moon
	MANSERS Ltd.	Jules Chorney	306-975-8550		PU
77	CULT ENGINEERING	7		Chokurt @ Transgas. sk. ca	8
2	Atco Pinelines	HIRM		Aroms, act @ colteny. com	SAM
The state of the s	S. Armer	O a u 办		ant. junz Catcorineline. co.	Contraction
\$ 1 mmonths of the control of the co	HOWIEL MCDONNELL	(200 S PANOUNDAY 613-947-3603		SPAPONIOMONI PANIE	
1	1.8	DEBBIE SIBNENS			THE CONTRACT OF THE PARTY OF TH
9	IPSCO INC			CED & NIMPSI. CO.P.	OS
*Annual Constitution of the Constitution of th		1	306-424-7385	+law rence @ 1,0500, com	a Mar

Managing Pipeline Integrity: Risk Assessment/Risk Management: Communications, Public Consultation, Planning April 10, 2001 3:30 p.m. - 5:00 p.m.

M	1	X.			3		market management to the state of the state	marketing to the American and the state of t								
foremer a home, com	afaquia @ campipe con	John Greenslade 403 259- 1857 greenslade.john@ colteng. am	Jan 704 757 8350 Lid, War M. O 1087. Con	H College	1											
(9%1-152 88	11×21/2 %	403 259- 1857	104 757 8350	(413)29/-1631	403 2326171								Providence de la companya de la comp			of the manuscripture of which the statement of the statem
FRANK CHRISTONSEN	HEX HAGANIS	-15hu Greenslade	Leve Clark	Las Saith	Mr Dowsett											
Fucuci	AMEUSE PIPE	OH Energy	C-COKE	Carlin Granthat	KWDI WEST INC											The state of the s
17	18	10	20	21	2,2	23	24	25	26	27	28	29	30	~	32	c





Group 9 Recommendations - Part 1

- Move from adversarial to consultative processes: i.e., consultation versus hearings.
- Understand the hazards and risks earlier in the process; i.e., ensure that we communicate the right message.
- Distinguish between risk communications techniques and risk communications processes.

April B- 12, 2001

Banif 2001 Pipaline Westahop



Group 9 Recommendations - Part 2

- Field staff provide the first contact with the public; they should be trained in risk communication techniques.
- The public are increasingly being contacted about energy development; efforts should be made to deliver the correct message and reduce the number of visits.

April 5-12, 2001

Bortl 2001 Pipeline Workshop



Group 9 Recommendations - Part 3

- Issues are more important than numbers:
 i.e., an annual risk of fatality of 1.0E-06 has
 no meaning to the public, they will only hear
 the word fatality.
- Understand the issues and concerns expressed by the public and incorporate these into the design of and operation of the system.

Apr# \$-12, 2001

Benff 2001 Pipaline Werlehop

Working Group 10 - EXTERNAL CORROSION Tuesday, April 10, 2001 at 10:30 a.m. - 5:00 p.m.

Co-Chair: Robert Worthingham, TransCanada Pipelines

Co-Chair: Trevor Place, Corrosion Service

Rapporteur: Coral Lukaniuk, Global Thermoelectric

Summary from Banff/1999 Pipeline Workshop

This working group was focused on monitoring, assessing and predicting external corrosion. Approximately, 55 participants attended the first session on Remaining Strength and approximately, 85 participants attended the session on Corrosion Growth.

For Remaining Strength Assessment, the working group agreed that more direction in CSA Z662 would be helpful. The CSA Subcommittee would consider including a reference to RSTRENG using a "commentary". The CSA Subcommittee has included a reference of RSTRENG in the latest draft. Also, over 80% of the attendees indicated that training in remaining strength assessment would be beneficial. Based on this, it was recommended to CEPA to organize a 3rd party training program. This has occurred as part of this.

For Corrosion Growth, the working group was going to discuss with the CEPA the possibility of preparing a standard guideline for field measurement of corrosion damage. Similarly, the working group was going to discuss with the CEPA the possibility of using the CEPA Database for collecting soil analysis and associated corrosion rate information. The suggestions are currently being reviewed by CEPA.

10.1 Environmental Impact of Groundbeds

Katherine Ikeda-Cameron, NRTC & Tom Jack, NRTC

Objectives

- 10.1.1 Review recent investigations into environmental impact of impressed current groundbeds (NRTC research).
- 10.1.2 Understand possible ramifications to the corrosion control industry.

Questions & Discussion

- 1. Dave Hektner, BJ Pipeline Inspection Services How deep is an anode bed. Grant Firth, Corrpro Canada Approx. 100m.
- 2. Jamie Cox, DuPont Canada Is temp an issue? Tom Jack, NRTC Different electrochemical reactions may depend on temperature.
- 3. Doug Waslen, NEB Are they moving back towards graphite anodes?

- 4. Bob Gummow, Correng Consulting There is coke around the anode and the oxidation reaction is around the coke. Maybe we need more carbon backfill or to run the beds at a lower current density (higher pH). Tom Jack, NRTC many of the studies were around petroleum coke.
- 5. Stan Wong, CC Technologies Any problems with aquifers mixing? Peter Haas, Corrpro Canada Some problems and in some cases, had to modify the groundbeds.
- 6. Grant Firth, Corrpro Canada One of the clients is more concerned with surface water getting into the well bore. Any thoughts on contamination with shallow groundbeds as oppose to deep beds? Trevor Place, Corrosion Service Was there a difference between the two? Tom Jack, NRTC Have some data on the shallow beds and have noticed some contamination within a meter of the anodes. It quickly diminishes to background levels. All studies for deep anode beds have been based on spit up water.
- 7. David Jolivette, Canspec Any data on the beds before they went into place? Grant Firth, Corrpro Canada Most clients do not complete an analysis but soil resistivity is measured. Are there similarities in the soils? Doug Waslen, NEB There is a lack of understanding/sharing in the industry but it has come a long ways. It is much better to share info.
- 8. Bob Gummow, Correng Consulting Types of contamination. Tom Jack, NRTC Guidelines seem to be applicable for the hexavalent chromium. Hexavalent chromium is strongly dependent on the pH.
- 9. Reg Eadie, NRTC What are guidelines for, shallow or deep beds? Doug Not at this time. It makes sense to treat the deeps as water wells.
- 10. Cliff Mitchell, CJ Mitchell & Associates High concentration around the anode? Tom Jack, NRTC The exceedances are not very high and often within experimental error.
- 11. Tom Jack, NRTC Would the roots of crops mobilize these metals? Robert Worthingham, TransCanada There doesn't seem to be a strong concern but will keep Alberta Environmental Branch informed of future studies.
- 12. Cliff Mitchell, CJ Mitchell & Associates Alfa and clover are very deep. Tom Jack, NRTC confirmed that clover has deep roots and it is common to find them at 2m (shallow bed).
- 13. Peter Haas, Corrpro Canada That beds that have spit up have occurred in areas where there is a high water table. Most simple solution seems to be to run a higher standpipe.
- 14. Tom Jack, NRTC Commented that some of pressure in the standpipe has reached as high as 10psi.
- 15. Vote Deep beds spit up.
 - Totals: 23 consultants, 9 researchers, 3 regulators, 7 downstream, 2 upstream
 - a. Is this a problem? YES 10 consultants, 4 researchers, 3 regulators, 2 downstream, 0 upstream
 - b. Should more work be done? YES 19 consultants, 7 researchers, 3 regulators, 6 downstream, 1 upstream
 - c. Do we need more communication? YES 14 consultants, 7 researchers, 3 regulators, 5 downstream, 2 upstream
- 16. Cliff Mitchell, CJ Mitchell & Associates From the research, shouldn't there be recommendations to use materials that produce the least amount of contamination? Trevor Place, Corrosion Service We need a balance. Doug Waslen, NEB What's the tolerable level of risk? Robert Worthingham, TransCanada We should work more closely with the regulating bodies. Water and soil guidelines for contamination exist. Tom Jack, NRTC This is an argument for compliance. Reg Eadie, NRTC Some work has been done but

- maybe not enough to put forth recommendations. Robert Worthingham, TransCanada -TransCanada is currently looking at a number of sites.
- 17. Grant Firth, Corrpro Canada Is fluid "spit-up" from deep beds just a problem in AB? Peter Haas, Corrpro Canada - Confirms that he has seen it throughout the province. Robert Worthingham, TransCanada - Does anyone uses deep beds outside of AB? Bob Gummow, Correng Consulting - Hasn't seen any evidence in Ontario but believes more work needs to
- 18. John Chase Hunter McDonnell Pipeline Services Who funds the research? Robert Worthingham, TransCanada - TC has funded this to get an understanding of the situation. Maybe we can suggest to CEPA to do more work.
- 19. Peter Haas, Corrpro Canada Believes it is easy to quantative the amount of chemicals in the soil. Believes the contamination is very low and therefore, it is not a problem.
- 20. Tom Weber, Trenton Corp. NACE would be a good source to form a task group to study this. Robert Worthingham, TransCanada - There is some discussion on the NACE web

Review of Cathodic Protection Codes & Standards 10.2

R.A. Gummow, CORRENG Consulting Service Inc.

Objectives

- 10.2.1 Review of industry codes and practices governing CP.
- 10.2.2 Explore differences in code interpretation and code intention.
- 10.2.3 Determine if codes and standards adequately address the intention of asset management.
- 10.2.4 Review accepted cathodic protection criteria and developments in monitoring technologies intended to satisfy protection criteria.
- 10.2.5 Explore difficulties in assessing CP criteria conformance (interpretation and application).

Questions & Discussion

- 1. Barry Martens, Rainbow Pipeline We had more difficulty achieving -850mV criteria than
- 2. Bob Gummow, Correng Consulting Is it more economical to use 100mV?
- 3. Grant Firth, Corrpro Canada Shouldn't the criteria be set by science and not owners? Bob Gummow, Correng Consulting - This is just a position.
- 4. Barry Martens, Rainbow Pipeline More choices are maybe better. Bob Gummow, Correng Consulting - The criterion do not give you zero corrosion.
- 5. Doug Waslen, NEB Would the 100mV criteria achieve the minimum to avoid SCC? Bob Gummow, Correng Consulting - Need to beware of sensitive areas.
- 6. Bob Gummow, Correng Consulting Reference to OCC-1-1996, Section B.2.5. How many people change their criteria based on these "other considerations"? Robert Worthingham, TransCanada - Confirmed that TransCanada does. 7. Vote – CP Criteria

Total of 34 attendees that are users.

- a. -850mV off? YES 53%
- b. 100mV polarization? YES 35%
- c. Other? YES 12%

- 8. Doug Waslen, NEB If you're not following industry practices, then you should document why you are not.
- 9. Bob Gummow, Correng Consulting Do you use more rigorous criteria downstream of compressor stations?
- 10. Bob Gummow, Correng Consulting With time, we're going to see less provincial and national standards and more international standards.
- 11. Robert Worthingham, TransCanada How many people are using coupons? 3
- 12. Doug Waslen, NEB Reiterated Bob Gummow's comment that Canadian situations are unique. Doesn't think NACE standards are fully accepted in Canada.
- 13. Bob Gummow, Correng Consulting Is -950mv an imposition?
- 14. Trevor Place, Corrosion Service Do the upstream companies simply work with prescriptive guidelines? Doug Waslen, NEB The industry wants both prescriptive and goal oriented regulations and it is very difficult to know the best path. It is difficult to audit. Alex Petrusev, Corrosion Service Why is it difficult? Don't you require seeing that a company is meeting the benchmarks? Doug Waslen, NEB Many companies meet the criteria but could still have corrosion.
- 15. Reg Eadie, NRTC As a member of the public, I wouldn't be happy with 100mV if other companies are doing more. We need adequate protection to protect the public.
- 16. Barry Martens, Rainbow Pipeline If you had a leak, how do you determine what is adequate? Doug Waslen, NEB It depends on the situation, e.g. tape applied coating that shields the CP. Can't take one issue and dictate your corrosion program.
- 17. Robert Worthingham, TransCanada I encourage you to get involved with CSA and CGA to avoid future surprises.
- 18. Tom Morrison, Morrison Scientific Mentioned that NACE was encouraging the move towards to 100mV based on the info at the NACE National... ~4 papers.
- 19. Alex Petrusev, Corrosion Service Why discount the -850mV criteria? John Beavers, CC Technologies 100mV proves to be more beneficial for many companies that cannot achieve the 850mV. Doesn't think NACE will drop the -850mV as the 100mV takes extra work. Bob Gummow, Correng Consulting The 100mV doesn't appear in any of the world standards.
- 20. Barry Martens, Rainbow Pipeline Checked for CP by using a holiday detector on a tape-coated line. Wherever, it jeeped, SCC wasn't detected.
- 21. Tom Weber, Trenton Corp. Has anyone found SCC under other types of coatings? Doug Waslen, NEB yes, asphalt. Offered the SCC report. John Beavers, CC Technologies It is more likely to find it under tape but will find it under asphalt. Made a reference to finding SCC under swamp weights. For high pH SCC to occur, need high CP levels.
- 22. Alex Petrusev, Corrosion Service What about seasonal variations and how it affects the criteria? Bob Gummow, Correng Consulting Some companies monitor these situations. Doug Waslen, NEB Isn't TransCanada doing some work on seasonal CP? Robert Worthingham, TransCanada yes. Greg VanBoven, NRTC Resistance goes down in spring and goes up in the summer. In the winter, the resistance may be more electronegative. Dry soils are a concern as there are more fluctuations.
- 23. Tom Jack, NRTC Criteria are general rules but do not necessarily achieve the end result of corrosion protection. If the object is to protect the pipe, how relevant are the criteria in 100000 ohm-cm soils? How much influence, would this have in a dry environment?

- 24. Mark Johnson, Marr Associates The criteria assists with both general corrosion and SCC so we need criteria.
- 25. Cliff Mitchell, CJ Mitchell & Associates How do you know the pipe is protected? Dig it up to prove it?
 - Aside: Many of the comments refer to the overhead slide on German criteria, which is based on operating temperature and soil resistance, for unalloyed and low-alloy ferrous materials.
- 26. Greg VanBoven, NRTC 100mv is almost impossible to prove, as the soil is not homogenous. This hard to prove. Germans are looking at things they can measure on the surface. Likes what the Germans are saying.
- 27. John Beavers, CC Technologies Highlighted that all the existing criteria measures the average around the pipe, not just the 100mV criteria. Non-homogenous soil affects all criteria.
 - Aside: Turn off sufficient cp current sources that influence the pipe at the test site until at least 100mV cp polarization decay... (10.2.5.7.1) (overhead slide)
- 28. Robert Worthingham, TransCanada How do the regulators feel about pipelines being unprotected while depolarized surveys are being performed to confirm alternate criteria is being met? Doug Waslen, NEB The regulator is not going to say what to do and what not to do but it is up to the industry to follow their own programs
- 29. Bob Gummow, Correng Consulting Isn't the cracking range and the 100mV criteria in conflict? John Beavers, CC Technologies Care must be taken to ensure the pipe is not inside the SCC cracking range when applying the 100mV criteria.
- 30. Tom Jack, NRTC an unprotected pipeline proved to be quite a challenge to bring up the CP levels after a long absence of protection.
- 31. Robert Worthingham, TransCanada What length of time is required for depolarization to occur? Alex Petrusev, Corrosion Service Relied on the field personnel to inform him of the length a time needed to depolarize. Each area was unique. Bob Gummow, Correng Consulting There isn't a consensus on how long to leave it off. Some people suggest using a coupon as a way to assess the protection. Doug Waslen, NEB As long as the coupon is a representation of a pipe. Bob Gummow, Correng Consulting A coupon is more like a holiday on the pipe.
- 32. Reg Eadie, NRTC What about temp? Is the coupon the same temp as the pipeline? Bob Gummow, Correng Consulting Not always.
- 33. Bob Gummow, Correng Consulting Do you find coupons expensive? We need to think of the long-term savings.
- 34. Alex Petrusev, Corrosion Service What is the savings by using the 100mV? Bob Gummow, Correng Consulting Most companies only use the 100mV criteria if 850mV could not be met.
- 35. Bob Gummow, Correng Consulting The standards would most likely avoid specifying where to put coupons. Coupon use wouldn't be necessary if you were meeting the 850mV criteria.
- 36. Bob Gummow, Correng Consulting Reference to NACE Test Method TM0497-97 Use of Coupons to Determine the Adequacy of Cathodic Protection
- 37. Doug Waslen, NEB How do you know if coupons represent the pipe? Peter Haas It was accepted for Alyeska. John Beavers, CC Technologies There was zinc ribbon along the whole line. CC did some modelling work to demonstrate the effectiveness.

- 38. David Jolivette, Canspec Are pipe depth CP readings taken at excavations being used? Robert Worthingham, TransCanada TransCanada is collecting info (soils data, ILI data, etc.) in a database to assist with CP system.
- 39. Barry Martens, Rainbow Pipeline Commented that current is going through the coatings but you need to check.
- 40. John Chase, Hunter McDonnell Is the CP data being correlated to the ILI data? Robert Worthingham, TransCanada It is difficult to correlate the data. Care must be taken when determining what the correlations mean.

10.3 Corrosion Field Measurement and Growth Modeling

Objectives

- 10.3.1 Review recent field validation of corrosion growth models.
- 10.3.2 Determine application and limitations of corrosion growth models.
- 10.3.3 Discuss recent developments in external corrosion mapping techniques.

10.3a Corrosion Rate and Severity Results from In-Line-Inspection Data Guy Desjardins, Morrison Scientific

Questions & Discussion

- 1. Brad Smith, Enbridge How do we keep tack of variable growth rates? Guy Desjardins, Morrison Scientific There are seasonal changes and therefore, some variability. Brad Smith, Enbridge Is corrosion growth linear?
- Fraser King, NRTC Do you take into account that changes may occur yearly between inspections? Guy Desjardins, Morrison Scientific Yes. There is not much difference in rates. Growth was a few percent per inspection.
- 3. Bruce Dupuis, Baseline Technologies -Was MIC involved in the data sets considered? Robert Worthingham, TransCanada yes. Guy Desjardins, Morrison Scientific Some cases there were shallow features and others were deep. All features were included.
- 4. Stan Wong, CC Technologies Growth size and accuracy. Guy Desjardins, Morrison Scientific Used ILI data and compared it to field data. Found that it is within the 10%.
- 5. Greg VanBoven, NRTC Is it valid to overlay CP data over time to validate if CP is related to disbonded coatings? Tom Morrison, Morrison Scientific Can be done. Greg VanBoven, NRTC There would be benefit. Tom Morrison, Morrison Scientific Depends on the CIS data accuracy.
- 6. Doug Waslen, NEB This type of analysis is very worthwhile as it helps companies to defend their position.
- 7. Doug Waslen, NEB In the US the ILI frequency intervals are very arbitrary.
- 8. Barry Martens, Rainbow Pipeline Did you achieve what you wanted to? Robert Worthingham, TransCanada TransCanada was able to extend there interval period form 4 to 6 years on one line.
- 9. Stan Wong, CC Technologies Regarding the error banding, the model doesn't seem to follow a linear pattern. Robert Worthingham, TransCanada The acceptable risk is up to the company, which is handled outside of the prediction model. The prediction can aid in potentially high-risk areas.

- 10. David Jolivette, Canspec How accurate are the predictions? Guy Desjardins, Morrison Scientific Calculate probability of failure, etc for features along the pipeline. David Jolivette, Canspec How is soil incorporated in the predictions? Robert Worthingham, TransCanada The soil data helps to prioritize pipelines for their first inspections.
- 11. Harvey Haines, Gas Technology Institute Have these been compared to the British Gas results? Robert Worthingham, TransCanada PII is looking at the raw inspections to see if there is a change. Must be done with two PII data sets. As long as the data, from repeated inspections, is in a similar format, various sets of data can be reviewed with the Morrison Methodology. This is independent of the ILI tool used.
- 12. Harvey Haines, Gas Technology Institute Direct assessment in the US... can the data be shared with some of the companies in the US? Robert Worthingham, TransCanada We could consider this depending on the type of data they are looking for.
- 13. Barry Martens, Rainbow Pipeline We really need to understand and be confident of the data you receive from the ILI vendor.
- 14. Ivani de S. Bott, Catholic University of Rio de Janeiro—What about the compositions? Can you use the prediction on other pipeline? Robert Worthingham, TransCanada—The composition and rate are applied per site. It is being investigated and has been applied with some success.
- 15. Vote How many want to see more updates? ~50% of attendees

10.3b Laser-Based Corrosion Mapping System for Pipelines Richard Kania, RTD Quality Services Inc.


Questions & Discussion

- 1. Trevor MacFarlane, Dynamic Risk Feels this what the industry needs. The burst pressure is determined by remaining metal. Is there anything that RTD does to account for coincident small scale bulging, which may result in a non-conservative assessment? Richard Kania, RTD Quality Services We've developed software to overcome some of the problems. The data is marked circumferentially. Each line is assessed independently. By doing this, we can see the deformations. We use a pencil probe to verify the remaining wall thickness is as expected.
- 2. Reg Eadie, NRTC Methods using people vs. automation. For example, a human will see crud but the machine won't. Richard Kania, RTD Quality Services The surface has to be clean otherwise, the mapping results will be inaccurate. Tool operator checks cleanliness.
- 3. Kyle Keith, Foothills Pipelines Foothills has used the tool and has found it beneficial. Richard Kania, RTD Quality Services In the future, would like to measure the pipe without having a cleaned surface.
- 4. Dave Katz, Williams Pipeline West Would like to see something like this in the US. Is the tool used mostly to map complicated corrosion areas? Kyle Keith, Foothills Pipelines It saves the most money when it can be used for a long section.
- 5. Robert Worthingham, TransCanada The faster you can get in and out of a repair site, the more money is saved as the crews who are on stand-by can take the next steps. The quality of info is very good and you get a much better feel of what is really there.

6. Harvey Haines, Gas Technology Institute – Are you sharing your data with vendors? Robert Worthingham, TransCanada – Yes.

Possible Topics for 2003

- Comparison of ILI data with above ground techniques.
- Latest developments on CP criteria NACE, CSA, CGA
- Internal Corrosion Experience in Transmission Pipelines monitoring & mitigation
- Correlation of GIS data sets ILI, soil, etc.
- Soil models for predicting corrosion.
- Update of the environmental impact due to groundbeds.





WG 10: External Corrosion

- Have Fun
- Learn from each other
- Share experiences

April 5-12, 2001

Berill 2001 Pripating Workshop



Action Items From 1999 WG

- Objective: Determine if CSA should be revised to explicitly reference RSTRENG. Explicit references decrease the flexibility and life of a standard; however, the group recognizes that more direction in CSA Z662 would be helpful.
- Action: The CSA Subcommittee consider including a reference to RSTRENG using a "Commentary".
- Status: The CSA Subcommittee has included a reference to RSTRENG in the latest draft.

April 9-12, 2001

Bend 2001 Pi poline Worksho

59de 3



Action Items From 1999 WG

- Objective: Determine if training in remaining strength assessment is required. Over 80% of attendees indicated they would find such training beneficial.
- Action: Working Group Co-Chairs will recommend CEPA arrange a 3rd party training program to be rolled out in late 1999/2000.
- Status: This has occurred.

April 9-12, 2001

Sanif 2001 Presine Watsha

Side 4



Action Items From 1999 WG

- Objective: Explore advances of direct and indirect corrosion growth monitoring methods.
 - Determination of site-specific corrosion rates have been demonstrated and used in planning maintenance.
- Action: Working Group Co-Chairs to discuss with CEPA the possibility of preparing a standard guideline for field measurement of corrosion damage.
- Status: Database is under revision. Suggestion will be considered.

April 9-12, 2001

Sant 2001 Pipeline Western

8**244** \$



Action Items From 1999 WG

- Objective: Explore advances of direct and indirect corrosion growth monitoring methods.
 - Soil coupons are an alternative in locations where ILi data are difficult to obtain. Concern was expressed on how to analyze and characterize soils for corrosion rate correlations
- Action: Working Group Co-Chairs to discuss with CEPA the possibility of using the CEPA Database for collecting soil analysis and associated corrosion rate information.
- Status: Database is under revision. Suggestion will be considered.

 And Serv. 2001

 Seed 2001 Plante Water 2001

 Seed 2001 Plan

DAME 2001 Pr pages Works

Strain I



Objectives

- · Have Fun
- · Learn from each other
- Share experiences

April 1-12, 2001

Barel 2001 Planting Water

*4- *



Environmental Impact of Impressed Current CP Groundbeds

- The significance of soil contamination caused by impressed current groundbed operation
- · Possible ramifications to the corrosion control industry

10:30 - 12:00

April 8-12, 200

anii 2001 in padra Wolkshop

Steen 2



Codes and Practices Relating to Cathodic Protection

- · Regulations and non-regulatory guidelines
- CSA Z662, OCC-1, NACE RP-0169, Canadian Electrical Code, CSA C.22.3 No. 6, NACE RP-0177
- · Differences in code interpretation and code intention.
- Accepted CP criteria and developments in monitoring technologies intended to satisfy protection criteria.
- · Differences in criteria interpretation and application
- · Problems with CP application

1:30 - 3:00

April 8-52, 2001

Sard 2001 Prpoles Westshop



Corrosion Field Measurement and Growth Modelling

- · Corresion growth modelling update
 - limitations, accuracy, success of present models
 - Review of year 2000 field validations
- Recent developments in external corrosion mapping techniques
 - ease of application, accuracy, correlation to ILI data.

3:30 - 5:00

April 9-1 2, 2001

nd 2001 Pi poline Workshop

Silver 10




Expectations

- · No Judgement or Criticism passed
- Difference of Opinion is OK
- · Different Circumstances
 - = Different Approaches
- · Share, Learn, Have Fun
- Don't take this TOO seriously!

April 8-12, 2001

Barel 2007 Pi poline Workshop

58de 11






Promote teamwork within the working group

- Identify and capitalize on diverse skills and experience
- Maximize sharing of experience and questions
- Encourage participation to insure common understanding
- Here to learn NOT judge

S\$## 13






Ground Rules

- Participation of everyone is encouraged
- · Listen with understanding
- Stay with the Agenda
- · Honour the time limits
- One speaker at a time
- Don't dominate the discussion
- Show patience and respect

April 6-12, 2001


Skide 15








Environmental Impact of Impressed Current CP Groundbeds


- The significance of soil contamination caused by impressed current groundbed operation
- Possible ramifications to the corrosion control industry















































Review of Cathodic Protection Codes & Standards

Banff / 2001 Pipeline Workshop April 2001

R.A. Gummow, P.Eng.
CORRENG Consulting Service Inc.

CSA - Z662-94 Oil and Gas Pipeline Systems

Section 9.2 External Corrosion Control of Buried or Submerged Pipeline Systems

- Cathodic protection must be applied to new piping "as soon as practicable, but not later than one year after installation and shall be maintained during the useful life of the piping" [9.2.1.2]
- Cathodic protection "shall be provided and maintained on existing coated piping" [9.2.2]
- For existing bare piping where a corrosion investigation indicates "corrosion will create a hazard, corrosion control measures or other remedial action shall be undertaken" [9.2.3]
- "Cathodic protection shall be maintained on piping that is out of service but not abandoned" [9.2.4]

Section 9.2.10 Cathodic Protection Systems

 "Cathodic protection systems shall provide sufficient current to satisfy the selected critéria for cathodic protection"


("Note: Criteria are given in Appendix 'B' of CGA Recommended Practice OCC-1")

CGA-OCC-1-1996 – Recommended Practice for the Control of External Corrosion on Buried or Submerged Metallic Piping Systems – Canadian Gas Association

Section B.2.1 Criteria (Note this is an Appendix)

- A negative polarized potential ('instant-off') potential of at least 850mVcse.
- A negative polarized ('on') potential of at least 850mV accounting for the voltage drops listed in subsection B.3.
- A minimum of 100mV of cathodic polarization between the structure and a reference electrode contacting the electrolyte as measured by the formation or decay of polarization.

Note: Where steel piping systems are susceptible to stress corrosion cracking (SCC) caution is advised against selecting polarized potentials more electropositive than -770mVcse when using the 100mV polarization criteria.



Comparison of the Results from Stress Corrosion Tests (Continuous Lines)
with those from Polarization Curves at Fast and Slow Potential Sweep Rates
for Different Carbonate-bicarbonate Solutions, indicating the Extent to which the Experimentally Observed
Cracking Range can be Predicted from Electrochemical Measurements

Source: Parkins, R.N. and Fessler, R.R., "Line Pipe Stress Corrosion Cracking - Mechanisms & Remedies", NACE Corrosion '86, Paper No. 320.

NACE RP0169-96 – Recommended Practice Control of External Corrosion on Underground or Submerged Metallic Piping Systems

Criteria - Section 6

- A negative polarized potential of at least 850mV relative to a copper/copper sulfate reference electrode. [6.2.2.1.2]
- A negative (cathodic) potential of at least 850mV with the cathodic protection applied. This potential is measured with respect to a saturated copper/copper sulfate reference electrode contacting the electrolyte.
 Voltage drops other than those across the structure-to-electrolyte boundary must be considered for valid interpretation of this voltage measurement. [6.2.2.1.1]
- A minimum of 100mV of cathodic polarization between the structure and a stable reference electrode contacting the electrolyte. The formation or decay of polarization can be measured to satisfy this criterion. [6.2.2.1.3]

VOLTAGE IR DROP

OCC-1-1996

The following factors shall be accounted for when interpreting potential measurements for compliance to the criteria listed in Section B.2


- a) Voltage (IR) drop between the structure and the reference electrode
- b) IR drop in the pipe steel and the lead wire during close interval surveys
- c) the presence of dissimilar metals
- d) the influence of other structures
- e) the presence of stray and telluric currents

NACE RP0169-96


Consideration (for voltage drop) is understood to mean the application of sound engineering practice in determining the significance of voltage drops by methods such as:

- a) measuring or calculating the voltage drop(s);
- reviewing the historical performance of the cathodic protection system;
- evaluating the physical and electrical characteristics of the pipe and its environment, and;
- d) determining whether or not there is physical evidence of corrosion.






Typical Pipe-to-Soil Potential Measurment




Equipotential Lines and Cathodic Protection Current Paths Around a Bare Pipe


Source: Parker, Marshall, E., "Pipe Line Corrosion and Cathodic Protection. Publishing, Houston, TX, 1954, p. 16




Representation of Current Flow to a Holiday in a Coated Pipe



Cathodic Polarization at a Coating Holiday




Percentage of Soil Voltage Drop with Distance Away from a Holiday



IR Voltage Drop Relationship to Soil Resistivity and Area of Coating Holiday


Source: McCoy, John, "Cathodic Protection on the Dampier to Perth Pipeline Australia", MP, NACE, Feb. 1989.

PIPE IR DROP



Error in Pipe-to-Soil Potential Measurement Due to Current in Pipe

CABLE IR DROP



Error in Pipe-to-Soil Potential Measurement Due to Current in Bond Cables

OTHER CONSIDERATIONS

OCC-1-1996 Section B.2.5

- In the presence of sulfides, bacteria, elevated temperature, acid environment and dissimilar metals, the -850mVcse criteria may not be sufficiently electronegative.
- In some environments (concrete, dry or aerated high resistivity soil, etc.)
 values more electropositive than the -850mVcse criteria may be
 sufficient.

NACE RP0169-96

- In some situations, such as the presence of sulfides, bacteria, elevated temperature, acid environments, and dissimilar metals the criteria in Section 6.2.2.1 may not be sufficient. [6.2.2.2.2]
- When a pipeline is encased in concrete or buried in dry or aerated high resistivity soil, values less negative than the criteria in Section 6.2.2.1 may be sufficient [6.2.2.2.3]



German Standard DIN 30 676 Design and Application of Cathodic Protection of External Surfaces

		Free corrosion potential in the absence of cell formation (guideline value), in V	Protective Potential, in V _{CSE}	
Unalloyed	at temperatures below 40 °C	-0.65 to -0.40	-0.85	
and low-alloy ferrous materials	at temperatures higher than 60°C	-0.80 to0.50	-0.95	
	in anaerobic media	-0.80 to -0.65	-0.95	
	in sandy soils with resistivities greater than 500 Ωm	-0.50 to0.30	-0.75	

80-002 Wiring Methods for Direct Current Conductors

- (1) DC wiring in non-hazardous areas shall conform to the requirements of Section 12 of this Code except that wiring below ground shall be permitted to be:
 - (a) Buried at a depth of not less than 450 mm; or
 - (b) Buried at a depth of not less than 200 mm where installed in raceway or where mechanical protection is provided in accordance with Rule 12-012(3)
- (2) DC wiring in hazardous areas shall conform to the requirements of Section 18 and 20.
- (3) Notwithstanding Rule 20-004(8), underground dc wiring below a Class I area shall be permitted to be installed in accordance with Subrule (1) provided:
 - (a) The wiring is in threaded rigid metal conduit where it emerges from the ground; and
 - (b) The conduit is sealed where it emerges from the ground and at other locations as required by Rule 18-108 or 18-158.

80-004 Conductors

- (1) Conductors for dc cathodic protection wiring shall be not smaller than No. 12 AWG and shall be suitable for the conditions of use as indicated in Table 19 for the particular location where installed.
- (2) Notwithstanding Subrule (1), conductors smaller than No. 12 AWG shall be permitted to be used for instrumentation and reference electrode leads.

80-010 Operating Voltage

When a cathodic protection system has a maximum available voltage of more than 50 V, the voltage difference between any exposed point of the protected system and a point 1 m away on the earth's surface shall not exceed 10 V.


80-012 Warning Signs and Drawings


- (1) Tanks, pipes, or structures protected by a cathodic protection system shall bear a marking, either on the structure, or on a tag attached to the conductor close to the connection to the structure, warning that the connection is not to be disconnected unless the power source is turned off.
- (2) A notice shall be placed in a conspicuous location adjacent to the disconnecting means for any electrical apparatus that is connected to the cathodically protected structures advising that the cathodic protection must be turned off before equipment or piping is replaced or modified.
- (3) Notwithstanding Subrule (2), in a non-hazardous location the required sign shall be permitted to advise the use of a temporary conductor, sized for the maximum available current, to bypass the location where equipment or piping is to be replaced or modified, as an alternative to turning off the cathodic protection.
- (4) A drawing showing the location of underground wiring, polarity, and anodes shall be provided inside the rectifier cabinet or in a location near the cabinet.
- (5) When the immersed surfaces of a storage or process container are cathodically protected, a notice shall be placed in a conspicuous location adjacent to the entrance way advising that the cathodic protection system must be turned off before entering the container.

Table 53 – Minimum Cover Requirements for Direct Buried Conductors, Cables or Raceways

	Minimum Cover - Millimetres								
Wiring	Non-vehicu	ılar Areas	Vehicular Areas						
Method	750V or Less	Over 750V	750V or Less	Over 750V					
Conductors or cable not having a metal sheath or armour	600	750	900	1000					
Conductor or cables having a metal sheath or armour	450	750	600	100					
Raceway	450	750	600	1000					

Note: Minimum cover means the distance between the top surface of the conductor, cable or raceway and the finished grade.







How to Measure Corrosion Rates

- Single in-line inspection
- Multiple in-line inspection
- Failure and repair history of the pipeline
- From similar pipelines in similar environments (especially a parallel pipeline)

April 9-12, 2001

Banff 2001 Pipeline Warkshop



What do you do with corrosion rate information

- Locate sites where corrosion is active so that coating, interference, slope stability, or other issues can be addressed
- Predict future corrosion severity
- Assess the need for future inspections of the pipeline

April 9-12, 2001

Sent 2001 Pipoline Workshop





Matching the defects between inspections


- Matching defects between two inspection needs to account for all of the complications from corrosion growth and repair history of the pipeline.
- Other complications include: odometer slippage; orientation differences; limited ILI accuracy measurements of depth, length, and width.
- Changing resolution of ILI tools.
- Sheer number of defect can be large.


April 9-12, 200


Senf 201 Process Western



























Failure Pressure Analysis


- Calculation may be based on
 - B31G
 - modified B31G
- Iterative Effective Area calculation (like RStreng)
- Defect-interaction rules are used to make duster defects.
- All pressure calculations are a function of defect length and depth.
 - Accuracy of the measurements of length and depth affect accuracy of the failure pressure calculation


April 9-12, 2001


Senii 2001 Pipakra Warlahoj























Laser-Based Corrosion Mapping System for Pipelines

Richard Kania, RTD Quality Services Inc.



Beneff 2001

Data Collection

- Difficulty in providing accurate corrosion representation and measurements from the field to the head office.
- Circumstances of particular excavation.
 - Limited pressure reduction period, limited time to perform inspection
 - Corrosion at 6 o'clock difficult to map, for example.

Basel 2002

Inspection Challenges

- · Limited time available for inspection
- Pipes are not straight or round!
 Able to accurately map corrosion in the presence of welds and surface deformations (suck down, side and over bends, bulges).
- Accurate data required for assessment



Ban# 2001

kert 7655

LPIT Specification Highlights

- Software with built-in RSTRENG module for quick data assessment in the field.
- Depth measurement resolution: +/- 1.5% of Wall Thickness (80% of the time).
- Digital imaging and reporting.

Ban# 300


Testing and Evaluation


Comparison of LPIT, Pit Gage and Ultrasonic Pencil Probe mapping.

Test specimen:

 5 ft² of 20" Diameter pipe inspected by all three methods. Corrosion present in approximately 18% of mapped area.

Panel 30





Testing and Evaluation

Results

Setup, inspection, and assessment time combined.

 1. Laser
 1.2 hrs

 2. Pit Gauge
 3.1 hrs

 3. Pen Probe
 4.3 hrs

Testing and Evaluation

Conclusions following the tests:

- Inspection and data assessment time is substantially lower for laser system
- Confirming the deepest pits is difficult when using manual techniques – raises questions about data accuracy and quality. Need for accurate corrosion measurement techniques.

Barrel 2001

Applications

- Corrosion measurement and assessment during excavation projects
- ILI verification/correlation
- Corrosion growth modeling
- Assessment using FEA

Sunf 102

Managins, 'lipeline Integrity: External Corrosion April 10, 2001–10:30 a.m. - 3:00 p.m.

Cannizado I Pipelirio Worksho	Signature			7-1		Story Contract of the story of	W Carlo	<i>)</i>	J 8.	the second		W.	O AME	Odosh_	Com	11	JAN.	Shu (In
	E-mail	sacktu (Novachem. com	Ld hely trong by omices	Kingt & reverthemice	regredied collecters	itedacke novachem con	403-314-7491 galem@novachem.com		~	melboujd ONRan. gc. Ca	tanis. elmeusplein das mi	decilemon o by his abics	CSMITCHE TEMS PLANUT	dwosten @neb.gc.co	Lee, Greenya @ Postingraped	MANBOLE & O NO. ACHEM. COM	295-6060 Wenast @ Caller	To Cade Sion Lea
Phone	(403)	163/	531-7530	41/4		1000 453 1000 050-4706			612-947-3603	195-3971	$\overline{}$	276.7116	0	0000		103 550 0601 1/4 1/6 3 2 3 5 6 6 0 1	403-295-60F0 W	
Name	Tow JACK	74	Mich	A*	KEG EADE	ay Katherine Ikada-Cam	Plany Cole	4. 13 emoz	M - MANINGORD	TATIO FIN		CLIFF MICCHERA	Down WASLEN	13 (A. 13)	1.00 V. 3	Potol Kee	Stan Wong	
	1 NovA Chemicals	2 January	3 Wich Rosenal	4 HOUTH RESEMBAT	5 Nath Dress 1 s.T.	6 North Children Cameron	CANMET/1.100	8 CANON [7] MT	9 CAUMETIMIL	10	11 CENTRA GAS	12 CJ MITCHEL SASSE	13 NATIONAL ENERGY BOARD.	14 Postive fronds Ist.	15 NOVA ROCACH & TECH		17 CC Technologies	dessignation dessignation and the second

Banff/2001 Pipelir. Worksho

managing Pipeline integrity: External Corrosion April 10, 2001–10:30 a.m. - 3:00 p.m.

Ex falinit	1	100 CS	A. h. h.	SCN®	W.	Za	707		.ca			Die	0.8		May May May	" Williams
Baseline Technologies REx KALEWITH CAR 417-4300 MEXKD baselinetech com By folial	garys bosclinetechicom &	713 799 5180 Jansons@ Euboscupe um	403) 204-6163 garnorm @globalte.com	7	Circle Lukanink 403 2046174 Hukaninkon alubalteran	403 580-8316 Am. tan 0+ mulanda con	guy Emorsises scientific com	Mohammed Townes (403) 20,8-0134 Janash @ PTI - Comente us	. N	HEMPEL COATINGS JACQUES EBERLE (604) 273-3200 Sales. Car Ohembel. Com ()	(780) 457-4111 is cobsessed its sessed com	(780) 420 5383 OBD. DITHELP CAPT. ENTITEDGE. CEM	(780)4(20-8715 don. enven 6 C1101. enbuidge.com	INDERITY HSSENIEW TECATO BACCORI (403) 296-3298 HOLLANDEROUP, Com	403.258.233 Michigan @ Marr-asseciates. Com	Alex Petrusev 403-233-2001 apetruseve corrosionericeion
CNB-114 (BK)	780) 417 4312	0315 995 515	(403) 204-6163	1055-512-504	403 204 6174	403 580-8216	(403) 262.8160	(403)26,8,0634	(403) 262.7883	(604) 273-3200	(750) 457-4111	(38) 420 5383	(780/420-8715	(403) 296-3298	403.258.2233	403-333-2001
S REX KALEWITH	GARRY SOMMER (780) 417 4312	-b-in Parsons			Coul Lukanink	SIL [M]	1	Mohammed Joures	'	JACYVES EBERLE	BERNIE JACOBSON			Tecalo Baccari	MARK JOHNSON	Alex Petruser
Baseline Technologie	CASELINE TECHNOLIES	Tulsoscoff	Clobed the modernic Grand Mesterns	Alliance Pipeline	Globel Them.	Trans Capaler	Morrison Scientific	PLI	27 PROACTIVE TECH INC. JASPER	MEMPEL COATINGS.	HEMPER COATINGS	ENBEIDGE TRELIDES	ENBRIDGE PREMESING DON ENGEN	INTEGRITY HSSE MICHI SKOLD	MARE ASSOCIATES	Comosin Service Gong
8	6	9	21 (22	23	24	25	26	27	28	29	30	31	32	CC	34

Managin, ipeline Integrity: External Corrosion April 10, 2001–10:30 a.m. - 3:00 p.m.

o i pellio worksho		200	Sums 1	San Marie	400 M	7	John State of the	d'an M	**			G.	X	2-tha
	dioline the G Co. C.	Track 6 ms Com	(403) 299-3101 Indubris@neh.ac.ca	franks bo pii - canuda can	(281) 556-1000 Trenton Hous AOL. COM	THAMES@ SOLDMOISCURTUSES.COM	grant, firth e compruser	Christmak His oce. C.	JCHASE @ HMPSI	(3)	botto mailz rdc puc-no.n.	Maner@evi.net 11-pipe@swbe/1.net	Hogermanble DII-USA, com	+
	780-490-2550 die	403.298.3634 rro	(403) 299-31C1 Indu	7220-862 (50/1)	(281) 556-1000	(703)254645 THX				£ ,	55(21) 5400 xc3 botto	713-849-6346 111-0	403-262-8160 temamorrowscient, E.	406-498-3318 Chris
ļ		Kima Raad	2	BRIAN FRANKS	I rentan Corp.	Jamie Cox	Grant Firth	JOHN CHOS	CORRENG CONSULTING 905-509 7713	Wayne for	IVANI de S. FOUT			Chris Harthell
Christopi	THE STREET GROUP FOR	MMILLINAR ENERS BOARD	National Energy Band	Ton Webs	So-page Contract	Outout Courds Inc	REC OFF & Fr.		Bob Gummon &		PII North America Flacing	PIN CK+H AMERICA, INC BRUCE HAGERMAN	Hunter Mcdonnell Che Town Wollson	- Falline Sel M. Cer
35	¥.	Land Control of the C	**************************************	39	40	41	43	4		46	48	a verballage	00 5	O THE STATE OF THE

Managing Pipeline Integrity: External Corrosion April 10, 2001 10:30 a.m. - 3:00 p.m.

AMERICAN CONTRACTOR OF THE PROPERTY OF THE PRO	AND THE PROPERTY OF THE PROPER			Agenty in the second of the se	
52	Rimber Poeline	Barry Martans	780-449-5856	780-4445856 Barry martens @ cmul. mb/cm	10x
53	ENBRIDGE PIPELINES INC	A. 2. SI D. 8.	760. 4w 5267	780. 420 5267 Scott. 1 carside (d. cno), enbridge cen	Sept of the sept o
54	IMPERIAL OIL PIPELINES	KORNA HARRON	480-955-617	480-955-6177 Porna, harron @ 8550. Com.	
S S	C.C. Technologias	John Beavers	614 761 -1214	614 761-1214 Dayvers(8 Cc+1465, 10m	The San San
99	SIMMONS. BROWN INC	Don HERMAN	403 841 5308	S/mmons @ Codorising Com	A.
57	Sudge Edgesy Mackerick	ZE AND DENNIS	780 449 2108	EDENTE (2) CUNTOR. COM	Story
28		CYRIC KARJONEN	_	Curlo Karvanene Jillamsier	1
59	Alliance Poetin	Lorne Carlon	l .	Docat Sonta affaire - system in	in fraction
09	TransMountain Pipe Line	Kyla Loewen		Kylal (2 tmpl.ea	100
9	Trans Mountain	Shawn MeGregor.	250-371-4011	© may cythologic document control control makes and make	Diffen.
62				The state of the s	0/9
63	EN 27.16G6	BAS Sury	780.020.8607	bred. smith @ cnpl. enbridg.com	J. J
2	CANMET	Jenny Bren	613-992 4252	613-992-4252 Speen Erwcan, gc.ca	
65	GIREENPIPE	MEST HUMBY	403-30-62	403-360-622 nashava @ a mana 2010-2010	
99	En bridge		780 420.8684	780 420.8684 Shaw.dawe @ Capl. enbridge. con	R
<i>L</i> 9	William Pro 12-	3	801 584 1,911	801 584 6911 DAVEC 1/24P. WILL CO.	20
89	KOCH P/LS	Mac S. Hay	403) 716-7670	403) 716-7670 HAVINE KOCHIND. CON	Hell Stay

Managin, ./ipeline Integrity: External Corrosion April 10, 2001 10:30 a.m. - 3:00 p.m.


Carring Out of Pripelitic Worksho	7. 7. 7.		1		1	i	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1001	JUAN 1	More land	Cour 1	2 d		gens and	The state of the s	12 S		***	M	apy	
	Jiwong Dwei. ora	man 3 y		goyle Mart Can Scient Affector	RSmy THE PETROLINE		and will was on		is ther land @ biservices, ca	***************************************		15m1+h@ Surcandian.com	Carles. Parde @ capleahr.	Conter a transan ch .		whater los ca	Cother Ope mo . Con.	Acres, mazuraka ta	SAWYErta Cii-USI CON		gleun, yvenle dynamiorisk met
	604-691-5973	7261-125 201	· · · · · · · · · · · · · · · · · · ·	291879 190	63 27-8383	281.925.0280			403 531 -5300	Haus 780-468-3611	41x 489	128100 00	780-420 8434	(Sb)777-935 Z	510-888-4267	78724	403-232 8212	403 218-4676	7/3-840-6203		403 SM-18038
+	Jenniter Wong	Marie Britis	Costa (AT)	(heyes blum	The second secon	ーガンガン	o. i.i.	Cohous having	HAV SMITH			CURTS PARKER	DUANE (Rowin			Mazurak	ION SAWIER		Skin Yven
69 Westroast E	70 77	THEY SONSTERIOR IT	7 0077	72 PETROLINE	73 CKEN 1	74	1, 02, 1	75 BS Pipeline Secure	76 PIN D. 14 C.	77 Cin	SUM-CANADIAN PREUNE	78 Enbridge Pack	79 TRANK 45	51 mismin 08	المعهري رص	81 Mach An Volume	82 Tri Cran Eginenhallo	83 FT	With a state of the state of th		Systems, La.

Banff/2001 Pipelir. Worksho

Managing Pipeline Integrity: External Corrosion April 10, 2001 10:30 a.m. - 3:00 p.m.

				J. M. Sound of July	-
	BC GAS OTHER TO CHRIS BILLINGON		250-868-4586	The section of the se	
87	Gas Technology Institute	Harvey Haines	1680-891-668	harvey. haines & gastechalizyg. cry Tames from	द्य
88	SING DUPUIS	BASELINE TEHNOLOGIES	403 266 3406	bucced@baselinetech. an 18	
68	Kyle Keith	Foothills Pipe Lines	9hth 468 50t	Kyle. Keith@foothillspipe.com	
90	JERFIN STORTEY	WARR ASSECATES	+# +% 895 2755	+4+ 748952755 clstorapement-articipals	\mathbf{x}
16	Chris Jungan	BC Cas Utilly	250-868-4511	Cyngan & begas com	-(1)
92	BRUNO ORUCZEK	BCGAS	250-862-6525	BORLICZELD DEGAS COM LEL	2
93	Trew MacFarlank	Dynamic Rok	405,547.8638	trever-machinama dynamicisk, act or	5
94	Cowses CANNOW LANTE	Brue More	306 5'36.75'20	bruce I manie Ocean courses, car True Mond	lone
95	Jack Kap NEB		०६%- १११ (१५५)	jkopre @ neb. gc. ca	3
96					
16					***************************************
86					
66					
100					
II.AMILIMAII.	mm_mmmmm m, いかかわりい indigated a mmm-deadea-south-construction into the construction of the indicated to minimate the construction of the indicated to the indi				

2md 51 3rd 7





Environmental Impact of Impressed Current CP Groundbeds

- The significance of soil contamination caused by impressed current groundbed operation
- Possible ramifications to the corrosion control industry

April 9-12, 2001

Benff 2001 Promine Wastehau

Side 2



Environmental Impact of Impressed Current CP Groundbeds

- Very localized concentrations, slightly exceeding agricultural soil guidelines, have been observed within the groundbed only
- is not considered a significant problem
- Additional study should be performed
- · Improved discussion within the industry is recommended
- Need identified for consistent construction and abandonment approaches for anode beds in general

April 9-12, 2001

Banif 2001 Pipalina Workshop

Side 3



Environmental Impact of Impressed Current CP Groundbeds

ACTION ITEM for Banff 2003:

- Recommendations will be made to NACE International and CEPA to commission industry study of the issue
- Recommendation will be made to NACE international to review construction and abandonment practices for anode beds

April 9-12, 2001

Banif 2001 Pipaine Workshop

Side



Codes and Practices Relating to Cathodic Protection

- Regulations and non-regulatory guidelines
 - CSA Z662, OCC-1, NACE RP-0169, Canadian Electrical Code, CSA C.22.3 No. 6, NACE RP-0177
- · Differences in code interpretation and code intention.
- Accepted CP criteria and developments in monitoring technologies intended to satisfy protection criteria.
- · Differences in criteria interpretation and application
- · Problems with CP application

April #-12, 2001

Sanif 2001 Pipeline Wartehop

Silde S



Codes and Practices Relating to Cathodic Protection

- Only first part of agenda completed
- North American and German CP criteria were discussed
- NACE RP0169 is under review this year changes may be expected
- Prescriptive vs goal oriented regulations were discussed

April 6-12, 2001

Sanfi 2001 Pipaline Workstop

Side 6



Codes and Practices Relating to Cathodic Protection

ACTION ITEMS for 2003

- · Follow changes to codes highlight changes
- · Discuss AC interference
- · Discuss CP monitoring methods

April 9-12, 2001

Banf 2001 Pipaline Workshop

Side 7



Corrosion Growth Modelling

- · Growth modelling methods continue to be refined
- · Accuracy of this technique has been demonstrated
- Growth modelling based on a triplet of iLI data has shown accuracy approaching that of an ILI run

April 9-12, 2001

Banff 2001 Pipuline Workship

06-6- K



Corrosion Growth Modelling

ACTION ITEMS for Banff 2003:

- · Continue with technology updates
- Report on any developments in soils models for predicting external corrosion
- · Report on efforts to correlate with other GIS data sets
 - ie. Compare iLl and growth data to aboveground CP data

April 9-12, 2001

Sanif 2001 Physine Workshop

Sáde 9



Corrosion Field Measurement

- Recent developments in external corrosion mapping techniques
 - ease of application
 - accuracy
 - correlation to ILI data

April 9-12, 2001

Banff 2001 Pipeine Workshop

Siide 10



Corrosion Field Measurement

- Laser mapping is a fast and accurate method to assess external corrosion damage
- Provides superior visualization of corrosion features
- · Can reduce overall excavation and downtime costs
- · Especially suited to large corrosion features

April 9-12, 2001

Earl 2001 Barrier Washing

8166 11




Corrosion Field Measurement

- ACTION ITEMS for Banff 2003
 - Technology update

April 6-12, 200

Banif 2001 Pipalina Workshop

38de 12



Workshop 11 - Offshore & Arctic Pipelines: Challenges & Needs

Tuesday, April 10, 2001, at 10:30 a.m.

Chair

John Greenslade, Colt Engineering Corporation

Co-Chair Allan Murray Principia Consulting

Opening remarks by John Greenslade indicated that the workshop, and the associated presentations, were to stimulate audience participation with issues specific to northern and offshore pipelines. Further, it was pointed out that the workshop was to be a forum for information exchange and education.

John Greenslade, Colt Engineering Corporation then made a presentation entitled Offshore & Arctic Pipelines: Challenges & Needs

- This presentation reviewed issues of strain based design, slope stability, uplift buckling, etc. to stimulate conversation
- Q: John Greenslade asked what were the effects of leaving a pipeline on grade as was done in many parts of the world.
- A: Jim Oswald suggested that the primary reason for burial of pipelines was to prevent/minimize mechanical damage from external forces.
- Q: Larry Dyck indicated that a Geological Survey bulletin existed regarding frost settlement and how much did the large ice content in backfill materials contribute to slope instability
- A: Keith Leewis said that slope stability could be monitored with satellite surveys.
- A: Allan Murray indicated that any movement vertically or laterally could be identified by satellite but longitudinal movement of the pipeline would not be detected.

Jim Oswald, AMEC Earth & Environment made a presentation entitled Environmental Challenges of Arctic Gas Pipelines

- Information presented indicated that the pipeline and right-of-way above the pipeline had subsided to varying degrees over the pipeline operating life and the active zone above the permafrost had increased.
 - the loss of tree cover on the Norman Wells pipeline ROW was believed to have contributed to thawing as solar radiation more readily reached the ground surface.
 - the operating temperature of the pipeline contributed to ground thawing.
- Varying degrees of ditch subsidence existed with different construction techniques
- Q: Jasper Price asked when the chilled state of the pipeline ended.
- A: Jim Oswald responded that the pipeline was initially required to be chilled to -1°C at the Norman Wells discharge. After several years of operation, the requirement was changed to permit the average temperature at Norman Wells to be -1°C. This meant that the pipeline discharge temperature at Norman Wells may be as high as -10°C in the summer or as low as -4°C in winter as long as the average temperature remained at -1°C.

- Q: John Greenslade asked if there was any change in the permafrost depth related to the pipeline temperature variations.
- A: Jim Oswald indicated that no studies had been done to address this issue.
- Q: John Greenslade asked if there was any other effect to the right-of-way or pipeline related to the pipeline temperature variations.
- A: Derick Nixon replied that the pipeline at KP2 moved up to 20 cm each season with no detrimental effects indicated for the pipeline.
- Q: John Greenslade asked if ditch subsidence in Alaska or elsewhere was an acceptable situation.
- A: Dennis Hinnah responded that ditch subsidence in Alaska was aesthetically unacceptable in the last frontier.
- A: Derick Nixon replied that with gas pipelines any significant ditch subsidence may allow uplift buckling of the pipe.
 - Rick Doblanko advised that uplift had occurred on the Norman Wells pipeline with the cause being temperature variation and not necessarily ditch subsidence. After the integrity of the pipeline was confirmed, the pipe was bermed to ensure protection from the public.
- Q: Rick Doblanko asked if anyone had solutions to minimize ΔT on similar pipelines other than his experience of pumping hot air through the pipeline during the backfilling procedure.
- A: John Greenslade advised that in some instances operators used double walled pipe with hot water pumped through the annulus to minimize ΔT .
- Q: Dave Webster asked if the wood chips used as partial backfill at some slope locations prevented subsidence because of the insulation properties or because the wood chips replaced backfill having high ice content and further whether wood chip rotting was a concern.
- A: Jim Oswald indicated that the lack of ice content in the wood chips was the primary reason that ditch subsidence didn't occur. In addition, wood chips had the ability to bridge voids in the backfill that occurred over time. A mixture of hardwood and softwood chips were used and fungicidal decay of the hardwood chips had been an identified problem. This was being dealt with through various handling techniques.

Jack Clark, C-CORE, made a presentation entitled Offshore Pipeline Design for Ice Scoured Environments

• The presentation included information on pressure ridge and iceberg scour as well as strudel scour and then dealt briefly with the use of double walled pipe in offshore installations.

- Q: John Greenslade asked if there was any specific water depth where strudel scour effects could be ignored as a pipeline design issue.
- A: Dennis Hinnah indicated that his experience showed that at water depths of 15 to 20 feet (~5 to 6 metres) the problem could be ignored.
- A: Jack Clark responded that if a pipeline was designed to avoid ice scour affects, strudel scour could then be ignored.
- Q: Jenny Been asked for information on corrosion/corrosion control issues relating to double walled and offshore pipelines.
- A: Dave Webster advised that the external corrosion control techniques used for the outer pipe of a double wall installation and for a conventional single wall pipeline were identical and provided no specific concerns as long as the current density requirements of a particular location were addressed. In the case of a double walled installation, maintaining the integrity of the pipe surfaces in the annular space was of primary concern and this was usually accomplished by displacing the annulus to an inert gas and sealing the annular space to prevent the ingress of water and air.
- Q: John Greenslade asked if the use of double walled pipe had any benefit in ice scour locations.
- A: Jack Clark indicated that the robust nature of the external pipe was probably a benefit from the point of view of impact damage.
- Q: Ian Scott asked what research was underway or need to be done.
- A: Jack Clark indicated that more research was required to:
 - determine the strength of the ice in pressure ridge scour situations
 - to assess the structural response of different pipe grades to scour damage
 - to determine the minimum safe depth of burial for a pipeline in a scour zone
 - to determine the affect of harmonizing US and Canada codes with respect to strain based design for offshore pipelines
- Q: Slade van Rooyen asked if heavy wall pipe would be necessary for arctic construction or only for pressure containment.
- A: John Greenslade responded that hydraulics and bending stresses usually dictated the need for heavy wall pipe in a pipeline design, regardless of location.

Environmental Challenges of Arctic Gas Pipelines

Jim Oswell AMEC Earth & Environmental Thanks to Enbridge Pipelines (NW) Inc. for permission to use design and performance data.

Issues

- Right-of-Way-Temperatures
- Thaw Settlement
- Slope Performance
- Right-of-Way Drainage and Erosion


Right-of-Way Temperatures


- Significant warming of ground temperatures in early years after construction (some impact due to global warming).
- Pump station influence on line temperatures decrease with distance.
 In case of Enbridge Pipelines (NW) Inc pipeline, effect is negligible after about 50 km.


Thaw Settlement

- Design Thaw Settlement
 - 0.8 m in mineral soils for northern region
 - 0.7 to 0.75 m in mineral soils for southern region
 - 1.2 m in high organic soils

Site	Thaw Depth (m) 1996	ROW Settlement (m)	Thaw Strain (%)	Pipe Settlement (m)	Thaw Strain (%)
1	2.75	0.6	21.8	0.35	20
2A	4.5	0.2	4.4	0.00	20
28	0.75	0.15	20	***	
2C	4.5	0.1	2.2		
ЗА	2.25	0.3	13.3	j	
7A	4	0.2	21.3	0.2	0.67
78	5.5	0.5	16.4		0.07
7C	4.25	0.3	7.1	٥	0
128	4.5	1.2	26.7	1.1	
58	3.25	0.5	15.4	0.5	31.4 22.2
6	5.5	0.8	14.5	0.6	12.2
		Average Strain	15%	Average Strain	14 %








Thaw Performance - Slopes


Frozen and unfrozen slopes

- Approx. 150 slopes
- 37 % have no mitigation measures
- 33 % have select backfill
- 16 % slopes were cut-back
- 46 % insulated
- 8% cut-back and insulated

Thaw Performance - Slopes


- Insulation used was woodchips (gravel was considered but not used).
- Purpose was to retard the rate of thawing.








Physical ROW Condition	1986	1988
No Significant Features	64%	78%
Ditch line Subsidence	29%	15%
Ditch line Subsidence under Woodchip Slopes	0%	1%
Standing Water	1%	2%














Performance Records


- > Performance records for offshore pipelines in the Gulf of Mexico are comparable to overland pipelines - failure rate is in the range of 1×10^{-3} to
- > The factors contributing to failures are different than on land system - third party interventions are lower but still significant. They include, vessels, anchors, fishing trawls, dropped objects








Performance Records (cont'd)


- Failure rates include pipelines built many years ago to less rigorous standards than exist today
 - > corrosion can be significantly reduced if not eliminated by present day coatings
 - > materials are much improved no spiral welds
 - construction techniques improved
 - design requirements set out in codes of practice are much more rigorous today than a decade ago
 - * CSA Z662-99 Oil & Gas Onshore and Offshore
 - API RP1111 1999 Offishore Hydrocarbon Liquids & Gases
 - * DNV 1996 Offshore Liquid & Gas
 - * 85 8010 Liquid & Gaz
 - ASME B31-4 1992 Gas Liquids Hydrocarbon
 - * ASMI 231-8 1995 Gas
 - * US DOT Part 195 Hazardous Liquids













































































































Major Issues

- > Harmonization of Design Codes
 - >Strain based design
 - > Definition of allowable strain limits
- > Definition of Failure
 - >Functional Defect pipeline can be operated and inspected by pigging. Repairs can be scheduled - e.g. pop up, wrinkle
 - > Functional Failure pipeline can continue to operate but cannot be pigged. Some flexibility in repair scheduling - e.g. landslide.
 - >Containment Failure loss of product. Pipeline is shut in immediately.



A containment failure is defined as pipeline system damage with loss of product containment integrity, that is product loss to the external environment




A functional failure is defined as pipeline system damage without loss of product

containment integrity to the environment. (A functional defect, as shown

here, is one where the pipe has been damaged but where all operations including inspection can carry on as before.

A functional failure is one where there is no product loss but the configuration will not allow all operations such as pigging or full operational pressure.)



Banff 2001 Pipeline Workshop Working Group 11

ARCTIC AND OFFSHORE PIPELINES


O TECHNICAL CHALLENGES

@ENV IRONMENTAL CHALLENGES

OARCTIC OFFSHORE PIPELINES

Werking Group 11 Arctic and Offshore Plactimes

Bantf 2001 Pipeline Workshop



Technical Challenges

Establishing:

- Strain Limit
- ♦ Steel Grade
- Girth Weld Flaw Acceptance Criteria

for Pipelines Buried in Permafrost

Working Group 11 Arcse and Officiare Pipelines

Benff 2001

Technical Challenges
Pipelines in Permafrost

- ♦ Strain Based
- Limit States Design

Working Group 11 Arctic and Offichero Pipelines

Sant 2001

Technical Challenges


Pipelines in Permafrost


Design


Permaneae


Design


Determine
Lands























Banff/2001 Pipelir workshop

No Noon Moner (780) 420-8428 garrett. Wilkie @ capl. entridge, com Manut - Jiter がなみ Signature 707 (Acis) 900 (5504 | reena-sahney etanscarabla com 3 Wine. Berezowski @ Amec. Com BOUGHER, DARIUS @ COLTENGIOM 782 4255326 rick doblant Capitenbridger 907346-1633 Dennis. Hinnaha umsgov (408) 920 6035 | biring rothwill transcarredge tou PETEL-H. MARRECU @ COM. HOBIL OF FCbridge Calgaly. Know. com deallene ad visionism (Carple enbrigge. 5+ 4500 encangaca dan. powell@ compro.ea Im. Oswell @ amec. com Carey johannessen @ Cwpl. 63 992-7924 Cipingne () Masing 30, ex Sattle Capp. ca Ohniskaliki E-mail (403)231-5984 Managins, dipeline Integrity: Offshore & Arctic Pipelines: Challedges & Needs April 10, 2001–10:30 a.m. - 3:00 p.m. JOHN SKALSKI 280 "40 5362 403 235-8135 403-247-0200 613-772-7523 1870-922-804 (403) 259-1889 7611-172 (804) (403) 235-6400 (403) 260.779 E 403 235 8113 Phone EMBRIDGE VIPELIDES CARDINESSES FRED CLARINE DARIUS BOUCHER Berezowsk EXXOLHORIC CAHALLA Minerals Management Some Deunis Hinnah Sect PICK DOG 4 10 Wempershers Garrett Wilkie Brian Kothwell B.11 Tyson AMEC Earth & Environment I'm Oswell Powell Deide Mais Han N. Ke NIC PL Name Dan Komex MERMITIONA NRCOM - CANNET Niner Geotor (H) SINDEN A NRCAN-COMMET PETER H. MARREDL Corres Coule Exibridge COLT ENC'S THE STATE Enbridge AMEC Company CAPP 1705T FEENA N 9 ------é 4 2 5 9 13 4 9[00 15 6

Managing Pipeline Integrity: Offshore & Arctic Pipelines: Challenges & Needs April 10, 2001 10:30 a.m. - 3:00 p.m.

205EN - 1/2 1150	BOWR Rown	181.95.0380	Lh	1
Howard 110 1111 1		2000 10 10 11	Literature las musician (
1400	Summer William May	102100	huallace Deeluxun com	Market
INDY OMACUAN		(43)202-054B	403/202-0548 CSMALMAN @HOME, COM	7
BRIAN FUNG	SHEU	641-4289	P.R. AM. FING GUS. 11	787
терен бининайта рафизикалана, у предассева	JOEL Thou	The state of the s	Je B. Alsonellins acold of	1000
Translanada	Catherine Arream	403-920-6575	Catherine - pineau (Otran Scandla. com)	[K ma. al
Pacefee Northern Gar	John Crasg	664-691-5857	j Crat g @ Wei. 6vq	14 00.
	TES HAMRE	780 490 2432	Thanse cange com.	
J. D. HAIR'S ASSOC.	JOHN HAIR	418 7479945	Shain @Jdhain.com	JO C
And property commands and appropriate to appropriate the second s	Lin Zhav	281-877-6116	LZHAO@EAGLE,ORG	101/105
y ke	Nut. Losouca Con.	613 996 1967	Byke Chreangena	Jun 120.
Aliance Prehis	LORNE CARLSON	403.517-6303	leaden @ affaire - Dishie Com	the College
& Brand	National Every Brail France Jeglic	403-284 2774	fjeglic anchoc.co.	
John Cattry	Gult Conada		John - coffrex @gult.co	Chr. 10h
Doel Billette	NR Can.	(613)992-3738	(613)9923738 NBILLETTO NREADIGCEA	R.M. A.
ath Caris	lits tearnoway.	SRJ-85-08%	849/768-0890 Katto Lewis @ lix kenned, old	
KOBERT LAZOR	FLEET TECHNOLOGY	730-465-0077	780-465-0077 rlazor@fleetech.com	Car

Managin___ipeline Integrity: Offshore & Arctic Pipelines: Cha.__.ges & Needs April 10, 2001–10:30 a.m. - 3:00 p.m.

Stund Know Winier Justande Tal. taysmild 15 columnes com Jack : clark (orc. cone, co bruce grow transcauada.com ptiil prouture.in atagona Clampiza.com].mitchellocampipe.ab Vantoos (a) campire. com Shaun. dawe a cnpl. enboidge.co 613-992-4252 Sbeen Swean.gc.ca (403) 263-4848 mayacode@cadvistalo.com debe housinon [] Pick@Unaterloo.ca National Enrigh Board 403-209-3652 | MSuntander@ndo-ge.ca melboujd andrango.ca mhad neb.go.ca mys of moscorr com 110E(1012 CENSON 1905 (403) 241-1680 704 7378350 PREZIVE & SERVICES 780-913-477 403-213-8854 519-888-6567 IASSER Park ROACTIVE TEH 403 UD 7885 National Energy Exard (403) 2999-2762 780 672-SIII 78 67-3116 (402) 531 1923 403.9w.6088 780 tro. 8684 CANNET (MIL - Othawa (613) 995-3771 UNIV. OF WATERIED CAMROSE PRE 10 Hoossor Eng Ltd. Myles Portym MAYA DATABASE INC dail Clark C-CORE CAMBOE/RE (O. ACCE. The Acces gall d hum しよりとのこ Enbridge SLADE VAN KOOYEN DEPOSITE SIENENS Jim MITCHEL Monica Santander EAV SMITH Wimown Elberidain; RICK CITCHESTERN BRUNO KOMERO ACK HERBANIS Sees Dawe Bruce Gray Minh Ho Jeruny 1 Ray Pier Shaun 36 35 37 38 39 40 46 4 42 44 43 \$ 47 48 49 20 S

Managing Pipeline Integrity: Offshore & Arctic Pipelines: Challenges & Needs April 10, 2001 10:30 a.m. - 3:00 p.m.

		d	Y	h													
	10.br Kith	ingress Ch	" Mer Mund														And the second s
in alman @ prom. ac	boff Omail. Ide for - no. br	reamy 403 259- 1857 graenslade, john @ CHENYLOW	Me-movey ahome com	usebster.david Ocalleng.com													A THE TAXABLE PROPERTY OF THE
613. 995.8249	55 (15) Syboot 05	40 259-854	403-212.5637	25-88 852 5ep									a management of the state of th				
CANHET-MTL	lative conventy	Calt Frenen	Minaypan 0 0	Coll Enqueering													
Jenny Jackman		Tolyn Greensland Cott Ins.	alor Mung	Dave ule leter		and the state of t											
52	53	54	55	95	57	58	65	99	19	62	69	2	65	99	<i>L</i> 9	89	

Offshore and Arctic Pipelines

Offshore & Arctic Pipelines: Challenges & Needs - John Greenslade

- . Strain Limit
- Steel Grade
- . Girth Weld Flaw Acceptance Criteria
- · Limit States Design

Worting Gibup 11 Offstore & Actic Pauli

Environmental Challenges of Arctic Gas Pipelines - Jim Oswald

- Permafrost
- ROW
- Slope stability
- · Pipeline integrity

Wanting Group 11 Offeren & Assis Plantings

Offshore Pipeline Design for Ice Scoured Environments - Jack Clark

- Pressure ridge scour
- Iceberg scour
- Strudel scour
- · Double walled pipe

Working Group 11 Offerent & Auto: Pages

Conclusions

- Construction issues in permafrost
 - Backfili subsidence
 - Affect on permafrost and ROW vegetation
- Harmonization of US/Canada offshore design codes
- Burial depth for an offshore pipeline in a scour zone
- Design issues
 - strain based design, slope stability, uplift buckling

Working Group 11 Otherone & Ancie Plandings

aging Pipeline Integrity: A WALLINE WORKSHOP	April 9 - 12, 2001
Managi	

Confession (The Company)	AND THE PROPERTY OF THE PROPER			rrow/St.	Phone	- 6x	E-Mail
Bert	Johnson	4. Vonting	10.00				
	Zhao	William William Alt Improduction of Journal of Comment Assessment Comment Assessment Comment C	Calgary	AD	And any control of the control of th		
Chris	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN THE PERSON NAMED IN COLUMN TWO IS NAMED IN THE PERSON NAMED IN	ABS Group Inc.	Months and an artist and an artist and artist artist artist and artist arti	2	403 686-8412	403 995-2014	and Andrews and the control of the c
	HOTKOFF	AEC OIL & Gas	Diego,	<u>×</u>	281-877-6116		man@ensplanet.net
100 mg 11 0 man 1 mg 1 m	Charlesworth	AFIR	Medicine Hat	AB	403 500 0000	281-877-6111	izhao@eagle.com
Brad	Anderson	A Tentral september 1 and 1 an	Red Deer	AB	7055-705-504	200 - 200 -	sherrygould@aec.ca
Bernie	The state of the s	And the Chamber of Resources	Edmonton	AD	403 340-5429	403 340-5136	101. Charlesworth @
Chris	Grant	Alberta Energy and Utilities Board	Drayton Vallay	Ye Ye	780 420-1030	780 425-4623	acr@telusnjanat not
Dave	Graft	Alberta Energy and Utilities Board	Calgary	9	780 542-5182	780 542-2540	Dernie francesconomic and a seconomic and a se
When the Parties of t	TAYA	Alberta Energy and Utilities Board	Calcar	AB	403-297-6687		chie
Administration of Statement Williams	Leonard	Alberta Energy and Utilities Board	A TO A DAY	AB	403 297-8432	403 297 3820	an explaint@gov.ab.ca
- Annual Volume of the second	Ullay	Alberta Energy and Illiting.	of, Albert	AB	780 460-3806	720	dave.grzyb@gov.ab.ca
oue C.	Lee	Aberts From	Calgary	AB	403 207 000	1 00 400-3802	earlleonard@gov.ab.ca
	Posta	Alberta E.	Calgary		400 000	403 297-8398	Jim.dilay@eub.gov.ab.ca
Sharon	Rubuliak	A Carrier By and Utilities Board	Calgary		1987-787 con	403 297-3520	Shu lee Cook at an
Ronald	And the state of t	Alberta Research Council	To de not a second		403 297-8148	403 297.3520	B) (B. 103
***************************************	Pyette	All West X-Ray Ltd.	camonton	AB	780 450-5384	780 436 4337	lom.pesta@gov.ab.ca
***************************************	Bhatla	Allance Pipalina Imito	Books	AB	403-734-3775		Sharonr@arc.ab.ca
ļ	Wendland	A STATE OF THE PROPERTY OF THE	Calgary	AB	402 547 770-	403-362-4138	rpyette@telusplanet.net
		Australia Cimited	Grande Prairie		17/1-/100	403 266-4237	art, bhata@allance.inetin
Windleson Williams	A COLUMN TO A COLU	America Pipeline Limited	Calgar		780 518-7622	780 402-3134	Wendlad@alliano
A	3	Alliance Pipeline Limited	Edon On-1-1		403 517-6303	A STATE OF THE PARTY OF THE PAR	tod
- The state of the		Alliance Pipeline Limited	Luch Frame	N N	952 983-1008	052 044 0400	rcanson@allance-pipeline.com
	, dohnston	Allance Pipalipo I imit. 1	Calgary	AB	403 517-7740	9915-4-6700	guistar@alliance-pipeline.com
Leonard	Lozowy	Alacas Infilia	Calgary	AB	403 547 7764	403 263-4491	rob.power@alliance-pipeline com
	Oswell	The state of the s	Leduc		1027-11-00	403 266-4472	terni, johnston@alliance-ninelina
A		ance Earth & Environmental Ltd.	Calgary		/ ou 980-7313	780 986-0919	HOWOWO AGE COM
And the supplemental state of the supplement		AMEC Earth & Environmental Ltd.	Column		403 235-8113	403 248-2188	Hio. magain.
)vern	Anderson Exploration I td	Cargary	AB 40	403 235-8135	403 240 2400	Juli.oswell@amec.com
	MIdd	APPI / Agra Pipolino b. f	Calgary	AB 40	403 232-7018	0017-047 001	mike.berezowski@amec.com
A COMMAND IN COMMAND OF THE PARTY OF THE PAR	Janz	ATCO Pinaling	Houston	TX	713 562 2202	And the second s	mcgovec@axl.ca
	Sokol	The state of the s	Edmonton		70.707 N	281 920-0186	Pgnidd@attobal net
	And the state of t	C Pipalines	Edmonton		780 420-7536	780 420-7411	attiduz@atconing
A Company of the control of the cont	The state of the s	Daker Atlas	Rod Door		780 420-7581	780 420-7411	HO) salmadido.
The second second second second second		Baker Hughes	JAAC PAUL	AB 40:	403 350-1770	403 346 6000	peri.soxol@atcopipelines.com
	A CONTRACTOR OF THE PERSON OF	hnologies inc	Calgary	AB 403	403-537-3400	403 050 1220	thetu@telusplanet.net
VIII AND VII	Dupuis Ba		Calgary	AB 403	403 266-3800		tim.hetu@bakeratlas.com
	Sommer		Calgary	AB 403	403-266-3800		bruced@baselinetech.com
			Sherwood Dark		100 miles (100 miles of 100 mil	403-762-9154	Driver Man Land Contract Contr

BANFF 2001 PIPELINE WORKSHOP Managing Pipeline Integrity: A Workshop for Sharing Technology and Experience April 9 - 12, 2001

	Sumame	corporation	Ž		Phone	Ž.	
OSS AUTHERN ESSENN NO AMERICA PRE	ACTION OF THE PROPERTY OF THE	And the second s					
Ken	Clark	Baseline Technologies inc.	Calgary	AB	403-266-3800	403-265-9145	kenc@baselinetech.com
Rex	Kalenith	Baseline Technologies inc.	Edmonton	AB	Property and the second	THE COLUMN ASSESSMENT OF THE COLUMN ASSESSMENT ASSESSME	
J. Bruce	Nestleroth	Battelle	Columbus	НО	614 424-3181	614 424-3725	nestlero@battelle.org
Ваглу	Anderson	BC Gas Utility Ltd.	Kelowna	BC	250 868-4572	250 763-8912	bwanderson@bccas com
Bruno	Orliczek	BC Gas Utility Ltd.	Kelowna	80	250 868-4568	250 763-8912	beliezek Abrase com
Chris	Billinton	BC Gas Unity Ltd.	Kelowna	BC	250 868-4586	250 763-8912	chilinton@hcrae.com
Chris	Jungen	BC Gas Utility Ltd.	Kelowna	BC	250 868-4574	250 763-8912	Chinas Chesas can
Fred	Baines	BC Gas Utility Ltd.	Surrey	80	504-576-7806	604-576-7-105	ANNA SALINA AMERIKAN
Norm	Trusler	BC Gas Utility Ltd.	Surrey	BC	604 576-7004	250 576-7105	ntrusler@bcoas.com
Chris	Hallam	BJ Pipeline Inspection Services	Calgary	AB	403 531-5171	403 236-8740	challam@biservices ca
Dave	Hektner	BJ Pipeline Inspection Services	Calgary	AB	403 531-7530	403 236-8740	dhektner@bisevices.ca
Joff	Sutherland	BJ Pipeline Inspection Services	Calgary	AB	403 531-5300	403 236-8940	sutherland@biservices.ca
Peter	Chan	BJ Pipeline Inspection Services	Calgary	AB	403 531-2520	403 236-8740	pchan@biservices.ca
Rafeol	Mora	BJ Pipeline Inspection Services	Calgary	AB	403 531-5332	403 236-8740	mora@biservices.ca
Kaith	Cartmell	BP Canada	Calgary	AB	403 233-6324	403 233-6318	carmewk@bp.com
Raymond	Price	BP Canada Energy Company	Calgary	AB	403 233-6351	403 233-6318	pricere@bp.com
Robert	Longpre	BP Canada Energy Company	Calgary	AB	403 233-1230	403 233-6318	longprri@bp.com
Vince	Kittleson	BP Canada Energy Company	Calgary	AB	403 233-6359	403 233-6318	kittelvw@bp.com
Patrick	Teevens	Broadsword Corrosion Engineering Ltd.	Calgary	AB	403-202-2060	403-247-8805	Dieevens@telusplanet.net
Alex	Afaganis	Camrose Pipe Company	Camrose	AB	780 672-3116	780 679-0690	afagana@campipe.com
Jim	Mitchell	Camrose Pipe Company	Calgary	AB	403 213-8855	403 264-1216	michel@campine ab ca
Stade	van Rooyen	Camrose Pipe Company	Camrose	AB	780-672-3116 ex. 436	780-672-3116 ex.669	Vanroos@csmploe.com
ue	Scott	Canadian Association of Petroleum Prod Calgary	Calgary	AB	403 267-1132	403 266-3214	scott@capa ca
Jake	Abes	Canadian Energy Pipeline Association	Calgary	AB	403 221-8779	403 221-8760	iabes@cena.com
Robert	=	Canadian Energy Pipeline Association	Calgary	AB	403 221-8778	403 221-8760	bhil@cena com
Allan	Hobbins	Canadian Hunter Exploration Ltd.	Grande Prairie	AB	780 539-3007	780 532-3569	alfan hobbins@chel com
Aldo	O Flumeri	Canadian Natural Resources Ltd.	Calgary	AB	403 517-7276	403 517-7366	aldod@cn1 com
Chrstine	Savary	Canadian Natural Resources Ltd.	Calgary	AB	403 517-6713	403 517-7362	christs@cmf.com
Cody	Klatt	Canadian Natural Resources Ltd.	Calgary	AB	403 517-6712	403 517-7362	codyk@cnf.com
Dale	Vickery	Canadian Natural Resources Ltd.	Calgary	AB	403 517-7152	403 517-7362	date: Och com
Ronald	Schlachter	Canadian Natural Resources Ltd.	Calgary	АВ	403 517-6714	403 517-7362	rens@cnd.com
Jenny	Jackman			***************************************			

nce	a wa	
/ and Experie	Fax	HPVMINANTONY (ILIDAY MARKET)
SHOP g Technology	Phone	613 ago Apen
NE WORK p for Sharin	Prov/St. Phone	AND NO
BANFF 2001 PIPELINE WORKSHOP ne Integrity: A Workshop for Sharing Techn. April 9 - 12, 2001	City	Ottawa
Managing Pipeline Integrity: A Workshop for Sharing Technology and Experience April 9 - 12, 2001	Corporation	nolgy Lab.
Mana	C	Canmet Materials Techor

Jenny Been Mimoun Elboujdaini R. Winston Revie Sankara Papavinasam Alebachew Demoz Brain Paradis David Jolivette Ted Hamre	Canmet Materials Techonolgy [ab		104131,	Phone	Fax	E-Mail
n tion a a	Canmet Materials Techonology Lab					
tton tton	Canmet Materials Techonolgy Lab	The state of the s				
tton a a		CARGO CONTRACTOR OF THE PARTY O	Table and Application of the Parket of the P			
a a new	Cash Bat Later Late	Offawa	NO	612 000 4050	THE RESERVE THE PARTY OF THE PA	NV memory and property of the contract of the
16W	Carrier and the control of the control of the carrier and the	Offawa	Š	**************************************	613 992-8735	been@nrcan.ac.ca
Jew	Carmet Materials Techonolgy Lab.	Ottown	5	613 995-3971	613 992-8735	To the second se
Mar.	Canmot Materials Tack		<u>~</u>	613 992-1703		melbodja@nrcan.gc.ca
And the second of the second o	Carried Actionolgy Lab	Ottawa	NO	240 042	013 892-8735	wrevie@nrcan.gc.ca
And the second of the second o	Cannel Mestern Research Centra	Devon	0.4	2092-750	613 992-8735	spapavin@nrcan or re
And the second s	Calispec Group Inc.	Edmont	9	780 987-8607	780 987-8676	The state of the s
	Canspac Groun Inc		AB	780 490-2445	700 400	we (Concession)
	Carson Commencer	Edmonton	AB	780 400 pres	1 00 490-2426	bparadis@canspec.com
Ţ		Edmonton	AB	780 400 040	780 490-2426	djolivette@canspec.com
Sousa Bott	and any sign of Shaw Industries	Calgary	A D	7547-054 00 :	780 440-1167	tame (Deans of the Constant of
1	Catholic University of Rio De Janeiro	Die De i	9	403 218-8207	403 264-3649	
CORVEYS	CC Technologies		Brazil	55 21 5299589	55 24 540 0700	
Vieth	CC Technologies	nann	퓽	614 761-1244	COLOND	bott@mail2.rdc.puc-rio.br
Delanty	The state of the s	Dublin	В	***********	614 761-1633	Jbeavers@ccitabs com
Wallan	CC Technologies Canada Lid.	Calgary	5 :	014 /61-1214	614 761-1633	Dvieth@critate
hammer of the state of the stat	Centra Gas BC Inc.	Nancier	AB.	403 250-9041	403 250-9141	The state of the s
	Centra Gas Manitoba Inc	Olitera	90	250 751-8319	DEC VEL COLL	accourse@lelusplanet.net
Rombouts	C-FER Technologi	Winnipeg	MN	204 480 6570	430 (31-6330	dwallace@centrabc.wel.org
Al-Bomo		Edmonton	VD	V2	204 480-5599	dacoleman@hydro mh ca
Market Ma	Citation Coating Services Ltd.	Calgary	2	/80 450-8989x202	450-3700	n tombourte & f
TO THE WAR THE PROPERTY OF THE	Charter Coating Services Ltd.		AB	403-250-3027	403-250-1254	Clerification (Com
BOLDS WITH THE PARTY OF THE PAR	Charter Costing Services 11.1	Calgary	ΑB	403-250-3027	STATE OF THE PARTY	aalborno@chartercoating.com
Goodfellow	Chevron Canada B.	Calgary	AB	403-250-20-2	+971-707-coa	bmorse@chartercoating.com
Hitchell	Carinta Resources	Calgary		1700.00	403-250-1254	charter (Ocatyleion com
A commendation of the company of manager of manager of manager of the company of	Ly Mitchell & Assoc, Ltd.	Calgary		403 234-5425	403 234-5124	HON HOLE THE STORY
JOHO TO THE	Clock Spring Company	ć m Ar	AB	403 279-7118	-	accidention.com
Harms		nouston	× ×	281-590-8491	,	cimitch@telusplanet.net
Boucher	The second secon	Calgary	AB	A02 250 40***		Pporter@clockspring.com
Webster	не Мануска да Мускуна подвержава пределава у склада у сущену у Суденува да да устанава у станава у станава ста	Calgary		No 4584187 3		harms.art@coltneg.com
Wallace	The second secon	Calgary		405-409-1888	403 258-5893	boucher derins montana
THE PROPERTY OF THE PROPERTY O	The state of the s	Calman		403 258-8675	403 258-5893	LIO CINCIPICATION CONTRACTOR CONT
Ci vensiade	Colt Engineering	(man)	AB	403 259-1811		websief, aavid@colleng.com
Hopkins	A STATE OF THE PROPERTY OF THE	Calgary	AB	403 250 4050		hwallace@cadvision.com
		Rock Springs		8091-807 co	403 258-5893	greenslade john Grooten
A marginal of Mathematical Commercials	Ited (PTC Pipeline)	75 A		307 382-4514	307 382-1198	H
*	fallind		X X	306 536-7520		III.M.hopkins@usa.conoco.com
Coote	TOTAL CHARGE AND	*	NO 44	416.630.2800	-	bruce.l.moore@can.conoco.com
Polland		Calgary		0007-000	416-636-9570 b	bqummownivenessistens and a second se
	Cornerstone Pipeline Inspection Group	The state of the s		403 247-1480	White and the same of the same	
			77	713-869-5040	713.889.7974	worken@nome.com

			Î		5	į.	
							NA OPERATOR AND
Greg	Ŧ	Corridor Pipeline	Sherwood Park	AB	780 416-2284	780 416-2447	gregh@corridorpipeline.com
Reynold	Hinger	Corridor Pipeline	Sherwood Park	AB	780 416-2446	780 416-2447	reynoldh@tmpl.ca
Daryl	Baxandall	CorrOcean Canada Inc.	Calgary	AB	403 286-0606	403 265-9750	daryl@corrocean.com
Alex	Patrusev	Corrosion Service Company Ltd.	Calgary	AB	403 233-2601	403 233-2658	apetrusev@corrosionservice.com
Trevor	Place	Corrosion Service Company Ltd.	Calgary	AB	403 233-2601	403 233-2658	tplace@corrosionservice.com
James	Ferguson	Corrosion Watch Inc.	Calgary	AB	403 517-2200	403 265-6338	jamesferguson@corrosionwatch.com
Daniel	Powell	Corrpro Canada Inc.	Calgary	AB	403 235-6400	403 272-4623	dan.powell@corrpro.ca
Dennis	Zadeny	Corrpro Canada Inc.	Calgary		A CONTRACTOR OF THE PROPERTY O		
Doug	Doran	Corrpro Canada Inc.	Calgary				
Grant	Firth	Corrpro Canada Inc.	Edmonton	АВ	780 447 4565	780 447-3215	grant.firth@corrpro.ca
Peter	Haas	Corrpro Canada Inc.	Calgary	ΑB	403 235-6400	403 272-9508	peter.haas@corrpro.ca
Zane	Reinhart	Corrpro Canada Inc.	Calgary	АВ	403 235-6400	403 272-8508	zane.reinhart@coпрго.ca
Sudi	Kalra	CSA International	Toronto	N	416 747-2794	416 747-2473	sudi.kalra@csa-international.org
Wayne	Duncan	CSI Coatings Systems Inc.	Edmonton	AB	780 955-2856	780 955-7215	wduncan@csicoating.com
Chukwueneka	Kwentua	Cynergy Limited	Lagos	Nigeria	01 584 4562	234-1-5844 568	rini@rci.nig.com
Darlington	Onuotta	Cynergy Limited	Lagos	Nigeria	01 584 4562	234-1-5844 568	rinl@rd.nig.com
Paul	Kwentua	Cynergy Limited	Lagos	Nigeria	01 584 4562	234-1-5844 568	rini@rd.nig.com
Iflanyic O.	Wisdom	Dar Sento Organisations	Lagos	Nigeria	01 545 4866	234-1-3050 611	darsento+N110@yahoo.com
Glenn	Macintosh	Denso North America Inc.	Sherwood Park	AB	780 910-1717	780 449-5300	glenn@densona.com
Jamle J.W.	Cox	DuPont Canada Inc.	Calgary	AB	403 254-6145	403 254-4129	jamie.cox@can.dupont.com
Glenn	Yuen	Dynamic Risk Assessment Systems Inc. Calgary	Calgary	АВ	403 547-8638	403 547-8628	glenn_yuen@dynamicrisk.net
Trevor	MacFarlane	Dynamic Risk Assessment Systems Inc. Calgary	Calgary	AB	403 547-8638	403 547-8628	trevor_macfarlane@dynamicrisk.net
William	Kantors	Eclipse Scientific Products	Calgary	AB	403-720-4822	519-794-4437	bkanters@eclipsescientfic.com
George	Prociw	Enbridge Consumers Gas	Scarborough	NO.	416 495-6332	416 495-5871	george.prociw@ecg.enbridge.com
Tanis	Elm	Enbridge Pipeline US	Dulfh	N	218-725-0100	218-725-0139	tanis.elm@uspl.enbridge.com
An	Meyer	Enbridge Pipelines Inc.	Edmonton	AB	780 420-8495	780 420-5389	art.meyer@cnpl.enbridge.com
Brad	Smith	Enbridge Pipelines Inc.	Edmonton	AB	780 420-8607	780 420-5234	brad.smith@cnpl.enbridge.com
Carey	Johannesson	Enbridge Pipelines Inc.	Calgary	AB	403-231-5984	403-231-7390	carey.johannesson@cnpl.enbridge.com
Carlos	Pardo	Enbridge Pipelines Inc.	Edmonton	AB	780 420-8434	780 420-5234	carlos.pardos@cnpl.enbridge.com
Deb	BIlley	Enbridge Pipelines Inc.	Edmonton	AB	780 420-5383	780 420-5234	deb.billey@cnpl.enbridge.com
Don	Engen	Enbridge Pipelines Inc.	Edmonton	AB	780 420-8715	780 420-5234	don.engen@cnpl.enbridge.com
Carrett	Wilkle	Character Dineth Control Contr	Edmonton	q	760 430 0430	700 400 6004	

POSICIE TORICOMEN				10	Phone	Fax X	E-Mall
der unschharmen kanten	THE CONTRACTOR CONTRACTOR PROPERTY OF THE CONTRACTOR OF T	The state of the s					
	Skalski	Enbridge Ploelings Inc	TO FROM THE WAY TO STATE OF THE PROPERTY OF TH	ALTHOUGH CONTRACTOR CO	AVOID THE PROPERTY OF THE PROP		
	Doblanko	Entriche Pinaling	Edmonton	AB	780 420-5368	780 420-8801	Of the supplementary of the su
	Ironside		Edmonton	AB.	780 420-5356	780 420 8904	John Shill Chpi enbridge.com
Afrikalist Communication of the	Dawa		Edmonton	AB	780 420-5267	700 430 430	rick.dobianko@cnpl.enbridge.com
	X	Etibriuge Pipelines Inc.	Edmonton	AB	780 430 0604	6070-074 nn -	scott.ironside@cnpl.enbridge.com
	Transference description of the contract of th	Enbridge Pipelines Inc.	Edmonton	1 0	100 450-6054	780 420-5234	shaun.dawe@cnpl.enbridge.com
	Christensen	F. M. Christensen Metallurgical Consulti	Urgical Consultin Ossalicum Decent	2 1	rau 420-8290	780 420-5234	walter.kresic@cnpl.enbridge.com
	Carroll			သူ	250 752-1467	206-973-0269	mental and the most of the comment o
VII.	Lazor	Fleet Technology Ltd.	ratiata	No.	613-592-2830	613-592-4950	bcarrol@fleetech com
	Ulsifer	Flint Field Services 1 th	camonton	AB	780 465-0077	780 465-0085	(Azor@lean
	Kelth	NA	Ked Deer	ΑB	403 342-8066	403 340-1066	Anteston and a second a second and a second and a second and a second and a second
	Hanes	***************************************	Calgary	AB	403 294 4446	403 584 4495	describe militaria y com
	Markement to the state of the s	Ses reciliology institute	DesPlaines	1	847 768 804	C 11 4 40 4 60 4	Kyle. Keith@foothillspipe.com
		Cas lecthology institute	Des Plaines		100 000	1060-997 /+0	harvey.haines@gastechnology.org
	Dyke	Geological Survey of Canada	Offawa	ج پ	847 768-0890	847 768-0501	keith leewis@gastechnology ord
The state of the s	Lukaniuk			5	613 996-1967	613 992-0190	ldyke@nrcan oc ra
	Meszaros	- con- con- con- con- con-	Cargary	ΑB	403-204-6174	403-204-6102	WAAA TATUURAA AA
••••	Morbacher	The state of the s	Calgary	AB	403 720-1192	403 204-1151	ED3 ale college
	Ho	The state of the s	Calgary	AB	403 260-6746	403 260.6704	Varietin@globaite.com
	Stuart	(BS)	Calgary	AB	403 260-8776	402 200 020	morbacherae@greenpipe.com
-			AAAA WAXAA TARAA AAAA AAAA AAAA AAAA AAAA AAAA			L079-007 con	billho@greenpipe.com
	Carrette		Calgary	AB	403 260 6700	And the second s	THE TRANSPORT OF THE TR
			Calgary		400 000 000	40.3 250-6701	donrobertson@greenpipe.com
-	Nng	Greenpipe Industries	Calcam		403 260-6748	403 260-6701	glenncameron@greenpipe.com
	Webster	The state of the s	· Kana		403 260-6714	403 260-6701	Greeneking@creensine.com
~	Alvares	The state of the s	Calgary	АВ	403 260-8776	403 260-6701	
-	Hardy	A STATE OF THE PARTY OF THE PAR	Calgary	AB	403 260-6702	403 260-6701	niatwebstet @greenpipe.com
	Lemon	W.V.C.C.C.C.C.C.C.C.C.C.C.C.C.C.C.C.C.C.	Calgary	AB	403 260-8787	ART SEA COAL	
	Coffee of the contract of the		Calgary	AB	403 280 8797	10/0-007 504	sharonhardy@greenpipe.com
7 3		sources	Calgar		77 70 70 70	403 260-6701	stevelemon@greenpipe.com
۲.	Nchois	HCI Canada Inc.	Rod Door		403 Z33-3039	403 233-5331	John_caffrey@quif.ca
٥	Don	HCI Canada inc.			403 391-1335	403 341-4609	Drichols@heissur.com
\$	Warner	THE PARTY OF THE P	Calgary	AB	403-720-5662	403-720-8174	
-5	Jacobson	AND THE RESERVE THE PARTY OF TH	Calgary	AB	403-232-0456	402.292.284.	WORLDWAY CON
ū	Fbara	The state of the s	Edmonton		780 457 4444		Jwarner@hciww.com
	Wilder Service Control of the Contro		Richmond			780 457-9700	Jacobson@icrossroads.com
=	narmeli	Hunter McDonnell Pipeline Services B	Billings		004 4/3-3200	604 273-6110	Jacobson@icrossroads.com
				•	C 200 000 000	A STATE OF THE PARTY OF THE PAR	The state of the s

BANFF 2001 PIPELINE WORKSHOP Managing Pipeline Integrity: A Workshop for Sharing Technology and Experience April 9 - 12, 2001

		EXCEPTION 1	2	L roy/st.	Phone	Fax	
Denene	Gelssler	Hunter McDonnell Pipeline Services	Edmonton	AB	780 436-4400 x 107	780 989-0040	denene@hmpsi.com
John	Chase	Hunter McDonnell Pipeline Services	Edmonton	AB	780 436-4400	780 989-0040	Jchase@hmpsi.com
Len	Krissa	Hunter McDonnell Pipeline Services	Edmonton	AB	780 436-4400 X 108 780 989-0040	780 989-0040	len@hmpsi.com
Shamus	McDonnell	Hunter McDonnell Pipeline Services	Edmonton	AB	780 436-4400 x 105 780 989-0040	780 989-0040	shamus@hmpsi.com
Scott	Amdt	Husky Olf	Lloydminster	₹	780 871-6553	780 871-6563	scoft.amdt@husky.oil.com
Doug R.	Adamson	Imperial Oil - Pipeline Operations	Nisku	AB	780 955-6159	780 955-6159	doug.adamson@esso.com
£	Cunningham	Imperial Oil - Pipeline Operations	Nisku	AB	780 955-6137	780 955-6139	ian.cunningham@esso.com
Loma	Harron	Imperial Oil - Pipeline Operations	NSKU	AB	780 955-6177	780 955-6139	lorna,harron@esso.com
Darryl	Shylan	Imperfal Oil Resources	Bonnyville	AB	780 639-5813	780 639-5102	darryl.shylan@iol.sprint.com
Reg	MacDonald	Imperial Oil Resources	Calgary	AB	403 237-2548	403 237-4195	reg_w_macdonald@email.mobil.com
Wayne H.	Fell	Imperial Oil Resources	Calgary	ΑB	403 237-2470	403 237-3319	wayne.feil@esso.com
ষ	Forth	Imperial Oil, Samia Products Pipeline	Waterdown	NO	905 689-6621	905 689-3553	al forth@esso.com
Jerald	Baccari	Integrity Assessment Group	Calgary	AB	403-296-3298	403-296-3296	baccari@lagroup.org
Francesco	Sorrentino	Integrity Service Consulting	Aurora	NO	905 754-0973	905 751-1039	sorrento@aci.on.ca
David	S S S S S S S S S S S S S S S S S S S	Invicta Corrision Services	Calgary	AB	403 288-8005		blackdg@3web.net
Dean	Bethune	IPEC Ltd.	Calgary	AB.	403 215-5446	403 215-5445	dean.buthune@ipectid.com
Tom	L.awrence	IPSCO Inc.	Regina	쏤	306 924-7385	(306) 924-7470	tawrence@ipsco.com
Richard	Edelmuth	Socan	Calgary	AB	403-253-0929	403-253-1904	isocan@lelusplanet.net
John	Hair	J.D. Hair & Associates, Inc.	Tulsa	ž	918-747-9945	918-742-7408	jhair@jdhair.com
i, yle	Gerlitz	JLG Engineering	Calgary	AB	403 547-7136	403 547-7138	Igeritz@telusplanet.net
Delton	Gray	Keyspan Energy Canada Inc.	Edmonton	AB	780 464-9133	780 467-5046	dellon_gray@keyspancanada.com
Martyn	Welden	Koch Pipelines Canada Ltd.	Calgary	AB	403 716-7586	403 716-7604	welden+N114m@kochind.com
Non	Нау	Koch Pipelines Canada Ltd.	Calgary	AB	403 716-7670	403 716-7604	hayn@kochind.com
Fraderic	Claridge	Komex International Ltd.	Calgary	AB	403 247-5713	403 247 4811	fclaridge@calgary.komex.com
Linda	Gray	KTA - Tator (Canada) Inc.	Edmonton	AB	780 440-9391	780 440-9405	igray@kta.com
Derek	Storey	Marr Associates	Calgary	ΑB	403 258-2233	403 258-1123	dstorey@marr-associates.com
E	War	Marr Associates	Calgary	AB	403 258-2233	403 258-1123	jmarr@marr-associates.com
Joei	Ashworth	Marr Associates	Calgary	AB	403 258-2233	403 258-1123	jashworth@marr-associates.com
Kar	Johnson	Marr Associates	Calgary	AB	403 258-2233	403 258-1123	mjohnson@marr-associates.com
Tracey	Cunningham	Marr Associates	Calgary	ΑB	403 258-2233	403 258-1123	tcunningham@marr-associates.com
Bruno	Romero	Maya Database & Internet Applic.	Calgary	AB	403 263-4848	403 263-9876	mayacode@cadvision.com
Jack	Cark	Memorial University of Newfoundland	St. John's	불	709 737-8350	709 737-4706	Jack, clark@c-core, ca

			ĵ		Phone	X	
APPROXIMATION CONTINUES AND APPROXIMATION	And the second s						
Roy	Baguley	Metal Engineers Int. Inc.		ALTERNATION OF THE PROPERTY AND THE PROP	THE PROPERTY OF THE PROPERTY O	AWAY COMPANY OF THE PROPERTY O	
Dennis W.	Hinnah	Mingrate Management Comments	COCUTANO	AB	403 932-4848	509 693-4153	metal@supernet ab ca
Paul E.	Maria	PAN ISC HOLLOS	Anchorage	¥	907 271-6514	907 271-6504	dennis hinahamman
Robert W.	Smith	mind dis management Service	Herndon	Ϋ́	703 787-1626	703 787.4549	TOTAL STREET, TO
7.6		Minorals Management Service	Herndon	ΑX	703 787 4590	17 27 202	Paul Hidi Will Will Boy
1652 1652		Minerals Management Service	Camarilio		2001-10-20-	103 (87-1548	robert.w.smith@mmc.gov
David	Feser	Mobil Oil Canada		¥5	805 389-7554	805 389-7592	theresa.bell@mms.gov
Pater	Warrock	Wobii Oil Canada	- Calgary	AB	403-260-7338	403-260-4332	david a feser@email mobil com
To a second seco	Poloway	Mobiltox Data I rd	Calgary	AB	403-260-7795	403-260-4332	peler m marreck@email mobil com
CONTRACTOR OF THE PARTY OF THE	Stavin	Mobiltex Data Ltd	Calgary	48	403-291-2770	403-250-6795	Kpoloway@mobiltex.com
Brad	Carson	Morrison Scientific Inc	Calgary	AB	403-291-2770	403-250-6795	rslevin@mobiltex com
	Desjardins	Horison Scientific to	Calgary	ΑВ	403-262-8160	403-264-3828	brad@morrisonsciantific com
Тот	Morrison	Morrison Scientific Inc.	Calgary	AB	403 262-8160	403 264-3828	duv@morrisonscientific com
Doug	Wasten	National France Documents	Calgary	AB	403 262-8160	403 264-3828	tom@morrisonscientific com
Dr. Framci	JEGLIC	National Control Contr	Calgary	AB	403 299-3680	403 292-5875	Cuzeler Crash and an an
Frank	Garoa	Marchial Ellery Board	Calgary	Æ	403 299-2774	403 292-5875	beautiful de la contraction de
The second secon	Daviestie	watches energy soard	Calgary	AB	403 299-3676	403 200 27es	10 Str. (Carlotte and Carlotte
Administration of the second s		National Energy Board	Calgary	AB	403 299-3864	465 565 5515	Igareau@neb.gc.c
TOTAL SECTION OF SECTION ASSESSMENT OF SECTI	Tp	National Energy Board	Calgary	QV		G/2C-7R7 COM	Jpaviglianiti@neb.gc.ca
awrence	Ator	National Energy Board	The second secon	2	403 288-3195	403 292-5875	kyip@neb.gc.ca
***************************************	Jansen	National Energy Board	Calan	AB.	403 292-4911	403 292-5875	lator@neb.gc.ca
	H	National Energy Board		AB	403 299-2777	403 292-5875	jansen@neb.gc.ca
Monica	Santander	National Fnerry Bown	Caigary	AB	403-299-2762	403-292-5503	mho@neb.ac.ca
Nancy	THE REAL PROPERTY OF THE PERSON NAMED IN	National English	Calgary	A8	403 299-3652	403 299-3100	msanlander@neb or ce
Nathan	***************************************	National Electric	Calgary	AB	403 299-3101	403 299-2785	odibole@neb or or
The second of th	la	The Color of the C	Calgary	AB	403 299-2794	403 292,5875	
to the same of the		National Energy Board	Calgary	AB		200	INCIN (WINDED DC.CA
7.III.a	Arbum of sabbulum on themses or themses	National Energy Board	Calgary	AR	AND DOC COL	THE PARTY IN COMMENT OF THE PARTY IN COLUMN TWO IS NOT THE PARTY IN COLUMN TO THE PARTY IN COLUMN TWO IS NOT THE PARTY IN CO	Office and the state of the sta
Wenyue		Natural Resources Canada	A Commence of the Commence of		403 285-3624	403 292-5503	rraad@neb.gc.ca
	Billette		O. C.	₹	613-922-7904	613-992-6735	wenyue@nrcan.gc.ca
	Tyson	Matter Rosenies	Ottawa	Õ	613 992-3738	613 995-6146	abilette@nran re-
Roger	Vooel	NOT E	Ottawa	N	613 992-9573	613 992-8735	hive and a second
	940		Stutensee	Germany	49(0)7244 74750	S	
	THE PERSON NAMED IN COLUMN	To the second se	Calgary		403 531,1926	Awara.	r.vogel@ndt-eng.de
Wave of Administration of Administration of the Administration of			Calgary			/761-1 CC COA	allan@neocorr-com
Cann	Radke	NeoCorr Engineering	The state of the s		THE REAL PROPERTY AND PERSONS ASSESSMENT AND PERSONS ASSESSMENT AND PERSONS ASSESSMENT A		bali@neocorr.com
		•		~			Obligament and a second

BANFF 2001 PIPELINE WORKSHOP Managing Pipeline Integrity: A Workshop for Sharing Technology and Experience April 9 - 12, 2001

Zenew etter	Sumame	Corporation	Clfy	Prov/St.	Phone	Fax	E-Mail
***************************************						WOOD OF THE PARTY	
Myles	Artym	NeoCarr Engineering	Calgary	AB	403 531-1926	403 531-1927	Activities to the control cont
Dorick	Nixon	Nixon Geotech Ltd.	Calgary	AB	403 226-0481	403 226-3902	derickn@cadvision.com
Charles	Savoie	Norwest Labs	Calgary	AB	THE PROPERTY OF THE PROPERTY O	**************************************	chucks@norwestlabs.com
Mary	Gale	NOVA Chemicals Corp.	Red Deer	AB	403 314-7491	403 314-8985	galem@novachem.com
Mary	Cate	NOVA Chemicals Corp.	Red Deer	AB		V-1-70 144 0 444 0	1904 (Auda administration and annual
Ray	Jones	NOVA Chemicals Corp.	Red Deer	AB	403 357-8319	***************************************	jonesr@novachem.com
Fraser	King	NOVA Research	Calgary	AB	403 250-4714	403 250-0633	kingf@novachem.com
Greg	Van Boven	Nova Research & Technology Centre	Calgary	AB	403 250-0601	403 250-0633	vanboveg@novachem.com
Katerine	lkeda-Cameron	Nova Research & Technology Centre	Calgary	AB	403 250-4706	403 250-0633	lkedack@novachem.com
Tom	Jack	Nova Research & Technology Centre	Calgary	AB	403 250-4751	403 250-0633	jacktr@novachem.com
Reg	Eadle	WRTC	Calgary	YB.	403 250-4526	403 250-0635	eadiere@novachem.com
Bruce	Fowfie	Nu-Trac Management Consulting Ltd.	Calgary	АВ	403 451-0387	403 251-0387	fowlieb@cadvision.com
John	Craig	Pacific Northern Gas Ltd.	Vancouver	BC	604-691-5857	604-691-5863	jcraig@wel.org
Alan	Miler	PanCanadian Resources	Calgary	AB	403 290-3340	403 290-2059	alan_miller@pcp.ca
Dave	Kwas	Pembina Pipeline Corporation	Calgary	АВ	403 231-7508	403 266-1177	dkwas@pembina.com
Pete	Donnelly	Pembina Pipeline Corporation	Drayton Valley	AB	780 542-5341 x 8516 780 542-2782	5780 542-2782	pdonnel@pembina.com
Phi	Gauthlor	Pengrowth Corporation	Swan HIIIs	AB	780 333-7109	780 333-7115	philg@pengrowth.com
Henry	Au	Petro-Canada	Caigary	AB	403 296-4750	403 296-5374	hau@petro-canada.ca
Bob	Smyth	Petro-Line	Nisku	ΑB	780-955-2401	403-955-3466	rsmyth@petroline.com
Chris	Pierce	Pierce Consulting Ltd.	Calgary	AB	403 335-7701	403 335-7569	cpierce@telusplanet.net
Brlan	Franks	Pil (Canada) Limitod	Calgary	AB	403 262-7447	403 237-9693	franks@pii-canada.com
Dary	Ronsky	Pii (Canada) Limited	Calgary	AB	403 262-7447	403 237-9693	ronskynd@pil-canada.com
Gary	Flannigan	Pil (Canada) Limited	Concord	NO	905 738-7559	905 738-7561	flannigan@pil-canada.com
Keith	Grimes	Pil (Canada) Limited	Cramlington	ž	011 191 247-3200	011 44 191 247-51	011 44 191 247-510 keith.grimes@pli-uk.com
Mohammed	Jaarah	Pil (Canada) Limited	Calgary	AB	403 262-7447	403 237-9693	jaarahm@pii-canada.com
Neb	Uzelak	Pli (Canada) Limited	Concord	NO	905 738-7559	905 738-7561	uzelacn@pii-canada.com
Tom	Sawyer	Pil (Canada) Limited	Houston	ΥL	713 849-6300	713 937-0740	sawyert@pil-usa.com
Bruce	Hagarman	Pil North America Inc.	Houston	¥	713-849-6332	713-9370740	hagermanb@pii-usa.com
Christine	Rubedeau	Pil North America inc.	Houston	¥	713-849-6346	713-937-0740	rubadeauc@pii-usa.com
Ravi	Krishnamurthy	Pli North America Inc.	Houston	×	713 849-6339	713 849-6300	krishnamurthyr@pii-usa.com
Robert	Vilyus	Pii North America Inc.	Houston	¥	713 849-6300	713 937-0740	vilyusr@pii-usa.com
lain	Colquhoun	Pipeline integrity international	Calgary	AB	403-241-3163		colquhol@pii-usa.com

80

		BANFF 2001 PIPELINE WORKSHOP Managing Pipeline Integrity: A Workshop for Sharing Technology and Experience April 9 - 12, 2001	BANFF 2001 PIPELINE WORKSHOP e Integrity: A Workshop for Sharing Tech April 9 - 12, 2001	E WORK for Sharin 2001	SHOP g Technology ar	d Experience	
Name	Surname	Corporation	City	Prov/St.	Phone	Fax	E-Mail
THE FOR CITY AND STORY AND	SSAVYMENT CONTROL OF C						
Serry	Wikinson	Positive Projects international Ltd.	Calgary	AB	403 235-1650	403 235.3740	
	Greanya	Positive Projects international Ltd.	Calgary	AB	403 235 48ED	4 D C C C C C C C C C C C C C C C C C C	yerry, wirantson@positiveprojects, com
Maury	Dumba	Positive Projects International Ltd.	Calgary	AB	403 225 4650	403 235-3710	lee.greanya@positiveprojects.com
Alan	Murray	Principla Consulting / ASME Pipeline Sub Caloany	Calgary	2	DC01-007-004	403 235-3710	maury.dumba@positiveprojects.com
Jasper	Price	Proactive Technologies Int'l Inc) mamo	P.	403 282-5637	403 289-9287	arrurray@ucalgary.ca
David	Munro	Queen's School of Business	Calgary	A 8	403-262-7885	403-264-0755	ptil@proactive.ca
Joel	Alden	A THE REAL PROPERTY OF THE PRO	Kingston	NO.	613-533-6000 ex.75836 613-533-6281	5613-533-6281	dave_munro@mbast.queensu.ca
Ramesh	Singh	27011 64	Kingston	3	613-533-6000 ex. 75821613-533-6281	1613-633-6281	Joel_aiden@mbast.queensu.ca
Barry	Martens	Reinform Divalles Comments	Edmonton	A.B	780 469-2401	780 468-2422	ramesh@raeinspection.com
Daryl	Rivest	Rivert Tork of the last of the	Sherwood Park	AB	780-449-5856	780-467-4368	barry i martens@email mobil com
Bryce	Brown	Rosen Pholice Inc.	Edmonton	AB	780-469-8333	780-469-8884	rivestg@xradiance.com
Rick	Steimaschuk	The state of the s	Houston	ĭ	281 442-8282	281 442-8866	bbrown@rosenitsa.com
Andra	***************************************		Calgary	AB	403 269-1191	403 204-8490	
Pob	THE WILL WILL WAS A STATE OF THE	KID Quality Services Inc.	Edmonton	AB	780 440-6600	780 440.2538	
nna :	Simmons	ic,	Edmonton	AB	780 488-3840	700 440 0220	alman aun @rdquality.com
Warshall	Rosichuk	RTD Quality Services Inc.	Edmonton) av	700 400 400	7 ou 440-2538	bsimmons@rtdquality.com
Richard	Kanla	Ğ.	Edmonton	2 4	700-408-3001	780-440-2538	mrosichuk@rtdquality.com
Dave	Russell	Ċ.	Fanotion Formation	2 :	780 440-6600	780 440-2538	rkonia@rtdquality.com
Jim	Yukes	The second of th		AB	780 468-6800	780 462-9378	drussell@russelltech.com
lan	Dowsett	7,110,000	Edmonton O-1	AB	780-468-6800	780-462-9378	lyukes@russelltech.com
Brian	Fung	Tile Contract of the Contract	Valgary Otto	AB	403 232-6771	403 232-6762	ian.dowsett@rwdiwest.com
Karol	Szkiarz	A CANADA CONTRACTOR MANAGEMENT OF THE CONTRACTOR	Cargary	AB	403 691-4289	403 691 4850	brian.fung@shell.ca
Ken	Kovacs		Calgary	AB	403 284-6550	403 284-6662	karol,szklarz@shell.ca
Dave	Toporowsky	Planting District	Calgary	AB	403 932-8316		ken.kovacs@shell.ca
Don	Herman	Pineline Division	cagary	AB	403 541-5319	403 245-5156	simmons@cadvision.com
Lorance	Pasiechnyk	Displication District	Cagaz	AB	403 244-5340	403 245-5156	simmons@cadvision.com
John	Baron	r sponso Division	Cagary		403 244-5340	403 245-5156	simmons@cadvision.com
Kelly	Mabbott	And the second s	Calgary		403 216-3485	403 216-3486	jbaron@skystone.ca
Wike	Hallpan	0.000	Calgary		403 216-3485	403 216-3486	kmabbott@skystone.ca
Paola	Bonandrini	717.7	Calgary	AB	403 216-3485	403 216-3486	mhallihan@skystone.ca
Doug	Macdonald	And a person in the purpose of the person of	Italy		39 02-52048686	39 02-52048617	padia bonandrini@snam ani it
Thomas	A THE RESIDENCE OF THE PROPERTY OF THE PROPERT		Calgary	AB	403 294-6657	403 294-2875	DECIMAL STATES
Jim	Banach		Edmonton	AB	780 413-4545	780 432-6063	muray@solomonashon
	- Carach	Specialty Polymer Coatings Inc.	Langley				im@spc.net.com
						1	